

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

96-11-06 De Havilland, Inc.: Amendment 39-9631. Docket 95-NM-110-AD.

**Applicability:** Model DHC-7 series airplanes, serial numbers 3 through 27 inclusive, on which de Havilland Modification No. 7/1697 has not been installed; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the emergency lighting system due to voltage spikes from other equipment or due to inadvertent override of the emergency lighting switches, accomplish the following:

(a) Within 6 months after the effective date of this AD, modify the emergency lights circuitry by accomplishing de Havilland Modification No. 7/1697 (Emergency Lights-Revised Switching Logic), in accordance with the Accomplishment Instructions of de Havilland Service Bulletin No. 7-33-7, dated October 17, 1980.

(b) As of the effective date of this AD, no person shall install an emergency light switch, part number MS24659-21A, on any airplane subject to this AD.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) The modification shall be done in accordance with de Havilland Service Bulletin No. 7-33-7, dated October 17, 1980. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained

from Bombardier, Inc., Bombardier Regional Aircraft Division, Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, Engine and Propeller Directorate, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on June 28, 1996.

Issued in Renton, Washington, on May 15, 1996.

S.R. Miller,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 96-12729 Filed 5-23-96; 8:45 am]

BILLING CODE 4910-13-U

**14 CFR Part 39**

[Docket No. 95-NM-197-AD; Amendment 39-9632; AD 96-11-07]

RIN 2120-AA64

**Airworthiness Directives; Learjet Model 31 and 35A Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Learjet Model 31 and 35A airplanes, that requires replacement of two segments of 16 American Wire Gauge (AWG) wire with 8 AWG wire at the connector that is connected to the auxiliary cabin heater relay box. This amendment is prompted by a report that two segments of the 16 AWG wire in the auxiliary cabin heater that were spliced during production do not provide adequate current-carrying capacity. The actions specified by this AD are intended to prevent electrical arcing and a subsequent fire hazard that could result from wiring with inadequate current-carrying capacity.

**DATES:** Effective June 28, 1996.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 28, 1996.

**ADDRESSES:** The service information referenced in this AD may be obtained from Learjet, Inc., One Learjet Way, Wichita, Kansas 67209-2942. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office,

Small Airplane Directorate, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Dale Bleakney, Aerospace Engineer, Flight Test Branch, ACE-117W, FAA, Small Airplane Directorate, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; telephone (316) 946-4135; fax (316) 946-4407.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Learjet Model 31 and 35A airplanes was published in the Federal Register on March 7, 1996 (61 FR 9119). That action proposed to require replacement of two segments of 16 AWG wire with 8 AWG wire at the P190 connector that is connected to the E33 auxiliary cabin heater relay box.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

**Conclusion**

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

**Cost Impact**

There are approximately 52 Learjet Model 31 and 35A airplanes of the affected design in the worldwide fleet. The FAA estimates that 44 airplanes of U.S. registry will be affected by this AD, that it will take approximately 4 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will be supplied by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$10,560, or \$240 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

**Regulatory Impact**

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various

levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

96-11-07 Learjet, Inc.: Amendment 39-9632. Docket 95-NM-197-AD.

*Applicability:* Model 31 airplanes having serial numbers 31-002 through 31-029 inclusive, and Model 35A airplanes having serial numbers 35-647 through 35-670 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not

been eliminated, the request should include specific proposed actions to address it.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent electrical arcing and subsequent fire hazard, accomplish the following:

(a) Within 6 months after the effective date of this AD, replace two segments of 16 American Wire Gauge (AWG) wire with 8 AWG wire at the P190 connector that is connected to the E33 auxiliary cabin heater relay box, in accordance with Learjet Service Bulletin SB 31-21-10, dated August 11, 1995 (for Model 31 airplanes), or Learjet Service Bulletin SB 35-21-24, dated August 11, 1995 (for Model 35A airplanes), as applicable.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA, Small Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The replacement shall be done in accordance with Learjet Service Bulletin SB 31-21-10, dated August 11, 1995, or Learjet Service Bulletin SB 35-21-24, dated August 11, 1995, as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Learjet, Inc., One Learjet Way, Wichita, Kansas 67209-2942. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, Small Airplane Directorate, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on June 28, 1996.

Issued in Renton, Washington, on May 15, 1996.

S.R. Miller,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 96-12730 Filed 5-23-96; 8:45 am]

**BILLING CODE 4910-13-U**

### **14 CFR Part 39**

[Docket No. 95-NM-85-AD; Amendment 39-9630; AD 96-11-05]

**RIN 2120-AA64**

### **Airworthiness Directives; Airbus Industrie Model A300, A300-600, and A310 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Airbus Industrie Model A300, A300-600, and A310 series airplanes, that requires inspections to detect cracks in the lower spar axis of the pylons between ribs 6 and 7, and repair, if necessary. This amendment is prompted by reports that fatigue cracking has been found on the lower spar of the pylon. The actions specified by this AD are intended to prevent such fatigue cracking, which could result in reduced structural integrity of the lower spar of the pylon.

**DATES:** Effective June 28, 1996.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 28, 1996.

**ADDRESSES:** The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Tim Backman, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2797; fax (206) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Airbus Industrie Model A300, A300-600, and A310 series airplanes was published in the Federal Register on March 6, 1996 (61 FR 8892). That action proposed to require inspections to detect cracks in the lower spar axis of the pylons between ribs 6 and 7, and repair, if necessary.

Interested persons have been afforded an opportunity to participate in the