

may be incurred and the imposition of assessments.

The assessment rate recommended by the Committee for the 1995–96 crop year was derived by dividing anticipated expenses by expected receipts and acquisitions of farmers' stock peanuts. It applies to all assessable peanuts received or acquired by handlers from July 1, 1995. Farmers' stock peanuts received or acquired by handlers signatory to the agreement, other than from those described in §§ 998.31 (c) and (d), are subject to assessments. Because that rate is applied to actual receipts and acquisitions, it must be established at a rate which will produce sufficient income to pay the Committee's expenses. Approximately 95 percent of the domestically produced peanut crop is marketed by handlers who are signatory to the agreement.

Public Law 101–220 amended section 608b of the Act to require that all peanuts handled by persons who have not entered into the agreement (non-signers) be subject to quality and inspection requirements to the same extent and manner as are required under the Agreement. Approximately 5 percent of the U.S. peanut crop is marketed by non-signer handlers.

Public Law 103–66 (107 Stat. 312) provides for mandatory assessment of farmers' stock peanuts acquired by non-signatory peanut handlers. Under this law, paragraph (b) of section 1001, of the Agricultural Reconciliation Act of 1993, specified that: (1) Any assessment (except indemnification assessments) imposed under the Agreement on signatory handlers also shall apply to non-signatory handlers, and (2) such assessment shall be paid to the Secretary.

The 1995–96 Committee budget was published in the Federal Register as an interim final rule on May 17, 1995 (60 FR 26348), and finalized on July 18, 1995 (60 FR 36635). The non-signatory handler assessment rate was published in the Federal Register as an interim final rule on August 21, 1995 (60 FR 43353), and finalized on November 24, 1995 (60 FR 57907). The administrative expenses and assessment rate for the 1995–96 crop year were based on an estimated assessable tonnage of 1,525,000. The Committee now projects that total tonnage will only be about 1,300,000. In order to have sufficient revenue to cover budgeted expenses of \$1,067,500, the Committee met on March 19, 1996, and unanimously recommended that the 1995–96 crop year administrative assessment be increased from \$0.70 to \$0.83 per net ton of assessable farmers' stock peanuts.

An interim final rule regarding this action was published in the June 13, 1996, issue of the Federal Register (61 FR 29926). That interim final rule amended §§ 997.100 and 998.408 to increase the administrative assessment rate for the 1995–96 crop year for the Committee and non-signatory handlers. That rule provided that interested persons could file comments through July 15, 1996. No comments were received.

While this action will impose some additional costs on handlers, the costs are in the form of uniform assessments on all handlers signatory to the agreement. Some of the additional costs may be passed on to producers. However, these costs will be significantly offset by the benefits derived from the operation of the marketing agreement. This administrative assessment is required by law to be applied uniformly to all non-signatory handlers and will be of benefit to all. Therefore, the AMS has determined that this rule will not have a significant economic impact on a substantial number of small entities.

After consideration of all relevant material presented, including the information and recommendations submitted by the Committee and other available information, it is hereby found that this rule, as hereinafter set forth, will tend to effectuate the declared policy of the Act.

Pursuant to 5 U.S.C. 553, it is also found and determined that good cause exists for not postponing the effective date of this rule until 30 days after publication in the Federal Register because: (1) The Committee needs to have sufficient funds to pay its expenses which are incurred on a continuous basis; (2) Public Law 103–66 requires the Department to impose an administrative assessment on peanuts received or acquired for the account of non-signatory handlers; (3) the 1995–96 crop year began on July 1, 1995, and the marketing agreement and Pub. L. 103–66 require that the rate of assessment for the crop year apply to all peanuts handled during the crop year; (4) handlers are aware of this action which was unanimously recommended by the Committee at a public meeting and is similar to other budget actions issued in past years; and (5) an interim final rule was published on this action and provided for a 30-day comment period, and no comments were received.

## List of Subjects

### 7 CFR Part 997

Food grades and standards, Peanuts, Reporting and recordkeeping requirements.

### 7 CFR Part 998

Marketing agreements, Peanuts, Reporting and recordkeeping requirements.

## PART 997—PROVISIONS REGULATING THE QUALITY OF DOMESTICALLY PRODUCED PEANUTS HANDLED BY PERSONS NOT SUBJECT TO THE PEANUT MARKETING AGREEMENT

## PART 998—MARKETING AGREEMENT REGULATING THE QUALITY OF DOMESTICALLY PRODUCED PEANUTS

Accordingly, the interim final rule amending 7 CFR parts 997 and 998 to increase the administrative assessment rates which was published at 61 FR 29926 on June 13, 1996, is adopted as a final rule without change.

Dated: August 9, 1996.

Robert C. Keeney,  
Director, Fruit and Vegetable Division.  
[FR Doc. 96–20790 Filed 8–19–96; 8:45 am]  
BILLING CODE 3410–02–P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 96–NM–54–AD; Amendment 39–9718; AD 96–17–09]

RIN 2120–AA64

### Airworthiness Directives; Beech (Raytheon) Model Hawker 1000 and BAe 125–1000A Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

**SUMMARY:** This amendment supersedes an existing airworthiness directive (AD), applicable to certain Beech (Raytheon) Model Hawker 1000 and BAe 125–1000A series airplanes, that currently requires inspections to detect various discrepancies of the fuel hose assemblies on the auxiliary power unit (APU), and correction of any discrepancy found. That AD was prompted by several reports of heat damage to the fuel hose assembly on the APU. This amendment adds a requirement to replace the existing conduit of the fuel feed hose with new

improved conduit, which will terminate the repetitive inspections. The actions specified by this AD are intended to prevent failure of a fuel hose due to heat damage caused by incorrect routing or bleed air leakage; such failure could result in a malfunction of the APU, a fuel fire in the fuselage rear equipment bay, and reduced structural integrity of the surrounding structure.

**DATES:** Effective September 24, 1996.

The incorporation by reference of Beech (Raytheon/Hawker) Service Bulletin SB.49-47-25A825A, dated August 1, 1995, listed in the regulations is approved by the Director of the Federal Register as of September 24, 1996.

The incorporation by reference of Raytheon Service Bulletin SB 49-44, dated January 20, 1995, listed in the regulations was approved previously by the Director of the Federal Register as of May 23, 1995 (60 FR 22501, May 8, 1995).

**ADDRESSES:** The service information referenced in this AD may be obtained from Beech Aircraft Corporation, Hawker Customer Support Department, P.O. Box 85, Wichita, Kansas 67201-0085. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, Small Airplane Directorate, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Karl Schletzbaum, Aerospace Engineer, ACE-116W, Wichita Aircraft Certification Office, FAA, Small Airplane Directorate, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; telephone (316) 946-4146; fax (316) 946-4407.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 95-10-01, amendment 39-9218 (60 FR 22501, May 8, 1995), which is applicable to certain Beech (Raytheon) Model Hawker 1000 and BAe 125-1000A series airplanes, was published in the Federal Register on May 21, 1996 (61 FR 25418). That action proposed to supersede AD 95-10-01 to continue to require inspections to detect various discrepancies of the fuel hose assemblies on the auxiliary power unit (APU), and correction of any discrepancy found. That action also proposed to add a new requirement to

replace the existing vinyl conduit of the fuel feed hose for the APU with a new improved conduit, which would constitute terminating action for the repetitive inspection requirements.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### Cost Impact

There are approximately 48 Beech Model Hawker 1000 and BAe 125-1000A series airplanes of the affected design in the worldwide fleet. The FAA estimates that 31 airplanes of U.S. registry will be affected by this proposed AD.

The actions that are currently required by AD 95-10-01 and retained in this new AD take approximately 1 work hour per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact on U.S. operators of the actions currently required is estimated to be \$1,860, or \$60 per airplane.

The new actions that are required by this new AD will take approximately 4 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts will cost approximately \$218 per airplane. Based on these figures, the cost impact on U.S. operators of the new requirements of this AD is estimated to be \$14,198, or \$458 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

#### Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44

FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-9218 (60 FR 22501, May 8, 1995), and by adding a new airworthiness directive (AD), amendment 39-9718, to read as follows:

96-17-09 Beech Aircraft Corporation (formerly DeHavilland; Hawker Siddeley; British Aerospace, plc; Raytheon Corporate Jets, Inc.): Amendment 39-9718. Docket 96-NM-54-AD. Supersedes AD 95-10-01, Amendment 39-9218.

*Applicability:* Model Hawker 1000 and BAe 125-1000A series airplanes, post modification 259722C; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Note 2: Beech (Raytheon) Model BAe 125-1000B series airplanes are similar in design to the airplanes that are subject to the requirements of this AD and, therefore, also may be subject to the unsafe condition

addressed by this AD. However, as of the effective date of this AD, those models are not type certificated for operation in the United States. Airworthiness authorities of countries in which the Model BAe 125-1000B series airplanes are approved for operation should consider adopting corrective action, applicable to those models, that is similar to the corrective action required by this AD.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of a fuel hose assembly on the auxiliary power unit (APU), which could result in a malfunction of the APU, a potential fuel fire in the fuselage rear bay, and reduced structural integrity of the surrounding structure, accomplish the following:

(a) Within 30 days after May 23, 1995 (the effective date of AD 95-10-01, amendment 39-9218), perform inspections to detect discrepancies of the fuel feed hose assemblies on the APU; an inspection to assure proper positioning of the air leak detection system; and an inspection of the bleed air system for signs of leakage; in accordance with paragraph 2.B. of the Accomplishment Instructions of Raytheon Service Bulletin SB 49-44, dated January 20, 1995.

(1) If no discrepancy is found: Thereafter, following the last flight of each day, perform an inspection to detect discoloration of the fuel hose assembly (outlet from the fuel pump box) on the APU, in accordance with paragraph 2.B.(2) and 2.C. of the Accomplishment Instructions of the service bulletin.

(2) If any discrepancy is found, prior to further flight, correct the discrepancy in accordance with paragraph 2.B. of the Accomplishment Instructions of the service bulletin.

(b) Within 200 flight hours after the effective date of this AD, replace the existing conduit of the fuel feed hose for the auxiliary power unit (APU) with new improved conduit (modification 25A825A), in accordance with Beech (Raytheon/Hawker) Service Bulletin SB.49-47-25A825A, dated August 1, 1995. Accomplishment of the replacement constitutes terminating action for paragraph (a) of this AD.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA, Small Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) The actions shall be done in accordance with Raytheon Service Bulletin SB 49-44,

dated January 20, 1995, or Beech (Raytheon/Hawker) Service Bulletin SB.49-47-25A825A, dated August 1, 1995. The incorporation by reference of Beech (Raytheon/Hawker) Service Bulletin SB.49-47-25A825A, dated August 1, 1995, was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. The incorporation by reference of Raytheon Service Bulletin SB 49-44, dated January 20, 1995, was approved previously by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51 as of May 23, 1995 (60 FR 22501, May 8, 1995). Copies may be obtained from Beech Aircraft Corporation, Hawker Customer Support Department, P.O. Box 85, Wichita, Kansas 67201-0085. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, Small Airplane Directorate, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on September 24, 1996.

Issued in Renton, Washington, on August 12, 1996.

Darrell M. Pederson,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 96-21009 Filed 8-19-96; 8:45 am]

BILLING CODE 4910-13-U

#### 14 CFR Part 39

[Docket No. 95-NM-255-AD; Amendment 39-9719; AD 96-17-10]

RIN 2120-AA64

#### **Airworthiness Directives; Beech Model 400, 400A, MU-300-10, and 2000 Airplanes, and Model 200, B200, 300, and B300 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Beech Model 400, 400A, MU-300-10, and 2000 airplanes, and Model 200, B200, 300, and B300 series airplanes, that requires replacement of outflow/safety valves with serviceable valves. This amendment is prompted by a report of cracking and subsequent failure of outflow safety valves in the pressurization system. The actions specified by this AD are intended to prevent such cracking and subsequent failure of the outflow/safety valves, which could result in rapid decompression of the airplane.

**DATES:** Effective September 24, 1996.

The incorporation by reference of certain publications listed in the

regulations is approved by the Director of the Federal Register as of September 24, 1996.

**ADDRESSES:** The service information referenced in this AD may be obtained from AlliedSignal Aerospace, Technical Publications, Dept. 65-70, P.O. Box 52170, Phoenix, Arizona 85072-2170. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, Transport Airplane Directorate, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Walter Eierman, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (310) 627-5336; fax (310) 627-5210.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Beech Model 400, 400A, MU-300-10, and 2000 airplanes, and Model 200, B200, 300, and B300 series airplanes was published in the Federal Register on April 15, 1996 (61 FR 16416). That action proposed to require replacement of certain discrepant outflow/safety valves with serviceable valves.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### **Cost Impact**

There are approximately 150 Beech Model 400, 400A, MU-300-10, and 2000 airplanes, and Model 200, B200, 300, and B300 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 105 airplanes of U.S. registry will be affected by this AD, that it will take approximately 12 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. The parts manufacturer has advised that it will provide replacement parts at no cost to operators. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$75,600, or \$720 per airplane.