

accordance with the applicable service bulletin.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The actions shall be done in accordance with Shorts Service Bulletin SD330-27-34, dated September 12, 1995; Shorts Service Bulletin SD360-27-24, dated September 12, 1995; or Shorts Service Bulletin SD3 SHERPA-27-1; dated September 12, 1995; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Short Brothers PLC, 2011 Crystal Drive, Suite 713, Arlington, Virginia 22202-3719. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on November 29, 1996.

Issued in Renton, Washington, on October 10, 1996.

S.R. Miller,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96-26718 Filed 10-23-96; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-CE-45-AD; Amendment 39-9788; AD 96-21-11]

RIN 2120-AA64

Airworthiness Directives; The New Piper Aircraft, Inc. (Formerly Piper Aircraft Corporation) PA31, PA31P, and PA31T Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule

SUMMARY: This amendment supersedes Airworthiness Directive (AD) 93-25-08, which currently requires replacing the main landing gear (MLG) actuator reinforcement bracket with a part of

improved design on certain The New Piper Aircraft, Inc. (Piper) PA31, PA31P, and PA31T series airplanes. This AD action will require the same action as AD 93-25-08. An incorrect designation of Piper Model PA31-310 airplanes made in AD 93-25-08 prompted the proposed AD action. The actions specified by this AD are intended to prevent the MLG from extending, when not selected and while the airplane is in flight, caused by actuator reinforcement bracket failure, which could result in substantial airplane damage or loss of control of the airplane.

DATES: Effective December 16, 1996.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 16, 1996.

ADDRESSES: Service information that applies to this AD may be obtained from The New Piper Aircraft, Inc., Attn: Customer Service, 2926 Piper Dr., Vero Beach, Florida 32960. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket 95-CE-45-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Christina Marsh, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, Campus Building, 1701 Columbia Avenue, suite 2-160, College Park, Georgia 30337-2748; telephone (404) 305-7362; facsimile (404) 305-7348.

SUPPLEMENTARY INFORMATION:

Events Leading to This Action

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to Piper PA31, PA31P, and PA31T series airplanes was published in the Federal Register on May 3, 1996 (61 FR 19865). This action would supersede AD 93-25-08 with a new AD that would retain the same requirements as AD 93-25-08 and change the model designation in the Applicability section from Piper Model PA31-310 airplanes to Piper Model PA31 airplanes.

Related Service Information

Accomplishment of this action will be in accordance with Piper Service Bulletin (SB) No. 923, dated August 16, 1989.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

Cost Impact

The FAA estimates that 2,448 airplanes in the U.S. registry will be affected by this AD, that it will take 4 workhours per airplane to accomplish the inspection and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$308 per airplane. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$1,341,504. This AD requires the same action as AD 93-25-08. The only difference between this AD and AD 93-25-08 is the change in model designation from PA31-310 to PA31. With this in mind, the proposed action would not provide any additional cost impact upon U.S. operators over that already required by AD 93-25-08.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy

of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:
 Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing AD 93-25-08, Amendment 39-8774, and by adding a new airworthiness directive (AD) to read as follows:

96-21-11 The New Piper Aircraft, Inc.:
 Amendment 39-9788, Docket No. 95-CE-45-AD; Supersedes AD 93-25-08, Amendment 39-8774.

Applicability: The following Model and serial number airplanes, certificated in any category.

Model	Serial No.
PA31, PA31-300, and PA31-325.	31-2 through 31-8312019.
PA31-350	31-5001 through 31-8553002.
PA31P	31P-1 through 31P-7730012.
PA31P-350	31P-8414001 through 31P-8414050.
PA31T	31T-7400001 through 31T-8120104.
PA31T1	31T-7804001 through 31T-8304003 and 31T-1104004 through 31T-1104017.
PA31T2	31T-8166001 through 31T-8166076 and 31T-1166001 through 31T-1166008.
PA31T3	31T-8275001 through 31T-8475001 and 31T-5575001.

Note 1: This AD applies to each airplane identified in the preceding applicability revision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an

alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 200 hours time-in-service (TIS) after February 11, 1994 (effective date of AD 93-25-08) or within the next 25 hours TIS after the effective date of this AD, whichever occurs later, unless already accomplished.

To prevent the main landing gear (MLG) from extending, when not selected and while the airplane is in flight, because of actuator reinforcement bracket failure, which could result in substantial airplane damage or loss of control of the airplane, accomplish the following:

(a) Replace any MLG actuator reinforcement bracket having part number (P/N) 40776-00 with a new MLG actuator reinforcement bracket, P/N 73786-02, in accordance with the INSTRUCTIONS section of Piper Service Bulletin (SB) No. 923, dated August 16, 1989.

(b) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, FAA, Atlanta Aircraft Certification Office, Campus Building, 1701 Columbia Avenue, suite 2-160, College Park, Georgia 30337-2748. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta Aircraft Certification Office.

(d) Alternative methods of compliance approved in accordance with AD 93-25-08 (superseded by this action) are considered approved as alternative methods of compliance with this AD.

(e) The replacement required by this AD shall be done in accordance with Piper Service Bulletin No. 923, dated August 16, 1989. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from The New Piper Aircraft, Inc., Attn: Customer Service, 2926 Piper Dr., Vero Beach, Florida, 32960. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment supersedes AD 93-25-08, Amendment 39-8774.

(g) This amendment (39-9738) becomes effective on December 16, 1996.

Issued in Kansas City, Missouri, on October 10, 1996.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96-26751 Filed 10-23-96; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 96-AAL-17]

Revision of Class E Airspace; Port Heiden, AK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action revises Class E airspace at Port Heiden Airport, AK. The development of a Very High Frequency (VHF) omni-directional radio range (VOR)/Distance Measuring Equipment (DME) instrument approach to RWY 13 at Port Heiden, AK, has made this action necessary. The intended effect of this action is to provide adequate controlled airspace for IFR operations at Port Heiden Airport, AK.

EFFECTIVE DATE: 0901 UTC, January 30, 1997.

FOR FURTHER INFORMATION CONTACT: Robert van Haastert, System Management Branch, AAL-538, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-7587; telephone number (907) 271-5863.

SUPPLEMENTARY INFORMATION:

History

On July 29, 1996, a proposal to amend part 71 of the Federal Aviation Regulations (14 CFR part 71) to revise the Class E airspace at Port Heiden was published in the Federal Register (61 FR 39368). The development of a VOR/DME instrument approach procedure to RWY 13 at Port Heiden Airport, AK, has made this action necessary.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments to the proposals were received, thus, the rule is adopted as written.

The coordinates for this airspace docket are based on North American Datum 83. Class E airspace areas designated as 700/1200 foot transition areas are published in Paragraph 6005 of Federal Aviation Administration Order 7400.9D, dated September 4, 1996, and effective September 16, 1996, which are incorporated by reference in 14 CFR