

has examined the findings of the CTA; reviewed all available information, including the service information referenced above; and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of the Provisions of the Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop in other Aeromot Models AMT-100 and AMT-200 powered gliders of the same type design registered in the United States, the proposed AD would require replacing all main landing gear attaching bolts and nuts with attaching bolts and nuts of improved design. Accomplishment of the proposed action would be in accordance with Aeromot SB No. SB-200-32-044, Issue Date August 18, 1997.

Cost Impact

The FAA estimates that 18 powered gliders in the U.S. registry would be affected by the proposed AD, that it would take approximately 1 workhour per powered glider to accomplish the proposed action, and that the average labor rate is approximately \$60 an hour. Parts are provided by the manufacturer at no cost. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$1,080 for the fleet or \$60 per glider.

Compliance Time

The compliance time of the proposed AD is in calendar time instead of hours time-in-service (TIS). The average monthly usage of the affected glider ranges throughout the fleet. For example, one owner may operate the glider 25 hours TIS in one week, while another operator may operate the glider 25 hours TIS in one year. In order to ensure that all of the owners/operators of the affected gliders have replaced the attaching bolts and nuts on the main landing gear within a reasonable amount of time, the FAA is proposing a compliance time of 30 calendar days.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

Aeromot-Industria Mecanico Metalurgica LTDA: Docket No. 97-CE-78-AD.

Applicability: Model AMT-100 powered gliders (serial numbers (S/N) 100.001 through 100.039 and 100.041 through 100.044) and Model AMT-200 powered gliders (S/N 200.040 and 200.045 through 200.080), certificated in any category.

Note 1: This AD applies to each glider identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For gliders that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 30 calendar days after the effective date of this AD, unless already accomplished.

To prevent failure of the main landing gear, which could cause loss of control of the

sailplane during landing operations, accomplish the following:

(a) Replace all main landing gear attaching bolts (part number (P/N) TH 6x30 PL11 or an FAA-approved equivalent part number) and nuts (P/N 6 PA-108 or an FAA-approved equivalent part number) with attaching bolts (P/N DIN 931 M6x30 (Pitch 1.0) Class 10.9 or an FAA-approved equivalent part number) and nuts (P/N DIN 982 M6 (Pitch 1.0) or an FAA-approved equivalent part number) in accordance with the Procedures section in AEROMOT-IND. MECANICO-METALURGICA LTDA. Service Bulletin No. SB-200-32-044, Issue Date August 18, 1997.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the glider to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Blvd., suite 450, Atlanta, Georgia 30349. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta Aircraft Certification Office.

(d) All persons affected by this directive may obtain copies of this document referred to herein upon request to Grupo Aeromot, Aeromot-Industria Mecanico Metalurgica Ltda., Av. das Industrias-1210, Bairro Anchieta, Caixa Postal 8031, 90200-Porto Alegre-RS, Brazil; or may examine these documents at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Note 3: The subject of this AD addresses Brazilian CTA AD 97-09-06, dated August 14, 1997.

Issued in Kansas City, Missouri, on November 17, 1997.

Larry E. Werth,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 97-30866 Filed 11-24-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-138-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-400 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 747-400 series airplanes. This proposal would require removal and reconfiguration of the battery grounds of the auxiliary power unit (APU). This proposal is prompted by reports of smoke or fire coming from the APU due to battery grounds that were not installed or maintained properly. The actions specified by the proposed AD are intended to prevent overheating and heat damage of the APU battery grounds due to improper installation of the APU battery ground, which could result in heat damage and consequent smoke or fire on the airplane.

DATES: Comments must be received by January 9, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-138-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207.

This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Forrest Keller, Senior Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington; telephone (425) 227-2790; fax (425) 227-1181.

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-138-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-138-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports of smoke or fire during ground operation and after auxiliary power unit (APU) start that occurred below the APU battery ground on certain Boeing Model 767 series airplanes. Investigation revealed that the APU, which has a pre-installed, single-ground, single-lug configuration, was the possible source of ignition; fuel for the fire was attributed to debris in the area. Further investigation revealed that an APU battery ground wire connection was loose and the torque of the nut (less than 140 inch-pounds) was less than the minimum (180 inch-pounds) necessary for the ground configuration. The APU battery ground showed signs of arcing and did not have the two washers necessary for the ground build-up. Such improper installation or maintenance, if not corrected, could result in heat damage to the battery grounds of the APU and consequent smoke or fire on the airplane.

Related AD's

On July 11, 1997, the FAA issued AD 97-15-09, amendment 39-10083 (62 FR 38204, July 17, 1997), applicable to all Boeing Model 757 and 767 series airplanes. That AD requires repetitive inspections to detect damage and to verify proper configuration of the battery ground terminations of the APU at the battery and connected structure; and removal, replacement, and repair of the battery ground termination, if

necessary. That AD was prompted by reports of smoke or fire coming from the APU due to battery grounds that were not installed or maintained properly.

Similar Model Subject to the Unsafe Condition

APU battery ground configurations installed on Boeing Model 757 and 767 series airplanes are similar to those APU battery grounds installed on Boeing Model 747-400 series airplanes; therefore, Model 747-400 series airplanes may be subject to the same unsafe condition described previously.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 747-24A2214, dated June 19, 1997, which describes procedures for reconfiguring the APU battery grounds from a single-ground, single-lug configuration to a dual-direct ground, single-lug configuration. This new configuration has less mounting hardware and a larger electrical bonding surface area, which will prevent overheating of the APU battery ground due to improper installation of the APU battery grounds.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require reconfiguring the APU battery grounds from a single-ground, single-lug configuration to a dual-direct ground, single-lug configuration. The actions would be required to be accomplished in accordance with the alert service bulletin described previously.

Cost Impact

There are approximately 359 Model 747-400 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 26 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 16 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$1,325 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$59,410, or \$2,285 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 97-NM-138-AD.

Applicability: Model 747-400 series airplanes; as listed in Boeing Alert Service Bulletin 747-24A2214, dated June 19, 1997; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an

alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the auxiliary power unit (APU) from overheat and heat damage due to an improperly installed/maintained APU battery ground, accomplish the following:

(a) Within 6 months after the effective date of this AD, reconfigure the APU battery grounds to a dual-direct ground, single-lug configuration, in accordance with Boeing Alert Service Bulletin 747-24A2214, dated June 19, 1997.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 18, 1997.

James V. Devany,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 97-30868 Filed 11-24-97; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-11-AD]

RIN 2120-AA64

Airworthiness Directives; Lockheed Model L-1011-385 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to all Lockheed Model L-1011-385 series airplanes, that currently requires inspections to detect cracking and other discrepancies of certain web-to-cap

fasteners of the rear spar between inner wing stations (IWS) 310 and 343, and of the web area around those fasteners; and various follow-on actions. That AD also provides for an optional modification, which, if accomplished, would defer the initiation of the inspections for a certain period of time. This action would require accomplishment of the previously optional modification. This proposal is prompted by an FAA determination that the optional terminating modification specified in the existing AD must be accomplished within a specified period of time to ensure an acceptable level of safety of the affected fleet. The actions specified by the proposed AD are intended to prevent fatigue cracking in the web of the rear spar of the wing, which could result in failure of the rear spar of the wing and consequent fuel spillage.

DATES: Comments must be received by January 5, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-11-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Lockheed Aeronautical Systems Support Company (LASSC), Field Support Department, Dept. 693, Zone 0755, 2251 Lake Park Drive, Smyrna, Georgia 30080. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia.

FOR FURTHER INFORMATION CONTACT: Thomas Peters, Aerospace Engineer, Systems and Flight Test Branch, ACE-116A, FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30337-2748; telephone (770) 703-6063; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address