

various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

McDonnell Douglas: Docket 97-NM-21-AD.

Applicability: Model DC-9-10, -20, -30, -40, -50 and C-9 (military) series airplanes, as listed in McDonnell Douglas DC-9 Service Bulletin 53-256, Revision 1, dated November 29, 1994; Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) series airplanes and MD-88 airplanes, as listed in McDonnell Douglas MD-80 Service Bulletin 53-265, dated June 13, 1994; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD.

The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking of longerons 22 through 26 and the attaching frames, which could result in reduced structural integrity of the fuselage, and consequent loss of pressurization of the airplane; accomplish the following:

(a) Prior to the accumulation of 40,000 total landings, or within 6,000 landings after the effective date of this AD, whichever occurs later: Perform a visual inspection to detect cracking of the left lower nose of longerons 22 through 26 (inclusive) and the respective attaching frames at station frames Y=160.000 and Y=200.000; in accordance with McDonnell Douglas DC-9 Service Bulletin 53-256, dated August 12, 1993, or Revision 1, dated November 29, 1994 [for Models DC-9, -10, -20, -30, -40, -50, and C-9 (military) series airplanes]; or McDonnell Douglas MD-80 Service Bulletin 53-265, dated June 13, 1994 (for Model DC-9-81, -82, -83, and -87 series airplanes, and MD-88 airplanes); as applicable.

(1) If no cracking is detected: Prior to further flight, install clips and doublers under the longeron flanges and shim the longerons in accordance with the applicable service bulletin.

(2) If any cracking is detected: Prior to further flight, repair the cracks and install clips and doublers under the longeron flanges and shim the longerons in accordance with the applicable service bulletin.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Manager, Los Angeles ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on March 17, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-7524 Filed 3-23-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-121-AD]

RIN 2120-AA64

Airworthiness Directives; Industrie Aeronautiche e Meccaniche Model Piaggio P-180 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to certain Industrie Aeronautiche e Meccaniche (I.A.M.) Model Piaggio P-180 airplanes. The proposed AD would require accomplishing a leakage check of all lavatory water tube/hose connections, and correcting the installation of these connections if leakage is found. The proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Italy. The actions specified by the proposed AD are intended to prevent water leakage from the lavatory water duct system, which could collect in the fuselage, freeze in cold weather conditions, and cause the rudder control system to jam.

DATES: Comments must be received on or before April 28, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-121-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from I.A.M. Rinaldo Piaggio S.p.A., Via Cibrario, 4 16154 Genoa, Italy. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. David O. Keenan, Project Officer, FAA, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6934; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such

written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 97-CE-121-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 97-CE-121-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

The Registro Aeronautico Italiano (R.A.I.), which is the airworthiness authority for Italy, recently notified the FAA that an unsafe condition may exist on certain I.A.M. Model Piaggio P-180 airplanes. The R.A.I. reports an incident where water leakage from the lavatory system collected in the bottom of the fuselage between frames 5792 and 6000. This water then rose up to the height of the rudder control cable and froze during flight, which caused the rudder control system to jam.

Relevant Service Information

I.A.M. has issued Piaggio Service Bulletin No. SB-80-0096, dated January 31, 1997, which specifies procedures for accomplishing a leakage check of all lavatory water tube/hose connections, and correcting the installation of these connections if leakage is found.

The R.A.I. classified this service bulletin as mandatory and issued Italian AD No. 97-022, dated March 2, 1997, in

order to assure the continued airworthiness of these airplanes in Italy.

The FAA's Determination

This airplane model is manufactured in Italy and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, R.A.I. has kept the FAA informed of the situation described above.

The FAA has examined the findings of the R.A.I.; reviewed all available information, including the service information referenced above; and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of the Provisions of the Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop in other I.A.M. Model Piaggio P-180 airplanes of the same type design registered in the United States, the FAA is proposing AD action. The proposed AD would require accomplishing a leakage check of all lavatory water tube/hose connections, and correcting the installation of these connections if leakage is found. Accomplishment of the proposed installation would be in accordance with the previously referenced service information.

Compliance Time of the Proposed AD

Although the potential of the rudder control system to jam because of water freezing will only be unsafe while the airplane is in flight, this unsafe condition is not a result of the number of times the airplane is operated. The chance of this situation occurring is the same for an airplane with 10 hours time-in-service (TIS) as it is for an airplane with 500 hours TIS. For this reason, the FAA has determined that a compliance based on calendar time should be utilized in the proposed AD in order to assure that the unsafe condition is addressed on all airplanes in a reasonable time period.

Cost Impact

The FAA estimates that 5 airplanes in the U.S. registry would be affected by the proposed AD, that it would take approximately 2 workhours per airplane to accomplish the proposed action, and that the average labor rate is approximately \$60 an hour. Based on these figures, the total cost impact of the proposed AD on U.S. operators is

estimated to be \$600, or \$120 per airplane.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

Industrie Aeronautiche E Meccaniche:
Docket No. 98-CE-21-AD.

Applicability: Model Piaggio P-180 airplanes, serial numbers 1002, 1004, 1006 through 1017, 1019, and 1021 through 1030, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or

repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent water leakage from the lavatory water duct system, which could collect in the fuselage, freeze in cold weather conditions, and cause the rudder control system to jam, accomplish the following:

(a) Within the next 3 calendar months after the effective date of this AD, accomplish a leakage check of all lavatory water tube/hose connections in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Piaggio Service Bulletin (Mandatory) No. SB-80-0096, dated January 31, 1997. If leakage is found, prior to further flight, correct the installation of these connections in accordance with the above-referenced service bulletin.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(d) Questions or technical information related to Piaggio Service Bulletin (Mandatory) No. SB-80-0096, dated January 31, 1997, should be directed to I.A.M. Rinaldo Piaggio S.p.A., Via Cibrario, 4 16154 Genoa, Italy. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Note 3: The subject of this AD is addressed in Italian AD 97-022, dated March 2, 1997.

Issued in Kansas City, Missouri, on March 17, 1998.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-7523 Filed 3-23-98; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-01-AD]

RIN 2120-AA64

Airworthiness Directives; Maule Aerospace Technology Corp. M-4, M-5, M-6, M-7, MX-7, and MXT-7 Series Airplanes and Models MT-7-235 and M-8-235 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to supersede Airworthiness Directive (AD) 95-26-18, which currently requires inspecting (one-time) certain wing lift struts for internal corrosion on Maule Aerospace Technology Corp. (Maule) M-4, M-5, M-6, M-7, MX-7, and MXT-7 series airplanes and Models MT-7-235 and M-8-235 airplanes, and replacing any wing lift strut where corrosion is found. That AD was the result of a report of an accident where the wing separated from one of the affected airplanes. The proposed AD would retain the initial inspection and possible replacement requirements of AD 95-26-18, would require the inspections to be repetitive, and would provide the option of using ultrasonic procedures to accomplish the inspection requirements. The actions specified by the proposed AD are intended to prevent failure of the wing lift struts caused by corrosion damage, which could eventually result in the wing separating from the airplane.

DATES: Comments must be received on or before May 22, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-01-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Maule Aerospace Technology Inc., 2099 GA. Highway, 133 South, Moultrie, Georgia 31768; telephone: (912) 985-2045; facsimile: (912) 890-2402. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Cindy Lorenzen, Aerospace Engineer, FAA, Atlanta Aircraft Certification

Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6078; facsimile: (770) 703-6097.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-01-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-01-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

AD 95-26-18, Amendment 39-9476 (61 FR 623, January 9, 1996), currently requires the following on Maule Aerospace Technology Corp. (Maule) M-4, M-5, M-6, M-7, MX-7, and MXT-7 series airplanes and Models MT-7-235 and M-8-235 airplanes that are equipped with part number (P/N) 2079E rear wing lift struts and P/N 2080E front wing lift struts: inspecting (one-time) the wing lift struts for internal corrosion, and replacing any wing lift strut where corrosion is found. Accomplishment of the actions required by AD 95-26-18 is in accordance with