(g) The modification required by this AD shall be done in accordance with Avions Mudry & Cie Service Bulletin CAP 10B No. 16 (ATA 57–004), dated April 27, 992. The inspections required by this AD shall be done in accordance with Avions Mudry & Cie Service Bulletin No. 15, CAP10B–57–003, Revision 1, dated April 3, 1996.

(1) The incorporation by reference of Avions Mudry & Cie Service Bulletin No. 16 (ATA 57–004), dated April 27, 1992, was previously approved by the Director of the Federal Register as of July 23, 1993 (58 FR

31342, June 2, 1993).

(2) The incorporation by reference of Avions Mudry & Cie Service Bulletin No. 15, CAP10B–57–003, Revision 1, dated April 3, 1996, was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(3) Copies may be obtained from Avions Mudry & Cie, (c/o Akrotech), 9 route del'Aviation, Aerodrome, 21121 Darois, France. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

**Note 5:** The subject of this AD is addressed in French AD 92–240(A)R1, dated October 22, 1997.

(h) This amendment supersedes AD 93–10–11, Amendment 39–8592.

(i) This amendment becomes effective on July 17, 1998.

Issued in Kansas City, Missouri, on May 29, 1998.

## Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98–15085 Filed 6–5–98; 8:45 am] BILLING CODE 4910–13–U

## **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. 97-CE-141-AD; Amendment 39-10569; AD 98-12-13]

RIN 2120-AA64

# Airworthiness Directives; Industrie Aeronautiche e Meccaniche Model Piaggio P–180 Airplanes

AGENCY: Federal Aviation Administration, DOT. ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain Industrie
Aeronautiche e Meccaniche (I.A.M.)
Model Piaggio P–180 airplanes. This AD requires modifying the low pitch stop switch support. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Italy. The

actions specified by this AD are intended to prevent low pitch stop switch support displacement, which could result in an improper cockpit indication that the propeller is in the Beta range and cause loss of control of the airplane.

DATES: Effective July 18, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 18, 1998.

ADDRESSES: Service information that applies to this AD may be obtained from Industrie Aeronautiche e Meccaniche Rinaldo Piaggio S.p.A., Via Cibrario, 4 16154 Genoa, Italy. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 97–CE–141–AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. David O. Keenan, Project Officer, FAA, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426–6934; facsimile: (816) 426–2169.

#### SUPPLEMENTARY INFORMATION:

# **Events Leading to the Issuance of This AD**

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain I.A.M. Model Piaggio P–180 airplanes was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on March 2, 1998 (63 FR 10157). The NPRM proposed to require modifying the low pitch stop switch support. Accomplishment of the proposed action as specified in the NPRM would be in accordance with I.A.M. Piaggio Service Bulletin (Mandatory) No. SB–80–0080, dated July 3, 1997.

The NPRM was the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Italy.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

### The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has

determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

## **Cost Impact**

The FAA estimates that 5 airplanes in the U.S. registry will be affected by this AD, that it will take approximately 6 workhours per airplane to accomplish this action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$100 per airplane. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$2,300, or \$460 per airplane.

# **Regulatory Impact**

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

# List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## **Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

## 98-12-13 Industrie Aeronautiche E Meccaniche: Amendment 39-10569; Docket No. 97-CE-141-AD.

Applicability: Model Piaggio P–180 airplanes, serial numbers 1001, 1002, 1004, and 1006 through 1033, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 150 hours time-in-service (TIS) after the effective date of this AD, unless already accomplished.

To prevent low pitch stop switch support displacement, which could result in an improper cockpit indication that the propeller is in the Beta range and cause loss of control of the airplane, accomplish the following:

(a) Modify the low pitch stop switch support in accordance with Industrie Aeronautiche e Meccaniche Piaggio Service Bulletin (Mandatory) No. SB–80–0080, dated July 3, 1997.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(d) Questions or technical information related to I.A.M. Piaggio Service Bulletin (Mandatory) No. SB–80–0080, dated July 3, 1997, should be directed to I.A.M. Rinaldo Piaggio S.p.A., Via Cibrario, 4 16154 Genoa, Italy. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(e) The modification required by this AD shall be done in accordance with I.A.M. Piaggio Service Bulletin (Mandatory) No. SB-80–0080, dated July 3, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from I.A.M. Rinaldo Piaggio S.p.A., Via Cibrario, 4 16154 Genoa, Italy. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in Italian AD 97–217, dated July 28, 1997.

(f) This amendment becomes effective on July 18, 1998.

Issued in Kansas City, Missouri, on May 29, 1998.

#### Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-15083 Filed 6-5-98; 8:45 am] BILLING CODE 4910-13-U

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

## 14 CFR Part 39

[Docket No. 97-CE-146-AD; Amendment 39-10570; AD 98-12-14]

# RIN 2120-AA64

## Airworthiness Directives; AERMACCHI S.p.A. S.205 Series and Models S.208 and S.208A Airplanes

**AGENCY:** Federal Aviation Administration, DOT. **ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that applies to certain AERMACCHI S.p.A. (AERMACCHI) S.205 series and Models S.208 and S.208A airplanes. This AD requires inspecting the flap cable pulley bracket for correct alignment and correcting any misalignment; inspecting the flap control cable for wear (nicks, cuts, frays, etc.), and replacing the flap control pulley bracket and flap control cable if worn. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Italy. The actions specified by this AD are intended to prevent flap control failure, which could result in loss of control of the airplane.

DATES: Effective July 18, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 18, 1998

ADDRESSES: Service information that applies to this AD may be obtained from SIAI Marchetti, Product Support, Via Indipendenza 2, 21018 Sesto Calende (VA), Italy; telephone: +39–331–929117; facsimile: +39–331–922525. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 97–CE–146–AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. David O. Keenan, Project Officer, FAA, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426–6934; facsimile: (816) 426–2169.

#### SUPPLEMENTARY INFORMATION:

# **Events Leading to the Issuance of This AD**

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain AERMACCHI S.205 series and Models S.208 and S.208A airplanes was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on March 13, 1998 (63 FR 12418). The NPRM proposed to require: inspecting the flap control pulley bracket for alignment; correcting any misalignment; inspecting the flap control pulley cable for wear; and, replacing the bracket and cable if worn. Accomplishment of the proposed actions as specified in the NPRM would be in accordance with SIAI Marchetti Service Bulletin No. 205B60, dated July 24, 1995.

The NPRM was the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Italy.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

## The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor