

subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent the windshield wiper arm from corroding, detaching from the airplane during flight, and penetrating the fuselage, which, if not corrected, could result in possible injury to pilot and passengers; and to prevent collapse of the nose landing gear caused by design deficiency, which could result in loss of control of the airplane during landing operations, accomplish the following:

(a) Within the next 90 days after the effective date of this AD, replace the windshield wiper arm and windshield wiper attachment bolt in accordance with the Accomplishment Instructions section in Jetstream Series 3100/3200 Service Bulletin (SB) 30-JA 950641, which incorporates the following pages:

Pages	Revision level	Date
1	Revision 1	March 18, 1997.
2 through 8 ...	Revision 2	March 18, 1997.

This service bulletin specifies following the procedures provided in the Accomplishment Instructions section of Rosemount Aerospace Inc. Service Bulletin No. 2314M-30-16, dated December 1996.

(b) Within the next 90 days after the effective date of this AD, measure the outer wall thickness of the nose landing gear (NLG) toggle bracket lugs and the axle bracket lugs in accordance with the Accomplishment Instructions in APPH Precision Hydraulics SB No. 32-66, which incorporates the following pages:

Pages	Revision level	Date
1, 3, 4, and 5	Revision 1	October 1996.
2 and 6	Revision 2	March 1997.

Note 2: The APPH SB is referenced in the Accomplishment Instructions in Jetstream Series 3100/3200 Alert Service Bulletin No. 32-JA 960601, Revision No. 1, April 11, 1997, Original Issue, October 25, 1996.

(1) Prior to further flight, replace the NLG toggle bracket lugs and axle bracket lugs, if the measurements of the outer wall thickness do not meet the criteria set out in the Table contained in paragraph B. (5) of the Accomplishment Instructions section in APPH Precision Hydraulics SB No. 32-66, as referenced in paragraph (b) of this AD.

(2) If the measurements of the outer wall thickness are within the criteria set out in the Table contained in paragraph B. (5) of the Accomplishment Instructions section in APPH Precision Hydraulics SB 32-66, as referenced in paragraph (b) of this AD, replace the NLG toggle bracket lugs and axle bracket lugs at the end of the fatigue life limits of the part, as specified in the Table referenced above, or within the next 50 landings after the measurement is taken, whichever occurs later.

Note 3: The compliance time in this AD takes precedence over the compliance times published in the applicable service bulletins.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(e) Questions or technical information related to the service information referenced in this AD should be directed to British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone (01292) 79888; facsimile (01292) 671715. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(f) The replacements required by this AD shall be done in accordance with Jetstream Series 3100/3200 Service Bulletin 30-JA 950641, which incorporates the following pages:

Pages	Revision level	Date
1	Revision 1	March 18, 1997.
2 through 8 ...	Revision 2	March 18, 1997.

This service bulletin specifies following the procedures provided in Rosemount Aerospace Inc. Service Bulletin No. 2314M-30-16, dated December, 1996;

—APPH Precision Hydraulics Service Bulletin No. 32-66, which incorporates the following pages:

Pages	Revision level	Date
1, 3, 4, and 5	Revision 1	October 1996.
2 and 6	Revision 2	March 1997.

This service bulletin is referenced in Accomplishment Instructions section of Jetstream Series 3100/3200 Alert Service Bulletin No. 32-JA 960601, Original Issue: October 25, 1996, Revision No. 1: dated April 11, 1997.

(1) This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) Copies may be obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 5: The subject of this AD is addressed in British AD 002-10-96, not dated, for the nose landing gear condition; and British AD 006-08-96, not dated, for the windshield wiper condition.

(g) This amendment becomes effective on July 28, 1998.

Issued in Kansas City, Missouri, on June 3, 1998.

Ronald K. Rathgeber,
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-15360 Filed 6-11-98; 8:45 am]
BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-54-AD; Amendment 39-10584; AD 98-12-31]

RIN 2120-AA64

Airworthiness Directives; British Aerospace Jetstream Model 3101 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain British Aerospace Jetstream Model 3101 airplanes. This AD requires repositioning the fuel cross feed pipes in the lower center fuselage to give an overall clearance of 2 inches when measuring from the bottom of Frame Station 223. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified in this AD are intended to prevent the fuel pipe from fracturing during a wheels up landing because of the positioning of the fuel cross feed pipes, which could result in an airplane fire.

DATES: Effective September 10, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 10, 1998.

Comments for inclusion in the Rules Docket must be received on or before July 17, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-54-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Service information that applies to this AD may be obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-54-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. S.M. Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6934; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Events Leading to the Issuance of This AD

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, notified the FAA that an unsafe condition may exist on certain British Aerospace Jetstream Model 3101 airplanes. The CAA reports that current positioning of the fuel cross feed pipes in the lower center fuselage could present a problem in the event of a wheels-up landing. A clearance of 2 inches measured from the bottom of Frame Station 223 is necessary to assure adequate crashworthiness of the airplane. Under the current configuration, this clearance is not present.

This condition, if not corrected, could result in the fuel pipe fracturing during a wheels up landing and could lead to an airplane fire.

Relevant Service Information

British Aerospace has issued Jetstream Service Bulletin 28-JM 7161, dated December 19, 1983, which specifies procedures for repositioning

the fuel cross feed pipes in the lower center fuselage to give an overall clearance of 2 inches when measured from the bottom of Frame Station 223.

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, classified this service bulletin as mandatory in order to assure the continued airworthiness of these airplanes in the United Kingdom. The CAA classifying a service bulletin as mandatory in the United Kingdom is the same as the FAA issuing an AD in the United States.

The FAA's Determination

This airplane model is manufactured in the United Kingdom and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above.

The FAA has examined the findings of the CAA; reviewed all available information, including the service information referenced above; and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of the Provisions of This AD

Since an unsafe condition has been identified that is likely to exist or develop in other British Aerospace Jetstream Model 3101 airplanes of the same type design registered in the United States, the FAA is issuing an AD. This AD requires repositioning the fuel cross feed pipes in the lower center fuselage to give an overall clearance of 2 inches when measured from the bottom of Frame Station 223. Accomplishment of the actions of this AD would be required in accordance with the previously referenced service bulletin.

Cost Impact

The FAA estimates that 2 airplanes in the U.S. registry will be affected by this AD, that it will take approximately 20 workhours per airplane to accomplish the required action, and that the average labor rate is approximately \$60 per work hour. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$2,400, or \$1,200 per airplane.

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in adverse or

negative comment and therefore is issuing it as a direct final rule. The requirements of this direct final rule address an unsafe condition identified by a foreign civil airworthiness authority and do not impose a significant burden on affected operators. In accordance with Section 11.17 of the Federal Aviation Regulations (14 CFR 11.17) unless a written adverse or negative comment, or a written notice of intent to submit an adverse or negative comment, is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the date on which the final rule will become effective. If the FAA does receive, within the comment period, a written adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a final rule and was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must

submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-54-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is noncontroversial and unlikely to result in adverse or negative comments. For reasons discussed in the preamble, I certify that this regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

98-12-31 British Aerospace: Amendment 39-10584; Docket No. 98-CE-54-AD.

Applicability: Jetstream Model 3101 airplanes, serial numbers 602 through 605, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 100 hours time-in-service (TIS) after the effective date of this AD, unless already accomplished.

To prevent the fuel pipe from fracturing during a wheels up landing because of the positioning of the fuel cross feed pipes, which could result in an airplane fire, accomplish the following:

(a) Reposition the fuel cross feed pipes in the lower center fuselage to give an overall clearance of 2 inches when measured from the bottom of Frame Station 223. Accomplish this action in accordance with British Aerospace Jetstream Service Bulletin 28-JM 7161, dated December 19, 1983.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be used if approved by the Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(d) The repositioning required by this AD shall be done in accordance with British Aerospace Jetstream Service Bulletin 28-JM 7161, dated December 19, 1983. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in British Aerospace Jetstream Service Bulletin 28-JM 7161, dated December 19, 1983. The airworthiness authority for the United Kingdom classified this service bulletin as mandatory.

(e) This amendment becomes effective on September 10, 1998.

Issued in Kansas City, Missouri, on June 3, 1998.

Ronald K. Rathgeber,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-15499 Filed 6-11-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF COMMERCE

Bureau of Export Administration

Title 15, Chapter VII

[Docket No. 980520134-8134-01]

RIN 0694-AB49

Exports of Humanitarian Goods and Services to Cuba

AGENCY: Bureau of Export Administration, Commerce.

ACTION: Notice of policy.

SUMMARY: On March 20, 1998, the President announced three initiatives to increase the provision of humanitarian goods and services to Cuba. The Bureau of Export Administration (BXA) is streamlining procedures to facilitate the export of humanitarian goods consistent with recent legislation that provides support for the Cuban people.

FOR FURTHER INFORMATION CONTACT: James A. Lewis, Director, Office of Strategic Trade and Foreign Policy Controls, Bureau of Export Administration, telephone: (202) 482-4196.

SUPPLEMENTARY INFORMATION: On March 20, President Clinton announced that the United States is taking a number of steps to expand the flow of humanitarian assistance to Cuba and to help strengthen independent civil society and increase religious freedom in that country. These included lifting the ban imposed in 1996 on direct humanitarian flights to Cuba, streamlining procedures for the sale of medicines and medical equipment to Cuba, and allowing family remittances of specified amounts to close relatives in Cuba. These measures are fully consistent with the Cuban Democracy Act of 1992 (CDA) which, in addition to sustaining economic sanctions, also enable and encourage the Administration to conduct a program of support for the Cuban people. The resumption of direct humanitarian cargo flights will enable humanitarian assistance to reach the Cuban people in less time and at less cost.

As a result of this decision, direct humanitarian cargo flights may resume