

electric trim manual override loads after the new motor is installed, and making any necessary adjustments. Accomplishment of the proposed modification would be in accordance with the service bulletins previously referenced.

Cost Impact

The FAA estimates that 25 airplanes in the U.S. registry would be affected by the proposed AD, that it would take approximately 6 workhours per airplane to accomplish the proposed action, and that the average labor rate is approximately \$60 an hour. The manufacturer will provide parts at no cost to the owner/operator. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$9,000, or \$360 per airplane.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

British Aerospace: Docket No. 98-CE-32-AD.

Applicability: Jetstream Model 3101 airplanes, certificated in any category, with the following serial numbers, that are equipped with an autopilot:

Serial Numbers

601	603	604	606	607	609
610	612	614	616	620	621
622	626	629	634	637	641
645	648	649	655	665	686
690					

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 100 hours time-in-service (TIS) after the effective date of this AD, unless already accomplished.

To prevent the elevator trim servo motor drive gear assembly from remaining engaged when the autopilot is disengaged, which could result in the pilot having to manually overpower the elevator trim control, and possibly lose directional control of the airplane during critical phases of flight, accomplish the following:

(a) Replace the elevator trim servo motor with a new elevator trim servo motor of improved design at fuselage station (F.S.) 421, aft of the rear bulkhead, in accordance with the ACCOMPLISHMENT INSTRUCTIONS section in JETSTREAM Alert Service Bulletin (SB) 22-A-JA 860413, ORIGINAL ISSUE: April 16, 1986.

(b) Inspect the cable tension, system friction, and electric trim manual override and make any necessary adjustments in accordance with the ACCOMPLISHMENT INSTRUCTIONS section in JETSTREAM SB No. 22-A-JA 851231, ORIGINAL ISSUE: April 9, 1986.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that

provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(e) Questions or technical information related to British Aerospace Jetstream Service Bulletin 22-A-JA 851231, dated April 9, 1986, and Jetstream Alert Service Bulletin 22-A-JA 860413, dated April 16, 1986, should be directed to British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Note 3: The subject of this AD is addressed in British Aerospace Jetstream Service Bulletin 22-A-JA 851231, dated April 9, 1986, and British Aerospace Jetstream Service Bulletin 22-A-JA 860413, dated April 16, 1998. These service bulletins are classified as mandatory by the United Kingdom Civil Aviation Authority (CAA).

Issued in Kansas City, Missouri, on June 9, 1998.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-16024 Filed 6-16-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-36-AD]

RIN 2120-AA64

Airworthiness Directives; Lockheed Model L-1011-385 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Lockheed Model L-1011-385 series airplanes. This proposal would require the replacement of the flap position indicator with an improved flap position indicator. This proposal is prompted by a report indicating that an airplane landed at an excessive sink rate and sustained substantial structural

damage when the leading edge slats failed to extend for landing and the flightcrew failed to increase airspeed in response, due to inadequate announcement of the slat failure. The actions specified by the proposed AD are intended to prevent such inadequate announcement, which could result in the flightcrew being unaware when the leading edge slats fail to extend properly; such failure could result in reduced stall margins, and consequent reduced controllability of the airplane.

DATES: Comments must be received by August 3, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-36-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Lockheed Aeronautical Systems Support Company (LASSC), Field Support Department, Dept. 693, Zone 0755, 2251 Lake Park Drive, Smyrna, Georgia 30080. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia.

FOR FURTHER INFORMATION CONTACT: Thomas Peters, Program Manager, Systems and Flight Test Branch, ACE-116A, FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30337-2748; telephone (770) 703-6063; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic,

environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-36-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-36-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received a report indicating that the flightcrew of a Lockheed Model L-1011-385 series airplane failed to notice that the leading edge slats did not extend during approach for landing. As a result, the approach speed was not adjusted to compensate for this abnormal configuration. The airplane landed at an excessive sink rate and sustained substantial structural damage. The cause has been attributed to the existing design of the flap and slat display system, which does not provide adequate announcement to the flightcrew when the leading edge slats have failed to extend. The existing flap position indicator of the flap and slat display system does not provide a conspicuous warning should the leading edge slats fail to extend or retract properly during flap operation. This condition, if not corrected, could result in the flightcrew being unaware when the leading edge slats fail to extend properly; such failure could result in reduced stall margins, and consequent reduced controllability of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Lockheed Service Bulletin 093-27-128, Revision 2, dated December 1, 1997, which describes procedures for replacement of the flap position indicator with an improved flap position indicator. Accomplishment of the actions specified in the service

bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the action specified in the service bulletin described previously.

Cost Impact

There are approximately 164 airplanes of the affected design in the worldwide fleet. The FAA estimates that 89 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 2 work hours per airplane to accomplish the proposed replacement, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$25,000 per airplane. Based on these figures, the cost impact of the replacement proposed by this AD on U.S. operators is estimated to be \$2,235,680, or \$25,120 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Lockheed: Docket 98–NM–36–AD.

Applicability: Model L–1011–385–1, –14, and –15 series airplanes, as listed in Lockheed Service Bulletin 093–27–128, Revision 2, dated December 1, 1997; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent inadequate annunciation to the flightcrew of leading edge slat failures, which could result in reduced stall margins, and consequent reduced controllability of the airplane, accomplish the following:

(a) Within 18 months after the effective date of this AD, replace the flap position indicator with a new, improved flap position indicator, in accordance with Lockheed Service Bulletin 093–27–128, Revision 2, dated December 1, 1997.

Note 2: Replacement of the flap position indicator accomplished prior to the effective date of this AD, in accordance with Lockheed Service Bulletin 093–27–128, dated November 8, 1976, or Revision 1, dated January 17, 1977, is considered acceptable for compliance with paragraph (a) of this AD.

(b) As of the effective date of this AD, no person shall install a flap position indicator, part number 672563–111 or 672563–115, on any airplane.

(c) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA, Small Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on June 9, 1998.

John J. Hickey,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98–16022 Filed 6–16–98; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Airspace Docket No. 96–AWP–26]

Proposed Establishment of Class E Airspace; Willits, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to establish a Class E airspace area at Willits, CA. Additional controlled airspace extending upward from 700 feet or more about the surface of the earth is needed to contain aircraft executing the Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 16 and GPS RWY 34 SIAP at Ells Field-Willits Municipal Airport. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Ells Field-Willits Municipal Airport, Willits, CA.

DATES: Comments must be received on or before July 27, 1998.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Attn: Manager, Airspace Branch, AWP–520, Docket No. 96–AWP–26, Air Traffic Division, 15000 Aviation Boulevard, Lawndale, California, 90261.

The official docket may be examined in the Office of the Assistant Chief Counsel, Western Pacific Region, Federal Aviation Administration, Room

6007, 15000 Aviation Boulevard, Lawndale, California, 90261.

An informal docket may also be examined during normal business at the Office of the Manager, Airspace Branch, Air Traffic Division at the above address.

FOR FURTHER INFORMATION CONTACT:

Larry Tonish, Airspace Specialist, Airspace Branch, AWP–520, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California, 90261, telephone (310) 725–6531.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with the comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 96–AWP–26." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in the light of comments received. All comments submitted will be available for examination in the Airspace Branch, Air Traffic Division, 15000 Aviation Boulevard, Lawndale, California 90261, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Airspace Branch, 15000 Aviation Boulevard, Lawndale, California 90261. Communications must identify the notice number of this NPRM. Persons