between 7:30 a.m. and 4:15 p.m. on Federal workdays.

You may also provide comments via the NRC's interactive rulemaking website (http://ruleform.llnl.gov). This site provides the capability to upload comments as files (any format), if your web browser supports that function. For information about the interactive rulemaking website, contact Ms. Carol Gallagher, 301–415–5905 (e-mail: cag@nrc.gov).

FOR FURTHER INFORMATION CONTACT: James Smith Office of Nuclear Materi

James Smith, Office of Nuclear Material Safety and Safeguards, U.S. Nuclear Regulatory Commission, Washington, DC 20555–0001, Telephone: 301–415–6459, or toll-free: 800–368–5642.

Dated at Rockville, Maryland, this 27th day of October, 1999.

For the Nuclear Regulatory Commission.

Annette L. Vietti-Cook,

Secretary of the Commission.
[FR Doc. 99–28596 Filed 11–2–99; 8:45 am]
BILLING CODE 7590–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-262-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Mystere-Falcon 50 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the supersedure of an existing airworthiness directive (AD), applicable to certain Dassault Model Mystere-Falcon 50 series airplanes, that currently requires a revision to the Limitations section of the FAA-approved Airplane Flight Manual (AFM) to include procedures to use certain values to correctly gauge the minimum allowable N1 speed of the operative engines during operation in icing conditions. This proposed AD would add a new requirement for operators to adjust the thrust reverser handle stop, install new wiring, and modify the Digital Electronic Engine Control (DEEC) software, which would terminate the AFM revision. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are

intended to prevent flightcrew use of erroneous N1 thrust setting information displayed on the Engine Indication Electronic Display (EIED), which could result in in-flight shutdown of engine(s). DATES: Comments must be received by December 3, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-262-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to

Docket Number 98–NM–262–AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-262-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On November 5, 1997, the FAA issued AD 97-21-16, amendment 39-10202 (62 FR 60773, November 13, 1997), applicable to certain Dassault Model Mystere-Falcon 50 series airplanes, to require a revision to the Limitations section of the FAA-approved Airplane Flight Manual (AFM) to include procedures to use certain values to correctly gauge the minimum allowable N1 speed of the operative engines during operation in icing conditions. That action was prompted by a report indicating that erroneous minimum anti-icing N1 thrust setting indications were displayed on the Engine Indication Electronic Display (EIED). The erroneous minimum N1 indications do not correspond with minimums specified in the Normal Procedures Section of the AFM for operations in icing conditions. The requirements of that AD are intended to prevent flightcrew use of erroneous N1 thrust setting information displayed on the EIED and consequent in-flight shutdown of engine(s).

Actions Since Issuance of Previous Rule

In the preamble to AD 97–21–16, the FAA indicated that the actions required by that AD were considered "interim action" and that further rulemaking action was being considered. The FAA now has determined that further rulemaking action is indeed necessary, and this proposed AD follows from that determination.

Explanation of Relevant Service Information

Dassault Aviation has issued Service Bulletin F50–276, dated June 24, 1998, which describes procedures for adjustment of the thrust reverser handle stop, installation of new wiring, and modification of the Digital Electronic Engine Control (DEEC) software whereby push-lights are installed and wired to the DEEC. The software changes affect the N1 synch, Mach hold logic, thrust reverser logic, and wing anti-ice and takeoff schedules. Accomplishment of the actions specified in the service bulletin is intended to adequately address the

identified unsafe condition. The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, classified this service bulletin as mandatory and issued French airworthiness directive 98–228–021(B), dated June 17, 1998, in order to assure the continued airworthiness of these airplanes in France.

Dassault Service Bulletin F50–276 refers to Allied Signal Service Bulletin TFE731–76–5107, dated December 24, 1997, as an additional source of service information for accomplishment of the modification.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of §§ 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would supersede AD 97-21-16 to retain the requirement to revise the Limitations section of the FAA-approved Airplane Flight Manual (AFM) to include procedures to use certain values to correctly gauge the minimum allowable N1 speed of the operative engines during operation in icing conditions, and add a new requirement for adjustment of the thrust reverser handle stop, installation of new wiring, and modification of the Digital Electronic Engine Control (DEEC) software, which would terminate the need for the AFM revision.

Cost Impact

There are approximately 7 airplanes of U.S. registry that would be affected by this proposed AD.

The action that is currently required by AD 97–21–16, and retained in this AD, takes approximately 1 work hour per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the currently required actions on U.S.

operators is estimated to be \$60 per airplane.

The new actions that are proposed in this AD action would take approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$1,026 per airplane. Based on these figures, the cost impact of the proposed requirements of this AD on U.S. operators is estimated to be \$8,022, or \$1,146 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the current or proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39–10202 (62 FR 60773, November 13, 1997), and by adding a new airworthiness directive (AD), to read as follows:

Dassault Aviation: Docket 98–NM–262–AD. Supersedes AD 97–21–16, Amendment 39–10202.

Applicability: Model Mystere-Falcon 50 series airplanes, serial numbers 251, 253, and subsequent; equipped with Allied-Signal TFE731–40 engines; certificated in any category; except those that have been modified in accordance with Dassault Service Bulletin F50–276, dated June 24, 1998.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent in-flight shutdown of the engine(s) due to the flight crew using erroneous N1 speed values displayed on the engine Indication Electronic Display (EIED), accomplish the following:

Restatement of the Requirements of AD 97-21-16, Amendment 39-10202

AFM Revision

(a) Within 1 day after November 18, 1997 (the effective date of AD 97–21–16, amendment 39–10202), revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to add the following. This may be accomplished by inserting a copy of this AD in the AFM. "Operation in Icing Conditions:

The N1 speed of the operating engines must not be less than the minimum values specified in Normal Section 4, Sub-section 140, Page 2, of the AFM."

New Requirements for This AD

Modification

(b) Within 6 months after the effective date of this AD, adjust the thrust reverser handle stop, install new "push-light" wiring on the instrument panel, and modify the Digital Electronic Engine Control (DEEC) software; in accordance with Dassault Service Bulletin F50–276, dated June 24, 1998. Accomplishment of such actions constitutes terminating action for the AFM revision required by paragraph (a) of this AD. Following accomplishment of the terminating action, the AFM revision

required by paragraph (a) of this AD may be removed from the AFM.

Note 2: Dassault Service Bulletin F50–276 refers to Allied Signal Service Bulletin TFE731–76–5107, dated December 24, 1997, as an additional source of service information for accomplishment of the modification.

Spares

(c) As of the effective date of this AD, no person shall install DEEC software, part number 2118882–4002, on any airplane.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in French airworthiness directive 98–228–021(B), dated June 17, 1998.

Issued in Renton, Washington, on October 27, 1999.

Vi L. Lipski,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 99–28656 Filed 11–2–99; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 99-AGL-53]

Proposed Modification of Class E Airspace; Bemidji, MN.

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to modify Class E airspace at Bemidji, MN. A Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (Rwy) 31 has been developed for Bemidji-Beltrami County Airport. Controlled airspace extending upward from 700 to 1,200 feet above ground level (AGL) is needed to contain aircraft executing the approach. This action proposes to increase the radius of the existing controlled airspace for this airport.

DATES: Comments must be received on or before December 17, 1999.

ADDRESSES: Sand comments on the

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Office of the Assistant Chief Counsel, AGL-7, rules Docket No. 99–AGL-53, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

The official docket may be examined in the Office of the Assistant Chief Counsel, Federal Aviation
Administration, 2300 East Devon Avenue, Des Plaines, Illinois. An informal docket may also be examined during normal business hours at the Air Traffic Division, Airspace Branch, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois.

FOR FURTHER INFORMATION CONTACT: Denis C. Burke, Air Traffic Division, Airspace Branch, AGL–520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294–7568. SUPPLEMENTARY INFORMATION:

Interested parties are invited to

Comments Invited

participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 99-AGL-53." The postcard will be date/ time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the rules Docket, FAA, Great Lakes Region, Office of the

Assistant Chief Counsel, 2300 East Devon Avenue, Des Plaines, Illinois, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Office of Public Affairs, Attention: Public Inquiry Center, APA–230, 800 Independence Avenue, SW, Washington, DC 20591, or by calling (202) 267–3484. Communications must identify the docket number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11–2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to 14 CFR part 71 to modify Class E airspace at Bemidiji, MN, to accommodate aircraft executing the proposed GPS Rwy 31 SIAP at Bemidji-Beltrami County Airport by modifying the existing controlled airspace. Controlled airspace extending upward from the surface is needed to contain aircraft executing the approach. The area would be depicted on appropriate aeronautical charts. Class E airspace areas designated as a surface area for an airport are published in paragraph 6002 and Class E airspace designations for airspace areas extending upward from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9G dated September 1, 1999, and effective September 16, 1999, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, Therefore this, proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule will