

repayment determination; the committee's opportunity for an administrative review of any repayment determination; and the procedures involved in Commission repayment determinations under 11 CFR 9038.2.

\* \* \* \* \*

(c) *Preliminary Audit Report: Issuance by Commission and committee response.*

(1) Commission staff will prepare a written Preliminary Audit Report, which will be provided to the committee after it is approved by an affirmative vote of four (4) members of the Commission. The Preliminary Audit Report may include—

(i) An evaluation of procedures and systems employed by the candidate and committee to comply with applicable provisions of the Federal Election Campaign Act, the Presidential Election Campaign Fund Act and Commission regulations;

(ii) The accuracy of statements and reports filed with the Commission by the candidate and committee; and

(iii) Preliminary calculations regarding future repayments to the United States Treasury.

(2) The candidate and his or her authorized committee may submit in writing within 60 calendar days after receipt of the Preliminary Audit Report, legal and factual materials disputing or commenting on the proposed findings contained in the Preliminary Audit Report. In addition, the committee shall submit any additional documentation requested by the Commission. Such materials may be submitted by counsel if the candidate so desires.

(d) \* \* \*

(1) \* \* \* The Commission-approved audit report may address issues other than those contained in the Preliminary Audit Report. \* \* \*

\* \* \* \* \*

Dated: November 9, 1999.

**Scott E. Thomas,**

*Chairman, Federal Election Commission.*

[FR Doc. 99-29694 Filed 11-12-99; 8:45 am]

BILLING CODE 6715-01-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-NM-70-AD; Amendment 39-11407; AD 99-23-11]

RIN 2120-AA64

#### **Airworthiness Directives; British Aerospace Model BAe 146 and Avro 146-RJ Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain British Aerospace Model BAe 146 and Avro 146-RJ series airplanes, that requires repetitive inspections to detect signs of chafing to the fuel feed pipe, and repair or replacement of the fuel feed pipe with a serviceable part, if necessary; and ensuring that responder units, electrical connector backshells, and associated wiring are undamaged and are positioned correctly to provide maximum clearance with the fuel pipe. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent damage to the fuel feed pipe, which could result in fuel leaks and an increased potential for fire on the airplane.

**DATES:** Effective December 20, 1999.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the **Federal Register** as of December 20, 1999.

**ADDRESSES:** The service information referenced in this AD may be obtained from British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the **Federal Register**, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal

Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain British Aerospace Model BAe 146 and Avro 146-RJ series airplanes was published in the **Federal Register** on August 12, 1999 (64 FR 43955). That action proposed to require repetitive inspections to detect signs of chafing to the fuel feed pipe, and repair or replacement of the fuel feed pipe with a serviceable part, if necessary; and ensuring that responder units, electrical connector backshells, and associated wiring are undamaged and are positioned correctly to provide maximum clearance with the fuel pipe.

#### **Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

#### **Request To Change the Repetitive Inspection Interval**

One commenter, the manufacturer, states that the repetitive inspection interval required by paragraph (a) of the proposed AD is not consistent with the interval described in the service bulletin. The service bulletin indicates that the interval should be at each "C" check, which the manufacturer has confirmed to be at 4,000 flight cycles, or within 2 years, whichever occurs first.

The FAA infers that the commenter is requesting that the inspection interval be revised to correspond to "C" check intervals. The FAA concurs. It was the FAA's intention to require repetitive inspections at an interval corresponding to the majority of operators' scheduled "C" checks. The interval in the proposed AD was erroneously stated as 3,000 flight hours. Based on the information provided by the manufacturer, the FAA has revised the repetitive inspection interval in paragraph (a) of the final rule to specify an inspection interval of 4,000 flight cycles, or within 2 years, whichever occurs first.

#### **Request To Change the Cost Impact**

The commenter estimates that there are 45 U.S.-registered airplanes affected by this AD. In the notice of proposed rulemaking, the FAA had estimated that 20 airplanes were affected.

The FAA concurs and has changed the cost impact paragraph in the final rule to indicate that 45 airplanes are affected by this AD.

### Request To Change Service Information Address

The commenter states that the address used to obtain service information has been changed from AI(R) American Support to British Aerospace Regional Aircraft American Support. The remainder of the address is unchanged: 13850 Mclearn Road, Herndon, Virginia 20171.

The FAA concurs and has changed the final rule to indicate the new address.

### Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

### Cost Impact

The FAA estimates that 45 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$2,700, or \$60 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

### Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory

Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

#### 99-23-07 British Aerospace Regional Aircraft (Formerly British

Aerospace Regional Aircraft Limited, Avro International Aerospace Division; British Aerospace, PLC; British Aerospace Commercial Aircraft Limited): Amendment 39-11407. Docket 99-NM-70-AD.

**Applicability:** Model BAe 146 and Avro 146-RJ series airplanes, except those on which Modification HCMO1638A (British Aerospace Service Bulletin SB.26-44-01638A, dated February 25, 1999) has been accomplished; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent damage to the fuel feed pipe, which could result in fuel leaks and an increased potential for fire on the airplane, accomplish the following:

(a) Within 30 days after the effective date of this AD, perform a detailed visual inspection of the fuel feed pipe for signs of chafing, and ensure that responder units are

undamaged and positioned correctly in relation to clamps and that electrical connector backshells and associated wiring are undamaged and are oriented to provide maximum clearance with the fuel pipe; in accordance with British Aerospace Service Bulletin SB.26-44, dated February 25, 1999.

(1) If no chafing is detected, repeat the inspection thereafter at intervals not to exceed 4,000 flight cycles or 2 years, whichever occurs first, until accomplishment of paragraph (b) of this AD.

(2) If any sign of chafing is detected, prior to further flight, accomplish paragraph (a)(2)(i) or (a)(2)(ii) of this AD, as applicable, in accordance with British Aerospace Service Bulletin SB.26-44, dated February 25, 1999. Repeat the inspection thereafter at intervals not to exceed 4,000 flight cycles or 2 years, whichever occurs first, until accomplishment of paragraph (b) of this AD.

(i) If the damage does not exceed one-half the thickness of the fuel feed pipe wall, prior to further flight, repair the pipe.

(ii) If the damage exceeds one-half the thickness of the fuel feed pipe wall, prior to further flight, replace the pipe with a serviceable part.

**Note 2:** For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(b) Modification of the clamping arrangement for the firewall responder units in accordance with British Aerospace Service Bulletin SB.26-44-01638A, dated February 25, 1999, constitutes terminating action for the requirements of this AD.

### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

### Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

### Incorporation by Reference

(e) The actions shall be done in accordance with British Aerospace Service

Bulletin SB.26-44, dated February 25, 1999. This incorporation by reference was approved by the Director of the **Federal Register** in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the **Federal Register**, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 4:** The subject of this AD is addressed in British airworthiness directive 009-02-99.

(f) This amendment becomes effective on December 20, 1999.

Issued in Renton, Washington, on November 1, 1999.

**Vi L. Lipski,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-29055 Filed 11-12-99; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-SW-48-AD; Amendment 39-11414; AD 99-23-18]

RIN 2120-AA64

#### Airworthiness Directives; Bell Helicopter Textron Canada Model 407 Helicopters

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) applicable to Bell Helicopter Textron Canada (BHTC) Model 407 helicopters. This action requires, before further flight, revising the life limits for certain parts and replacing each part that has exceeded its life limit. The AD also requires revising the applicable component history cards or equivalent records and the Airworthiness Limitations Schedule of the BHTC Model 407 maintenance manual to reflect these new life limits. This amendment is prompted by an engineering evaluation of additional flight test data, which resulted in redefining the service life for certain parts and revising the Airworthiness Limitations Schedule. The actions specified in this AD are intended to prevent a fatigue failure of certain parts that may have exceeded revised life limits and subsequent loss of control of the helicopter.

**DATES:** Effective November 30, 1999.

Comments for inclusion in the Rules Docket must be received on or before January 14, 2000.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-48-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

**FOR FURTHER INFORMATION CONTACT:** Shep Blackman, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5296, fax (817) 222-5961.

**SUPPLEMENTARY INFORMATION:** Transport Canada, the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on BHTC Model 407 helicopters. Transport Canada advises that a recent engineering evaluation has led to changes in the airworthiness limitations of certain helicopter parts to account for repeated torque events in terms of the Retirement Index Number (RIN) or time-in-service.

BHTC has issued Alert Service Bulletin 407-98-22, dated December 10, 1998 (ASB), which specifies changes to the Airworthiness Limitations Schedule for certain parts to reflect the maximum life expressed in hours or by Retirement Index Numbers (RIN). Transport Canada classified this ASB as mandatory and issued Transport Canada AD CF-99-04, dated February 24, 1999, to ensure the continued airworthiness of these helicopters in Canada.

This helicopter model is manufactured in Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, Transport Canada has kept the FAA informed of the situation described above. The FAA has examined the findings of Transport Canada, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other BHTC Model 407 helicopters of the same type design registered in the United States, this AD is being issued to prevent a fatigue failure of certain parts that may have exceeded revised life limits. This AD requires, before further flight, establishing new life limits for certain parts and replacing each part that has exceeded its life limit. The AD also

requires updating the component history cards or equivalent records for these parts. The short compliance time involved is required because the previously described critical unsafe condition could result in loss of control of the helicopter. Therefore, establishing a new life limit for certain parts and replacing each part that has exceeded its life limit is required prior to further flight and this AD must be issued immediately.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable and that good cause exists for making this amendment effective in less than 30 days.

The FAA estimates that 220 helicopters will be affected by this AD, that it will take approximately 21 work hours to replace all affected parts, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$39,109 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$8,881,180.

#### Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments