

location provided under the caption  
**ADDRESSES.**

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Turbomeca:** Docket No. 99-NE-11-AD.

**Applicability:** Turbomeca Makila 1A and 1A1 series turboshaft engines, installed on but not limited to Aerospatiale AS 332 Super Puma, AS 532 Cougar, and SA 330 Puma helicopters.

**Note 1:** This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent in-flight engine shutdown due to roller bearing failure following oil contamination, accomplish the following:

#### Inspection and Repair

(a) Within 25 hours time-in-service (TIS) after the effective date of this AD, accomplish the following:

(1) For engines that have been operated with 7.5 cSt oil for more than 100 hours TIS, and for engines whose operators can not show documentation that the engine has been operated with 7.5 cSt oil for 100 hours or less TIS, accomplish the following:

(i) Perform a one-time visual inspection of the scavenge and lubrication systems for obstruction due to coke deposits and repair as required, in accordance with section 2.A. and 2.B. of the "Instructions for incorporation" section of Turbomeca Makila 1 Service Bulletin (SB) No. A298 71 0137, dated December 12, 1997.

(ii) Replace the oil with approved oil other than 7.5 cSt and then recondition and check the engine oil system in accordance with section 2.C. and 2.D.(1) of Turbomeca Makila 1 SB No. A298 71 0137, dated December 12, 1997, prior to return to service.

(2) For engines that have been operated with 7.5 cSt oil for 100 hours or less TIS, replace the oil with approved oil other than 7.5 cSt and then recondition the engine oil system prior to return to service, in accordance with section 1.A.(2)(b) of Turbomeca Makila 1 SB No. A298 71 0137, dated December 12, 1997.

#### Alternative Method of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

#### Ferry Flights

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on December 1, 1999.

**Thomas A. Boudreau,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 99-31815 Filed 12-7-99; 8:45 am]

**BILLING CODE 4910-13-U**

#### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-NE-33-AD]

RIN 2120-AA64

#### Airworthiness Directives; Turbomeca Artouste III Series Turboshaft Engines

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Turbomeca Artouste III series turboshaft engines. This proposal would require smoke emissions checks after every ground engine shutdown. If smoke is detected, this AD would require inspecting for fuel flow. If fuel

flow is not detected, the engine may have injection wheel cracks, which would require removing the engine from service for repair; if fuel flow is detected, the engine may have a malfunctioning electric fuel cock, which would require removing the electric fuel cock from service and replacing with a serviceable part. This proposal is prompted by reports of cracked injection wheels. The actions specified by the proposed AD are intended to prevent injection wheel cracks, which could result in an in-flight engine shutdown.

**DATES:** Comments must be received by February 7, 2000.

**ADDRESSES:** Submit comments to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 99-NE-33-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may also be submitted to the Rules Docket by using the following Internet address: "9-ane-adcomment@faa.gov". Comments may be inspected at this location between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Turbomeca, 40220 Tarnos, France; telephone +33 05 59 64 40 00, fax +33 05 59 64 60 80. This information may be examined at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

#### FOR FURTHER INFORMATION CONTACT:

Glorianne Niebuhr, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7132, fax (781) 238-7199.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before

and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NE-33-AD." The postcard will be date stamped and returned to the commenter.

#### Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 99-NE-33-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

#### Discussion

The Direction Generale de L'Aviation Civile (DGAC), which is the airworthiness authority for France, recently notified the Federal Aviation Administration (FAA) that an unsafe condition may exist on Turbomeca Artouste III B-B1-D series turboshaft engines. The DGAC advises that cracks have been reported on the rear face of the injection wheels, which can lead to fuel leakage into the turbine shaft tube during operation. When the engine is shut down, fuel flows into the combustion chamber, which could result in a slight increase of rundown time and/or emissions of smoke through the exhaust pipe, the air intake, or the turbine casing drain after the rotating assembly has stopped. This condition may be caused by the thermal stresses to which the injection wheel is subjected or a malfunctioning electric fuel cock. These conditions, if not corrected, could result in injection wheel cracks, which could result in an in-flight engine shutdown.

#### Service Information

Turbomeca has issued Artouste III Service Bulletin (SB) No. 218 72 0099, dated September 14, 1998, that specifies procedures for smoke emission checks, and fuel flow inspections if smoke is detected. The DGAC classified this SB as mandatory and issued AD 98-432(A) in order to assure the airworthiness of these engines in France.

#### Bilateral Airworthiness Agreement

This engine model is manufactured in France and is type certificated for operation in the United States under the

provisions of Section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

#### Proposed Actions

Since an unsafe condition has been identified that is likely to exist or develop on other engines of the same type design registered in the United States, the proposed AD would require inspecting for fuel flow. If fuel flow is not detected, the engine may have injection wheel cracks, which would require removing the engine from service for repair; if fuel flow is detected, the engine may have a malfunctioning electric fuel cock, which would require removing the electric fuel cock from service and replacing with a serviceable part. The actions would be required to be accomplished in accordance with the SB described previously.

#### Economic Analysis

There are approximately 2,279 engines of the affected design in the worldwide fleet. The FAA estimates that 184 engines installed on rotorcraft of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per engine to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$3,500 per engine. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$655,040.

#### Regulatory Impact

This proposal does not have federalism implications, as defined in Executive Order No. 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this proposal.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44

FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Turbomeca:** Docket No. 99-NE-33-AD.

**Applicability:** Turbomeca Artouste III B-B1-D series turboshaft engines, installed on but not limited to Eurocopter SA 315 LAMA and SA 316 Alouette III helicopters.

**Note 1:** This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent injection wheel cracks, which could result in an in-flight engine shutdown, accomplish the following:

#### Smoke Check

(a) Following every engine ground shutdown, accomplish the following in accordance with Turbomeca Artouste III Service Bulletin (SB) No. 218 72 0099, dated September 14, 1998:

(1) After every flight, check for smoke emissions through the exhaust pipe, air

intake, or turbine casing drain during rundown and after every engine shutdown. If a smoke emission has been noticed, check the fuel system before the next flight to identify the origin of the smoke emissions.

(2) If smoke is not detected, no action is required until the next engine ground shutdown.

(3) If smoke is detected, inspect for fuel flow in accordance with paragraph 2.B.(1) and 2.B.(2) of the SB.

(i) If fuel flow is not detected, prior to further flight, remove the engine from service and replace with a serviceable engine.

(ii) If fuel flow is detected, remove the electric fuel cock from service and replace with a serviceable part in accordance with section 2.B.(4) and 2.B.(5) of the referenced SB.

(iii) Before entry into service, perform an engine ground run and check the fuel system again for smoke emissions through the exhaust pipe, air intake, or turbine casing drain during engine rundown and after shutdown; if smoke emissions still remain after replacement of the electric fuel cock, prior to further flight, remove the engine from service and replace with a serviceable engine.

(b) For the purpose of this AD, a serviceable engine is defined as an engine that does not exhibit smoke emissions.

#### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

#### Ferry Flights

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the rotorcraft to a location where the inspection requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on December 1, 1999.

**Thomas A. Boudreau,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 99-31814 Filed 12-7-99; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-SW-54-AD]

#### Airworthiness Directives; MD Helicopters Inc. Model MD600N Helicopters

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) applicable to MD Helicopters Inc. (MDHI) Model MD600N helicopters. This proposal would require inspecting each internal fuel hose connection to verify proper installation. This proposal is prompted by the discovery that certain fuel hose connections between the fuel cells and the engine can be incorrectly installed. The actions specified by the proposed AD are intended to prevent fuel starvation of the engine while the fuel gage indicates fuel remaining in the tank, engine flameout, and a subsequent forced landing.

**DATES:** Comments must be received on or before February 7, 2000.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-54-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from MD Helicopters Inc., Attn: Customer Support Division, 5000 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9797, telephone 1-800-388-3378 or 480-891-6342, datafax 480-891-6782. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

**FOR FURTHER INFORMATION CONTACT:** Bruce Conze, Aerospace Engineer, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Blvd., Lakewood, California 90712, telephone (562) 627-5261, fax (562) 627-5210.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

Interested persons are invited to participate in the making of the

proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 99-SW-54-AD." The postcard will be date stamped and returned to the commenter.

#### Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-54-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

#### Discussion

This document proposes the adoption of a new AD applicable to MDHI Model MD600N helicopters, serial numbers with a prefix of "RN" 003 through 045. This AD would require inspecting each internal fuel hose connection to verify appropriate installation. The manufacturer discovered, during a company production flight test, that certain fuel hose connections between the fuel cells and the engine were incorrectly installed. The manufacturer is currently attempting to develop new hoses that would eliminate the possibility of incorrectly installing the internal fuel hose connections. Such hoses, if developed, would replace the hoses currently in use. In the interim, a one-time inspection of each internal fuel hose connection for proper installation is necessary within 100 hours TIS. This condition, if not corrected, could result in fuel starvation of the engine while the gage indicates fuel remaining in the