

compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; facsimile: (816) 329-4090.

(g) *What if I need to fly the sailplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your sailplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with DG Flugzeugbau GmbH Technical Note No. 843/13, dated November 3, 1999. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from DG Flugzeugbau GmbH, Postbox 41 20, D-76646 Bruchsal, Federal Republic of Germany. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on April 27, 2001.

**Note 2:** The subject of this AD is addressed in German AD Number 1999-383, dated December 1, 1999.

Issued in Kansas City, Missouri, on February 26, 2001.

**Michael Gallagher,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-5276 Filed 3-9-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-CE-46-AD; Amendment 39-12138; AD 2001-05-02]

RIN 2120-AA64

#### Airworthiness Directives; Pilatus Aircraft Ltd. Model PC-7 Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment supersedes Airworthiness Directive (AD) 98-08-22,

which currently requires inspecting the elevator and rudder attachment brackets for cracks and corrosion on certain Pilatus Aircraft Ltd. (Pilatus) Model PC-7 airplanes and replacing any cracked or corrosion-damaged parts. Since the issuance of AD 98-08-22, Pilatus has redesigned the brackets. Installation of these brackets should inhibit corrosion, which resulted in cracks or corrosion damage. This AD requires you to replace the elevator and rudder attachment brackets with parts of improved design. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Switzerland. The actions specified by this AD are intended to prevent failure of the elevator and rudder attachment brackets because of cracks or corrosion damage. Such failure could result in the elevator or rudder separating from the airplane with consequent loss of airplane control.

**DATES:** This AD becomes effective on April 27, 2001.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of April 27, 2001.

**ADDRESSES:** You may get the service information referenced in this AD from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland; telephone: +41 41 619 6509; facsimile: +41 41 610 3351. You may examine this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-46-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Roman Gabrys, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4141; facsimile: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

*Has FAA taken any action to this point?* Reports received from the Federal Office for Civil Aviation (FOCA), which is the airworthiness authority for Switzerland, revealed instances of corrosion and cracking in the elevator and rudder attachment brackets on Pilatus Model PC-7 airplanes that have been operated in areas of high humidity or salt content. This caused FAA to issue AD 98-08-22, Amendment 39-10471 (63 FR 19175, April 17, 1998). That AD requires you to inspect the elevator and rudder

attachment brackets for cracks and/or corrosion, and replace any cracked or corrosion-damaged parts, as applicable.

*What has happened since AD 98-08-22 to initiate this action?* The FOCA recently notified FAA of the need to change AD 98-08-22. The FOCA reports that Pilatus has redesigned the elevator and rudder attachment brackets. Installation of these brackets should inhibit the cause of corrosion, which resulted in cracks or corrosion damage.

*Has FAA taken any action to this point?* We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Pilatus Model PC-7 airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on January 2, 2001 (66 FR 57). The NPRM proposed to supersede AD 98-08-22. AD 98-08-22 currently requires inspecting the elevator and rudder attachment brackets for cracks and corrosion, and replacing any cracked or corrosion-damaged parts. Since the issuance of AD 98-08-22, Pilatus has redesigned the brackets. Installation of these brackets should inhibit corrosion, which resulted in cracks or corrosion damage. The NPRM also proposed to require you to replace the elevator and rudder attachment brackets with parts of improved design.

*Was the public invited to comment?* Interested persons were afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

#### FAA's Determination

*What is FAA's final determination on this issue?* After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. We determined that these minor corrections:

- Will not change the meaning of the AD; and
- Will not add any additional burden upon the public than was already proposed.

#### Cost Impact

*How many airplanes does this AD impact?* We estimate that this AD affects 8 airplanes in the U.S. registry.

*What is the cost impact of this AD on owners/operators of the affected airplanes?* We estimate the following costs to accomplish the modification:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
8 workhours × \$60 per hour = \$480.	Parts will be provided by the manufacturer free of charge .....	\$480	\$480 × 8 = \$3,840

*Why is the compliance in hours time-in-service (TIS) and calendar time?* The affected airplanes are used in general aviation operations. Some operators may accumulate 100 hours TIS on the airplane in less than 6 months. We have determined that the dual compliance time:

- Gives all owners/operators of the affected airplanes adequate time to schedule and do the actions in this AD; and
- Ensures that the unsafe condition referenced in this AD will be corrected within a reasonable time period without inadvertently grounding any of the affected airplanes.

#### Regulatory Impact

*Does this AD impact various entities?* The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

*Does this AD involve a significant rule or regulatory action?* For the reasons

discussed above, I certify that this action (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. FAA amends § 39.13 by removing Airworthiness Directive (AD) 98–08–22, Amendment 39–10471 (63 FR 19175, April 17, 1998), and by adding a new AD to read as follows:

#### 2001–05–02 Pilatus Aircraft LTD:

Amendment 39–12138; Docket No. 2000–CE–46–AD; Supersedes AD 98–08–22, Amendment 39–10471.

(a) *What airplanes are affected by this AD?* This AD affects Model PC–7 airplanes, serial numbers MSN 001 through MSN 612, that are certificated in any category.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the above airplanes must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to prevent failure of the elevator and rudder attachment brackets because of cracks or corrosion damage, which could result in the elevator or rudder separating from the airplane with consequent loss of airplane control.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Replace the horizontal stabilizer brackets with new parts using replacement kit No. 500.50.07.132 and replace the vertical stabilizer bracket with new parts using replacement kit No. 500.50.07.133.	Within the next 100 hours time-in-service (TIS) or 6 months after April 27, 2001 (the effective date of this AD), whichever occurs first, unless already accomplished.	In accordance with the Accomplishment Instructions of Pilatus Service Bulletin No. 55–005, dated March 23, 2000, the aircraft maintenance manuals, and illustrated parts catalogs.
(2) Do not install any parts identified as old parts in replacement kit No. 500.50.07.132 (or FAA-approved equivalent part numbers) or 500.50.07.133 (or FAA-approved equivalent part number).	As of April 27, 2001 (the effective date of this AD).	Not Applicable.

(e) *Can I comply with this AD in any other way?*

(1) You may use an alternative method of compliance or adjust the compliance time if:

- (i) Your alternative method of compliance provides an equivalent level of safety; and
- (ii) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

(2) Alternative methods of compliance approved under AD 98–08–22, which is superseded by this AD, are not approved as

alternative methods of compliance with this AD.

**Note 1:** This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition

addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Roman Gabrys, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4141; facsimile: (816) 329–4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and

21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Pilatus Service Bulletin No. 55-005, dated March 23, 2000. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(i) *Does this AD action affect any existing AD actions?* This amendment supersedes AD 98-08-22, Amendment 39-10471.

(j) *When does this amendment become effective?* This amendment becomes effective on April 27, 2001.

**Note 2:** The subject of this AD is addressed in Swiss AD HB 2000-411, dated September 27, 2000.

Issued in Kansas City, Missouri, on February 26, 2001.

**Michael Gallagher,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-5275 Filed 3-9-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-CE-61-AD; Amendment 39-12139; AD 2001-05-03]

RIN 2120-AA64

#### Airworthiness Directives; SOCATA—Groupe AEROSPATIALE Model TBM 700 Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that applies to certain SOCATA—Groupe AEROSPATIALE (Socata) Model TBM 700 airplanes. This AD requires you to apply Loctite on attaching bolt/screw threads of inboard, central, and outboard carriages; increase tightening torques of associated hardware; and replace central carriage attaching bolts. This AD is the result of mandatory

continuing airworthiness information (MCAI) issued by the airworthiness authority for France. The actions specified by this AD are intended to prevent loose, or the loss of, flap attaching bolts/screws, which could cause rough or irregular control. Such rough or irregular control could lead to the loss of control of the airplane.

**DATES:** This AD becomes effective on April 27, 2001.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of April 27, 2001.

**ADDRESSES:** You may get the service information referenced in this AD from SOCATA Groupe AEROSPATIALE, Customer Support, Aerodrome Tarbes-Ossun-Lourdes, BP 930-F65009 Tarbes Cedex, France; telephone: (33) (0)5.62.41.73.00; facsimile: (33) (0)5.62.41.76.54; or the Product Support Manager, SOCATA—Groupe AEROSPATIALE, North Perry Airport, 7501 Pembroke Road, Pembroke Pines, Florida 33023; telephone: (954) 894-1160; facsimile: (954) 964-4191. You may examine this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-61-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; facsimile: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

*What events have caused this AD?* The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, recently notified FAA that an unsafe condition may exist on certain Socata Model TBM 700 airplanes. The DGAC reports two occurrences on Socata model TBM 700 airplanes where, following a flight, a screw of a flap attachment fitting was found partly unscrewed and another was missing. These occurrences are the result of flap vibration.

*What are the consequences if the condition is not corrected?* Loose or the

loss of flap attaching bolts/screws could result in rough or irregular control. Such rough or irregular control could lead to loss of control of the airplane.

*Has FAA taken any action to this point?* We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Socata Model TBM 700 airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on January 2, 2001 (66 FR 64). The NPRM proposed to require you to apply Loctite on attaching bolt/screw threads of inboard, central, and outboard carriages; increase tightening torques of associated hardware; and replace central carriage attaching bolts.

*Was the public invited to comment?* Interested persons were afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

Socata has revised Service Bulletin No. SB 70-087 57, dated September 2000 (Amendment 1, dated November 2000), to incorporate minor procedural changes. This AD requires no further action if the original service bulletin is accomplished.

#### FAA's Determination

*What is FAA's final determination on this issue?* After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as proposed except for the addition of the revised service information and minor editorial corrections. We determined that this addition and these minor corrections:

- Will not change the meaning of the AD; and
- Will not add any additional burden upon the public than was already proposed.

#### Cost Impact

*How many airplanes does this AD impact?* We estimate that this AD affects 75 airplanes in the U.S. registry.

*What is the cost impact of this AD on owners/operators of the affected airplanes?* We estimate the following costs to accomplish the modification:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
6 workhours × \$60 per hour = \$360 .....	\$10	\$360 + \$10 = \$370	\$370 × 75 = \$27,750