Order Relative to Handling of Tart Cherries Grown in the States of Michigan, New York, Pennsylvania, Oregon, Utah, Washington and Wisconsin

It is therefore ordered, That on and after the effective date hereof, all handling of tart cherries grown in the States of Michigan, New York, Pennsylvania, Oregon, Utah, Washington, and Wisconsin, shall be in conformity to, and in compliance with, the terms and conditions of the said order as hereby amended as follows:

The provisions of the proposed marketing agreement and order amendments contained in the Secretary's Decision issued by the Administrator on December 5, 2000, and published in the **Federal Register** on December 11, 2000, shall be and are the terms and provisions of this order amending the order and are set forth in full herein.

List of Subjects in 7 CFR Part 930

Marketing agreements, Reporting and recordkeeping requirements, Tart cherries.

For the reasons set forth in the preamble, 7 CFR part 930 is amended as follows:

PART 930—TART CHERRIES GROWN IN THE STATES OF MICHIGAN, NEW YORK, PENNSYLVANIA, OREGON, UTAH, WASHINGTON, AND WISCONSIN

1. The authority citation for 7 CFR part 930 continues to read as follows:

Authority: 7 U.S.C. 601-674.

2. In part 930, § 930.16 is revised to read as follows:

§ 930.16 Sales constituency.

Sales constituency means a common marketing organization or brokerage firm or individual representing a group of handlers and growers. An organization which receives consignments of cherries and does not direct where the consigned cherries are sold is not a sales constituency.

3. In § 930.50, paragraph (a) is revised to read as follows:

§ 930.50 Marketing policy.

(a) Optimum supply. On or about July 1 of each crop year, the Board shall hold a meeting to review sales data, inventory data, current crop forecasts and market conditions in order to establish an optimum supply level for the crop year. The optimum supply volume shall be calculated as 100 percent of the average sales of the prior three years reduced by average sales that

represent dispositions of restricted percentage cherries qualifying for diversion credit for the same three years, unless the Board determines that it is necessary to recommend otherwise with respect to sales of restricted percentage cherries, to which shall be added a desirable carryout inventory not to exceed 20 million pounds or such other amount as the Board, with the approval of the Secretary, may establish. This optimum supply volume shall be announced by the Board in accordance with paragraph (h) of this section.

Dated: July 3, 2001.

Kenneth C. Clayton,

Acting Administrator, Agricultural Marketing Service

[FR Doc. 01–17125 Filed 7–9–01; 8:45 am]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NE-07-AD; Amendment 39-12310; AD 2001-13-28]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Limited, Aero Division-Bristol, S.N.E.C.M.A. Olympus 593 Mk. 610–14– 28 Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for

comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to Rolls-Royce Limited, Aero Division-Bristol, S.N.E.C.M.A. (RR) Olympus 593 Mk. 610-14-28 turbofan engines. This action requires replacement of the low-oil pressure (LOP) switch. This amendment is prompted by a report of the failure of the low pressure (LP) and high pressure (HP) rotor thrust bearings due to oil starvation that was caused by the loss of the LOP switch function and resulted in a delayed engine shutdown. The actions specified in this AD are intended to prevent the failure of the LOP switch to indicate an LOP event, which could contribute to uncontained engine failure due to oil starvation in the thrust bearings.

DATES: Effective August 9, 2001. The incorporation by reference of certain publications listed in the rule is approved by the Director of the Federal Register as of August 9, 2001.

Comments for inclusion in the Rules Docket must be received on or before September 10, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000–NE–07–AD, 12 New England Executive Park, Burlington, MA 01803–5299. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov." Comments sent via the Internet must contain the docket number in the subject line.

The service information referenced in this AD may be obtained from Rolls-Royce Defence (Europe) Technical Publications Department, P.O. Box 3, Filton, Bristol BS34 7QE, England; telephone 011 7979 6060; FAX 011 7979 7234. This information may be examined at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803–5299; telephone 781–238–7176; fax 781–238–7199.

SUPPLEMENTARY INFORMATION: The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom (UK), recently notified the FAA that an unsafe condition may exist on RR Olympus 593 Mk. 610-14-28 turbofan engines. The CAA advises that the failure of a low-oil pressure (LOP) switch cable at the LOP switch connector resulted in increased secondary damage after an LP compressor blade failure. The failed blade caused a rotor imbalance, which caused cracking of the oil tank and loss of engine oil. Because the LOP switch cable had failed, no LOP warning was received in the cockpit. Since no LOP warning was received, the engine was not immediately shut down and the LP and HP rotor thrust bearings failed from oil starvation. The failure of the LP and HP compressor rotor bearings caused an increase in secondary damage to the engine.

Manufacturer's Service Information

RR has issued Olympus 593 Service Bulletin (SB) No OL.593–71–9056–33, Revision 2, dated December 7, 2000, that specifies procedures for reworking the plug of existing electrical harness for the LOP switch. The CAA classified this service bulletin as mandatory and issued AD 002-10-98 in order to ensure the airworthiness of these RR engines in the UK.

Bilateral Airworthiness Agreement

This engine model is manufactured in the UK, and is type certificated for operation in the United States under the provisions of § 21.29 of the Code of Federal Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Requirements of This AD

Although none of these affected engine models are used on any airplanes that are registered in the United States, the possibility exists that the engine models could be used on airplanes that are registered in the United States in the future. Because an unsafe condition has been identified that is likely to exist or develop on other Olympus 593 Mk.610–14–28 engines of the same type design, this AD requires reworking the plug of the existing electrical harness for the LOP switch. The actions must be done in accordance with the service bulletin described previously.

Immediate Adoption

Since there are currently no domestic operators of this engine model, notice and opportunity for prior public comment are unnecessary. Therefore, a situation exists that allows the immediate adoption of this regulation.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety, and was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption ADDRESSES. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD

action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available in the Rules Docket for examination by interested persons, both before and after the closing date for comments. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000–NE–07–AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

This final rule does not have federalism implications, as defined in Executive Order No. 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this final rule.

The FAA has determined that this regulation may be issued immediately to correct an unsafe condition in aircraft, and is not a "significant regulatory action" under Executive Order No. 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Code of Federal Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2001–13–28 Rolls-Royce Limited, Aero Division-Bristol, S.N.E.C.M.A.: Amendment 39–12310. Docket 2000– NE–07–AD.

Applicability

This airworthiness directive (AD) is applicable to Rolls-Royce Limited, Aero Division-Bristol, S.N.E.C.M.A. (RR) Olympus 593 Mk. 610–14–28 turbofan engines. These engines are installed on, but not limited to, Concorde airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with this AD is required as indicated below, unless already done.

To prevent the failure of the LOP switch to indicate an LOP event, which could contribute to uncontained engine failure due to oil starvation in the thrust bearings, do the following:

(a) Install a revised LOP switch incorporating an extended support bush in combination with an angled backshell and additional cable slack in accordance with the accomplishment instructions of RR Service Bulletin OL.593–71–9056–33, Revision 2, dated December 7, 2000.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Incorporation by Reference Material

(c) The actions specified in this AD must be done in accordance with the following Rolls-Royce Olympus service bulletin:

Document No.	Pages	Revision	Date
OL.593-71-9056-33	1	2	Dec. 7, 2000. Oct. 5, 1998. Dec. 7, 2000. Feb. 19, 1999. Oct. 5, 1998. Dec. 7, 2000. Feb. 19, 1999.
Total pages: 8			

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Rolls-Royce Defence (Europe) Technical Publications Department, P.O. Box 3, Filton, Bristol BS34 7QE, England; telephone 011 44 7979 6060; FAX 011 44 7979 7234. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in CAA airworthiness directive 002–10–98.

Effective Date of This AD

(d) This amendment becomes effective on August 9, 2001.

Issued in Burlington, Massachusetts, on June 28, 2001.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 01–16926 Filed 7–9–01; 8:45 am]
BILLING CODE 4910–13–P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 520

Oral Dosage Form New Animal Drugs; Chlortetracycline Powder

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect approval of an abbreviated new animal drug application (ANADA) filed by Pennfield Oil Co. The ANADA provides for oral use of chlortetracycline soluble powder in solutions administered to cattle, swine, chickens, and turkeys for the control and treatment of various bacterial diseases. Technical amendments are also being made.

DATES: This rule is effective July 10, 2001.

FOR FURTHER INFORMATION CONTACT:

Lonnie W. Luther, Center for Veterinary Medicine (HFV-102), Food and Drug Administration, 7500 Standish Pl., Rockville, MD 20855, 301-827-0209. SUPPLEMENTARY INFORMATION: Pennfield Oil Co., 14040 Industrial Rd., Omaha, NE 68137, filed ANADA 200–295 for PennchlorTM 64 (chlortetracycline) Soluble Powder. The application provides for oral use of chlortetracycline soluble powder administered in drinking water or in solutions dosed by mouth in cattle, swine, chickens, and turkeys for the control and treatment of various diseases caused by bacteria susceptible to chlortetracycline. Pennfield Oil Co.'s PennchlorTM 64 is approved as a generic copy of American Cyanamid's Aureomycin® (chlortetracycline) Soluble Powder Concentrate, approved under NADA 65-440. The ANADA is approved as of April 27, 2001, and the regulations are amended in 21 CFR 520.445b to reflect the approval. The basis of approval is discussed in the freedom of information summary.

Section 520.445b is further amended in paragraph (d)(4)(iii)(C) by removing the Pennfield Oil Co. drug labeler code (DLC #053389) which was added in error (59 FR 39438, August 3, 1994) and by correcting the drug labeler code for ADM Animal Health & Nutrition Division (DLC #017519) which in error was not changed in this paragraph when the drug labeler code was changed elsewhere in this section (62 FR 27691, May 21, 1997). Publication of this document constitutes final action on these changes under the Administrative Procedure Act (5 U.S.C. 553). Notice and public procedure are unnecessary because FDA is merely correcting nonsubstantive errors.

In accordance with the freedom of information provisions of 21 CFR part 20 and 514.11(e)(2)(ii), a summary of safety and effectiveness data and

information submitted to support approval of this application may be seen in the Dockets Management Branch (HFA–305), Food and Drug Administration, 5630 Fishers Lane, rm. 1061, Rockville, MD 20852, between 9 a.m. and 4 p.m., Monday through Friday.

The agency has determined under 21 CFR 25.33(a)(1) that this action is of a type that does not individually or cumulatively have a significant effect on the human environment. Therefore, neither an environmental assessment nor an environmental impact statement is required.

This rule does not meet the definition of "rule" in 5 U.S.C. 804(3)(A) because it is a rule of "particular applicability." Therefore, it is not subject to the congressional review requirements in 5 U.S.C. 801–808.

List of Subjects in 21 CFR Part 520

Animal drugs.

Therefore, under the Federal Food, Drug, and Cosmetic Act and under authority delegated to the Commissioner of Food and Drugs and redelegated to the Center for Veterinary Medicine, 21 CFR part 520 is amended as follows:

PART 520—ORAL DOSAGE FORM NEW ANIMAL DRUGS

1. The authority citation for 21 CFR part 520 continues to read as follows:

Authority: 21 U.S.C. 360b.

§520.445b [Amended]

2. Section 520.445b Chlortetracycline powder (chlortetracycline hydrochloride or chlortetracycline bisulfate) is amended in paragraph (b) by removing "as in paragraphs (d)(1)(i)(A) and (d)(2)(i)(A)" and adding in its place "as in paragraph (d)"; and in paragraph (d)(4)(iii)(C) by removing ", 012286, and 053389" and adding in its place "and 017519".