

Continuous Airworthiness Maintenance Program

(e) FAA-certificated air carriers that have an approved continuous airworthiness maintenance program in accordance with the record keeping requirement of § 121.369 (c) of the Federal Aviation Regulations [14 CFR 121.369 (c)] of this chapter must maintain records of the mandatory inspections that result from revising the Airworthiness Limitations Section of the applicable ESM and the air carrier's continuous airworthiness program. Alternatively, certificated air carriers may establish an approved system of record retention that provides a method for preservation and retrieval of the maintenance records that include the inspections resulting from this AD, and include the policy and procedures for implementing this alternate method in the air carrier's maintenance manual required by § 121.369 (c) of the Federal Aviation Regulations [14 CFR 121.369 (c)]; however, the alternate system must be accepted by the appropriate PMI and require the maintenance records be maintained either indefinitely or until the work is repeated. Records of the piece-part inspections are not required under § 121.380 (a)(2)(vi) of the Federal Aviation Regulations [14 CFR 121.380 (a)(2)(vi)]. All other operators must maintain the records of mandatory inspections required by the applicable regulations governing their operations.

Note 3: The requirements of this AD have been met when the ESM changes are made and air carriers have modified their continuous airworthiness maintenance plans to reflect the requirements in the applicable ESM.

Issued in Burlington, Massachusetts, on October 1, 2001.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 01-25078 Filed 10-4-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 98-ANE-41-AD]

RIN 2120-AA64

Airworthiness Directives; General Electric Company CF6-6, CF6-45, and CF6-50 Series Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The Federal Aviation Administration (FAA) proposes to supersede an existing airworthiness directive (AD), applicable to General Electric Company (GE) CF6-6, CF6-45,

and CF6-50 series turbofan engines, that currently requires revisions to the Time Limits Section of the manufacturer's Instructions for Continued Airworthiness (ICA) to include required inspection of selected critical life-limited parts at each piece-part exposure. This proposal would modify the airworthiness limitations section of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate additional inspection requirements. A Federal Aviation Administration (FAA) study of in-service events involving uncontained failures of critical rotating engine parts has indicated the need for mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. The actions specified by this proposed AD are intended to prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane.

DATES: Comments must be received by December 4, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-ANE-41-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov". Comments sent via the Internet must contain the docket number in the subject line. Comments may be inspected at this location between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT:

Karen Curtis, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7192, fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the

proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-ANE-41-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-ANE-41-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

On April 14, 2000, the FAA issued AD 2000-08-11, Amendment 39-11697 (65 FR 21636, April 24, 2000), to require revisions to the Time Limits Section of the Manufacturer's Instructions for Continued Airworthiness (ICA) for General Electric Company (GE) CF6-6, CF6-45, and CF6-50 series turbofan engines to include required inspection of selected critical life-limited parts at each piece-part exposure.

Additional Inspection Procedures

Since the issuance of that AD, a Federal Aviation Administration (FAA) study of in-service events involving uncontained failures of critical rotating engine parts has indicated the need for additional mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. This proposal would modify the airworthiness limitations section of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate additional inspection requirements.

Proposed Actions

Since an unsafe condition has been identified that is likely to exist or

develop on other products of this same type design, the proposed AD would supersede AD 2000-08-11 to add additional inspections for certain HPC and LPT components at each piece-part opportunity.

Economic Impact

The FAA estimates that 730 engines installed on airplanes of US registry would be affected by this proposed AD, that it would take approximately 10 work hours per engine to accomplish the proposed new inspections, and that the average labor rate is \$60 per work hour for a total approximate cost of \$600 per engine. It is further estimated that there will be about 299 shop visits per year that result in piece-part exposure of the additional affected components. Based on these figures, the total cost impact of the additional inspections on U.S. operators is estimated to be \$179,400.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not

a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-11697 (65 FR 21636, April 24, 2000), and by adding a new airworthiness directive, to read as follows:

General Electric Company: Docket No. 98-ANE-41-AD. Supersedes AD 2000-08-11, Amendment 39-11697.

Applicability: This airworthiness directive (AD) is applicable to General Electric Company (GE) CF6-6, CF6-45, and CF6-50 series turbofan engines, installed on but not limited to Airbus Industrie A300 series, Boeing 747 series, and McDonnell Douglas DC-10 series airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless already done.

To prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane, do the following:

Inspections

(a) Within the next 30 days after the effective date of this AD, revise the manufacturer's Time Limits Section of the Instructions for Continued Airworthiness (ICA), and for air carrier operations revise the approved continuous airworthiness maintenance program, by adding the following:

"MANDATORY INSPECTIONS

(1) Perform inspections of the following parts at each piece-part opportunity in accordance with the instructions provided in the applicable manual provisions:

Part nomenclature	Part No. (P/N)	Inspect per engine shop manual chapter
For CF6-6 Engines:		
Disk, Fan Rotor Stage One	All	72-21-03 Paragraph 2.F. or Paragraph 2.A.B. Fluorescent-Penetrant Inspect, and 72-21-03 Paragraph 3 or 3.A. Eddy Current Inspection.
Fan Forward Shaft	All	72-21-05 Paragraph 1. Magnetic Particle Inspection.
Fan Mid Shaft	All	72-24-01 Paragraph 1. and Paragraph 2. Magnetic Particle Inspection.
Disk, HPC Rotor, Stage 1	All	72-31-04 Paragraph 1. Fluorescent Penetrant Inspection.
Disk, HPC Rotor, Stage 2	All	72-31-05 Paragraph 1. Fluorescent Penetrant Inspection.
Spool, HPC Rotor, Stages Three thru Nine	All	72-31-06 Paragraph 1. Fluorescent Penetrant Inspection.
Disk, HPC Rotor, Stage 10	All	72-31-07 Paragraph 1. Fluorescent Penetrant Inspection.
Spool, HPC Rotor, Stages 11-13	All	72-31-08 Paragraph 1. Fluorescent Penetrant Inspection.
Spool, HPC Rotor, Stages 14-16	All	72-31-08 Paragraph 1. Fluorescent Penetrant Inspection.
HPC Rear Shaft	All	72-31-09 Paragraph 1. and Paragraph 1.E. Fluorescent Penetrant Inspection.
No. 4R Bearing Rotating (CDP) Air Seal	All	72-31-10 Fluorescent Penetrant Inspection.
No. 4R Bearing Rotating (CDP) Air Seal Support	All	72-31-10 Fluorescent Penetrant Inspection.

Part nomenclature	Part No. (P/N)	Inspect per engine shop manual chapter
Disk, HPT Rotor Stage One	All	72-53-03 Paragraph 1. Fluorescent-Penetrant Inspect, and 72-53-03 Paragraph 4. Eddy Current Inspection of the HPTR Disk Rim Boltholes and 72-53-03 Paragraph 5. Disk Bore Area Eddy Current Inspection.
Disk, HPT Rotor Stage Two	All	72-53-04 Paragraph 1. Fluorescent-Penetrant Inspect, and 72-53-04 Paragraph 4. Eddy Current Inspection of the Stage 2 HPTR Disk Rim Boltholes and 72-53-04 Paragraph 5. Eddy Current Inspection of the Stage 2 Disk Inner Boltholes and 72-53-04 Paragraph 6. Disk Bore Area Eddy Current Inspection.
Disk, LPT Rotor, Stages One thru Five	All	72-57-02 Paragraph 1. Fluorescent Penetrant Inspection.
LPT Forward Shaft	All	72-57-03 Paragraph 1. Fluorescent Penetrant Inspection.
LPT Rear Shaft	All	72-57-04 Paragraph 1. Fluorescent Penetrant Inspection.
For CF6-45, CF6-50 Engines:		
Disk, Fan Rotor Stage One	All	Task 72-21-03-230-051 Fluorescent Penetrant Inspection., and Task 72-21-03-250-002-052 Manual Eddy Current Inspection or 72-21-03-250-003-053 Automated Eddy Current Inspection.
Forward Shaft, Fan	All	Task 72-21-05-240-056 Magnetic Particle Inspection.
Mid Shaft, Fan	All	Task 72-24-01-240-001-051 Magnetic Particle Inspection.
Disk, HPC Rotor Stage 1	All	Task 72-31-04-230-001-051 Fluorescent Penetrant Inspection.
Disk, HPC Rotor Stage 2	All	Task 72-31-05-230-001-051 Fluorescent Penetrant Inspection.
Spool, HPC Rotor Stages 3-9	All	Task 72-31-06-230-001-063 Fluorescent Penetrant Inspection.
Disk, HPC Rotor Stage 10	All	Task 72-31-07-230-001-051 Fluorescent Penetrant Inspection.
Spool, HPC Rotor Stages 11-13	All	Task 72-31-08-230-001-051 Fluorescent Penetrant Inspection.
Disk, HPC Rotor Stage 14	All	Task 72-31-07-230-001-055 Fluorescent Penetrant Inspection.
Rear Shaft, HPC Rotor	All	Task 72-31-09-230-001-051 Fluorescent Penetrant Inspection.
Spool/Shaft, HPC Rotor Stages 11-14	All	Task 72-31-26-230-001-052 Fluorescent Penetrant Inspection.
Rotating (CDP) Air Seal, No. 4R Bearing	All	Task 72-31-10-230-001-051 Fluorescent Penetrant Inspection.
Rotating (CDP) Air Seal Support, No. 4R Bearing ...	All	Task 72-31-10-230-001-051 Fluorescent Penetrant Inspection.
Disk, HPT Rotor Stage One	All	Task 72-53-03-230-001-059 Fluorescent Penetrant Inspect Disk, and Task 72-53-03-250-052 Eddy Current Inspection of the HPTR Stage 1 Rim Boltholes, and Task 72-53-03-250-060 Disk Bore Area Eddy Current Inspection.
Disk, HPT Rotor Stage Two	All	Task 72-53-04-230-001-057 Fluorescent Penetrant Inspect Disk, and Task 72-53-04-250-053 Eddy Current Inspection of the HPTR Stage 2 Rim and/or Inner Boltholes, and Task 72-53-04-250-060 Disk Bore Area Eddy Current Inspection.
Disks, LPT Rotor Stages 1-4	All	Task 72-57-02-230-001-051 Fluorescent Penetrant Inspection.
Forward Shaft, LPTR	All	Task 72-57-03-230-001-057 Fluorescent Penetrant Inspection.
Rear Shaft, LPTR	All	Task 72-57-04-230-001-051 Fluorescent Penetrant Inspection.

(2) For the purposes of these mandatory inspections, piece-part opportunity means:

(i) The part is considered completely disassembled when accomplished in

accordance with the disassembly instructions in the manufacturer's engine manual; and

(ii) The part has accumulated more than 100 cycles in service since the last piece-part

opportunity inspection, provided that the part was not damaged or related to the cause for its removal from the engine."

(b) Except as provided in paragraph (c) of this AD, and notwithstanding contrary provisions in section 43.16 of the Federal Aviation Regulations (14 CFR 43.16), these mandatory inspections shall be performed only in accordance with the Time Limits Section of the manufacturer's ICA.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Engine Certification Office (ECO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector (PMI), who may add comments and then send it to the ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Continuous Airworthiness Maintenance Program

(d) FAA-certificated air carriers that have an approved continuous airworthiness maintenance program in accordance with the record keeping requirement of § 121.369 (c) of the Federal Aviation Regulations [14 CFR 121.369 (c)] must maintain records of the mandatory inspections that result from revising the Time Limits Section of the Instructions for Continuous Airworthiness (ICA) and the air carrier's continuous airworthiness program. Alternately, certificated air carriers may establish an approved system of record retention that provides a method for preservation and retrieval of the maintenance records that include the inspections resulting from this AD, and include the policy and procedures for implementing this alternate method in the air carrier's maintenance manual required by § 121.369 (c) of the Federal Aviation Regulations [14 CFR 121.369 (c)]; however, the alternate system must be accepted by the appropriate PMI and require the maintenance records be maintained either indefinitely or until the work is repeated. Records of the piece-part inspections are not required under § 121.380 (a) (2) (vi) of the Federal Aviation Regulations [14 CFR 121.380 (a) (2) (vi)]. All other Operators must maintain the records of mandatory inspections required by the applicable regulations governing their operations.

Note 3: The requirements of this AD have been met when the engine shop manual changes are made and air carriers have modified their continuous airworthiness maintenance plans to reflect the requirements in the engine shop manuals.

Issued in Burlington, Massachusetts, on September 25, 2001.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 01-25077 Filed 10-4-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-59-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-11 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model MD-11 series airplanes. This proposal would require installation of protective sleeving on the right emergency alternating current wire assembly of the overhead switch panel. This action is necessary to ensure that protective sleeving is installed on the right emergency alternating current (AC) wire assembly of the overhead switch panel. Lack of such sleeving could result in loss of redundant electrical power during certain cockpit overhead wiring faults. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by November 19, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-59-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-59-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the FAA, Transport

Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT:

Brett Portwood, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5350; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received. Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001-NM-59-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No.