

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 99-SW-67-AD; Amendment 39-12056; AD 2000-26-06]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland GMBH Model MBB-BK 117 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD) that applies to Eurocopter Deutschland GMBH (ECD) Model MBB-BK 117 helicopters. That AD currently requires, before further flight, creating a component log card or equivalent record and determining the calendar age and number of flights on each tension-torsion (TT) strap. This amendment establishes a life limit for certain main rotor TT straps. This amendment is prompted by an accident in which a main rotor blade (blade) separated from an ECD Model MBB-BK 117 helicopter due to fatigue failure of a TT strap. The actions specified by this AD are intended to prevent fatigue failure of a TT strap, loss of a blade, and subsequent loss of control of the helicopter.

DATES: Effective February 26, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 26, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Charles Harrison, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5128, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 2000-01-11, Amendment 39-11509 (65 FR 2017, January 13, 2000), which applies to ECD

Model MBB-BK 117 helicopters, was published in the **Federal Register** on September 18, 2000 (65 FR 56275). That action proposed establishing a life limit for the TT straps of 120 months since installation on any helicopter or 25,000 flights, whichever occurs first.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 127 helicopters of U.S. registry will be affected by this AD, that it will take approximately 16 work hours per helicopter to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$10,400 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$1,442,720.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-11509 (65 FR 2017, January 13, 2000), and by adding a new airworthiness directive (AD), Amendment 39-12056, to read as follows:

2000-26-06 Eurocopter Deutschland GMBH: Amendment 39-12056. Docket No. 99-SW-67-AD. Supersedes AD 2000-01-11, Amendment 39-11509, Docket No. 99-SW-60-AD.

Applicability: Model MBB-BK 117 A-1, A-3, A-4, B-1, B-2, and C-1 helicopters, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue failure of a tension-torsion (TT) strap, loss of a main rotor blade (blade), and subsequent loss of control of the helicopter, accomplish the following:

(a) Before further flight,

(1) Remove TT straps, P/N 2604067 (Bendix) or J17322-1 (Lord), from service or re-identify them as P/N 117-14110 or 117-14111, respectively, in accordance with the Accomplishment Instructions, paragraph 2.B.1.2., Eurocopter Deutschland GMBH Alert Service Bulletin MBB-BK-117 No. ASB-MBB-BK 117-10-120, Revision 1, dated August 31, 1999 (ASB). TT straps, P/N 2604067 (Bendix) or J17322-1 (Lord), are no longer eligible for installation.

(2) Create a component log card or equivalent record for each TT strap.

(3) Review the history of the helicopter and each TT strap. Determine the age since initial installation on any helicopter (age) and the number of flights on each TT strap. Enter both the age and the number of flights for each TT strap on the component log card or equivalent record. When the number of flights is unknown, multiply the number of hours time-in-service (TIS) by 5 to determine the number of flights.

(4) Remove any TT strap from service if the total hours TIS or number of flights and age cannot be determined.

(b) Before further flight, remove any TT strap, part number (P/N) 117-14110 or 117-

14111, that has been in service 120 months since initial installation on any helicopter or accumulated 25,000 flights (a flight is a takeoff and a landing). Replace the TT strap with an airworthy TT strap.

(c) This AD revises the Airworthiness Limitations Section of the maintenance manual by establishing a life limit for the TT strap, P/N 117-14110 and 117-14111, of 120 months or 25,000 flights, whichever occurs first.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(e) Special flight permits may be issued in accordance with § 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(f) The modification shall be done in accordance with the Accomplishment Instructions, paragraph 2.B.1.2., Eurocopter Deutschland GMBH Alert Service Bulletin MBB-BK-117 No. ASB-MBB-BK 117-10-120, Revision 1, dated August 31, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) This amendment becomes effective on February 26, 2001.

Note 3: The subject of this AD is addressed in the Luftfahrt Bundesamt (Federal Republic of Germany) AD 1999-284/2, dated September 1, 1999.

Issued in Fort Worth, Texas, on December 15, 2000.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 01-1585 Filed 1-19-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-03-AD; Amendment 39-12086; AD 2001-02-02]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-200, and -300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Bombardier Model DHC-8-200, and -300 series airplanes. This action requires repetitive inspections to detect chafing or arcing damage to the cable/wire and fuel tube assemblies on the right hand side of each engine, and replacement with new components, if necessary. This action also provides an optional terminating action for the repetitive inspections required by this AD. This action is necessary to prevent chafing of the cable/wire bundles against the fuel line, which could result in arcing and a consequent fire or explosion. This action is intended to address the identified unsafe condition.

DATES: Effective February 6, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 6, 2001.

Comments for inclusion in the Rules Docket must be received on or before February 21, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-03-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarccomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-03-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

James Delisio, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7521; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION: Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, recently notified the FAA that an unsafe condition may exist on certain Bombardier Model DHC-8-200 and -300 series airplanes. TCAA advises that a pinhole in the high pressure fuel line was detected. Investigation revealed that the cause of the pinhole was due to arcing from an adjoining wire. The arcing occurred approximately four inches from the fuel-cooled oil cooler. Although the fuel line and wire are separated by two cushion clamps, the cushion clamps can rotate and thereby allow the wire bundle to chafe against the fuel line. Such chafing of the wire bundles could result in arcing and a consequent fire or explosion.

Explanation of Relevant Service Information

Bombardier has issued Alert Service Bulletin A8-73-23, dated November 3, 2000, which describes procedures for repetitive general visual inspections to detect chafing or arcing damage to the cable and the fuel tube assemblies on the right hand side of each engine, and replacement with new components, if necessary. The alert service bulletin also describes procedures for an optional modification that entails, among other things, rerouting the existing wire harness to the opposite side of the oil cooler, and shortening and securing the wire harness, if necessary. That modification eliminates the need for the repetitive inspections. TCAA classified this alert service bulletin as mandatory and issued Canadian airworthiness directive CF-2000-33, dated November 14, 2000, in order to assure the continued airworthiness of these airplanes in Canada.