

and a fire extinguisher of appropriate size and extinguishing agent must be installed in the immediate vicinity of the cooktop. A fire on or around the cooktop must not block access to the extinguisher. One of the fire extinguishers required by § 25.851 may be used to satisfy this requirement if the total complement of extinguishers can be evenly distributed throughout the cabin. If this is not possible, then the extinguisher in the galley area would be additional.

or

- An automatic, thermally-activated fire suppression system must be installed to extinguish a fire at the cooktop and immediately adjacent surfaces. The agent used in the system must be an approved total flooding agent suitable for use in an occupied area. The fire suppression system must have a manual override. The automatic activation of the fire suppression system must also automatically shut off power to the cooktop.

5. The surfaces of the galley surrounding the cooktop, which would be exposed to a fire on the cooktop surface or in cookware on the cooktop, must be constructed of materials that comply with the flammability requirements of Part III of Appendix F of part 25. This requirement is in addition to the flammability requirements typically required of the materials in these galley surfaces. During the selection of these materials, consideration must also be given to ensure that the flammability characteristics of the materials will not be adversely affected by the use of cleaning agents and utensils used to remove cooking stains.

6. The cooktop must be ventilated with a system independent of the airplane cabin and cargo ventilation system. Procedures and time intervals must be established to inspect and clean or replace the ventilation system to prevent a fire hazard from the accumulation of flammable oils. These procedures and time intervals must be included in the Instructions for Continued Airworthiness (ICA). The ventilation system ducting must be protected by a flame arrestor.

Note: The applicant may find additional useful information in "Air Conditioning Systems for Subsonic Airplanes," Society of Automotive Engineers, Aerospace Recommended Practice 85, Rev. E, dated August 1, 1991.

7. Means must be provided to contain spilled foods or fluids in a manner that will prevent the creation of a slipping hazard to occupants and will not lead to the loss of structural strength due to airplane corrosion.

8. Cooktop installations must provide adequate space for the user to immediately escape a hazardous cooktop condition.

9. A means to shut off power to the cooktop must be provided at the galley containing the cooktop and in the cockpit. If additional switches are introduced in the cockpit, revisions to smoke or fire emergency procedures of the AFM will be required.

10. A readily deployable cover must be provided to cover the cooktop during taxi, takeoff, and landing (TT&L) operation. The deployment of the cover must automatically shut off power to the cooktop.

Issued in Renton, Washington, on June 28, 2002.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-17375 Filed 7-9-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-SW-46-AD; Amendment 39-12801; AD 2002-14-01]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Model AS332L and AS332L1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for the specified Eurocopter France (ECF) helicopters that requires adding a supplement to the Limitations section of the applicable Rotorcraft Flight Manual (RFM) for helicopters with "SEFA" skis installed. This amendment is prompted by the need to limit the taxi and Vne speed of those helicopters with skis. The actions specified by this AD are intended to prevent structural failure of a ski and subsequent loss of control of the helicopter.

DATES: Effective August 14, 2002.

FOR FURTHER INFORMATION CONTACT:

Uday Garadi, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5123, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend 14 CFR part 39 to include an AD for ECF Model AS332L and AS332L1 helicopters was published in the **Federal Register** on February 6, 2002 (67 FR 5526). That action proposed to require adding the limitations contained in SUP.10.14, Ski Installation,

to the Limitations section of the RFM, requiring certain speed limitations for helicopters with skis installed.

The Direction Generale De L'Aviation Civile (DGAC), the airworthiness authority for France, notified the FAA that an unsafe condition may exist on ECF Model AS332L and AS332L1 helicopters equipped with "SEFA" skis. ECF issued Supplement, SUP.10.14, Ski Installation, Normal Revision 2, Issue 2, dated June 2001 to the applicable RFM. The DGAC classified these RFM supplements as mandatory and issued AD No. 2001-316-079(A), dated July 25, 2001. The DGAC advises incorporating the Ski Installation Supplement into the applicable RFM before the next flight and complying with the Vne and the maximum taxiing speed limitations to ensure the continued airworthiness of these helicopters in France.

These helicopter models are manufactured in France and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 3 helicopters of U.S. registry will be affected by this AD, that it will take approximately 10 minutes per helicopter to add the flight manual supplement, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$30.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a

“significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket at the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2002-14-01 Eurocopter France:

Amendment 39-12801. Docket No. 2001-SW-46-AD.

Applicability: Model AS332L and AS332L1 helicopters, with “SEFA” skis installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required before further flight, unless accomplished previously.

To prevent structural failure of a ski and subsequent loss of control of the helicopter, accomplish the following:

(a) Before the next flight with skis installed, add the limitations contained in SUP.10.14, Ski Installation, Normal Revision 2, Issue 2, dated June 2001 to the Limitations section of the applicable Rotorcraft Flight Manual.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on August 14, 2002.

Note 3: The subject of this AD is addressed in Direction General De L'Aviation Civile (France) AD 2001-316-079(A), dated July 25, 2001.

Issued in Fort Worth, Texas, on June 27, 2002.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 02-17245 Filed 7-9-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. 02-AGL-01]

Establishment of Class D Airspace; Marquette, MI; Modification of Class E Airspace; Marquette, MI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class D airspace at Marquette, MI, and modifies Class E airspace at Marquette, MI. The opening of a Federal Contract Tower is being planned for the Sawyer International Airport. Class D airspace is required during the hours the control tower is operating. Sawyer International Airport is served by Federal Aviation Regulations Part 121 (14 CFR part 121) air carrier operations. During periods when the control tower is closed, controlled airspace extending upward from the surface is needed to contain aircraft executing instrument flight procedures and provide a safer operating environment. This action establishes Class D airspace, and modifies Class E airspace for Sawyer International Airport.

EFFECTIVE DATE: 0901 UTC, October 3, 2002.

FOR FURTHER INFORMATION CONTACT: Denis C. Burke, Air Traffic Division, Airspace Branch, AGL-520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294-7568.

SUPPLEMENTARY INFORMATION:

History

On Tuesday, April 2, 2002, the FAA proposed to amend 14 CFR part 71 to establish Class D and modify Class E airspace at Marquette, MI (67 FR 15502). The proposal was to establish Class D airspace, and modify Class E airspace, to support the operation of a Federal Contract Tower, and to provide a safer operating environment after the tower is closed. Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments objecting to the proposal were received. Class D airspace designations are published in paragraph 5000, and Class E airspace areas extending upward from the surface of the earth in paragraph 6002, of FAA Order 7400.9J dated August 31, 2001, and effective September 16, 2001, which is incorporated by reference in 14 CFR 71.1. The Class D and Class E airspace designations listed in this document will be published subsequently in the Order.

The Rule

This amendment to 14 CFR part 71 establishes Class D airspace and modifies Class E airspace at Marquette, MI, to support the operation of a Federal Contract Tower, and to provide a safer operating environment after the tower is closed. The areas will be depicted on appropriations aeronautical charts.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.