

Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, 747SR, and 747SP series airplanes equipped with Pratt & Whitney JT9D-3, -7, -7Q, and -7R4G2 series engines was published as a supplemental notice of proposed rulemaking in the **Federal Register** on February 6, 2004 (69 FR 5781). That action proposed to require drilling witness holes through the cowl skin at the cowl latch locations in the left-hand side of the cowl panel assembly of each engine.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 481 airplanes of the affected design in the worldwide fleet. The FAA estimates that 114 airplanes of U.S. registry will be affected by this AD, that it will take approximately 8 work hours per airplane (2 work hours per engine) to accomplish the required actions, and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$59,280, or \$520 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is

determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-07-19 Boeing: Amendment 39-13563. Docket 2002-NM-207-AD.

Applicability: Model 747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, 747SR, and 747SP series airplanes; equipped with Pratt & Whitney JT9D-3, -7, -7Q, and -7R4G2 series engines; line numbers 1 through 814 inclusive, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent improper connection of the cowl latch located in the left-hand side of the cowl panel assembly of each engine, which could result in separation of a cowl panel from the airplane; accomplish the following:

Drill Holes

(a) Within 36 months after the effective date of this AD: Drill witness holes through the cowl skin at each of the six cowl latch locations located on the left-hand side of the cowl panel assembly of each engine, per paragraphs 3.B.1. through 3.B.4. of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-71-2301, Revision 1, dated August 21, 2003.

Credit for Actions Accomplished per Previous Service Bulletin

(b) Actions accomplished before the effective date of this AD per the Accomplishment Instructions of Boeing Service Bulletin 747-71-2301, dated May 30, 2002, are acceptable for compliance with the requirements of paragraph (a) of this AD.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Incorporation by Reference

(d) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Special Attention Service Bulletin 747-71-2301, Revision 1, dated August 21, 2003. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective on May 11, 2004.

Issued in Renton, Washington, on March 25, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-7299 Filed 4-5-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2004-NM-01-AD; Amendment 39-13564; AD 2004-07-20]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-400 and -400D Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 747-400 and -400D series airplanes. This action requires an inspection to determine the routing configuration of wire bundle W4489 and related investigative/corrective actions. This action is necessary to prevent possible

interference between wire bundle W4489 and the receptacle housing of the chiller boost fan, drain tubes, and adjacent structure, which could result in damage to the wire bundle and consequent arcing and fire. This action is intended to address the identified unsafe condition.

DATES: Effective April 21, 2004.

The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of April 21, 2004.

Comments for inclusion in the Rules Docket must be received on or before June 7, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2004-NM-01-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-iarcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2004-NM-01-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC. **FOR FURTHER INFORMATION CONTACT:** Suk Y. Jang, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6511; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: The FAA received a report of a fire in the cargo bay left sidewall at station 900 on a Boeing Model 747-400 series airplane. The fire was caused by arcing between wire bundle W4489 and the receptacle housing of the chiller boost fan, which also caused fire damage to the surrounding insulation blankets and cargo liner. In 1990, the manufacturer corrected this condition by rerouting wire bundle W4489 in the area of the

chiller boost fan. However, the corrective action may not have been properly applied to certain Model 747-400 and -400D series airplanes delivered prior to and after 1990. The incorrect wire routing configuration could lead to possible interference between wire bundle W4489 and the receptacle housing of the chiller boost fan, drain tubes, and adjacent structure. This condition, if not corrected, could result in damage to the wire bundle and consequent arcing and fire.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 747-21A2427, dated April 24, 2003, which describes procedures for inspecting to determine the routing configuration of wire bundle W4489 and related investigative/corrective actions, if necessary. The related investigative actions include a detailed inspection of wire bundle W4489 for damage; and a detailed inspection for missing wire clamps. The corrective actions include repairing any damage to wire bundle W4489; installing any missing wire clamps; and rerouting wire bundle W4489. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design that may be registered in the United States at some time in the future, this AD is being issued to prevent possible interference between wire bundle W4489 and the receptacle housing of the chiller boost fan, drain tubes, and adjacent structure, which could result in damage to the wire bundle and consequent arcing and fire. This AD requires an inspection to determine the routing configuration of wire bundle W4489 and related investigative/corrective actions, if necessary. The actions are required to be accomplished in accordance with the service bulletin described previously.

Cost Impact

None of the airplanes affected by this action are on the U.S. Register. All airplanes included in the applicability of this rule currently are operated by non-U.S. operators under foreign registry; therefore, they are not directly affected by this AD action. However, the FAA considers that this rule is necessary to ensure that the unsafe condition is addressed in the event that

any of these subject airplanes are imported and placed on the U.S. Register in the future.

Should an affected airplane be imported and placed on the U.S. Register in the future, it would require approximately 1 work hour to accomplish the required inspection, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of this AD would be \$65 per airplane.

Determination of Rule's Effective Date

Since this AD action does not affect any airplane that is currently on the U.S. register, it has no adverse economic impact and imposes no additional burden on any person. Therefore, prior notice and public procedures hereon are unnecessary and the amendment may be made effective in less than 30 days after publication in the **Federal Register**.

Comments Invited

Although this action is in the form of a final rule and was not preceded by notice and opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact

concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2004-NM-01-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-07-20 Boeing: Amendment 39-13564. Docket 2004-NM-01-AD.

Applicability: Model 747-400 and -400D series airplanes, as listed in Boeing Alert

Service Bulletin 747-21A2427, dated April 24, 2003; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent possible interference between wire bundle W4489 and the receptacle housing of the chiller boost fan, drain tubes, and adjacent structure, which could result in damage to the wire bundle and consequent arcing and fire, accomplish the following:

Inspection and Related Investigation/Corrective Actions

(a) Within 12 months after the effective date of this AD, inspect to determine the routing configuration for wire bundle W4489; and, before further flight, do all the related investigative/corrective actions, as applicable; by accomplishing all of the actions in the Accomplishment Instructions of Boeing Alert Service Bulletin 747-21A2427, dated April 24, 2003.

Alternative Methods of Compliance

(b) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Incorporation by Reference

(c) The actions shall be done in accordance with Boeing Alert Service Bulletin 747-21A2427, dated April 24, 2003. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(d) This amendment becomes effective on April 21, 2004.

Issued in Renton, Washington, on March 25, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-7298 Filed 4-5-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NE-48-AD; Amendment 39-13553; AD 2004-07-09]

RIN 2120-AA64

Airworthiness Directives; General Electric Aircraft Engines CT7 Series Turboprop Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) for certain General Electric Aircraft Engines (GEAE) CT7 series turboprop engines. That AD currently requires propeller gearbox (PGB) oil filter impending bypass button (IBB) inspections, oil filter inspections, replacement of left-hand and right-hand idler gears at time of PGB overhaul, and replacement of certain serial number (SN) PGBs before accumulating 2,000 flight hours. This AD requires the same actions, and adds additional SNs of affected PGBs. This AD results from reports of PGBs equipped with certain gears that do not meet design specifications, resulting in the same failure addressed in the existing AD. We are issuing this AD to prevent separation of PGB left-hand and right-hand idler gears, which could result in uncontained PGB failure and internal bulkhead damage, possibly prohibiting the auxiliary feathering system from fully feathering the propeller on certain PGBs.

DATES: This AD becomes effective May 11, 2004. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of May 11, 2004. The Director of the Federal Register approved the incorporation by reference of certain other publications listed in the regulations as of April 24, 2003 (68 FR 13618, March 20, 2003).

ADDRESSES: You can get the service information identified in this AD from General Electric Aircraft Engines, CT7 Series Turboprop Engines, 1000 Western Ave, Lynn, MA 01910; telephone (781) 594-3140, fax (781) 594-4805.

You may examine the AD docket, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Eugene Triozzi, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7148; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR Part 39 with a proposed AD. The proposed AD applies to certain GEAE CT7 series turboprop engines. We published the proposed AD in the **Federal Register** on