

classified as ASME Code Class 2 and Class 3 must be designed and be provided with access to enable the performance of inservice testing of the pumps and valves for assessing operational readiness set forth in the editions and addenda of Section XI of the ASME Boiler and Pressure Vessel Code incorporated by reference in paragraph (b) of this section (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, that are incorporated by reference in paragraph (b) of this section) applied to the construction of the particular pump or valve or the Summer 1973 Addenda, whichever is later.

* * * * *

(iv) * * *

(A) Pumps and valves, in facilities whose construction permit was issued before November 22, 1999, which are classified as ASME Code Class 2 and Class 3 must be designed and be provided with access to enable the performance of inservice testing of the pumps and valves for assessing operational readiness set forth in the editions and addenda of Section XI of the ASME Boiler and Pressure Vessel Code incorporated by reference in paragraph (b) of this section (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, that are incorporated by reference in paragraph (b) of this section) applied to the construction of the particular pump or valve or the Summer 1973 Addenda, whichever is later.

* * * * *

(4) * * *

(ii) Inservice tests to verify operational readiness of pumps and valves, whose function is required for safety, conducted during successive 120-month intervals must comply with the requirements of the latest edition and addenda of the Code incorporated by reference in paragraph (b) of this section 12 months before the start of the 120-month interval (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, or 1.192 that are incorporated by reference in paragraph (b) of this section), subject to the limitations and modifications listed in paragraph (b) of this section.

* * * * *

(g) * * *

(2) For a boiling or pressurized water-cooled nuclear power facility whose construction permit was issued on or after January 1, 1971, but before July 1, 1974, components (including supports) which are classified as ASME Code

Class 1 and Class 2 must be designed and be provided with access to enable the performance of inservice examination of such components (including supports) and must meet the preservice examination requirements set forth in editions and addenda of Section XI of the ASME Boiler and Pressure Vessel Code incorporated by reference in paragraph (b) of this section (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, that are incorporated by reference in paragraph (b) of this section) in effect six months before the date of issuance of the construction permit. The components (including supports) may meet the requirements set forth in subsequent editions and addenda of this Code which are incorporated by reference in paragraph (b) of this section (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, that are incorporated by reference in paragraph (b) of this section), subject to the applicable limitations and modifications.

(3) * * *

(i) Components (including supports) which are classified as ASME Code Class 1 must be designed and be provided with access to enable the performance of inservice examination of these components and must meet the preservice examination requirements set forth in the editions and addenda of Section XI of the ASME Boiler and Pressure Vessel Code incorporated by reference in paragraph (b) of this section (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, that are incorporated by reference in paragraph (b) of this section) applied to the construction of the particular component.

(ii) Components which are classified as ASME Code Class 2 and Class 3 and supports for components which are classified as ASME Code Class 1, Class 2, and Class 3 must be designed and be provided with access to enable the performance of inservice examination of these components and must meet the preservice examination requirements set forth in the editions and addenda of Section XI of the ASME Boiler and Pressure Vessel Code incorporated by reference in paragraph (b) of this section (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, that are incorporated by reference in paragraph (b) of this section) applied to the construction of the particular component.

* * * * *

(4) * * *

(i) Inservice examinations of components and system pressure tests

conducted during the initial 120-month inspection interval must comply with the requirements in the latest edition and addenda of the Code incorporated by reference in paragraph (b) of this section on the date 12 months before the date of issuance of the operating license (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, that are incorporated by reference in paragraph (b) of this section), subject to the limitations and modifications listed in paragraph (b) of this section.

(ii) Inservice examination of components and system pressure tests conducted during successive 120-month inspection intervals must comply with the requirements of the latest edition and addenda of the Code incorporated by reference in paragraph (b) of this section 12 months before the start of the 120-month inspection interval (or the optional ASME Code cases listed in NRC Regulatory Guide 1.147, through Revision 14, that are incorporated by reference in paragraph (b) of this section), subject to the limitations and modifications listed in paragraph (b) of this section.

* * * * *

Dated at Rockville, Maryland, this 21st day of July, 2004.

For the Nuclear Regulatory Commission.

Luis A. Reyes,

Executive Director for Operations.

[FR Doc. 04-17609 Filed 8-2-04; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-18670; Directorate Identifier 2002-NM-83-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-10-10, and DC-10-10F Airplanes; Model DC-10-15 Airplanes; Model DC-10-30 and DC-10-30F (KC-10A and KDC-10) Airplanes; Model DC-10-40 and DC-10-40F Airplanes; and Model MD-10-10F and MD-10-30F Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) for certain McDonnell Douglas transport category airplanes.

That AD currently requires implementation of a program of structural inspections to detect and correct fatigue cracking in order to ensure the continued airworthiness of these airplanes as they approach the manufacturer's original fatigue design life goal. This proposed AD would require the implementation of a program of structural inspections of baseline structure to detect and correct fatigue cracking in order to ensure the continued airworthiness of these airplanes as they approach the manufacturer's original fatigue design life goal. This proposed AD is prompted by a significant number of these airplanes approaching or exceeding the design service goal on which the initial type certification approval was predicated. We are proposing this AD to detect and correct fatigue cracking that could compromise the structural integrity of these airplanes.

DATES: We must receive comments on this proposed AD by September 17, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.
- Fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You can get the service information identified in this proposed AD from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024).

You may examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Ron Atmur, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood,

California 90712-4137; telephone (562) 627-5224; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Docket Management System (DMS)

The FAA has implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, new AD actions are posted on DMS and assigned a docket number. We track each action and assign a corresponding directorate identifier. The DMS AD docket number is in the form "Docket No. FAA-2004-99999." The Transport Airplane Directorate identifier is in the form "Directorate Identifier 2004-NM-999-AD." Each DMS AD docket also lists the directorate identifier ("Old Docket Number") as a cross-reference for searching purposes.

Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2004-18670; Directorate Identifier 2002-NM-83-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of our docket Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the Docket

You may examine the AD docket in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

On November 6, 1995, we issued Airworthiness Directive (AD) 95-23-09, amendment 39-9429 (60 FR 61649, December 1, 1995), for certain McDonnell Douglas transport category airplanes. That AD requires implementation of a program of structural inspections to detect and correct fatigue cracking in order to ensure the continued airworthiness of these airplanes as they approach the manufacturer's original fatigue design life goal. That AD was prompted by data submitted by the manufacturer indicating that certain revisions to the program are necessary in order to clarify some principal structural elements (PSE) and some non-destructive inspection (NDI) procedures. We issued that AD to prevent fatigue cracking that could compromise the structural integrity of those airplanes.

Supplemental Inspection Documents (SIDs) ADs

In the early 1980's, as part of our continuing work to maintain the structural integrity of older transport category airplanes, we concluded that the incidence of fatigue cracking may increase as these airplanes reach or exceed their design service goal (DSG). A significant number of these airplanes were approaching or had exceeded the DSG on which the initial type certification approval was predicated. In light of this, and as a result of increased utilization, longer operational lives, and the high levels of safety expected of the currently operated transport category airplanes, we determined that a supplemental structural inspection program (SSIP) was necessary to ensure a high level of structural integrity for all airplanes in the transport fleet.

Issuance of Advisory Circular

As a follow-on from that determination, we issued Advisory Circular (AC) No. 91-56, "Supplemental Structural Inspection Program for Large Transport Category Airplanes," dated May 6, 1981. That AC provides guidance material to manufacturers and

operators for use in developing a continuing structural integrity program to ensure safe operation of older airplanes throughout their operational lives. This guidance material applies to transport airplanes that were certified under the fail-safe requirements of part 4b ("Airplane Airworthiness, Transport Categories") of the Civil Air Regulations of the Federal Aviation Regulations (FAR) (14 CFR part 25), and that have a maximum gross weight greater than 75,000 pounds. The procedures set forth in that AC are applicable to transport category airplanes operated under subpart D ("Special Flight Operations") of part 91 of the FAR (14 CFR part 91); part 121 ("Operating Requirements: Domestic, Flag, and Supplemental Operations"); part 125 ("Certification and Operations: Airplanes having a Seating Capacity of 20 or More Passengers or a Maximum Payload of 6,000 Pounds or More"); and part 135 ("Operating Requirements: Commuter and On-Demand Operations") of the FAR (14 CFR parts 121, 125, and 135). The objective of the SSIP was to establish inspection programs to ensure timely detection of fatigue cracking.

Aging Aircraft Safety Act (AASA)

In October 1991, Congress enacted Title IV of Public Law 102-143, the AASA of 1991, to address aging aircraft concerns. That Act instructed the FAA administrator to prescribe regulations that will ensure the continuing airworthiness of aging aircraft.

SSID Team

In April 2000 the Transport Airplane Directorate (TAD) chartered a SSID Team to develop recommendations to standardize the SID/SSID ADs regarding the treatment of repairs, alterations, and modifications (RAMs). The report can be accessed at <http://www.faa.gov/certification/aircraft/transport.htm>.

FAA Responses to AASA

In addition to the SSID Team activity, there are other on-going activities associated with FAA's Aging Aircraft Program. This includes, among other initiatives, our responses to the AASA.

On November 1, 2002, as one of the responses to the AASA, we issued the Aging Airplane Safety Interim Final Rule (AASIFR) (67 FR 72726, December 6, 2002). The applicability of that rule addresses airplanes that are operated under part 121 of the FAR (14 CFR part 121), all U.S. registered multi-engine airplanes operated under part 129 of the FAR (14 CFR part 129), and all multi-engine airplanes used in scheduled operations under part 135 of the FARs (14 CFR part 135). The AASIFR requires

the maintenance programs of those airplanes to include damage tolerance-based inspections and procedures that include all major structural RAMs. Currently, the ASSIFR requires that these procedures be established and incorporated within four years after December 8, 2003, the effective date specified by the AASIFR.

Public Technical Meeting

The TAD also held a public meeting regarding standardization of the FAA approach to RAMs in SID/SSID ADs on February 27, 2003, in Seattle, Washington. We presented our views and heard comments from the public concerning issues regarding the standardization of the requirements of ADs for certain transport category airplanes that mandate SSIDs, and that address the treatment of RAMs for those certain transport category airplanes. Our presentation included a plan for the standardization of SID/SSID ADs, the results of the SSID Team findings, and the TAD vision of how SID/SSID ADs may support compliance to the AASIFR. We also asked for input from operators on the issues addressing RAMs in SID/SSID ADs. One of the major comments presented at the public meeting was that operators do not have the capability to accomplish the damage tolerance assessments, and they will have to rely on the manufacturers to perform those assessments. Furthermore, the operators believe that the timeframes to accomplish the damage tolerance assessments will not permit manufacturers to support the operators. Another major comment presented was from the Airworthiness Assurance Working Group (AAWG) of the Aviation Rulemaking Advisory Committee (ARAC). The AAWG requested that we withdraw the damage tolerance requirements from the final rule and task AAWG to develop a new RAM damage tolerance based program with timelines to be developed by ARAC. The public meeting presentations can be accessed at <http://www.faa.gov/certification/aircraft/transport.htm>.

Explanation of Relevant Service Information

We have reviewed Boeing Report No. L26-012, "DC-10 Supplemental Inspection Document (SID)," Volume I, Revision 6, dated February 2002. The SID provides a description of PSEs and NDI procedures and thresholds with repetitive inspection intervals for inspections of PSEs. For the purposes of this proposed AD, a PSE is defined as an element that contributes significantly to the carrying of flight, ground or pressurization loads, and the integrity of

that element is essential in maintaining the overall structural integrity of the airplane. Certain planning data (inspection threshold and repetitive inspections) and reporting requirements defined in Section 2 of Volume III-94, of the SID have been removed and are now included in Volume 1 of Revision 6 of the SID. We have determined that accomplishment of the actions specified in the service information will adequately address the unsafe condition.

We also have reviewed McDonnell Douglas Report No. MDC 91K0264, "DC-10/KC-10 Aging Aircraft Repair Assessment Program Document," Revision 1, dated October 2000, which provides procedures to determine the appropriate inspection or replacement program for certain repairs to the fuselage pressure boundary. These repairs and inspection/replacement programs are acceptable alternative methods of compliance for the repair and repair inspection programs specified in this proposed AD.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require implementation of a structural inspection program of baseline structure to detect and correct fatigue cracking in order to ensure the continued airworthiness of airplanes as they approach the manufacturer's original fatigue design life goal.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design. Therefore, we are proposing this AD, which would supersede AD 95-23-09. This proposed AD would continue to require revision of the FAA-approved maintenance program. This proposed AD would also require implementation of a structural inspection program of baseline structure to detect and correct fatigue cracking in order to ensure the continued airworthiness of airplanes as they approach the manufacturer's original fatigue design life goal. The following paragraphs summarize certain specific actions proposed in this AD.

Editorial Clarification of References

Paragraph (g) of AD 95-23-09 requires, among other things, that the maintenance program be revised to include the inspection threshold and

repetitive inspections (planning data) defined in Section 2 of Volume III-94 of the SID. Paragraph (g)(4) of AD 95-23-09 also requires inspection results to be reported per Section 2 of Volume III-94. Those planning and data reporting requirements are now contained in Section 4 of Volume I, Revision 6, dated February 2002. Therefore, this NPRM proposes use of the information in Section 4 of Volume 1 of Revision 6, and reference to Volume III has been removed in the new requirements of this proposed AD.

Revision of the Maintenance Program

Paragraph (i) of the proposed AD would require a revision of the maintenance inspection program that provides for inspection(s) of the PSE per Boeing Report No. L26-012, "DC-10 Supplemental Inspection Document (SID)," Volume 1, Revision 6, dated February 2002. PSEs are also defined and specified in the SID. All references in this proposed AD to the "SID" are to Revision 6, dated February 2002.

Supplemental Inspection Program (SIP)

Paragraph (j) of the proposed AD would specify that the SIP be implemented on a PSE-by-PSE basis before structure exceeds its 75% fatigue life threshold ($\frac{3}{4}N_{th}$), and its full fatigue life threshold (N_{th}). The threshold value is defined as the life of the structure measured in total landings, when the probability of failure reaches one in a billion. The DC-10 SID program is not a sampling program. All airplanes would be inspected once prior to reaching both PSE thresholds (once by $\frac{3}{4}N_{th}$ and once by N_{th}). In order for the inspection to have value, no PSE would be inspected prior to half of the fatigue life threshold, $\frac{1}{2}N_{th}$. The additional $\frac{3}{4}N_{th}$ threshold aids in advancing the threshold for some PSEs as explained in Section 3 of Volume I of the SID. Inspection of each PSE should be accomplished in accordance with the NDI procedures set forth in Section 2 of Volume II, Revision 8, dated November 2003.

Once threshold N_{th} is passed, the PSE would be inspected at repetitive intervals not to exceed $\Delta NDI/2$ as specified in Section 3 of Volume I of the SID per the NDI procedure, which is specified in Section 2 of Volume II of the SID. The definition of $\Delta NDI/2$ is half of the life for a crack to grow from a given NDI detectable crack size to instability.

SIP Inspection Requirements

Paragraph (k) of this proposed AD also would require, for airplanes that have exceeded the N_{th} , that each PSE be

inspected prior to reaching the established thresholds ($\frac{3}{4}N_{th}$ and N_{th}) or within 18 months after the effective date of this AD. The entire PSE must be inspected regardless of whether or not it has been repaired, altered, or modified. If any PSE is repaired, altered, or modified, it must be reported as "discrepant." A discrepant report indicates that a PSE could not be completely inspected because the NDI procedure could not be accomplished due to differences on the airplane from the NDI reference standard (*i.e.*, RAMs).

Reporting Requirements

Paragraph (l) of this proposed AD would require that all negative, positive, or discrepant findings of the inspection accomplished in paragraph (b) of the AD be reported to Boeing at the times specified, and in accordance with, the instructions contained in Section 3 of Volume 1 of the SID.

Corrective Action

Paragraph (m) of this proposed AD would require that any cracked structure detected during any inspection required per paragraph (g) of this AD be repaired before further flight. Additionally, paragraph (i) of this AD would require accomplishment of follow-on actions as specified in paragraphs (i)(1), (i)(2), and (i)(3) of this proposed AD, at the times specified below.

1. Within 18 months after repair, accomplish a Damage Tolerance Assessment (DTA) that defines the threshold for inspection and submit the assessment for approval to the Manager, Los Angeles Aircraft Certification Office (ACO), FAA.

2. Prior to reaching 75% of the threshold, submit the inspection methods and repetitive inspections intervals for the repair for approval by the Manager of the Los Angeles ACO.

3. Prior to the threshold, the inspection method and repetitive inspection intervals are to be incorporated into the FAA-approved structural maintenance or inspection program for the airplane.

For the purposes of this proposed AD, the FAA anticipates that submissions of the DTA of the repair, if acceptable, should be approved within six months after submission.

Transferability of Airplanes

Paragraph (n) of this proposed AD specifies the requirements of the inspection program for transferred airplanes. Before any airplane that is subject to this proposed AD can be added to an air carrier's operations specifications, a program for the

accomplishment of the inspections required by this proposed AD must be established. Paragraph (n) of the proposed AD would require accomplishment of the following:

1. For airplanes that have been inspected per this proposed AD, the inspection of each PSE must be accomplished by the new operator per the previous operator's schedule and inspection method, or per the new operator's schedule and inspection method, at whichever time would result in the earlier accomplishment date for that PSE inspection. The compliance time for accomplishment of this inspection must be measured from the last inspection accomplished by the previous operator. After each inspection has been performed once, each subsequent inspection must be performed per the new operator's schedule and inspection method.

2. For airplanes that have not been inspected per this proposed AD, the inspection of each PSE must be accomplished either prior to adding the airplane to the air carrier's operations specification, or per a schedule and an inspection method approved by the FAA. After each inspection has been performed once, each subsequent inspection must be performed per the new operator's schedule.

Accomplishment of these actions will ensure that: (1) An operator's newly acquired airplanes comply with its SSIP before being operated; and (2) frequently transferred airplanes are not permitted to operate without accomplishment of the inspections defined in the SSID.

Inspections Accomplished Previously

Paragraph (o) of this proposed AD merely provides approval of Boeing Report No. L26-012, "DC-10 Supplemental Inspection Document (SID)," Volume I, Revision 4, dated June 1993, and Revision 5, dated October 1994; and Volume II, Revision 6, dated October 1997, and Revision 7, dated August 2002; as acceptable for compliance with the requirements of paragraph (j) of this proposed AD for inspections accomplished prior to the effective date of the proposed AD.

Acceptable for Compliance

Paragraph (p) of this proposed AD also provides approval of McDonnell Douglas Report No. MDC 91K0264, "DC-10/KC-10 Aging Aircraft Repair Assessment Program Document," Revision 1, dated October 2000, as an acceptable means compliance with the requirements of paragraphs (i) and (m) of this proposed AD for repairs and inspection/replacement for certain repairs to the fuselage pressure shell

accomplished prior to the effective date of the proposed AD.

Change to Existing AD

This proposed AD would retain certain requirements of AD 95–23–09. Since AD 95–23–09 was issued, the AD format has been revised, and certain paragraphs have been rearranged. As a result, the corresponding paragraph identifiers have changed in this proposed AD, as listed in the following table:

REVISED PARAGRAPH IDENTIFIERS

Requirement in AD 95–23–09	Corresponding requirement in this proposed AD
paragraph (a)	paragraph (f).
paragraph (b)	paragraph (g).
paragraph (c)	paragraph (h).

Interim Action

This is considered to be interim action. We are currently considering requiring damage tolerance-based inspections and procedures that include all major structural RAMs, which may result in additional rulemaking. That rulemaking may include appropriate recommendations from the previously mentioned FAA team and a public meeting on how to address RAMs.

Costs of Compliance

There are about 419 McDonnell Douglas transport category airplanes worldwide of the affected design. This proposed AD would affect about 249 airplanes of U.S. registry and 13 U.S. operators.

The incorporation of the SID program into an operator's maintenance program, as required by AD 95–23–09, and retained in this proposed AD takes about 1,290 work hours per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the cost to the 13 affected U.S. operators to incorporate the SID program is estimated to be \$1,090,050.

The recurring inspection costs, as required by AD 95–23–09, are estimated to be 365 work hours per airplane per year, at an average labor rate of \$65 per work hour. Based on these figures, the recurring inspection costs required by AD 95–23–09 are estimated to be \$23,725 per airplane, or \$5,907,525 for the affected U.S. fleet.

Since no new recurring inspection procedures have been added to the program by this new proposed AD action, there is no additional economic burden on affected operators to perform any additional recurrent inspections.

Additionally, the number of required work hours for each proposed

inspection (and the SID program), as indicated above, is presented as if the accomplishment of those actions were to be conducted as "stand alone" actions. However, in actual practice, these actions for the most part will be accomplished coincidentally or in combination with normally scheduled airplane inspections and other maintenance program tasks. Further, any costs associated with special airplane scheduling are expected to be minimal.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by removing amendment 39–9429 (60 FR 61649 FR, December 1, 1995) and adding the following new airworthiness directive (AD):

McDonnell Douglas: Docket No. FAA–2004–18670; Directorate Identifier 2002–NM–83–AD.

Comments Due Date

(a) The Federal Aviation Administration must receive comments on this airworthiness directive (AD) action by September 17, 2004.

Affected ADs

(b) This AD supersedes AD 95–23–09, amendment 39–9429.

Applicability: (c) This AD applies to all McDonnell Douglas Model DC–10–10, and DC–10–10F airplanes; Model DC–10–15 airplanes; Model DC–10–30 and DC–10–30F (KC–10A and KDC–10) airplanes; Model DC–10–40 and DC–10–40F airplanes; and Model MD–10–10F and MD–10–30F airplanes; certificated in any category.

Unsafe Condition

(d) This AD was prompted by a significant number of these airplanes approaching or exceeding the design service goal on which the initial type certification approval was predicated. We are issuing this AD to detect and correct fatigue cracking that could compromise the structural integrity of these airplanes.

Compliance: (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Certain Requirements of AD 95–23–09

(f) Within 6 months after November 24, 1993 (the effective date of AD 93–17–09, amendment 39–8680), incorporate a revision into the FAA-approved maintenance inspection program which provides for inspection(s) of the Principal Structural Elements (PSE's) defined in Section 2 of Volume I of McDonnell Douglas Report No. L26–012, "DC–10 Supplemental Inspection Document (SID)," Revision 3, dated December 1992, in accordance with Section 2 of Volume III–92, dated October 1992, of the SID. The non-destructive inspection (NDI) techniques set forth in Section 2 and Section 4 of Volume II, Revision 3, dated December 1992, of the SID provide acceptable methods for accomplishing the inspections required by this paragraph. All inspection results (negative or positive) must be reported to McDonnell Douglas, in accordance with the instructions contained in Section 2 of Volume III–92, dated October 1992, of the SID. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120–0056.

(1) For those Fleet Leader Operator Sampling (FLOS) PSE's that do not have a Normal Maintenance Visual Inspection specified in Section 4 of Volume II, Revision 3, dated December 1992, of the SID, the procedure for general visual inspection is as follows: Perform an inspection of the general PSE area for cleanliness, presence of foreign objects, security of parts, cracks, corrosion, and damage.

(2) For PSE's 53.10.031E/.032E, 53.10.047E/.048E, and 57.10.029E/.030E: The ENDDATE for these PSE's is October 1993.

(For these PSE's, disregard the June 1993 ENDDATE specified in Section 2 of Volume III-92, dated October 1992, of the SID.)

(g) Within 6 months after December 1, 1995 (the effective date of AD 95-23-09, amendment 39-9429), replace the revision of the FAA-approved maintenance inspection program required by paragraph (f) of this AD with a revision that provides for inspection(s) of the PSE's defined in Section 2 of Volume I of McDonnell Douglas Report No. L26-012, "DC-10 Supplemental Inspection Document (SID)," Revision 5, dated October 1994, in accordance with Section 2 of Volume III-94, dated November 1994, of the SID. The NDI techniques set forth in Section 2 of Volume II, Revision 5, dated October 1994, of the SID provide acceptable methods for accomplishing the inspections required by this paragraph.

(1) Prior to reaching the threshold (N_{th}), but no earlier than one-half of the threshold ($N_{th}/2$), specified for all PSE's listed in Volume III-94, dated November 1994, of the SID, inspect each PSE sample in accordance with the NDI procedures set forth in Section 2 of Volume II, Revision 5, dated October 1994. Thereafter, repeat the inspection for that PSE at intervals not to exceed $\Delta NDI/2$ of the NDI procedure that is specified in Volume III-94, dated November 1994, of the SID.

(2) This AD does not require visual inspections of FLOS PSE's on airplanes listed in Volume III-94, dated November 1994, of the SID planning data at least once during the specified inspection interval, in accordance with Section 2 of Volume III-94, dated November 1994, of the SID.

(3) For PSE's 53.10.055/.056E, 55.10.013/.014B, 53.10.005/.006E, 53.10.031/.032E, 53.10.047/.048E, 57.10.029/.030E: The EDATE for these PSE's is June 1998. (For these PSE's, disregard the June 1996 EDATE specified in Section 2, of Volume III-94, dated November 1994, of the SID.)

(4) All inspection results (negative or positive) must be reported to McDonnell Douglas in accordance with the instructions contained in Section 2 of Volume III-94, dated November 1994, of the SID. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(h) Any cracked structure detected during the inspections required by paragraph (f) or (g) of this AD must be repaired before further flight, in accordance with a method approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA.

Note 1: Requests for approval of any PSE repair that would affect the FAA-approved maintenance inspection program required by this AD should include a damage tolerance assessment for that PSE repair.

New Requirements of This AD

Revision of the Maintenance Inspection Program

(i) Within 12 months after the effective date of this AD, incorporate a revision into

the FAA-approved maintenance inspection program that provides for inspection(s) of the PSEs, in accordance with Boeing Report No. L26-012, "DC-10 Supplemental Inspection Document (SID)," Volume I, Revision 6, dated February 2002." Unless otherwise specified, all further references in this AD to the "SID" are to Revision 6, dated February 2002.

Non-Destructive Inspections (NDIs)

(j) For all PSEs listed in Section 2 of Volume I of the SID, perform an NDI for fatigue cracking of each PSE in accordance with the NDI procedures specified in Section 2 of Volume II, Revision 8, dated November 2003, of the SID, at the times specified in paragraph (j)(1), (j)(2), or (j)(3) of this AD, as applicable.

(1) For airplanes that have less than three quarters of the fatigue life threshold ($\frac{3}{4}N_{th}$) as of the effective date of the AD: Perform an NDI for fatigue cracking no earlier than one-half of the threshold ($\frac{1}{2}N_{th}$) but prior to reaching three-quarters of the threshold ($\frac{3}{4}N_{th}$), or within 18 months after the effective date of this AD, whichever occurs later. Inspect again prior to reaching the threshold (N_{th}), but no earlier than ($\frac{3}{4}N_{th}$). Thereafter, after passing the threshold (N_{th}), repeat the inspection for that PSE at intervals not to exceed $\Delta NDI/2$.

(2) For airplanes that have reached or exceeded three-quarters of the fatigue life threshold ($\frac{3}{4}N_{th}$), but less than the threshold (N_{th}), as of the effective date of the AD: Perform an NDI prior to reaching the threshold (N_{th}), or within 18 months after the effective date of this AD, whichever occurs later. Thereafter, after passing the threshold (N_{th}), repeat the inspection for that PSE at intervals not to exceed $\Delta NDI/2$.

(3) For airplanes that have reached or exceeded the fatigue life threshold (N_{th}) as of the effective date of the AD: Perform an NDI within 18 months after the effective date of this AD. Thereafter, repeat the inspection for that PSE at intervals not to exceed $\Delta NDI/2$.

Discrepant Findings

(k) If any discrepancy (e.g., differences on the airplane from the NDI reference standard, such as PSEs that have been repaired, altered, or modified) is detected during any inspection required by paragraph (j) of this AD, accomplish the action specified in paragraph (k)(1) or (k)(2) of this AD, as applicable.

(1) If a discrepancy is detected during any inspection performed prior to $\frac{3}{4}N_{th}$ or N_{th} : The area of the PSE affected by the discrepancy must be inspected prior to N_{th} per a method approved by the Manager, Los Angeles ACO, FAA.

(2) If a discrepancy is detected during any inspection performed after N_{th} : The area of the PSE affected by the discrepancy must be inspected prior to the accumulation of an additional $\Delta NDI/2$, measured from the last non-discrepant inspection finding, per a method approved by the Manager of the Los Angeles ACO.

Reporting Requirements

(l) All negative, positive, or discrepant (discrepant finding examples are described in paragraph (k) of this AD) findings of the

inspections accomplished under paragraph (o) of this AD must be reported to Boeing, at the times specified in, and in accordance with the instructions contained in, Section 4 of Volume I of the SID. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

Corrective Actions

(m) Any cracked structure of a PSE detected during any inspection required by paragraph (j) of this AD must be repaired before further flight in accordance with an FAA-approved method. Accomplish follow-on actions described in paragraphs (m)(1), (m)(2), and (m)(3) of this AD, at the times specified.

(1) Within 18 months after repair, perform a damage tolerance assessment (DTA) that defines the threshold for inspection of the repair and submit the assessment for approval to the Manager of the Los Angeles ACO.

(2) Prior to reaching 75% of the threshold as determined in paragraph (j)(1) of this AD, submit the inspection methods and repetitive inspection intervals for the repair for approval by the Manager of the Los Angeles ACO.

(3) Prior to the threshold as determined in paragraph (j)(1) of this AD, incorporate the inspection method and repetitive inspection intervals into the FAA-approved structural maintenance or inspection program for the airplane.

Note 2: For the purposes of this AD, we anticipate that submissions of the DTA of the repair, if acceptable, should be approved within six months after submission.

Note 3: Advisory Circular AC 25.1529-1, "Instructions for Continued Airworthiness of Structural Repairs on Transport Airplanes," dated August 1, 1991, is considered to be additional guidance concerning the approval of repairs to PSEs.

Inspection for Transferred Airplanes

(n) Before any airplane that has exceeded the fatigue life threshold (N_{th}) can be added to an air carrier's operations specifications, a program for the accomplishment of the inspections required by this AD must be established per paragraph (n)(1) or (n)(2) of this AD, as applicable.

(1) For airplanes that have been inspected per this AD, the inspection of each PSE must be accomplished by the new operator per the previous operator's schedule and inspection method, or the new operator's schedule and inspection method, at whichever time would result in the earlier accomplishment date for that PSE inspection. The compliance time for accomplishment of this inspection must be measured from the last inspection accomplished by the previous operator. After each inspection has been performed once, each subsequent inspection must be performed per the new operator's schedule and inspection method.

(2) For airplanes that have not been inspected per this AD, the inspection of each PSE required by this AD must be

accomplished either prior to adding the airplane to the air carrier's operations specification, or per a schedule and an inspection method approved by the Manager, Los Angeles ACO. After each inspection has been performed once, each subsequent inspection must be performed per the new operator's schedule.

Inspections Accomplished Before the Effective Date of This AD

(o) Inspections accomplished prior to the effective date of this AD per Boeing Report No. L26-012, "DC-10 Supplemental Inspection Document (SID)," Volume I, Revision 4, dated June 1993, or Revision 5, dated October 1994; Volume II, Revision 6, dated October 1997, or Revision 7, dated August 2002; and Volume III-94, dated November 1994; are acceptable for compliance with the requirements of paragraph (j) of this AD.

Acceptable for Compliance

(p) McDonnell Douglas Report No. MDC 91K0264, "DC-10/KC-10 Aging Aircraft Repair Assessment Program Document," Revision 1, dated October 2000, provides inspection/replacement programs for certain repairs to the fuselage pressure shell. These repairs and inspection/replacement programs are considered acceptable for compliance with the requirements of paragraphs (i) and (m) of this AD for repairs subject to that document.

Alternative Methods of Compliance (AMOCs)

(q) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(r) AMOCs approved previously per AD 95-23-09, amendment 39-9429, are approved as AMOCs with the actions required by paragraph (j) of this AD.

Issued in Renton, Washington, on July 23, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 04-17592 Filed 8-2-04; 8:45 am]

BILLING CODE 4910-13-P

FEDERAL COMMUNICATIONS COMMISSION

47 CFR Parts 2 and 90

[ET Docket No. 04-243; FCC 04-156]

Narrowbanding for Private Land Mobile Radio Service

AGENCY: Federal Communications Commission.

ACTION: Proposed rule.

SUMMARY: This document proposes to revise our transition plan for Private Land Mobile Radio (PLMR) licensees in the 150.05-150.8 MHz, 162-174 MHz,

and 406.1-420 MHz bands. This action will provide for an orderly transition from wideband to narrowband operations, increase spectrum efficiency, maintain compatibility with Federal operations, permit PLMR licensees to operate using existing equipment with greater confidence that their critical operations will not be suddenly required to cease transmissions, and significantly reduce the probability that wideband PLMR operations will interfere with new Federal operations.

DATES: Written comments are due September 2, 2004, and reply comments are due September 17, 2004.

ADDRESSES: Office of the Secretary, Federal Communications Commission, 445 12th Street, SW., TW-A325, Washington, DC 20554.

FOR FURTHER INFORMATION CONTACT: Tom Mooring, Office of Engineering and Technology, (202) 418-2450, TTY (202) 418-2989, e-mail: Tom.Mooring@fcc.gov.

SUPPLEMENTARY INFORMATION: This is a summary of the Commission's *Notice of Proposed Rulemaking*, ET Docket No. 04-243; FCC 04-156, adopted June 30, 2004, and released July 6, 2004. The full text of this document is available for inspection and copying during regular business hours in the FCC Reference Center (Room CY-A257), 445 12th Street, SW., Washington, DC 20554. The complete text of this document also may be purchased from the Commission's copy contractor, Best Copy and Printing, Inc., 445 12th Street, SW., Room, CY-B402, Washington, DC 20554. The full text may also be downloaded at: <http://www.fcc.gov>. Alternative formats are available to persons with disabilities by contacting Brian Millin at (202) 418-7426 or TTY (202) 418-7365.

Pursuant to §§ 1.415 and 1.419 of the Commission's rules, 47 CFR 1.415, 1.419, interested parties may file comments on or before September 2, 2004, and reply comments on or before September 17, 2004. Comments may be filed using the Commission's Electronic Comment Filing System (ECFS) or by filing paper copies. See *Electronic Filing of Documents in Rulemaking Proceedings*, 63 FR 24121 (May 1, 1998). Comments filed through the ECFS can be sent as an electronic file via the Internet to <http://www.fcc.gov/e-file/ecfs.html>. Generally, only one copy of an electronic submission must be filed. If multiple docket or rulemaking numbers appear in the caption of this proceeding, however, commenters must transmit one electronic copy of the comments to each docket or rulemaking number referenced in the caption. In

completing the transmittal screen, commenters should include their full name, U.S. Postal Service mailing address, and the applicable docket or rulemaking number. Parties may also submit an electronic comment by Internet e-mail. To get filing instructions for e-mail comments, commenters should send an e-mail to ecfs@fcc.gov, and should include the following words in the body of the message, "get form <your e-mail address>." A sample form and directions will be sent in reply. Parties who choose to file by paper must file an original and four copies of each filing. If more than one docket or rulemaking number appears in the caption of this proceeding, commenters must submit two additional copies for each additional docket or rulemaking number.

All filings must be addressed to the Commission's Secretary, Office of the Secretary, Federal Communications Commission. Filings can be sent by hand or messenger delivery, by commercial overnight courier, or by first-class or overnight U.S. Postal Service mail (although we continue to experience delays in receiving U.S. Postal Service mail). The Commission's contractor, Natek, Inc., will receive hand-delivered or messenger-delivered paper filings for the Commission's Secretary at 236 Massachusetts Avenue, NE., Suite 110, Washington, DC 20002. The filing hours at this location are 8 a.m. to 7 p.m. All hand deliveries must be held together with rubber bands or fasteners. Any envelopes must be disposed of before entering the building. Commercial overnight mail (other than U.S. Postal Service Express Mail and Priority Mail) must be sent to 9300 East Hampton Drive, Capitol Heights, MD 20743. U.S. Postal Service first-class mail, Express Mail, and Priority Mail should be addressed to 445 12th Street, SW., Washington, DC 20554.

Summary of the Notice of Proposed Rulemaking

1. This proceeding was initiated in order to revise the procedures by which certain PLMR service operations on the Hydrological and Meteorological (Hydro), Forest Fire-Fighting and Conservation, and Public Safety channels, as well as Medical Radiocommunication Systems, are to transition to narrower, more spectrally efficient channels in a process commonly known as "narrowbanding." These PLMR operations occupy spectrum in the 150.05-150.8 MHz, 162-174 MHz, and 406.1-420 MHz bands that is allocated for Federal Government (Federal) use and, in many cases, is shared on the condition that