additional employees and fixed assets, and the associated costs;

• A description of the current and proposed office/branch structure, including a general description of the location(s); parking availability, public transportation availability, drivethrough service, lobby capacity, or any other service feature illustrating community access;

 Marketing plan addressing how the community will be served for the 24month period after the proposed conversion to a community charter, including the projected marketing budget, promotions, and time line;

• Details, terms and conditions of the credit union's financial products, programs, and services to be provided to the entire community; and

 Maps showing the current and proposed service facilities, ATMs, political boundaries, major roads, and other pertinent information.

An existing federal credit union may apply to convert to a community charter. Groups currently in the credit union's field of membership, but outside the new community credit union's boundaries, may not be included in the new community charter. Therefore, the credit union must notify groups that will be removed from the field of membership as a result of the conversion. Members of record can continue to be served.

Before approval of an application to convert to a community credit union, NCUA must be satisfied that the credit union will be viable and capable of providing services to its members.

Community credit unions will be expected to regularly review and to follow, to the fullest extent economically possible, the marketing and business plans submitted with their applications.

V.A.7—Community Boundaries

The geographic boundaries of a community federal credit union are the areas defined in its charter. The boundaries can usually be defined using political borders, streets, rivers, railroad tracks, etc.

A community that is a recognized legal entity may be stated in the field of membership—for example, "Gus Township, Texas," "Isabella City, Georgia," or "Fairfax County, Virginia."

A community that is a recognized MSA must state in the field of membership the political jurisdiction(s) that comprise the MSA.

V.A.8—Special Community

Charters

A community field of membership may include persons who work or

attend school in a particular industrial park, shopping mall, office complex, or similar development. The proposed field of membership must have clearly defined geographic boundaries.

V.A.9—Sample Community

Fields of Membership

A community charter does not have to include all four affinities (i.e., live, work, worship, or attend school in a community). Some examples of community fields of membership are:

- nPersons who live, work, worship, or attend school in, and businesses located in the area of Johnson City, Tennessee, bounded by Fern Street on the north, Long Street on the east, Fourth Street on the south, and Elm Avenue on the west;
- Persons who live or work in Green County, Maine;
- Persons who live, worship, or work in and businesses and other legal entities located in Independent School District No. 1, DuPage County, Illinois;
- Persons who live, worship, work (or regularly conduct business in), or attend school on the University of Dayton campus, in Dayton, Ohio;
- Persons who work for businesses located in Clifton Country Mall, in Clifton Park, New York; or
- Persons who live, work, or worship in the Binghamton, New York, MSA, consisting of Broome and Tioga Counties, New York.

Some Examples of insufficiently defined local communities, neighborhoods, or rural districts are:

- Persons who live or work within and businesses located within a tenmile radius of Washington, DC (using a radius does not establish a well-defined area);
- Persons who live or work in the industrial section of New York, New York. (not a well-defined neighborhood, community, or rural district); or
- Persons who live or work in the greater Boston area. (not a well-defined neighborhood, community, or rural district).

Some examples of unacceptable local communities, neighborhoods, or rural districts are:

- Persons who live or work in the State of California. (does not meet the definition of local community, neighborhood, or rural district).
- Persons who live in the first congressional district of Florida. (does not meet the definition of local community, neighborhood, or rural district).
- 4. Section III.A of Chapter 3 of IRPS 03–1, as amended by IRPS 06–1 and IRPS 07–1, is revised by removing the

second and third full paragraphs and the bulleted paragraphs in between them and adding in their place two paragraphs to read as follows:

For an underserved area, the well-defined local community, neighborhood, or rural district requirement is met if the area to be served meets the definition of a local community contained in Chapter 2 V.A.2.

If the area to be served does not meet the single political jurisdiction or statistical definition contained in Chapter 2 V.A.2, the application must include documentation to support that it is a well-defined local community, neighborhood, or rural district.

[FR Doc. E7–10398 Filed 6–4–07; 8:45 am] BILLING CODE 7535–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28348; Directorate Identifier 2007-NM-060-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737–600, –700, –700C, –800 and –900 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 737–600, –700, -700C, -800 and -900 series airplanes. This proposed AD would require sealing the fasteners on the front and rear spar inside the main fuel tank and on the lower panel of the center fuel tank, inspecting the wire bundle support installation in the equipment cooling system bays to identify the type of clamp installed and determine whether the Teflon sleeve is installed, and doing related corrective actions if necessary. This proposed AD results from a design review of the fuel tank systems. We are proposing this AD to prevent arcing at certain fuel tank fasteners, in the event of a lightning strike or fault current event, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

DATES: We must receive comments on this proposed AD by July 20, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to *http://dms.dot.gov* and follow the instructions for sending your comments electronically.
- Government-wide rulemaking Web site: Go to http://www.regulations.gov and follow the instructions for sending your comments electronically.
- *Mail*: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL–401, Washington, DC 20590.
 - Fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207, for the service information identified in this proposed AD

FOR FURTHER INFORMATION CONTACT:

Kathrine Rask, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6505; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the ADDRESSES section. Include the docket number "FAA-2007-28348; Directorate Identifier 2007-NM-060-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to http:// dms.dot.gov, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the Federal Register published on April 11, 2000 (65 FR

19477–78), or you may visit *http://dms.dot.gov*.

Examining the Docket

You may examine the AD docket on the Internet at http://dms.dot.gov, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647–5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the ADDRESSES section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

The FAA has examined the underlying safety issues involved in fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled "Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements" (67 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 ("SFAR 88," Amendment 21–78, and subsequent Amendments 21-82 and 21-83).

Among other actions, SFAR 88 requires certain type design (i.e., type certificate (TC) and supplemental type certificate (STC)) holders to substantiate that their fuel tank systems can prevent ignition sources in the fuel tanks. This requirement applies to type design holders for large turbine-powered transport airplanes and for subsequent modifications to those airplanes. It requires them to perform design reviews and to develop design changes and maintenance procedures if their designs do not meet the new fuel tank safety standards. As explained in the preamble to the rule, we intended to adopt airworthiness directives to mandate any changes found necessary to address unsafe conditions identified as a result of these reviews.

In evaluating these design reviews, we have established four criteria intended to define the unsafe conditions associated with fuel tank systems that require corrective actions. The percentage of operating time during which fuel tanks are exposed to flammable conditions is one of these criteria. The other three criteria address

the failure types under evaluation: single failures, single failures in combination with another latent condition(s), and in-service failure experience. For all four criteria, the evaluations included consideration of previous actions taken that may mitigate the need for further action.

We have determined that the actions identified in this AD are necessary to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

Boeing determined during the SFAR 88 review that certain non-conductive fasteners, which penetrate the main and center fuel tanks, could be subject to lightning strikes or fault currents induced by short circuits. During a lightning strike or fault current event, electrical current may be conducted to those non-conductive fasteners, which if unsealed could create arcing inside the fuel tanks. This condition, if not corrected, could result in a fuel tank explosion and consequent loss of the airplane.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 737–57A1279, dated January 24, 2007. The service bulletin describes procedures for the following actions (depending on airplane configuration):

- Sealing the fasteners on the front and rear spar inside the main fuel tank and on the lower panel of the center fuel tank:
- Inspecting the wire bundle support installation in the equipment cooling system bays to identify the type of clamp installed and determine whether the Teflon sleeve is installed;
- Replacing any incorrect clamp with a new correct clamp; and
- Installing any missing Teflon sleeving.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

There are about 1,754 airplanes of the affected design in the worldwide fleet;

of these, 645 airplanes are U.S. registered. The following table provides the estimated costs for U.S. operators to

comply with this proposed AD, at an average hourly labor rate of \$80.

ESTIMATED COSTS

Action	Group	Work hours	Average hourly labor rate	Cost per airplane	Number of U.S registered airplanes	Fleet cost
Sealant application	1	62	\$80	\$4,960	586	\$2,906,560
	2	28	80	2,240	44	98,560
	3	28	80	2,240	15	33,600
Inspection	1	3	80	240	586	140,640
	2	3	80	240	44	10,560
	3	2	80	160	15	2,400

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- 1. Is not a "significant regulatory action" under Executive Order 12866;
- 2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- 3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with

this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2007-28348; Directorate Identifier 2007-NM-060-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by July 20, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Model 737–600, –700, –700C, –800 and –900 series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 737–57A1279, dated January 24, 2007.

Unsafe Condition

(d) This AD results from a design review of the fuel tank systems. We are issuing this AD to prevent arcing at certain fuel tank fasteners, in the event of a lightning strike or fault current event, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Fastener Sealant

(f) Within 60 months after the effective date of this AD: Seal the fasteners on the front and rear spar inside the main fuel tank and on the lower panel of the center fuel tank, as applicable, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737–57A1279, dated January 24, 2007.

Inspection

(g) Within 60 months after the effective date of this AD: Perform a general visual inspection of the wire bundle support installation in the equipment cooling system bays to identify the type of clamp installed, and determine whether the Teflon sleeve is installed. Do these actions in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737–57A1279, dated January 24, 2007. Do all applicable corrective actions within 60 months after the effective date of this AD in accordance with the service bulletin.

Alternative Methods of Compliance (AMOCs)

- (h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.
- (2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on May 25, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–10755 Filed 6–4–07; 8:45 am]

BILLING CODE 4910-13-P