

has on the prices producers receive for their commodity. Without volume control, spearmint oil markets would likely be over-supplied, resulting in low producer prices and a large volume of oil stored and carried over to the next crop year. The model estimates how much lower producer prices would likely be in the absence of volume controls.

The recommended allotment percentages, upon which 2006–2007 producer allotments were based, are 153 percent for Scotch (a 108-percentage point increase from the original allotment percentage of 45 percent) and 55 percent for Native (a 9 percentage point increase from the original allotment percentage of 46 percent). Without volume controls, producers would not be limited to these allotment levels, and could produce and sell additional spearmint oil. The econometric model estimated a \$1.37 decline in the season average producer price per pound of Far West spearmint oil (combining the two classes of spearmint oil) resulting from the higher quantities that would be produced and marketed if volume controls were not used.

A previous price decline estimate of \$1.49 per pound was based on the original 2006–2007 allotment percentages (45 percent for Scotch and 46 percent for Native) published in the **Federal Register** on April 5, 2006 (71 FR 16986). The revised estimate reflects the impact of the additional quantities that have been made available by this rule compared to the original allotment percentages. In actuality, this rule made available 13,026 additional pounds of Scotch and 21,624 additional pounds of Native spearmint oil, since not all producers have reserve pool oil. Loosening the volume control restriction resulted in the smaller price decline estimate of \$1.37 per pound.

The use of volume controls allows the industry to fully supply spearmint oil markets while avoiding the negative consequences of over-supplying these markets. The use of volume controls is believed to have little or no effect on consumer prices of products containing spearmint oil and will not result in fewer retail sales of such products.

Based on projections available at the meeting, the Committee considered alternatives to each of the increases. The Committee not only considered leaving the salable quantity and allotment percentage unchanged, but also looked at various increases. The Committee reached each of its recommendations to increase the salable quantity and allotment percentage for Scotch and Native spearmint oil after careful

consideration of all available information, and believes that the levels recommended will achieve the objectives sought. Without the increases, the Committee believes the industry would not have been able to meet market needs.

This rule will not impose any additional reporting or recordkeeping requirements on either small or large spearmint oil handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies. In addition, as noted in the initial regulatory flexibility analysis, USDA has not identified any relevant Federal rules that duplicate, overlap or conflict with this rule.

The AMS is committed to complying with the E-Government Act, to promote the use of the Internet and other information technologies to provide increased opportunities for citizen access to Government information and services, and for other purposes.

The Committee's meeting was widely publicized throughout the spearmint oil industry and all interested persons were invited to attend the meeting and participate in Committee deliberations. Like all Committee meetings, the February 21, 2007, meeting was a public meeting and all entities, both large and small, were able to express their views on this issue.

An interim final rule concerning this action was published in the **Federal Register** on April 12, 2007. A notice of the rule was mailed by the Committee's staff to all committee members, producers, handlers, and other interested persons. In addition, the rule was made available through the Internet by USDA and the Office of the Federal Register. That rule provided for a 60-day comment period which ended June 11, 2007. No comments were received.

A small business guide on complying with fruit, vegetable, and specialty crop marketing agreements and orders may be viewed at: <http://www.ams.usda.gov/fv/moab.html>. Any questions about the compliance guide should be sent to Jay Guerber at the previously mentioned address in the **FOR FURTHER INFORMATION CONTACT** section.

After consideration of all relevant material presented, including the Committee's recommendation, and other information, it is found that finalizing the interim final rule, without change, as published in the **Federal Register** (72 FR 18345, April 12, 2007) will tend to effectuate the declared policy of the Act.

List of Subjects in 7 CFR Part 985

Marketing agreements, Oils and fats, Reporting and recordkeeping requirements, Spearmint oil.

PART 985—MARKETING ORDER REGULATING THE HANDLING OF SPEARMINT OIL PRODUCED IN THE FAR WEST

■ Accordingly, the interim final rule amending 7 CFR part 985, which was published at 71 FR 18345 on April, 12, 2007, is adopted as a final rule without change.

Dated: July 24, 2007.

Lloyd C. Day,

Administrator, Agricultural Marketing Service.

[FR Doc. E7–14622 Filed 7–30–07; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–28813; Directorate Identifier 2007–SW–09–AD; Amendment 39–15140; AD 2007–16–01]

RIN 2120–AA64

Airworthiness Directives; Enstrom Helicopter Corporation Model F–28, F–28A, F–28C, F–28C–2, F–28C–2R, F–28F, F–28F–R, 280, 280C, 280F, 280FX, TH–28, 480, and 480B Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for Enstrom Helicopter Corporation (Enstrom) Model F–28, F–28A, F–28C, F–28C–2, F–28C–2R, F–28F, F–28F–R, 280, 280C, 280F, 280FX, TH–28, 480, and 480B helicopters. This action requires a visual check to determine if a certain serial-numbered main rotor blade retention pin (retention pin) is installed, and removing and replacing any affected retention pin with an airworthy retention pin. This amendment is prompted by a report from the manufacturer that some retention pins were not manufactured in accordance with specifications cited on the engineering drawing. The actions specified in this AD are intended to prevent failure of a retention pin, separation of a main rotor blade from the helicopter, and subsequent loss of control of the helicopter.

DATES: Effective August 15, 2007.

Comments for inclusion in the Rules Docket must be received on or before October 1, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this AD:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically;

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically;

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590;

- *Hand Delivery:* Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays; or

- *Fax:* 202-493-2251.

You may get the service information identified in this AD from Enstrom Helicopter Corporation, 2209 22nd Street, P.O. Box 490, Menominee, Michigan 49858-0490.

EXAMINING THE DOCKET: You may examine the docket that contains the AD, any comments, and other information on the Internet at <http://dms.dot.gov>, or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located in Room W12-140 on the ground floor of the West Building at the street address stated in the

ADDRESSES section. Comments will be available in the AD docket shortly after the DMS receives them.

FOR FURTHER INFORMATION CONTACT:

Gregory J. Michalik, Senior Aerospace Engineer, FAA, Small Airplane Directorate, Chicago Aircraft Certification Office, 2300 E. Devon Ave., Room 107, Des Plaines, Illinois 60018, telephone (847) 298-7135, fax (847) 294-7834.

SUPPLEMENTARY INFORMATION: This amendment adopts a new AD for Enstrom Model F-28, F-28A, F-28C, F-28C-2, F-28C-2R, F-28F, F-28F-R, 280, 280C, 280F, 280FX, TH-28, 480, and 480B helicopters with a retention pin, part number (P/N) 28-14007-3, installed, with a serial number (S/N) that is listed in the following table:

RETENTION PIN S/N

04098-01 through 04098-56.
05018-01 through 05018-36.
05143-01 through 05143-56.
05341-1 through 05341-8.

RETENTION PIN S/N—Continued

05341-10 through 05341-17.
05341-19.
05341-21 through 05341-33.
05341-35 through 05341-42.
05341-44 through 05341-59.
05341-61.
05341-62.
05341-64 through 05341-71.
06214-3 through 06214-14.
06214-16 through 06214-23.
06214-25 through 06214-29.
06214-31.
06214-33 through 06214-35.
06214-37 through 06214-57.
06214-59 through 06214-68.

This action requires, before further flight, visually checking each retention pin to determine if the S/N, which is marked on the head of the retention pin, is listed in the Applicability section of this AD. If there is no serial number marked on the head of the retention pin (*i.e.*, the retention pin head is blank), the retention pin does not need to be replaced and this visual check constitutes a terminating action for the requirements of this AD for that retention pin. If an affected retention pin is installed, determining the retention pin's number of hours time-in-service (TIS) and removing and replacing it with an airworthy retention pin that has a S/N that is not listed in the Applicability section of this AD is required:

- Within the next 5 hours TIS or within 30 days, whichever occurs first, if the retention pin has 545 or more hours TIS, or
- On or before reaching 550 hours TIS or within 30 days, whichever occurs first, if the retention pin has less than 545 hours TIS.

This amendment is prompted by a report from the manufacturer that some retention pins were manufactured from steel that did not meet the specifications cited on the engineering drawing. The actions specified in this AD are intended to prevent failure of a retention pin, separation of a main rotor blade from the helicopter, and subsequent loss of control of the helicopter.

We have reviewed Enstrom Helicopter Corporation Service Directive Bulletin (SDB) No. 0102 and Enstrom Helicopter Corporation SDB No. T-029, both dated March 20, 2007, which specify visual and magnetic particle inspections for cracks in certain serial-numbered retention pins, and repairing or replacing retention pins in accordance with certain inspection criteria. This AD does not require inspections for cracks but requires that each affected retention pin be replaced.

This unsafe condition is likely to exist or develop on other helicopters of the same type design. Therefore, this AD is being issued to prevent failure of a retention pin, separation of a main rotor blade from the helicopter, and subsequent loss of control of the helicopter. This AD requires removing and replacing certain serial-numbered retention pins. The visual check required by this AD may be performed by an owner/operator (pilot), but must be entered into the aircraft records showing compliance with paragraph (a) of this AD in accordance with 14 CFR 43.11 and 91.417(a)(2)(v). This AD allows a pilot to perform this check because it involves only a visual check of the head of each retention pin to determine the S/N.

The short compliance time involved is required because the previously described critical unsafe condition can adversely affect the controllability and structural integrity of the helicopter. Therefore, removing and replacing each affected retention pin is required within 5 hours TIS or within 30 days, depending on the retention pin's hours TIS, which constitutes a very short time period, and this AD must be issued immediately.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

We estimate that this AD will affect 39 helicopters, and

- Determining the S/N of all retention pins (3 on each helicopter) will take approximately 0.5 work hour;
- Determining the hours TIS of three affected retention pins will take approximately 1 work hour; and
- Removing and replacing three retention pins will take approximately 3 work hours at an average labor rate of \$80 per work hour. Required parts will cost approximately \$680 per helicopter. Based on these figures, we estimate the total cost impact of the AD on U.S. operators to be \$1,040 per helicopter or \$40,560 if all retention pins get replaced on the entire fleet.

Comments Invited

This AD is a final rule that involves requirements that affect flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2007-28813; Directorate Identifier 2007-SW-09-AD"

at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of our docket Web site, you can find and read the comments to any of our dockets, including the name of the individual who sent the comment. You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with

this AD. See the DMS to examine the economic evaluation.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2007-16-01 Enstrom Helicopter

Corporation: Amendment 39-15140.

Docket No. FAA-2007-28813;

Directorate Identifier 2007-SW-09-AD.

Applicability: Model F-28, F-28A, F-28C, F-28C-2, F-28C-2R, F-28F, F-28F-R, 280, 280C, 280F, 280FX, TH-28, 480, and 480B helicopters, with a main rotor blade retention pin (retention pin) having a serial number (S/N) that is listed in the following table, installed, certificated in any category:

RETENTION PIN S/N

04098-01 through 04098-56.
05018-01 through 05018-36.
05143-01 through 05143-56.
05341-1 through 05341-8.
05341-10 through 05341-17.
05341-19.
05341-21 through 05341-33.
05341-35 through 05341-42.
05341-44 through 05341-59.
05341-61.
05341-62.
05341-64 through 05341-71.
06214-3 through 06214-14.
06214-16 through 06214-23.
06214-25 through 06214-29.
06214-31.
06214-33 through 06214-35.
06214-37 through 06214-57.
06214-59 through 06214-68.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of a retention pin, separation of a main rotor blade from the helicopter, and subsequent loss of control of the helicopter, accomplish the following:

(a) Before further flight, check the S/N that is marked on the head of each retention pin to see if it is a S/N that is listed in the Applicability section of this AD. See Figure 1 for the location of the S/N. If there is no serial number marked on the head of the retention pin (*i.e.*, the retention pin head is blank), the retention pin does not need to be replaced and this determination constitutes a terminating action for the requirements of this AD for that retention pin.




Figure 1

(b) The visual check required by paragraph (a) of this AD may be performed by an owner/operator (pilot) holding at least a private pilot certificate, and must be entered into the aircraft records showing compliance with paragraph (a) of this AD in accordance with 14 CFR sections 43.11 and 91.417(a)(2)(v).

(c) Determine the number of hours TIS for any affected retention pin and replace the retention pin with an airworthy retention pin as follows:

(1) For a retention pin with 545 or more hours TIS, remove the retention pin and replace it with an airworthy retention pin with a S/N that is not listed in the Applicability section of this AD within the next 5 hours TIS or within 30 days, whichever occurs first.

(2) For a retention pin with less than 545 hours TIS, remove the retention pin and replace it with an airworthy retention pin with a S/N that is not listed in the Applicability section of this AD on or before reaching 550 hours TIS or within 30 days, whichever occurs first.

Note: Enstrom Service Directive Bulletin No. T-029 and Enstrom Service Directive Bulletin 0102, both dated March 20, 2007, pertain to the subject of this AD.

(d) Removing any affected retention pin and replacing it with an airworthy retention pin that is not included in the Applicability section of this AD is considered a terminating action for the requirements of this AD for that retention pin.

(e) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Chicago Aircraft Certification Office, FAA, ATTN: Gregory J. Michalik, Senior Aerospace Engineer, 2300 E. Devon Ave., Room 107, Des Plaines, Illinois, 60018, telephone (847) 298-7135, fax (847) 294-7834, for information about previously approved alternative methods of compliance.

(f) This amendment becomes effective on August 15, 2007.

Issued in Fort Worth, Texas, on July 24, 2007.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 07-3711 Filed 7-30-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 558

New Animal Drugs For Use in Animal Feeds; Ractopamine and Tylosin

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect approval of a supplemental new animal drug application (NADA) filed by Elanco Animal Health. The supplemental NADA revises the indications for use of two-way combination Type B and Type C medicated swine feeds formulated with ractopamine hydrochloride and tylosin phosphate.

DATES: This rule is effective July 31, 2007.

FOR FURTHER INFORMATION CONTACT:

Harlan J. Howard, Center for Veterinary Medicine (HFV-120), Food and Drug Administration, 7500 Standish Pl., Rockville, MD 20855, 301-827-0231, e-mail: harlan.howard@fda.hhs.gov.

SUPPLEMENTARY INFORMATION: Elanco Animal Health, a Division of Eli Lilly & Co., Lilly Corporate Center, Indianapolis, IN 46285, filed a supplement to NADA 141-172 that provides for use of two-way combination Type B and Type C medicated swine feeds formulated with PAYLEAN (ractopamine hydrochloride) and TYLAN (tylosin phosphate) single-