

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39–14633 (71 FR 33606, June 12, 2006) corrected at 71 FR 36674, June 28, 2006, and adding the following new airworthiness directive (AD):

Goodrich (Formerly BF Goodrich): Docket No. FAA–2007–28882; Directorate Identifier 2007–NM–035–AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by September 20, 2007.

Affected ADs

(b) This AD supersedes AD 2006–12–08.

Applicability

(c) This AD applies to Goodrich Evacuation Systems Approved Under Technical Standard Order (TSO) TSO–C69b, as installed on Airbus Model A330–201, –202, –203, –223, –243, –301, –321, –322, –323, –341, –342, and –343 airplanes; Model A340–211, –212, –213, –311, –312, and –313 airplanes; and Model A340–541 and –642 airplanes; certificated in any category.

Unsafe Condition

(d) This AD results from a report indicating that, during maintenance testing, the pressure relief valves on the affected Goodrich evacuation systems did not seal when activated, which caused the pressure in the escape slide/raft to drop below the minimum allowable raft mode pressure. We are issuing this AD to prevent loss of pressure in the escape slides/rafts after an emergency evacuation, which could result in inadequate buoyancy to support the raft's passenger capacity during ditching, and increase the chance for injury to raft passengers.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2006–12–08

Inspection for Certain Part Number (P/N)

(f) For all airplanes: Within 36 months after July 17, 2006 (the effective date of AD 2006–12–08): Perform an inspection to determine the part number (P/N) of the pressure relief valve on the Goodrich evacuation systems in accordance with the Accomplishment Instructions of Goodrich Service Bulletin 25–355, dated July 25, 2005, or Goodrich Service Bulletin 25–355, Revision 1, dated July 24, 2006. After the effective date of this AD, only Goodrich Service Bulletin 25–355, Revision 1, dated July 24, 2006, may be used.

(1) If any pressure relief valve having P/N 4A3791–3 is installed, before further flight, replace the valve with a new or serviceable valve having P/N 4A3641–1 and mark the girt adjacent to the placard, in accordance with the Accomplishment Instructions of the service bulletin.

(2) If any pressure release valve having P/N 4A3641–1 is installed, before further flight, mark the girt adjacent to the placard in accordance with the Accomplishment Instructions of the service bulletin.

Part Installation for Airplanes Identified in Original Issue of the Service Bulletin

(g) As of July 17, 2006, no person may install a pressure relief valve having P/N 4A3791–3, on any airplane equipped with Goodrich evacuation systems identified in Goodrich Service Bulletin 25–355, dated July 25, 2005.

New Requirements of This AD

Inspection for Certain Other P/N

(h) For Model A340–541 airplanes: Within 36 months after the effective date of this AD, perform an inspection to determine the P/N of the pressure relief valve on the Goodrich evacuation systems in accordance with the Accomplishment Instructions of Goodrich Service Bulletin 25–355, Revision 1, dated July 24, 2006.

(1) If any pressure relief valve having P/N 4A3791–6 is installed, before further flight, replace the valve with a new or serviceable valve having P/N 4A3641–26 and mark the girt adjacent to the placard, in accordance with the Accomplishment Instructions of the service bulletin.

(2) If any pressure release valve having P/N 4A3641–26 is installed, before further flight, mark the girt adjacent to the placard in accordance with the Accomplishment Instructions of the service bulletin.

Parts Installation for All Airplanes

(i) As of the effective date of this AD, no person may install a pressure relief valve having P/N 4A3791–3, on any airplane equipped with Goodrich evacuation systems identified in Goodrich Service Bulletin 25–355, Revision 1, dated July 24, 2006.

(j) As of the effective date of this AD, no person may install a pressure relief valve having P/N 4A3791–6, on any airplane equipped with Goodrich evacuation systems identified in Goodrich Service Bulletin 25–355, Revision 1, dated July 24, 2006.

Alternative Methods of Compliance (AMOCs)

(k)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) AMOCs approved previously in accordance with AD 2006–12–08 are

approved as AMOCs for the corresponding provisions of this AD.

Issued in Renton, Washington, on July 30, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–15222 Filed 8–3–07; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–28881; Directorate Identifier 2006–NM–263–AD]

RIN 2120–AA64

Airworthiness Directives; McDonnell Douglas Model DC–9–10, DC–9–20, DC–9–30, DC–9–40, and DC–9–50 Series Airplanes, Equipped with a Tail Cone Evacuation Slide Container Installed in Accordance With Supplemental Type Certificate (STC) ST735SO

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for McDonnell Douglas Model DC–9–10, DC–9–20, DC–9–30, DC–9–40, and DC–9–50 series airplanes, equipped with tail cone evacuation slide containers as specified above. This proposed AD would require modifying the tail cone slide. This proposed AD also would require additional tail cone drops and slide deployments, and repair if necessary. This proposed AD results from several reports of inadvertent tail cone deployments in which the tail cone slide failed to deploy. We are proposing this AD to ensure that the tail cone evacuation slide deploys correctly; failure of the slide to deploy during an emergency evacuation could result in injury to flightcrew and passengers.

DATES: We must receive comments on this proposed AD by September 20, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide Rulemaking Web site:* Go to <http://www.regulations.gov> and follow

the instructions for sending your comments electronically.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Fax:** (202) 493-2251.

- **Hand Delivery:** Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Northwest Airlines, Inc., 7500 Airline Drive, Minneapolis, Minnesota, 55450-1101, Mail Stop: 8953, for the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT:

Cheyenne Del Carmen, Aerospace Engineer, Cabin Safety/Mechanical and Environmental Systems Branch, ANM-150L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5338; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2007-28881; Directorate Identifier 2006-NM-263-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in

person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground floor of the West Building at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

We have received several reports that the tail cone emergency slide failed to deploy on McDonnell Douglas Model DC-9-10, DC-9-20, DC-9-30, DC-9-40, and DC-9-50 series airplanes, equipped with tail cone evacuation slide containers installed in accordance with supplemental type certificate (STC) ST735SO. Although we are doing further investigation and analysis, it appears that the failures resulted from either the slide container not clearing the immediate area around the slide when the slide deployment handle is pulled, or contaminated Velcro attachments that allow the slide container lanyard to separate without pulling the container off and activating the inflation bottle.

STC ST735SO for the tail cone emergency slide containers was surrendered to the Los Angeles Aircraft Certification Office (ACO), FAA, on January 21, 2003. Therefore, there is no manufacturer's service information related to this proposed AD. The affected operator must submit a method of compliance to the FAA for approval.

Failure of the slide to deploy during an emergency evacuation could result in injury to flightcrew and passengers.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design. For this reason, we are proposing this AD, which would require operators to modify the tail cone slide in accordance with a method approved by the FAA. One approved method is Northwest Airlines STC ST01967CH, issued March 19, 2007. STC ST01967CH describes the modification of the DC-9 tail cone slide. (STC ST01967CH refers to Northwest Airlines, Drawing 9B25-41477, Revision B, dated September 14, 2006; and Northwest Airlines, Drawing 9B25-90399, Revision D, dated December 21, 2006; as additional sources of service information for modifying the tail cone slide.) This proposed AD also would require additional tail cone drops and slide deployments to be done no earlier than

150 flight cycles and no later than 24 months after modifying the tail cone slide, for a minimum of 10 percent of an operator's fleet of affected airplanes (if fewer than 10 airplanes in the fleet; at least 1 airplane). If the tailcone and slide deployment is unsuccessful, this proposed AD would require repair in accordance with a method approved by the FAA.

Costs of Compliance

There are about 400 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 300 airplanes of U.S. registry. The tail cone drops/slide deployments would take about 16 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts would cost about \$1,300 per airplane. Based on these figures, the estimated cost of the proposed AD for U.S. operators is about \$774,000, or \$2,580 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

McDonnell Douglas: Docket No. FAA–2007–28881; Directorate Identifier 2006–NM–263–AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by September 20, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to McDonnell Douglas Model DC–9–11, DC–9–12, DC–9–13, DC–9–14, DC–9–15, DC–9–15F, DC–9–21, DC–9–31, DC–9–32, DC–9–32 (VC–9C), DC–9–32F, DC–9–33F, DC–9–34, DC–9–34F, DC–9–32F (C–9A, C–9B), DC–9–41, and DC–9–51 airplanes, certificated in any category, equipped with a tail cone evacuation slide container installed in accordance with supplemental type certificate (STC) ST735SO.

Unsafe Condition

(d) This AD results from several reports of inadvertent tail cone deployments in which the tail cone slide failed to deploy. We are issuing this AD to ensure that the tail cone evacuation slide deploys correctly; failure of the slide to deploy during an emergency evacuation could result in injury to flightcrew and passengers.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Initial Actions To Address Slide Deployment Failures

(f) Within 24 months after the effective date of this AD: Modify the tail cone slide in accordance with a method approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Northwest Airlines STC ST01967CH, issued March 19, 2007, is one approved method.

Note 1: STC ST01967CH refers to Northwest Airlines, Drawing 9B25–41477, Revision B, dated September 14, 2006; and Northwest Airlines, Drawing 9B25–90399, Revision D, dated December 21, 2006; as additional sources of service information for modifying the tail cone slide.

Repeat Deployment and Terminating Action

(g) Within 150 flight cycles after doing the modification required by paragraph (f) of this AD, or within 150 days after the effective date of this AD, whichever occurs later: Do additional tail cone drops and slide deployments on a minimum of 10 percent of an operator's fleet of affected airplanes (if fewer than 10 airplanes in the fleet: At least one airplane).

(1) If the tailcone and slide deployments are successful according to the applicable McDonnell Douglas DC–9 maintenance manual, no further action is required by this AD.

(2) If any tailcone and slide deployment is unsuccessful according to the applicable McDonnell Douglas DC–9 maintenance manual, before further flight, repair in accordance with a method approved by the Manager, Los Angeles ACO, FAA.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Los Angeles ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on July 30, 2007.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E7–15237 Filed 8–3–07; 8:45 am]

BILLING CODE 4910–13–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA–R09–OAR–2007–0610; FRL–8448–7]

Revisions to the Arizona State Implementation Plan, Maricopa County

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve revisions to the Maricopa County portion of the Arizona State Implementation Plan (SIP). This revision concerns reductions of particulate matter (PM) emissions from the paving of unpaved road and use of these reductions to satisfy the offset requirements under the new source review provisions of the Clean Air Act as amended in 1990 (CAA or the Act). We are proposing to approve a local rule to assure that the PM emission reductions resulting from the road paving meet the criteria for valid offsets under the Act.

DATES: Any comments on this proposal must arrive by September 5, 2007.

ADDRESSES: Submit comments, identified by docket number EPA–R09–OAR–2007–0610, by one of the following methods:

1. *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the on-line instructions.
2. *E-mail:* steckel.andrew@epa.gov.
3. *Mail or deliver:* Andrew Steckel (Air-4), U.S. Environmental Protection Agency Region IX, 75 Hawthorne Street, San Francisco, CA 94105–3901.

Instructions: All comments will be included in the public docket without change and may be made available online at <http://www.regulations.gov>, including any personal information provided, unless the comment includes Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Information that you consider CBI or otherwise protected should be clearly identified as such and should not be submitted through <http://www.regulations.gov> or e-mail. <http://www.regulations.gov> is an “anonymous access” system, and EPA will not know your identity or contact information unless you provide it in the body of your comment. If you send e-mail directly to EPA, your e-mail address will be automatically captured and included as part of the public comment. If EPA cannot read your comment due to technical difficulties and cannot contact you for clarification, EPA may not be able to consider your comment. Electronic files should avoid the use of special characters, any form of encryption, and be free of any defects or viruses.

Docket: The index to the docket for this action is available electronically at <http://www.regulations.gov> and in hard copy at EPA Region IX, 75 Hawthorne Street, San Francisco, California. While all documents in the docket are listed in the index, some information may be publicly available only at the hard copy