

Customer Liaison Manager, CH 6371 STANS, Switzerland; telephone: + 41 (0)41 619 6580; fax: + 41 (0)41 619 6576; e-mail: [fodermatt@pilatus.aircraft.com](mailto:fodermatt@pilatus.aircraft.com).

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri on September 13, 2007.

**Kim Smith,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-18476 Filed 9-20-07; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2006-26441; Directorate Identifier 2006-NM-204-AD; Amendment 39-15139; AD 2007-15-10]

**RIN 2120-AA64**

#### Airworthiness Directives; Boeing Model 747 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; correction.

**SUMMARY:** The FAA is correcting a typographical error in an existing airworthiness directive (AD) that was published in the **Federal Register** on July 30, 2007 (72 FR 41438). The error resulted in certain compliance times being mislabeled as units of flight cycles instead of flight hours. This AD applies to all Boeing Model 747 airplanes. This AD requires an inspection of the No. 2 and No. 3 windows on the left and right sides of the airplane to determine their part numbers, and related investigative and corrective actions if necessary.

**DATES:** Effective September 21, 2007.

**ADDRESSES:** The AD docket contains the proposed AD, comments, and any final disposition. You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground level of the West Building at the DOT street address stated in the **ADDRESSES** section. This docket number is FAA-2006-26441; the directorate identifier for this docket is 2006-NM-204-AD.

#### FOR FURTHER INFORMATION CONTACT:

Steve Fox, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6425; fax (425) 917-6590.

**SUPPLEMENTARY INFORMATION:** On July 18, 2007, the FAA issued AD 2007-15-10, amendment 39-15139 (72 FR 41438, July 30, 2007), for all Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes. The AD requires an inspection of the No. 2 and No. 3 windows on the left and right sides of the airplane to determine their part numbers, and related investigative and corrective actions if necessary.

As published, the compliance times in paragraph (g) of AD 2007-15-10 were mislabeled as units of flight cycles instead of flight hours.

No other part of the regulatory information has been changed; therefore, the final rule is not republished in the **Federal Register**.

The effective date of this AD remains September 4, 2007.

#### § 39.13 [Corrected]

■ In the **Federal Register** of July 30, 2007, on page 41441, in the 2nd column, paragraph (g) of AD 2007-15-10 is corrected to read as follows:

\* \* \* \* \*

(g) Where Tables 1, 2, and 3 of paragraph 1.E. of Boeing Alert Service Bulletin 747-56A2012, dated August 24, 2006, specify counting the compliance time from “\* \* \* after the date on this service bulletin,” this AD requires counting the compliance time from the effective date of this AD. After replacing a discrepant window with a new window, do the initial detailed inspection of the new window at the applicable compliance time: (1) within 5,500 flight hours after installing part number (P/N) 65B27042-( ) or 65B27043-( ), or (2) within 22,000 flight hours after installing P/N 65B27046-( ) or 65B27047-( ).

\* \* \* \* \*

Issued in Renton, Washington, on September 10, 2007.

**Ali Bahrami,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-18472 Filed 9-20-07; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-27787 Directorate Identifier 2007-CE-032-AD; Amendment 39-15209; AD 2007-19-18]

**RIN 2120-AA64**

#### Airworthiness Directives; DG Flugzeugbau GmbH Model DG-1000T Gliders

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The digital engine indicating system (DEI-NT) and associated control unit must get their latest software update. It has been found out in operation, that some combinations of system states while pressing switches can cause electrical damages to the system. A new software update is mandated to correct this deficiency and to incorporate additional safety functions to the system.

We are issuing this AD to require actions to correct the unsafe condition on these products.

**DATES:** This AD becomes effective October 26, 2007.

On October 26, 2007, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Greg Davison, Glider Program Manager, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That

NPRM was published in the **Federal Register** on June 28, 2007 (72 FR 35371). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

The digital engine indicating system (DEI-NT) and associated control unit must get their latest software update. It has been found out in operation, that some combinations of system states while pressing switches can cause electrical damages to the system. A new software update is mandated to correct this deficiency and to incorporate additional safety functions to the system.

As a result, the Flight and Maintenance Manuals need to be revised, specifically regarding the stall warning.

You may obtain further information by examining the MCAI in the AD docket.

### Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

### Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the AD.

### Costs of Compliance

We estimate that this AD will affect 1 product of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with basic requirements of this AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$80 or \$80 per product.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

### Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

**2007-19-18 DG Flugzeugbau GmbH:**  
Amendment 39-15209; Docket No. FAA-2007-27787; Directorate Identifier 2007-CE-032-AD.

#### Effective Date

- (a) This airworthiness directive (AD) becomes effective October 26, 2007.

#### Affected ADs

- (b) None.

#### Applicability

- (c) This AD applies to DG-1000T gliders, all serial numbers, certificated in any category.

#### Subject

- (d) Air Transport Association of America (ATA) Code 77: Engine Indicating.

#### Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

The digital engine indicating system (DEI-NT) and associated control unit must get their latest software update. It has been found out in operation, that some combinations of system states while pressing switches can cause electrical damages to the system. A new software update is mandated to correct this deficiency and to incorporate additional safety functions to the system.

As a result, the Flight and Maintenance Manuals need to be revised, specifically regarding the stall warning.

#### Actions and Compliance

- (f) Within the next 60 days after October 26, 2007 (the effective day of this AD), unless already done, do the following actions:

(1) Replace the Digital Indicating System (DEI-NT) unit with an updated unit that incorporates software version V1.5, and replace the control unit with an updated unit that incorporates software version V1.9 following DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006.

(2) Insert the new Flight Manual pages 0.1, 0.5, 7.14, and 7.15 and the new Maintenance Manual pages 0.1, 0.3, 0.6, 0.10, 1.22, and 1.23, issued October 2006 marked with TN1000/09, and add Diagram 15a into your maintenance program (maintenance manual) following DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006.

(3) Prior to further flight after the action required by paragraph (f)(1) of this AD, do not install a DEI-NT or control unit in any DG-1000T airplane, unless it incorporates the software versions required in this AD.

**Note 1:** The referenced DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006, also includes instructions for replacement of the fuel cock, which is not required by this AD.

**Note 2:** As specified in the flight manual, the glider can only be operated in the non-powered configuration without the DEI-NT installed. Engine operation is not possible.

#### FAA AD Differences

**Note 3:** This AD differs from the MCAI as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Greg Davison, Glider Program Manager, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2007-0040, dated February 23, 2007; and DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006, for related information.

#### Material Incorporated by Reference

(i) You must use DG-Flugzeugbau GmbH Technical Note No. 1000/09, EASA approved December 12, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact DG-Flugzeugbau GmbH, Wilhelm Dirks, Chief of Design; Otto-Lilienthal-Weg 2, 76646 Bruchsal, Germany; telephone: +49 7251 3020 140; fax: +49 7251 3020 149; e-mail: [design@dg-flugzeugbau.de](mailto:design@dg-flugzeugbau.de).

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City,

Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on September 13, 2007.

**Kim Smith,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-18474 Filed 9-20-07; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2007-27519; Directorate Identifier 2007-NE-09-AD; Amendment 39-15203; AD 2007-19-12]**

**RIN 2120-AA64**

#### Airworthiness Directives; SICMA Aero Seat 50XXX Passenger Seats

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from Mandatory Continuing Airworthiness Information (MCAI) provided by the aviation authority of France to identify and correct an unsafe condition on SICMA Aero Seat 50XXX Passenger Seats. The MCAI states the following:

A release of smoke was experienced in the passenger compartment during flight after an overheating of a reading lights power box of a PN 5039201-4T SICMA seat. An analysis put into evidence that this overheating was caused by a short-circuit produced by the rupture of an electrical power supply component (PN 78147-B). It has been noticed that this power supply is not in compliance with DO 160 environmental standard.

The short-circuiting could result in arcing and consequent smoke or fire. We are proposing this AD to prevent a short-circuit in the power box, which could result in smoke or fire in the airplane cabin.

**DATES:** This AD becomes effective October 26, 2007. The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 26, 2007.

**ADDRESSES:** The Docket Operations office is located at U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Jeffrey Lee, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine and Propeller Directorate; 12 New England Executive Park, Burlington, MA 01803; e-mail: [Jeffrey.lee@faa.gov](mailto:Jeffrey.lee@faa.gov); telephone 781-238-7161; fax 781-238-7170.

#### SUPPLEMENTARY INFORMATION:

#### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on April 27, 2007 (72 FR 20963). That NPRM proposed to correct an unsafe condition for the specified products. The Direction Generale De L'Aviation Civile (DGAC) AD states that:

A release of smoke was experienced in the passenger compartment during flight after an overheating of a reading lights power box of a PN 5039201-4T SICMA seat. An analysis put into evidence that this overheating was caused by a short-circuit produced by the rupture of an electrical power supply component (PN 78147-B). It has been noticed that this power supply is not in compliance with DO 160 environmental standard.

The short-circuiting could result in arcing and consequent smoke or fire.

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

#### Request To Revise the Costs of Compliance

SICMA Aero Seat requests us to change the Costs of Compliance section of the AD to accurately depict the extent of the issue. SICMA has verified the number of affected power boxes installed in seats and the number already retrofitted. SICMA states that only 731 seats don't comply with the AD and we should change the Costs of Compliance to reflect the new numbers. We agree. We changed the Costs to Comply to reflect the reduced number of affected seats.

#### Conclusion

We reviewed the available data, including the comment[s] received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

#### Costs of Compliance

We estimate that this AD will affect about 731 seats installed on airplanes of