

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2007–19–17 McDonnell Douglas:

Amendment 39–15208. Docket No. FAA–2007–28301; Directorate Identifier 2007–NM–061–AD.

Effective Date

(a) This AD becomes effective October 26, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the following McDonnell Douglas airplanes, certificated in any category:

- (1) All Model MD–11 and MD–11F airplanes.
- (2) DC–10–10, DC–10–10F, DC–10–15, DC–10–30, DC–10–30F (KC–10A and KDC–10), DC–10–40, DC–10–40F, MD–10–10F, and MD–10–30F airplanes; as identified in Boeing Alert Service Bulletin DC10–29A147, dated February 9, 2007.

Unsafe Condition

(d) This AD results from a report of damage to the hydraulic system that occurred when pieces of a ruptured tire from the left main landing gear penetrated the wing trailing edge access panel during takeoff. We are issuing this AD to prevent damage to the system 3 hydraulic piping, which could result in loss of the hydraulic system.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification

(f) Within 24 months after the effective date of this AD, reroute system 3 hydraulic piping, install new pipe assemblies and unions, and install redesigned support brackets for system 3 hydraulic piping. Do these actions in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD11–29A068, Revision 1, dated February 9, 2007 (for Model MD–11 and MD–11F airplanes); or Boeing Alert Service Bulletin DC10–29A147, dated February 9, 2007 (for Model DC–10–10, DC–10–10F, DC–10–15, DC–10–30, DC–10–30F (KC–10A and KDC–10), DC–10–40, DC–10–40F, MD–10–10F, and MD–10–30F airplanes).

(g) Accomplishment before the effective date of this AD of the modification required by paragraph (f) of this AD in accordance with Boeing Alert Service Bulletin MD11–29A068, dated January 23, 2007, is acceptable for compliance with the requirements of paragraph (f) of this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(i) You must use Boeing Alert Service Bulletin MD11–29A068, Revision 1, dated February 9, 2007; or Boeing Alert Service Bulletin DC10–29A147, dated February 9, 2007; as applicable, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1–L5A (D800–0024), for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 10, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–18459 Filed 9–20–07; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–29089; Directorate Identifier 2007–NM–215–AD; Amendment 39–15197; AD 2007–18–52]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 737–600, –700, –700C, –800, –900, and –900ER Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: This document publishes in the **Federal Register** an amendment

adopting airworthiness directive (AD) 2007-18-52 that was sent previously to all known U.S. owners and operators of Boeing Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes by individual notices. This AD requires repetitive detailed inspections of the slat track downstop assemblies to verify that proper hardware is installed, one-time torquing of the nut and bolt, and corrective actions if necessary. This AD is prompted by reports of parts coming off the main slat track downstop assemblies. We are issuing this AD to detect and correct loose or missing parts from the main slat track downstop assemblies, which could result in a fuel leak and consequent fire.

DATES: This AD becomes effective September 26, 2007 to all persons except those persons to whom it was made immediately effective by emergency AD 2007-18-52, issued August 28, 2007, which contained the requirements of this amendment.

We must receive comments on this AD by November 20, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6440; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: On August 28, 2007, we issued emergency AD 2007-18-52, which applies to all Boeing Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. That emergency AD superseded emergency AD 2007-18-51, described below.

Background

On August 25, 2007, we issued emergency AD 2007-18-51 for all Boeing Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. That AD requires repetitive detailed inspections of the main slat track downstop assemblies to verify that proper hardware is installed, one-time torquing of the nut and bolt, and corrective actions if necessary. Corrective actions include installing a new or serviceable part; and doing a detailed inspection of the inside of the slat can for foreign object debris (FOD) and damage, and removing any FOD and repairing damage that is found.

That AD resulted from reports of parts of the main slat track downstop assembly coming off the main slat track. In one case, a nut fell into the slat track housing (referred to as "slat can") and, during a subsequent slat retraction, the track made contact with the nut, pushing it into the wall of the can and puncturing it. That operator reported finding fuel leaking from the drain hole in the slat track housing at the No. 5 slat track position. In another case, an initial investigation revealed that following retraction of the slats after landing on a Model 737-800 airplane, loose parts of the main slat track downstop assembly punctured the slat can, which resulted in a fuel leak and a fire that ultimately destroyed the airplane. We issued that AD to detect and correct loose or missing parts from the main slat track downstop assemblies, which could result in a fuel leak and consequent fire.

Actions Since Issuance of Emergency AD 2007-18-51

Since the issuance of emergency AD 2007-18-51, we have received additional reports of parts coming off the main slat track downstop assemblies. In these cases, the parts were found in the bottom of the slat track housing ("slat can"). Additionally, in one case, the slat can was damaged.

Based on this new information, we find that the 24-day compliance time specified in emergency AD 2007-18-51 for accomplishing the detailed inspection of each main slat track downstop assembly to verify proper installation of the slat track hardware is not adequate to address the unsafe condition. We have determined that the appropriate compliance time for this inspection is 10 days after receipt of emergency AD 2007-18-52. In addition, we have determined that an inspection using borescope techniques in lieu of a detailed inspection is acceptable.

Further, we have determined that by performing the initial detailed or

borescope inspection within the reduced compliance time of 10 days, the compliance time for torquing the nut and bolt can remain at 24 days after receipt of emergency AD 2007-18-51.

FAA's Determination and Requirements of This AD

Since the unsafe condition described is likely to exist or develop on other airplanes of the same type design, we issued emergency AD 2007-18-52 to detect and correct loose or missing parts from the main slat track downstop assemblies, which could result in a fuel leak and consequent fire.

This AD supersedes emergency AD 2007-18-51, which required repetitive detailed inspections of the main slat track downstop assemblies to verify that proper hardware is installed, one-time torquing of the nut and bolt, and corrective actions if necessary. Corrective actions include installing a new or serviceable part; and doing a detailed inspection of the inside of the slat can for foreign object debris (FOD) and damage, and removing any FOD and repairing damage that is found.

This AD continues to require the same actions as emergency AD 2007-18-51, but reduces the compliance time for the initial detailed inspection of each main slat track downstop assembly to verify proper installation of the slat track hardware from 24 days after receipt of emergency AD 2007-18-51 to 10 days after receipt of this new AD. This AD also provides an additional inspection method (using borescope techniques) in lieu of the detailed inspection.

Clarification of Determining Proper Installation of Hardware

Operators should note that it was not our intent that the hardware for the main slat track downstop assemblies be disassembled to determine proper installation of the sleeve. Proper installation of the sleeve need not be confirmed, and the stop location part may be installed on either the inboard or the outboard side of the slat track. Disassembling the parts provides additional opportunities for introducing the unsafe condition addressed in this AD. Therefore, we have revised paragraph (f) of this AD accordingly.

Clarification of Reference to Boeing Multi Operator Message

Paragraph (f)(1) of emergency AD 2007-18-51 identified "Boeing Correspondence (Multi Operator Message) Service Request ID 1-523812011, issued August 25, 2007," as one approved method for verifying proper installation; installing a new or serviceable part; and inspecting for

damage and FOD, and removing FOD and repairing damage. This AD identifies that document correctly as "Boeing Multi Operator Message Number 1-523812011-1, issued August 25, 2007."

Since the issuance of emergency AD 2007-18-51, Boeing has issued Boeing Multi Operator Message Number 1-527463441-1, issued August 28, 2007. We have referenced that document in this AD as an additional approved method for doing the specified actions.

We found that immediate corrective action was required; therefore, notice and opportunity for prior public comment thereon were impracticable and contrary to the public interest, and good cause existed to make the AD effective immediately by individual notices issued on August 28, 2007, to all known U.S. owners and operators of Boeing Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. These conditions still exist, and the AD is hereby published in the **Federal Register** as an amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13) to make it effective to all persons.

Interim Action

We consider this AD interim action. If final action is later identified, we might consider further rulemaking then.

Comments Invited

This AD is a final rule that involves requirements that affect flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any relevant written data, views, or arguments regarding this AD. Send your comments to an address listed in the **ADDRESSES** section. Include "Docket No. FAA-2007-29089, Directorate Identifier 2007-NM-215-AD," at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD that might suggest a need to modify it.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000

(65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground level of the West Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If this emergency regulation is later deemed significant under DOT Regulatory Policies and Procedures, we will prepare a final regulatory evaluation and place it in the AD Docket. See the

ADDRESSES section for a location to examine the regulatory evaluation, if filed.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2007-18-52 Boeing: Amendment 39-15197. Docket No. FAA-2007-29089; Directorate Identifier 2007-NM-215-AD.

Effective Date

(a) This AD becomes effective September 26, 2007, to all persons except those persons to whom it was made immediately effective by emergency AD 2007-18-52, issued on August 28, 2007, which contained the requirements of this amendment.

Affected ADs

(b) This AD supersedes emergency AD 2007-18-51, issued August 25, 2007.

Applicability

(c) This AD applies to all Boeing Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from additional reports of parts coming off the main slat track downstop assemblies. We are issuing this AD to detect and correct loose or missing parts from the main slat track downstop assemblies, which could result in a fuel leak and consequent fire.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Note 1: Paragraph (f) of this AD merely restates the requirements of paragraph (f)(1) of AD 2007-18-51. As allowed by the phrase, "unless the actions have already been done," if the applicable initial inspections required by paragraph (f)(1) of AD 2007-18-51 have already been done, this AD does not require that those inspections be repeated until the repetitive interval of 3,000 flight cycles.

Repetitive Detailed Inspections: New Initial Compliance Time

(f) Within 10 days after the effective date of this AD: Do a detailed inspection or a borescope inspection of each main slat track downstop assembly to verify proper installation of the slat track hardware (i.e., the bolt, washers, downstops, stop location, and nut shown in Figure 1 of Boeing Service Letter 737-SL-57-084-B, dated July 10, 2007, and in this AD). Proper installation of the sleeve need not be confirmed, and the stop location part may be installed on either the inboard or the outboard side of the slat track. If any part is missing or is installed improperly, before further flight, install a new or serviceable part using a method approved in accordance with the procedures specified in paragraph (h) of this AD; and do a detailed inspection of the inside of the slat can for foreign object debris (FOD) and

damage. Before further flight, remove any FOD found and repair any damage found using a method approved in accordance with the procedures specified in paragraph (h) of this AD. Using Boeing Multi Operator Message Number 1-523812011-1, issued August 25, 2007; or 1-527463441-1, issued August 28, 2007; is one approved method for verifying proper installation; installing a new or serviceable part; and inspecting for damage and FOD, and removing FOD and repairing damage. Repeat the actions required by paragraph (f) of this AD thereafter at intervals not to exceed 3,000 flight cycles.

Note 2: Paragraph (g) of this AD merely restates the requirements of paragraph (f)(2) of AD 2007-18-51. As allowed by the phrase, "unless the actions have already been done," if the torque application required by paragraph (f)(2) of AD 2007-18-51 has


already been done, this AD does not require that the torque application be repeated.

One-Time Torquing

(g) Within 24 days after receipt of AD 2007-18-51: Apply a torque between 50 to 80 inch-pounds to the nut. The bolt head must be held with the torque applied to the nut.

Note 3: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

BILLING CODE 4910-13-P



Slat Track Downstop Assembly

Figure 1

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously in accordance with AD 2007-18-51 are approved as AMOCs for the corresponding provisions of this AD.

Material Incorporated by Reference

(i) None.

Issued in Renton, Washington, on September 10, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-18436 Filed 9-20-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28374; Directorate Identifier 2007-NM-067-AD; Amendment 39-15199; AD 2007-19-08]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300-600R Series Airplanes; and Model A310-300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

While they were gaining access to the THS (trimmable horizontal stabilizer) fuel tank for maintenance check, several operators have found one or several of the 8 THS hoist point fitting bases cracked or broken-off. The breakage resulted in metallic debris being released within the Trim Tank. The origin of the damage is most probably due to interference with the THS hoisting lugs that are stowed in the hoist point fittings in the reverse position, being screwed too deep inside the THS hoist fittings. Damaged hoist point fittings could cause the release of metallic debris within the THS fuel system.

* * * Compliance with the requirements of this AD will also eliminate potential contributing factor[s] to ignition risks.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective October 26, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 26, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on June 18, 2007 (72 FR 33409). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

While they were gaining access to the THS (trimmable horizontal stabilizer) fuel tank for maintenance check, several operators have found one or several of the 8 THS hoist point fitting bases cracked or broken-off. The breakage resulted in metallic debris being released within the Trim Tank. The origin of the damage is most probably due to interference with the THS hoisting lugs that are stowed in the hoist point fittings in the reverse position, being screwed too deep inside the THS hoist fittings. Damaged hoist point fittings could cause the release of metallic debris within the THS fuel system.

This Airworthiness Directive (AD) requires the repair of any damaged THS hoist point fittings to prevent any risk of further hoist

point fittings damage as well as any fuel leak. Compliance with the requirements of this AD will also eliminate potential contributing factor[s] to ignition risks.

The corrective action is an inspection of the internal base of the THS hoist point fittings for signs of score, cracks, perforation or other damage; and an inspection of the hoist point fittings base inside the fuel tank for structural damage, as applicable, and applicable corrective actions (repair damaged fittings and install new plastic plugs). You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Clarification of Compliance

We have revised paragraphs (f)(3), (f)(4), (f)(5), and (f)(6) of this final rule to clarify that those actions are required before further flight following the inspection required by paragraph (f)(2) of the AD. Additionally, we have removed the references to doing corrective actions "before return to revenue service" throughout the AD.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD with the changes described previously. We determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

Based on the service information, we estimate that this AD affects about 137 products of U.S. registry. We also estimate that it takes about 10 work-hours per product to comply with the