

corrective actions before further flight. Repeat the test thereafter at intervals not to exceed 2,000 flight hours.

(1) For airplanes modified before the effective date of this AD in accordance with Airbus Service Bulletin A300-22-0117, dated September 7, 2004: Do the initial test within 2,000 flight hours after the effective date of this AD.

(2) For airplanes modified in accordance with Airbus Service Bulletin A300-22-0117, Revision 01, dated April 20, 2005; or Revision 02, dated September 14, 2005: Do the initial test within 2,000 flight hours after the modification required by paragraph (f) of this AD, or within 2,000 flight hours after the

effective date of this AD, whichever occurs later.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) AMOCs approved previously in accordance with AD 2005-13-33 are not approved as AMOCs with this AD.

Related Information

(i) French airworthiness directive F-2005-107, dated July 6, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(j) You must use the service information identified in Table 1 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

TABLE 1.—ALL MATERIAL INCORPORATED BY REFERENCE

Airbus service bulletin	Revision level	Date
A300-22-0117	Original	September 7, 2004.
A300-22-0117	01	April 20, 2005.
A300-22-0117	02	September 14, 2005.
A300-22-0118, excluding Appendix 01	Original	May 18, 2005.

(1) The Director of the Federal Register approved the incorporation by reference of the documents identified in Table 2 of this

AD in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

TABLE 2.—NEW MATERIAL INCORPORATED BY REFERENCE

Airbus service bulletin	Revision level	Date
A300-22-0117	01	April 20, 2005.
A300-22-0117	02	September 14, 2005.
A300-22-0118, excluding Appendix 01	Original	May 18, 2005.

(2) On August 1, 2005 (70 FR 36833, June 27, 2005), the Director of the Federal Register approved the incorporation by reference of Airbus Service Bulletin A300-22-0117, dated September 7, 2004.

(3) Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 5, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-2412 Filed 2-13-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-22039; Directorate Identifier 2005-NE-33-AD; Amendment 39-14940; AD 2005-17-17R1]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Arrius 2F Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is revising an existing airworthiness directive (AD) for Turbomeca S.A. Arrius 2F turboshaft engines. That AD currently requires replacing certain O-rings on the check valve piston in the lubrication unit, at repetitive intervals. This AD requires the same actions except it reduces the applicability from all Turbomeca S.A. Arrius 2F turboshaft engines, to Turbomeca S.A. Arrius 2F turboshaft engines that have not incorporated modification Tf75. This AD results from Turbomeca S.A. introducing a check

valve piston design requiring no O-ring. We are issuing this AD to prevent an uncommanded in-flight shutdown of the engine, which could result in a forced autorotation landing and damage to the helicopter.

DATES: This AD becomes effective March 21, 2007. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of March 21, 2007.

ADDRESSES: You can get the service information identified in this AD from Turbomeca S.A., 40220 Tarnos, France; telephone 33 05 59 74 40 00, fax 33 05 59 74 45 15.

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803, telephone (781) 238-7175; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR part 39 with

a proposed AD. The proposed AD applies to Turbomeca S.A. Arrius 2F turboshaft engines. We published the proposed AD in the **Federal Register** on November 8, 2006 (71 FR 65430). That action proposed to require replacing certain O-rings on the check valve piston in the lubrication unit, at repetitive intervals. This AD requires the same actions except it reduces the applicability from all Turbomeca S.A. Arrius 2F turboshaft engines, to Turbomeca S.A. Arrius 2F turboshaft engines that have not incorporated modification Tf75.

Examining the AD Docket

You may examine the docket that contains the AD, any comments received, and any final disposition in person at the Docket Management Facility Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5227) is located on the plaza level of the Department of Transportation Nassif Building at the street address stated in **ADDRESSES**. Comments will be available in the AD docket shortly after the DMS receives them.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the proposal or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

We estimate that this AD will affect about 124 engines installed on airplanes of U.S. registry. We also estimate that it will take about 1 work-hour per engine to perform the actions, and that the average labor rate is \$80 per work-hour. Required parts will cost about \$100 per engine. Based on these figures, we estimate the cost of the AD on U.S. operators, for one O-ring replacement to be \$22,320 for the fleet, or \$180 per engine.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary at the address listed under **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Amendment 14238 (70 FR 50164, August 26, 2005), and by adding a new airworthiness directive, Amendment 39-14940, to read as follows:

2005-17-17R1 Turbomeca S.A.:

Amendment 39-14940; Docket No. FAA-2005-22039; Directorate Identifier 2005-NE-33-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective March 21, 2007.

Affected ADs

(b) This AD revises AD 2005-17-17, Amendment 39-14238.

Applicability

(c) This AD applies to Turbomeca S.A. Arrius 2F turboshaft engines that have not incorporated modification Tf75. These engines are installed on, but not limited to, Eurocopter EC120B helicopters.

Unsafe Condition

(d) This AD results from Turbomeca S.A. introducing a check valve piston design requiring no O-ring. We are issuing this AD to prevent an uncommanded in-flight shutdown of the engine, which could result in a forced autorotation landing and damage to the helicopter.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

O-ring Replacement

(f) Replace the O-ring on the check valve piston in the lubrication unit at the intervals specified in Table 1 of this AD. Use the "Instructions to be Incorporated," 2.A. through 2.C. (2) of Turbomeca Alert Service Bulletin No. A319 79 4802, Update No. 1, dated April 3, 2006, to replace the O-ring.

TABLE 1.—COMPLIANCE TIMES FOR O-RING REPLACEMENT

If the class of oil is:	Then replace the O-ring by the later of:	Thereafter, replace the O-ring within:
(1) HTS or unknown	300 hours time-since-new (TSN) or 50 hours after the effective date of this AD.	300 hours time-since-last replacement (TSR).
(2) STD	450 hours TSN or 50 hours after the effective date of this AD.	500 hours TSR.

Alternative Methods of Compliance

(g) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(h) Contact Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone (781) 238-7175, fax (781) 238-7199; e-mail: christopher.spinney@faa.gov for more information about this AD. European Aviation Safety Agency AD No. 2006-0141, dated May 29, 2006, also addresses the subject of this AD.

Material Incorporated by Reference

(i) You must use Turbomeca Alert Service Bulletin No. A319 79 4802, Update No. 1, dated April 3, 2006, to perform the replacements required by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Turbomeca S.A., 40220 Tarnos, France; telephone 33 05 59 74 40 00, fax 33 05 59 74 45 15, for a copy of this service information. You may review copies at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on February 7, 2007.

Peter A. White,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. E7-2425 Filed 2-13-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-26241; Directorate Identifier 2006-NM-155-AD; Amendment 39-14938; AD 2007-04-07]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-400 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier Model DHC-8-400 series airplanes. This AD requires inspecting to determine the manufacturer's date of certain V-band clamps on the engine exhaust shroud assembly, and doing

related investigative/corrective actions if necessary. This AD results from a report of a discrepancy found during a maintenance inspection on a V-band clamp located on the engine exhaust duct shroud. The clamp ends were touching (although the correct fastener torque had been applied), resulting in reduced clamp force on the flanges. We are issuing this AD to prevent vibration in the duct shroud and fretting of the V-band clamp and flanges, which could result in cracking of the flanges and consequent release of hot exhaust gases from the engine tailpipe and damage to adjacent structure. This situation could trigger the fire warning system and result in an in-flight emergency, such as the flightcrew shutting down the engine and activating the fire suppression system.

DATES: This AD becomes effective March 21, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of March 21, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Richard Fiesel, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7304; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:**Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Bombardier Model DHC-8-400 series airplanes. That

NPRM was published in the **Federal Register** on November 3, 2006 (71 FR 64651). That NPRM proposed to require inspecting to determine the manufacturer's date of certain V-band clamps on the engine exhaust shroud assembly, and doing related investigative/corrective actions if necessary.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

This AD affects about 21 airplanes of U.S. registry. The required actions take about 3 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts cost is minimal. Based on these figures, the estimated cost of this AD for U.S. operators is \$5,040, or \$240 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.