

2008), which applies to certain Taylorcraft Models A, B, and F series airplanes. This proposed AD would require inspection of the wing strut attach fittings for corrosion or cracks and would require repair or replacement if corrosion or cracks are found.

The docket number was incorrectly referenced as "FAA-2007-0177" instead of "FAA-2008-0177." The NPRM is posted in the FAA-2008-0177 docket section of the FDMS.

#### Need for the Correction

This correction is needed to identify the docket number and should further reduce the confusion associated with the inadvertent error.

#### Correction of Publication

Accordingly, the publication of February 20, 2008 (73 FR 9239), which was the subject of FR Doc. E8-2995, is corrected as follows:

On page 9239, in the second column, in the first line under 14 CFR Part 39, replace "[Docket No. FAA-2007-0177;]" with "[Docket No. FAA-2008-0177;]"

On page 9240, in the first column, in the second line from the top of the page, replace "FAA-2007-0177;" with "FAA-2008-0177".

On page 9241, in the first column, in the third line under § 39.13 [Amended], replace "FAA-2007-0177;" with "FAA-2008-0177".

Action is taken herein to correct this reference in the NPRM.

Issued in Kansas City, Missouri, on February 25, 2008.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 08-892 Filed 2-29-08; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2008-0232; Directorate Identifier 2007-NM-309-AD]

**RIN 2120-AA64**

#### **Airworthiness Directives; Airbus Model A330-200 and A340-300 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed

AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During fatigue tests (EF3) on the A340-600, multiple damage were found in the upper side shell structure at skin and frame (FR) 84 & 85 interface, from stringer 6 to 15 LH/RH. This damage occurred between 58,341 and 72,891 simulated Flight Cycles (FC).

Due to the higher Design Service Goal and different design (e.g. skin thickness) for A330-200 and A340-300 aircraft series, the damage assessment concluded on [a] potential impact on these aircraft series.

\* \* \* \* \*

The unsafe condition is loss of integrity of the upper shell structure of the fuselage. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by April 2, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149.

#### **SUPPLEMENTARY INFORMATION:**

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0232; Directorate Identifier 2007-NM-309-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2007-0269R1, dated October 15, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

During fatigue tests (EF3) on the A340-600, multiple damage were found in the upper side shell structure at skin and frame (FR) 84 & 85 interface, from stringer 6 to 15 LH/RH. This damage occurred between 58,341 and 72,891 simulated Flight Cycles (FC).

Due to the higher Design Service Goal and different design (e.g. skin thickness) for A330-200 and A340-300 aircraft series, the damage assessment concluded on [a] potential impact on these aircraft series.

In order to allow early detection of cracks which could avoid possible crack propagation and consequently to maintain the structural integrity of the upper side shell structure between FR84 and FR87, this Airworthiness Directive (AD) mandates an inspection program of this area [for cracking] using a high frequency eddy current (HFEC) method and a modification to improve the upper shell structure.

This Revision 1 is issued to clarify that this AD is not applicable to aircraft A340-300 series on which both AIRBUS modifications 44205 and 45012 have been embodied in production.

The unsafe condition is loss of integrity of the upper shell structure of the fuselage between FR84 and FR87. Corrective actions include contacting Airbus and repairing any crack. You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

Airbus has issued Service Bulletin A330-53-3152, dated April 10, 2007;

Service Bulletin A330–53–3157, dated July 5, 2006; and Service Bulletin A340–53–4163, dated July 5, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

#### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 7 products of U.S. registry. We also estimate that it would take about 601 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$52,160 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$701,680, or \$100,240 per product.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Airbus:** Docket No. FAA–2008–0232;

Directorate Identifier 2007–NM–309–AD.

#### Comments Due Date

- (a) We must receive comments by April 2, 2008.

#### Affected ADs

- (b) None.

#### Applicability

(c) This AD applies to Airbus Model A330–200 and A340–300 series airplanes, certificated in any category, all certified models; all serial numbers on which Airbus Modification 44205 has been embodied in production, except those on which Airbus Modification 52974 or 53223 has been embodied in production. This AD is not applicable to Model A340–300 series airplanes on which both Modifications 44205 and 45012 have been embodied in production.

#### Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

#### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

During fatigue tests (EF3) on the A340–600, multiple damage were found in the upper side shell structure at skin and frame (FR) 84 & 85 interface, from stringer 6 to 15 LH/RH. This damage occurred between 58,341 and 72,891 simulated Flight Cycles (FC).

Due to the higher Design Service Goal and different design (e.g. skin thickness) for A330–200 and A340–300 aircraft series, the damage assessment concluded on [a] potential impact on these aircraft series.

In order to allow early detection of cracks which could avoid possible crack propagation and consequently to maintain the structural integrity of the upper side shell structure between FR84 and FR87, this Airworthiness Directive (AD) mandates an inspection program of this area [for cracking] using a high frequency eddy current (HFEC) method and a modification to improve the upper shell structure.

This Revision 1 is issued to clarify that this AD is not applicable to aircraft A340–300 series on which both AIRBUS modifications 44205 and 45012 have been embodied in production.

The unsafe condition is loss of integrity of the upper shell structure of the fuselage between FR84 and FR87. Corrective actions include contacting Airbus and repairing any crack.

#### Actions and Compliance

(f) Unless already done, do the following actions.

(1) For Airbus Model A330–200 series airplanes, as identified in paragraph (c) of this AD, on which Modification 45012 has been embodied in production: At the later of the compliance times specified in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD, do the HFEC inspection for cracking, and corrective actions as applicable; and modify the upper shell structure of the fuselage; in accordance with the Accomplishment Instructions of

Airbus Service Bulletin A330–53–3152, dated April 10, 2007. Do all applicable corrective actions before further flight.

(i) Prior to the compliance time shown in Table 1 of this AD after the first flight of the

airplane, depending on airplane configuration.

TABLE 1.—COMPLIANCE TIMES FOR MODEL A330 SERIES AIRPLANES WITH MODIFICATION 45012 EMBODIED

Airplane configuration	Threshold
Pre-modification 48827 (WV20 to WV27) .....	25,400 total flight cycles.
Post-modification 48827 (WV50 to WV56) .....	17,100 total flight cycles or 94,700 total flight hours, whichever occurs first.

(ii) Within 90 days after the effective date of this AD.

(2) For Airbus Model A330–200 and A340–300 series airplanes as identified in paragraph (c) of this AD, on which Modification 45012 has not been embodied in production: At the later of the compliance times specified in paragraphs (f)(2)(i) and (f)(2)(ii) of this AD, modify the upper shell structure of the fuselage in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330–53–3157 or Service Bulletin A340–53–4163, as applicable, both dated July 5, 2006.

(i) Prior to the compliance time shown in Table 2 of this AD after the first flight of the airplane.

TABLE 2.—COMPLIANCE TIMES FOR MODEL A330–200 AND A340–300 SERIES AIRPLANES WITHOUT MODIFICATION 45012 EMBODIED

Airplane series	Threshold
A330–200 .....	6,600 total flight cycles.
A340–300 .....	14,000 total flight cycles.

(ii) Within 90 days after the effective date of this AD.

#### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1138; fax (425) 227–1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-

approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

#### Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2007–0269R1, dated October 15, 2007, Airbus Service Bulletin A330–53–3152, dated April 10, 2007; Airbus Service Bulletin A330–53–3157, dated July 5, 2006; and Airbus Service Bulletin A340–53–4163, dated July 5, 2006; for related information.

Issued in Renton, Washington, on February 25, 2008.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E8–3969 Filed 2–29–08; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2008–0231; Directorate Identifier 2007–NM–218–AD]

**RIN 2120–AA64**

#### Airworthiness Directives; Fokker F.28 Mark 0070 and Mark 0100 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

To date, there have been at least 10 reported events on Fokker 70 (F28 Mark

0070) and Fokker 100 (F28 Mark 0100) aircraft where the flight crew manually overpowered the autopilot, inadvertently neglecting to disengage the autopilot. \* \* \* When the autopilot is not disengaged, the elevator servomotor is overpowered and the horizontal stabilizer is moved by the Automatic Flight Control & Augmentation System (AFCAS) auto-trim in a direction opposite to the (manual) deflection of the elevator, causing high elevator control forces. This condition, if not corrected, could cause the stabilizer to move to an extreme out-of-trim position, creating the (remote) possibility of loss of control of the aircraft, due to the extreme control loads.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by April 2, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493–2251.
- **Mail:** U.S. Department of

Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer,