

to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2006-0276, dated September 6, 2006; and Zodiac Service Bulletins 5035-30-001 and 5035-30-002, both dated April 15, 2002; for related information.

Material Incorporated by Reference

(i) You must use Zodiac Service Bulletin 5035-30-001, dated April 15, 2002; and Zodiac Service Bulletin 5035-30-002, dated April 15, 2002; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 8, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E8-8253 Filed 4-18-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-29116; Directorate Identifier 2007-NM-064-AD; Amendment 39-15476; AD 2008-08-22]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, -700C, -800, and -900 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes. This AD requires a one-time inspection to

determine the material of the forward and aft gray water drain masts. For airplanes having composite gray water drain masts, this AD requires installation of a bonding jumper between a ground and the clamp on the tube of the forward and aft gray water composite drain masts. This AD results from a report of charred insulation blankets and burned wires around the forward gray water composite drain mast found during an inspection of the forward cargo compartment on a Model 767-300F airplane. We are issuing this AD to prevent a fire near a composite drain mast and possible disruption of the electrical power system caused by a lightning strike on a composite drain mast, which could result in the loss of several functions essential for safe flight.

DATES: This AD is effective May 27, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 27, 2008.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Nicholas Wilson, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6476; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) (the "original NPRM") to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to all Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes. That NPRM was published in the **Federal Register** on

September 6, 2007 (72 FR 51201). That NPRM proposed to require a one-time inspection to determine the material of the forward and aft gray water drain masts. For airplanes having composite gray water drain masts, that NPRM also proposed to require installation of a bonding jumper between a ground and the clamp on the tube of the forward and aft gray water composite drain masts.

Actions Since NPRM Was Issued

Since we issued the NPRM, Boeing has issued new service information that includes corrected measurement values and procedures that should be followed if the resistance of the bonding jumper exceeds certain values during the initial resistance check.

We have reviewed Boeing Special Attention Service Bulletin 737-30-1056, Revision 1, dated October 25, 2007. The service bulletin describes procedures for installing a bonding jumper between a ground and the clamp on the tube of the forward and aft gray water composite drain mast. We have revised this final rule to refer to Revision 1 of the service bulletin as the appropriate source of service information for the required actions. We have also added paragraph (h) to this final rule to give credit for actions done previously in accordance with Boeing Special Attention Service Bulletin 737-30-1056, dated February 28, 2007, provided the results of the resistance measurement meet the values specified in Revision 1; we have re-identified subsequent paragraphs accordingly.

Comments

We have considered the following comments on the NPRM.

Request To Clarify the Proposed Applicability

Boeing requests that we revise the Applicability statement of the NPRM to clarify the affected airplanes. Boeing states that airplanes having line numbers 1935 and subsequent have the bonding jumper installed during production and should not be subject to the NPRM. Boeing asserts that the NPRM should only be applicable to airplanes delivered with composite drain masts without the bonding jumper or airplanes with spare interchangeability notes allowing replacement of the aluminum drain masts with composite drain masts.

We partially agree. For the reason stated by Boeing, we have determined that these airplanes should not be subject to this AD. However, we do not agree to revise the Applicability statement of this AD as suggested by

Boeing. Instead, we have revised the Applicability statement of this final rule to state, “Boeing Model 737–600, –700, –700C, –800, and –900 series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 737–30–1056, Revision 1, dated October 25, 2007.” We have confirmed that the effectivity of this service bulletin matches the applicability suggested by Boeing.

Request To Revise the Proposed Costs of Compliance

Air Transport Association (ATA), on behalf of its member American Airlines (AAL), states that the work-hour estimate of 9.75 hours per airplane provided in the service bulletin is more realistic than the 4-hour estimate provided in the NPRM.

From this comment, we infer that AAL is requesting that we revise the Costs of Compliance section of the NPRM to reflect 9.75 work-hours per airplane to do the proposed actions. We do not agree. The cost information below describes only the direct costs of the specific actions required by this AD. Based on the best data available, the manufacturer provided the number of

work hours (4) necessary to do the required actions. This number represents the time necessary to perform only the actions actually required by this AD. We recognize that, in doing the actions required by an AD, operators might incur incidental costs in addition to the direct costs. The cost analysis in AD rulemaking actions, however, typically does not include incidental costs such as the time required to gain access and close up, time necessary for planning, or time necessitated by other administrative actions. Those incidental costs, which might vary significantly among operators, are almost impossible to calculate. We have made no change to this final rule in this regard.

Request To Include Parts Installation Requirement

ATA, on behalf of its member Delta Airlines (Delta), suggests that the AD specify that a composite drain mast cannot replace an aluminum drain mast unless the bonding jumper is installed according to Boeing Special Attention Service Bulletin 737–30–1056, Revision 1, dated October 25, 2007. Delta asserts that, according to the airplane illustrated parts catalog, the composite

and aluminum drain masts are interchangeable, which could lead to unintentional non-compliance with the AD.

We agree that the composite and aluminum drain mast can be interchangeable. Therefore, for the reasons given by Delta, we have added a new paragraph (i), “Parts Installation,” to this final rule to prohibit installation of a composite gray water drain mast, unless a bonding jumper is also installed, as specified in paragraph (g) of this final rule.

Additional Changes to This Final Rule

We have also updated the Costs of Compliance section of this final rule to reflect the current number of U.S.-registered airplanes, and the cost of parts necessary to accomplish the required actions.

Costs of Compliance

There are about 1,906 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Inspection to determine gray water drain mast material. Installation of bonding jumper.	1	\$80	None	\$80	873	\$69,840.
	Between 2 and 4 (depending on airplane configuration).	80	Between \$8 and \$16, depending on kit.	Between \$168 and \$336.	Up to 873	Between \$146,664 and \$293,328.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2008–08–22 Boeing: Amendment 39–15476.
Docket No. FAA–2007–29116;
Directorate Identifier 2007–NM–064–AD.

Effective Date

(a) This airworthiness directive (AD) is effective May 27, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 737–600, –700, –700C, –800, and –900 series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 737–30–1056, Revision 1, dated October 25, 2007.

Unsafe Condition

(d) This AD results from a report of charred insulation blankets and burned wires around the forward gray water composite drain mast found during an inspection of the forward cargo compartment on a Model 767–300F airplane. We are issuing this AD to prevent a fire near a composite drain mast and possible disruption of the electrical power system caused by a lightning strike on a composite drain mast, which could result in the loss of several functions essential for safe flight.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection To Determine Material of Gray Water Drain Masts

(f) Within 60 months after the effective date of this AD, inspect the forward and aft gray water drain masts to determine whether the drain masts are made of aluminum or composite. A review of airplane maintenance records is acceptable in lieu of this inspection if the material of the forward and aft gray water drain masts can be conclusively determined from that review.

(1) For any aluminum gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD, no further action is required by this paragraph for that drain mast only.

(2) For any composite gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD, do the actions specified in paragraph (g) of this AD.

Installation of Bonding Jumper

(g) For any composite gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD: Within 60 months after the effective date of this AD, install a bonding jumper between a ground and the clamp on the tube of the gray water composite drain mast, in accordance with the Accomplishment Instructions of Boeing Special Attention

Service Bulletin 737–30–1056, Revision 1, dated October 25, 2007.

Actions Done Previously Using Previous Service Information

(h) Actions done before the effective date of this AD according to Boeing Special Attention Service Bulletin 737–30–1056, dated February 28, 2007, are considered acceptable for compliance with the corresponding actions specified in this AD provided the results of the resistance measurements meet the acceptable values specified in Boeing Special Attention Service Bulletin 737–30–1056, Revision 1, dated October 25, 2007.

Parts Installation

(i) As of the effective date of this AD, no person may install, on any airplane, a composite gray water drain mast, unless a bonding jumper is also installed, as specified in paragraph (g) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(k) You must use Boeing Special Attention Service Bulletin 737–30–1056, Revision 1, dated October 25, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 7, 2008.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E8–8254 Filed 4–18–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2008–0120; Directorate Identifier 2007–NM–327–AD; Amendment 39–15473; AD 2008–08–19]

RIN 2120–AA64

Airworthiness Directives; Gulfstream Aerospace LP Model Gulfstream G150 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Possible chafing between [the] electrical feeder cable connected to contactor 123P/2 and ground point 803GND, installed within the left DC power box, discovered during routine receiving inspection. This condition may exist on boxes installed on in-service aircraft. If this chafing condition is left unattended, an electrical short may develop, leading to disconnection of the battery and battery bus from the electrical system of the aircraft, [which could result in] overheating, arcing, smoke and fire.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective May 27, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 27, 2008.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Mike Borfitz, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–2677; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION: