

Rules and Regulations

Federal Register

Vol. 74, No. 49

Monday, March 16, 2009

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0169; Directorate Identifier 2008-SW-42-AD; Amendment 39-15833; AD 2009-05-09]

RIN 2120-AA64

Airworthiness Directives; Bell Helicopter Textron Inc. Model 412, 412CF, and 412EP Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for the specified Bell Helicopter Textron Inc. (Bell) model helicopters. This action requires reidentifying a certain part-numbered main rotor yoke (yoke) based on whether it was ever installed on a Model 412CF helicopter or on a Model 412 or 412EP helicopter with a slope landing kit. This AD also requires reducing the retirement life of the reidentified yokes from 5,000 hours time-in-service (TIS) to 4,500 hours TIS. Also, this AD requires recording the reidentified yoke part number (P/N) and the reduced retirement life on the component history card or equivalent record. This amendment is prompted by fatigue analysis that shows that the retirement life should be reduced on certain yokes. The actions specified in this AD are intended to prevent fatigue cracking of a yoke, failure of a yoke, and subsequent loss of control of the helicopter.

DATES: Effective March 31, 2009.

Comments for inclusion in the Rules Docket must be received on or before May 15, 2009.

ADDRESSES: Use one of the following addresses to submit comments on this AD:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You may get the service information identified in this AD from Bell Helicopter Textron, Inc., P.O. Box 482, Fort Worth, Texas 76101, telephone (817) 280-3391, fax (817) 280-6466 or at <http://www.bellcustomer.com/files/>.

Examining the Docket: You may examine the docket that contains the AD, any comments, and other information on the Internet at <http://www.regulations.gov>, or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located in Room W12-140 on the ground floor of the West Building at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Michael Kohner, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Certification Office, Fort Worth, Texas 76193-0170, telephone (817) 222-5170, fax (817) 222-5783.

SUPPLEMENTARY INFORMATION: This amendment adopts a new AD for the specified Bell model helicopters. This action requires reidentifying a certain part-numbered yoke based on whether it was ever installed on a Model 412CF helicopter or on a Model 412 or 412EP helicopter with a slope landing kit. This AD also requires reducing the retirement life of the reidentified yokes from 5,000 hours TIS to 4,500 hours TIS. Also, this AD requires recording the reidentified yoke P/N and the reduced retirement life on the component history card or equivalent record. This amendment is prompted by

fatigue analysis that shows that the retirement life should be reduced on certain yokes. This condition, if not corrected, could result in fatigue cracking of a yoke, failure of a yoke, and subsequent loss of control of the helicopter.

We have reviewed Bell Alert Service Bulletin (ASB) No. 412-08-128, dated March 4, 2008, for the Model 412 and 412EP helicopters and ASB No. 412CF-08-35 dated March 4, 2008, for the Model 412CF helicopters. The ASBs specify reducing the life limit of certain part-numbered yokes from 5,000 hours TIS to 4,500 hours TIS. The ASBs also describe procedures for reidentifying the yoke P/N and recording the information on a component history card or equivalent record.

This unsafe condition is likely to exist or develop on other helicopters of these same type designs. Therefore, this AD is being issued to prevent fatigue cracking of a yoke, failure of a yoke, and subsequent loss of control of the helicopter. This AD applies to Bell Model 412 and 412EP helicopters with a yoke, P/N 412-010-101-123, -127, -129, or -133, with a (BHT-412-SI-62) slope landing kit, installed. This AD also applies to Model 412CF helicopters with yoke, P/N 412-010-101-127 or -129, installed. This AD requires the following actions within 10 hours TIS for each affected model helicopter:

- Review the helicopter records to determine all of the helicopter models on which the affected yoke has been installed since its production and the hours TIS of each yoke.
- If an affected part-numbered yoke has ever been installed on a Model 412CF or on a Model 412 or 412EP helicopter with a (BHT-412-SI-62) slope landing kit, P/N 412-704-012-101, do the following:
 - Reidentify the P/N on the existing yoke data plate by using a vibrating stylus and etching two lines through the last three digits of the existing P/N and etching "137FM" adjacent to where you etched through the last three digits of the original P/N. This converts each affected yoke P/N to a new yoke P/N, 412-010-101-137FM. The serial number remains the same.
 - Record the reidentified P/N on the applicable component history card or equivalent record.
 - If you cannot determine all the model helicopters on which an affected

yoke has been installed since its production or whether it has ever been installed on a Model 412 or 412EP helicopter with a (BHT-412-SI-62) slope landing kit, P/N 412-704-012-101, installed, reidentify the yoke as P/N 412-010-101-137FM using a vibrating stylus. Record the reidentified P/N on the applicable component history card or equivalent record.

- For each reidentified yoke, P/N 412-010-101-137FM, record the revised 4,500-hour TIS life limit on the applicable component history card or equivalent record.

This AD revises the Airworthiness Limitations section of the applicable maintenance manual or the Instructions for Continued Airworthiness (ICAs) by reducing the retirement life from 5,000 hours TIS to 4,500 hours TIS for reidentified yoke, P/N 412-010-101-137FM.

The short compliance time involved is required because the previously described critical unsafe condition can adversely affect the structural integrity and controllability of the helicopter. Therefore, to prevent fatigue cracking, the actions described previously are required within 10 hours TIS. Also, replacing certain yokes that have exceeded 4,500 hours TIS but have not reached their previous 5,000 hours TIS retirement life is required before further flight, and this AD must be issued immediately.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

We estimate that this AD will affect 115 helicopters and will take about:

- 1 hour to review the records,
- 2 hours to revise the maintenance manual or ICAs, record the new retirement life, reidentify the P/N, and
- 20 hours to replace a yoke.

The average labor rate is estimated to be \$80 per work hour. Required parts will cost about \$40,157 per helicopter. Based on these figures, we estimate the total cost of the AD on U.S. operators will be \$278,142 (\$27,600 to review and revise the records and \$250,542 to replace the yokes, assuming 5 percent of the fleet or

a total of 6 yokes have exceeded the 4,500-hour life limit).

Comments Invited

This AD is a final rule that involves requirements that affect flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2009-0169; Directorate Identifier 2008-SW-42-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of our docket Web site, you can find and read the comments to any of our dockets, including the name of the individual who sent the comment. You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD. See the AD docket to examine the economic evaluation.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2009-05-09 Bell Helicopter Textron, Inc.:
Amendment 39-15833. Docket No. FAA-2009-0169; Directorate Identifier 2008-SW-42-AD.

Applicability: The following model helicopters with the listed part-numbered main rotor yoke assembly (yoke), installed, certificated in any category.

Model	With yoke part number (P/N) installed
412 and 412EP	412-010-101-123, -127, -129, or -133
412CF	412-010-101-127, -129

Compliance: Within 10 hours time-in-service (TIS), unless accomplished previously:

To prevent fatigue cracking of a yoke, failure of the yoke, and subsequent loss of control of the helicopter, do the following:

(a) Review the helicopter records to determine all of the helicopter models on which the affected yoke has been installed since its production and the hours TIS of each affected yoke.

(b) If an affected part-numbered yoke is installed or has ever been installed on a Model 412CF helicopter or on a Model 412 or 412EP helicopter with a (BHT-412-SI-62) slope landing kit, P/N 412-704-012-101, installed, do the following:

(1) Reidentify the P/N on the existing yoke data plate by using a vibrating stylus and etching two lines through the last three digits of the existing P/N and etching "137FM" adjacent to where you etched through the last three digits of the original P/N. This converts each affected yoke P/N to a new yoke P/N 412-010-101-137FM. The serial number remains the same.

Note 1: The "FM" P/N suffix denotes a field modified part.

(2) Record the reidentified P/N on the applicable component history card or equivalent record.

(c) If you cannot determine all the model helicopters on which an affected yoke has been installed since its production or whether it has ever been installed on a Model 412 or 412EP helicopter with a (BHT-412-SI-62) slope landing kit, P/N 412-704-012-101, installed, reidentify the yoke P/N as P/N 412-010-101-137FM using a vibrating stylus in accordance with paragraph (b)(1) of this AD. Record the reidentified P/N on the applicable component history card or equivalent record.

(d) For each reidentified yoke, P/N 412-010-101-137FM, reduce the retirement life from 5,000 hours TIS to 4,500 hours TIS. Record the revised life limit on the applicable component history card or equivalent record.

Note 2: Bell Helicopter Textron, Inc. Alert Service Bulletins No. 412-08-128 and No. 412CF-08-35, both dated March 4, 2008, pertain to the subject of this AD.

(e) This AD revises the Airworthiness Limitations section of the applicable maintenance manual or the Instructions for Continued Airworthiness (ICAs) by reducing the retirement life from 5,000 hours TIS to 4,500 hours TIS for each reidentified yoke, P/N 412-010-101-137FM.

(f) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Rotorcraft Directorate, FAA, ATTN: Michael Kohner, Aviation Safety Engineer, Rotorcraft Certification Office, Fort Worth, Texas 76193-0170, telephone (817) 222-5170, fax (817) 222-5783, for information about previously approved alternative methods of compliance.

(g) Special flight permits will not be issued.

(h) This amendment becomes effective on March 31, 2009.

Issued in Fort Worth, Texas, on February 12, 2009.

Scott A. Horn,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. E9-4950 Filed 3-13-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28689; Directorate Identifier 2006-SW-17-AD; Amendment 39-15832; AD 2009-05-08]

RIN 2120-AA64

Airworthiness Directives; Trimble or FreeFlight Systems 2101 I/O Approach Plus Global Positioning System (GPS) Navigation Systems

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for the Trimble or FreeFlight Systems 2101 I/O Approach Plus global positioning system (GPS) navigation system (2101 I/O Approach Plus system) that requires a software upgrade for this system. This amendment is prompted by an incident that led to the discovery of several annunciation errors with the 2101 I/O Approach Plus system. The actions specified by this AD are intended to prevent a pilot from making an unsafe decision based on erroneous information provided by the 2101 I/O Approach Plus system, which could result in loss of control of the aircraft.

DATES: Effective April 20, 2009.

ADDRESSES: You may get the service information identified in this AD from FreeFlight Systems, 3700 IH 35, Waco, Texas, USA, 76706, or by calling (254) 662-0000 or on the Internet at <http://www.freeflightsystems.com>.

Examining the Docket: You may examine the docket that contains this AD, any comments, and other information on the Internet at <http://www.regulations.gov> or at the Docket Operations office, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Sung-Hui Cavazos, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Special Certification Office, Fort Worth, Texas 76193-0190, telephone (817) 222-5142, fax (817) 222-5785.

SUPPLEMENTARY INFORMATION: A proposal to amend 14 CFR part 39 to include an AD for the specified navigation system was published in the **Federal Register** on July 13, 2007 (72 FR 38532). That action proposed to require, within 180 days after the effective date of the AD for aircraft approved for instrument flight rule (IFR) flight, or 270 days after the effective date of the AD for aircraft approved for visual flight rule (VFR) flight, upgrading the 2101 I/O Approach Plus system software to correct several software errors.

Freeflight Systems issued Service Information Letter (SIL) 81440-XX-00-17, dated November 7, 2005, when the manufacturer believed that software version 241H would correct the erroneous information displays. However, version 241H did not correct all the errors. Therefore, FreeFlight Systems issued SIL 81440-XX-00-19, dated May 10, 2006, which describes the release of new operating system software, version 241J, "that makes communication between the Host and the GPS processors more robust." Freeflight Systems subsequently issued Service Bulletin No. SB 81440-XX-00-19, dated December 12, 2006, that contains the instructions for obtaining and upgrading the software to version 241J. Although the proposed AD included a Note referencing SIL 81440-XX-00-17, this AD references the most recently available service information, Service Bulletin No. SB 81440-XX-00-19, dated December 12, 2006.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

The commenter, FreeFlight Systems, states that "the proposed AD specifies 81440-13-XXXX as being applicable for this upgrade. The 81440-13-XXXX is a number assigned for an NVG (night vision goggles) version of the 81440 that was never put into production so no units exist that would require this upgrade. The 81440-13-XXXX was included in error in the AD Worksheet identifying applicable systems provided to the FAA by FreeFlight Systems." Therefore, part number (P/N) 81440-13-XXXX (where XXXX is -241E, -241F, or 241G) should be removed from the AD. The FAA concurs and has removed those P/Ns from the AD.

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously. The FAA has determined that these changes will neither increase the economic burden