TABLE—ESTIMATED COSTS

Action	Action Work hours Average laborate per hou			Cost	Number of U.Sregistered airplanes	Fleet cost
Replacement	25	\$80	\$60,670	\$62,670	249	\$15,604,830

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Boeing: Docket No. FAA-2009-0293; Directorate Identifier 2008-NM-221-AD.

Comments Due Date

(a) We must receive comments by May 18, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 747–100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400, -400D, -400F, and 747SR series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 747–27–2422, dated October 30, 2008.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight controls.

Unsafe Condition

(e) This AD results from reports of the inboard trailing edge (TE) flaps blowing back due to the failure of a transmission carbon disk no-back brake. The no-back brake did not hold the flaps in the commanded position. The Federal Aviation Administration is issuing this AD to prevent a decrease of the aerodynamic controllability of the airplane, which could adversely affect the airplane's continued safe flight and landing.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Corrective Action

(g) Within 5 years after the effective date of this AD, replace the trailing edge flap transmission no-back brakes with skewed roller no-back brakes at the trailing edge flap transmission, positions 4 and 5, in accordance with Boeing Special Attention Service Bulletin 747–27–2422, dated October 30, 2008.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Douglas Tsuji, Aerospace Engineer, Systems and Equipment Branch, ANM–130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 917–6487; fax (425) 917–6590.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Issued in Renton, Washington, on March 18, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9–7273 Filed 3–31–09; 8:45 am]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0292; Directorate Identifier 2008-NM-011-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300, A310, and A300–600 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) that applies to certain Airbus Model A300 and A310 series airplanes. The existing AD currently requires replacement of the nose landing gear drag strut upper attachment pin. This proposed AD would require revising the Airworthiness Limitations section (ALS)

of the Instructions for Continued Airworthiness (ICA) to require additional life limits and/or replacements for certain main landing gear and nose landing gear components, and would also expand the applicability. This proposed AD results from revisions to the ALS of the ICA to include new or more restrictive life limits and/or replacements. We are proposing this AD to ensure the continued structural integrity of these airplanes.

DATES: We must receive comments on this proposed AD by May 1, 2009.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to http://www.regulations.gov. Follow the instructions for submitting comments.
 - Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M—30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet: http://www.airbus.com. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221 or 425–227–1152.

Examining the AD Docket

You may examine the AD docket on the Internet at http://www.regulations.gov; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800–647–5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1622; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2009-0292; Directorate Identifier 2008-NM-011-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to http://www.regulations.gov, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On July 21, 1987, we issued AD 87–16–06, amendment 39–5692 (52 FR 28241, July 29, 1987), for certain Airbus Model A300 and A310 series airplanes. That AD requires replacement of the nose landing gear drag strut upper attachment pin. That AD resulted from reports of pins which were found to be improperly manufactured. We issued that AD to prevent failure of the pin and collapse of the nose landing gear.

Actions Since Existing AD Was Issued

Since we issued AD 87–16–06, the manufacturer has revised the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness (ICA) to include new or more restrictive life limits and replacements for the main landing gear and the nose landing gear. These new limits affect the replacement of the upper attachment pin for the nose landing gear drag strut that was the subject of AD 87–16–06.

In addition, European Aviation Safety Agency (EASA) Airworthiness Directive 2007–0293, dated November 29, 2007, which is parallel to this proposed AD, includes Model A300–600 series airplanes. Those airplane models were not included in AD 87–16–06.

Relevant Service Information

Airbus has issued the following revisions to the ALS of the ICA. These documents provide each mandatory replacement time, structural inspection interval, and related structural inspection procedures or other procedures (e.g., modifications).

- For Model A300 Series Airplanes: "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated September 6, 2007.
- For Model A300–600 Series Airplanes: "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006.
- For Model A310 Series Airplanes: "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006.

Airbus has also issued Section 05–10–00, Revision 28, dated February 27, 1998, of Chapter 5, "Service Life Limits and Maintenance Checks," of the A300 Aircraft Maintenance Manual. Section 05–10–00 includes life limit values for the nose and main landing gears. This document is an alternate source for the life limits defined in Part 1, "Safe Life Airworthiness Limitation Items," dated September 6, 2007, of the ALS, for Model A300 series airplanes.

Airbus has also issued Service Information Letter (SIL) 32–118, Revision 02, dated October 24, 2007. This SIL gives instructions for calculating the life limit of main or nose landing gear parts where the history of accumulated landings is partial or unknown, or where the history of application details (airplane type, model, weight variant, etc.) is partial or unknown.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. EASA mandated the service information and issued Airworthiness Directive 2007–0292, dated November 29, 2007, to ensure the continued airworthiness of these airplanes in the European Union.

Other Relevant Rulemaking

On January 11, 1984, we issued AD 84–02–04 (49 FR 2746, January 23, 1984), for certain Airbus Model A300 B2 and B4 series airplanes. That AD requires inspection of main landing gear hinge arms for corrosion and cracks, and repair or modifications if needed. That AD also requires replacement of the main landing gear shock absorber sliding rod attachment fitting. That AD resulted from corrosion and cracks found on these components. We issued that AD to prevent landing gear failure.

The actions specified in paragraph (h) of this proposed AD would satisfy the

requirements of paragraph A. of AD 84–02–04. There are no actions in this proposed AD that would satisfy the requirements of paragraphs B. and C. of AD 84–02–04.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

This proposed AD would supersede AD 87–16–06 and would retain the requirements of that existing AD. This proposed AD would also add airplanes to the applicability and require revising the ALS of the ICA to incorporate additional life limits and/or structural inspections for certain main landing gear and nose landing gear components.

Change to Existing AD

This proposed AD would retain the requirements of AD 87–16–06. Since AD 87–16–06 was issued, the AD format has been revised. As a result, the corresponding paragraph identifiers have changed in this proposed AD, and paragraph (g) of this proposed AD corresponds to paragraph A. of AD 87–16–06.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.Sregistered airplanes	Fleet cost
Replacement (required by AD 87–16–06) Revision (new proposed action)	7	\$80	\$3,300	\$3,860	94	\$362,840
	1	80	0	80	238	19,040

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;

- 2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- 3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. *See* the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by Reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39–5692 (52 FR 28241, July 29, 1987) and adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA-2009-0292; Directorate Identifier 2008-NM-011-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by May 1, 2009.

Affected ADs

(b) This AD supersedes AD 87-16-06.

Applicability

(c) This AD applies to all Airbus Model A300, A310, and A300–600 series airplanes, certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 32: Landing Gear.

Unsafe Condition

(e) This AD results from revisions to the Airworthiness Limitations section (ALS) of the Instructions for Continued Airworthiness (ICA) to include new or more restrictive life limits and/or replacements. We are issuing this AD to ensure the continued structural integrity of these airplanes.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Note 1: This AD requires revisions to certain operator maintenance documents to include new replacements. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these replacements, the operator may not be able to accomplish the replacements described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (l) of this AD. The request should include a description of changes to the required replacements that will ensure the continued operational safety of the airplane.

Restatement of the Requirements of AD 87– 16–06

(g) For Model A300 and A310 Series Airplanes: Prior to the accumulation of 16,000 landings, or within the next 2,000 landings after September 3, 1987 (the effective date of AD 87–16–06), whichever occurs later, replace the nose landing gear drag strut upper attachment pin in accordance with Airbus Service Bulletin A300–32–374, Revision 1, dated July 15, 1986 (applicable to Model A300 airplanes); or A310–32–2023, Revision 2, dated November 14, 1986 (applicable to Model A310 airplanes).

New Requirements of This AD

ALS Revision

- (h) For Model A300, A310, and A300–600 Series Airplanes: Within 3 months after the effective date of this AD, revise the ALS of the ICA to incorporate the applicable document listed in paragraph (h)(1), (h)(2), or (h)(3) of this AD. Accomplishing the actions specified in the applicable document satisfies the requirements of paragraph A. of AD 84–02–04, amendment 39–4795.
- (1) For Model A300 Series Airplanes: Incorporate the document listed in paragraph (h)(1)(i) or (h)(1)(ii) of this AD.
- (i) Section 05–10–00, Revision 28, dated February 27, 1998, of Chapter 5, "Service Life Limits and Maintenance Checks," of the Airbus A300 Aircraft Maintenance Manual, except that the parts listed in Table 1 of this AD are subject to the life limits defined in the document listed in paragraph (h)(1)(ii) of this AD
- (ii) "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated September 6, 2007, of the Airbus A300 ALS.

TABLE 1—PARTS SUBJECT TO THE LIFE LIMITS SPECIFIED IN THE DOCUMENT IDENTIFIED IN PARAGRAPH (H)(1)(II) OF THIS AD

Part Number (P/N)	Part name

- (2) For Model A310 Series Airplanes: Incorporate "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006, of the Airbus A310 ALS.
- (3) For Model A300–600 Series Airplanes: Incorporate "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006, of the Airbus A300–600 ALS.

Initial Compliance Times and Repetitive Inspections

(i) Do the replacement at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, except as provided by paragraph (j) of this AD. The replacement must be done thereafter within the interval specified in the applicable document identified in paragraph (h)(1), (h)(2), or (h)(3) of this AD.

- (1) For any life limitation/task that has been complied with before the effective date of this AD in accordance with the applicable document listed in paragraph (h)(1), (h)(2), or (h)(3) of this AD, or in accordance with paragraph (g) of this AD, use the last accomplishment of each limitation/task as a starting point for accomplishing each corresponding limitation/task required by this AD.
- (2) For any life limitation/task that has not been complied with before the effective date of this AD in accordance with the applicable document listed in paragraphs (h)(1), (h)(2), and (h)(3) of this AD, or in accordance with paragraph (g) of this AD, the initial compliance time starts from the date of initial

entry into service as defined in the applicable document.

Special Compliance Times

(j) For any airplane on which the history of accumulated landings is partial or unknown, or where the history of application details (airplane type, model, weight variant, etc.) is partial or unknown, with or without using the information in Airbus Service Information Letter 32–118, Revision 02, dated October 24, 2007: Parts listed in Figure 1 of this AD must be replaced at the associated compliance time. The replacement must be done thereafter at the interval specified in the applicable document(s) specified in paragraphs (h)(1), (h)(2), and (h)(3) of this AD.

BILLING CODE 4910-13-P

Figure 1 – Special Compliance Times

	Aircraft type ap	plica	bilit	y				
	A300	X					liance Time urs first after the "start	
Designation	A310		X		Start date	1 `	date")	
	A300-600			X		,		
	P/N					Landings	Calendar Time	
	T + 221 +0022200		MAI	N LA	NDING GEAR	12.500		
	A32140032200xx	X			December 13, 2007	13,500	9 years	
	A32140056200xx	X			December 13, 2007	13,500	9 years	
	A32140056202xx	X			December 13, 2007	13,500	9 years	
Aft pintle pin	A32140057200xx	X			December 13, 2007	13,500	9 years	
	A32140057202xx	X		X	December 13, 2007	13,500	9 years	
	A32140062000xx	X			December 13, 2007	13,500	9 years	
	A32140063000xx	X		X	December 13, 2007	13,500	9 years	
	A32140036200xx	X			December 13, 2007	13,500	9 years	
	A32140036202xx	X			December 13, 2007	13,500	9 years	
	A32140036204xx	X			December 13, 2007	13,500	9 years	
	A32140036206xx	X			December 13, 2007	13,500	9 years	
Half ball housing	A32140042200xx	X		X	December 13, 2007	13,500	9 years	
(Fwd pintle bearing)	A32140042202xx	X		X	December 13, 2007	13,500	9 years	
	A32140068002xx	X			December 13, 2007	13,500	9 years	
	A32140068004xx	X			December 13, 2007	13,500	9 years	
	A32140069002xx	X		X	December 13, 2007	13,500	9 years	
	A32140069004xx	X		X	December 13, 2007	13,500	9 years	
Ball (Fwd pintle	A32140012202xx	X			December 13, 2007	13,500	9 years	
pin)	A32140043202xx	X		X	December 13, 2007	13,500	9 years	

	Aircraft type ap				nce Times (conti			
	A300	X					liance Time	
Designation	A310		X		Start date	(whichever occurs first after the "start date")		
8	A300-600			X				
	P/N					Landings	Calendar Time	
	A53833451200xx	X			December 13, 2007	13,500	9 years	
Pin (Multiple link/Frame 50)	A53833451206xx	X			December 13, 2007	13,500	9 years	
inik/riame 30)	A53834451200xx	X			December 13, 2007	13,500	9 years	
	A53834451202xx	X		X	April 25, 2007	13,500	9 years	
Pin (Drop link/Frame 50)	A53811122200xx		X		April 25, 2007	18,000	9 years	
	T	т	ML	G B	arrel Assembly	T		
	00-200-402	X			December 13, 2007	N/A	30 months	
Upper torque link	SL40089	X			December 13, 2007	N/A	30 months	
pin nut	SL40089P	X			December 13, 2007	N/A	30 months	
	SL40123	X			December 13, 2007	N/A	30 months	
	SL40123P	X	X	X	April 25, 2007	N/A	30 months	
	00-200-358	X			December 13, 2007	N/A	30 months	
Torque link	SL40114P	X	X		April 25, 2007	N/A	30 months	
medium pin nut	SL40132	X			December 13, 2007	N/A	30 months	
	SL40132P	X		X	April 25, 2007	N/A	30 months	
Attaching fitting pin	C62311-1	X			December 13, 2007	13,500	9 years	
Pili	C62311-20	X		X	April 25, 2007	13,500	9 years	
	C65815	X			December 13, 2007	13,500	9 years	
	C65815-1	X			December 13, 2007	13,500	9 years	
Pin (Connecting	C65815-20	X			December 13, 2007	13,500	9 years	
rod/Upper rod)	C66472	X			December 13, 2007	13,500	9 years	
	C66472-1	X			December 13, 2007	13,500	9 years	
	C66472-20	X		X	April 25, 2007	13,500	9 years	
	D52751		X		April 25, 2007	18,000	9 years	

	Aircraft type ap				ice Times (contin	T		
	A300	_		<u> </u>		Compliance Time (whichever occurs first after the "start		
Designation		X			Stant data			
Designation	A310		X		Start date	date")		
	A300-600			X			Γ	
	P/N					Landings	Calendar Time	
	1	ML	G Sh	ock A	Absorber Assembly	T	T	
	00-200-402	X			December 13, 2007	N/A	30 months	
Lower torque link	SL40089	X			December 13, 2007	N/A	30 months	
pin nut	SL40089P	X			December 13, 2007	N/A	30 months	
	SL40123	X			December 13, 2007	N/A	30 months	
	SL40123P	X	X	X	April 25, 2007	N/A	30 months	
	SL40054	X			December 13, 2007	at next remov	val / installation (1)(2)	
Bogie beam pivot	SL40054P	X		X	April 25, 2007	at next remov	val / installation (1)(2)	
pin nut	SL40413P		X		April 25, 2007	at next removal / installation (1)(2)		
	l	M	LG	Lock	Link Assembly			
Lock link medium	C61485-1	X			December 13, 2007	N/A	30 months	
pin	C61485-20	X		X	April 25, 2007	N/A	30 months	
		ľ			NDING GEAR			
Pintle pin	A32210079200xx	X	X	X	April 25, 2007	13,500	9 years	
		-		esco	pic Strut Assembly		T	
Nut (Cylinder /	C61375	X	X		April 25, 2007	13,500	9 years	
Locking cylinder)	D55955	X	X	X	April 25, 2007	13,500	9 years	
Locking sleeve	C61389	X	X		December 13, 2007	13,200	9 years	
	C61389-1	X	X	X	April 25, 2007	13,500	9 years	
			NLO	G Ba	rrel Assembly		,	
Pin (Clevis /	C62231-1	X			December 13, 2007	13,200	9 years	
Telescopic strut)	C62231-2	X			December 13, 2007	13,200	9 years	
	C62231-20		X		April 25, 2007	13,500	9 years	
	D56530	X	X	X	April 25, 2007	13,500	9 years	
Lowersin	C62268-1	X			December 13, 2007	13,200	9 years	
Lower pin (Link / Clevis)	C62268-2	X			December 13, 2007	13,200	9 years	
	C62268-20	X	X		April 25, 2007	13,500	9 years	
Link	C62230-1	X	X		April 25, 2007	13,500	9 years	
(Clevis / Barrel)	D56526	X	X	X	April 25, 2007	13,500	9 years	
Linnarnia	C62267-1	X			December 13, 2007	13,200	9 years	
Upper pin (Link / Barrel)	C62267-2	X			December 13, 2007	13,200	9 years	
	C62267-20	X	X	X	April 25, 2007	13,500	9 years	

	Aircraft type ar				nce Times (conti			
	A300	X	lity	\sqcap		Compliance Time		
Designation		Λ	-	H	Start date	(whichever occi	urs first after the "start	
Designation	A310		X		Start date		date")	
	A300-600			X				
	P/N					Landings	Calendar Time	
End fitting pin nut	D68062	X	X	X	December 13, 2007	1	val / installation (2)	
End fitting pin nat	MS17825-6	X	X	X	December 13, 2007		val / installation ⁽²⁾	
	AN6-17	X	X	X	December 13, 2007		val / installation (2)	
End fitting nin	D61183	X	X	X	December 13, 2007	at next remo	val / installation (2)	
End fitting pin	D68063	X	X	X	December 13, 2007	at next remo	val / installation (2)	
	NAS1306-22D	X	X	X	December 13, 2007	at next removal / installation (2)		
Management of the Control of the Con	C62032	X	X	X	April 25, 2007	13,500	9 years	
End fitting	C62032-1	X	X	X	April 25, 2007	13,500	9 years	
	C61453	X			December 13, 2007	13,200	9 years	
D !	C61453-1	X	X	X	April 25, 2007	13,500	9 years	
Rack	C61453-20	X	X	X	April 25, 2007	13,500	9 years	
	C61453-40	X	X	X	April 25, 2007	13,500	9 years	
	C61453-41	X	X	X	April 25, 2007	13,500	9 years	
Torque link pin	C62223-1	X			December 13, 2007	13,200	9 years	
(Upper & Lower)	C62223-20	X	X	X	April 25, 2007	13,500	9 years	
Torque link medium pin nut	SL40110P	X	X	X	April 25, 2007	N/A	30 months	
		NLG	Sho	ck A	Absorber Assembly	-		
Wheel axle nut	C62879	X	X	X	April 25, 2007	4,000	24 months	
Upper cam dowel	C62270	X	X	X	December 13, 2007	at next rem	oval / installation	
Upper cam	C62034-1	X	X	X	April 25, 2007	13,500	9 years	
Lower cam	C62035	X	X	X	April 25, 2007	13,500	9 years	
	C62036	X			December 13, 2007	13,200	9 years	
	C62036-1	X			December 13, 2007	13,200	9 years	
	C62036-2	X			December 13, 2007	13,200	9 years	
Restrictor	C67863	X			December 13, 2007	13,200	9 years	
	C67863-1	X	X	X	April 25, 2007	13,500	9 years	
	C67863-2	X	X	X	April 25, 2007	13,500	9 years	
	C67863-3	X			December 13, 2007	13,500	9 years	
	C67863-4	X	X	X	April 25, 2007	13,500	9 years	

	Aircraft type ap	plicab	oility			Compliance Time (whichever occurs first after the "start date")		
Designation	A300	X						
	A310		X		Start date			
	A300-600			X		,	,	
	P/N					Landings	Calendar Time	
Lower cam dowel	C62866	X	X	X	December 13, 2007	at next removal / installation (2)		
Nut (C/A/Damal)	C64040	X			December 13, 2007	at next removal / installation (1)(2)		
Nut (S/A/Barrel)	C64040-1	X	X	X	December 13, 2007	at next removal / installation (1)(2)		

Alternative Intervals or Limits

(k) Except as provided by paragraph (l) of this AD, after accomplishing the actions specified in paragraphs (h), (i), and (j) of this AD, no alternative replacements, replacement intervals, or limitations may be used.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, Manager, ANM-116, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Related Information

(m) European Aviation Safety Agency (EASA) Airworthiness Directive 2007–0293, dated November 29, 2007, also addresses the subject of this AD.

Issued in Renton, Washington, on March 12, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. E9–7267 Filed 3–31–09; 8:45 am]

BILLING CODE 4910-13-C

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA-R06-OAR-2008-0509; FRL-8788-7]

Approval and Promulgation of Implementation Plans; New Mexico; Albuquerque/Bernalillo County

AGENCY: Environmental Protection

Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve a revision to the New Mexico Albuquerque/Bernalillo County State Implementation Plan (SIP). This revision replaces Regulation 8, Airborne Particulate Matter, with NMAC 20.11.20, Fugitive Dust Control. This rulemaking action is being taken under section 110 of the Clean Air Act (CAA). DATES: Written comments must be received on or before May 1, 2009.

ADDRESSES: Comments may be mailed to Mr. Guy Donaldson, Chief, Air Planning Section (6PD–L), Environmental Protection Agency, 1445 Ross Avenue, Suite 1200, Dallas, Texas 75202–2733. Comments may also be submitted electronically or through hand delivery/courier by following the detailed instructions in the ADDRESSES section of the direct final rule located in the rules section of this Federal Register.

FOR FURTHER INFORMATION CONTACT: Joe Kordzi, Air Planning Section (6PD–L), Environmental Protection Agency, Region 6, 1445 Ross Avenue, Suite 700, Dallas, Texas 75202–2733, telephone (214) 665–7186; fax number 214–665–7263; e-mail address kordzi.joe@epa.gov.

SUPPLEMENTARY INFORMATION: In the final rules section of this Federal Register, EPA is approving the State's SIP submittal as a direct final rule without prior proposal because the Agency views this as a noncontroversial submittal and anticipates no adverse comments. A detailed rationale for the approval is set forth in the direct final rule. If no adverse comments are received in response to this action rule, no further activity is contemplated. If EPA receives adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed rule. EPA will not institute a second comment period. Any parties interested in commenting on this action should do so at this time. Please note that if EPA receives adverse comment on an amendment, paragraph, or section of this rule and if that provision may be severed from the remainder of the rule, EPA may adopt as final those provisions of the rule that are not the subject of an adverse comment.

For additional information, see the direct final rule which is located in the rules section of this **Federal Register**.

Dated: March 16, 2009.

Lawrence E. Starfield,

Acting Regional Administrator, Region 6. [FR Doc. E9–7297 Filed 3–31–09; 8:45 am] BILLING CODE 6560–50–P

⁽¹⁾ When the nut is temporarily removed and reinstalled for the purpose of performing maintenance outside a workshop, no replacement is required provided the nut's removal and reinstallation are performed on the same assembly and neither the assembly nor the nut accumulates time in service during the period between the removal and reinstallation.

⁽²⁾ If the removal / installation was done after the start date, but before the effective date of this AD, the compliance time is within 3 months after the effective date of this AD.