

In the most recent case, the aircraft had been modified in accordance with Airbus Service Bulletin A300–57–0205 (Airbus modification No. 04770). Investigations led by the manufacturer revealed that the centre hinge bracket developed a fatigue crack causing complete failure of the bracket. The tab rotated causing failure of the inboard link followed by the failure of the outboard link.

To avoid a detachment of a centre flap inner tab, which could be a potential risk to persons on [the] ground, this AD requires a

repetitive [high frequency eddy current] inspection of the centre flap inner tab hinge bracket and replacement of the bracket when cracks are detected * * * [and] reporting of inspection results to the TC holder [and provides] an optional terminating action.
* * *

* * * * *

Actions and Compliance

(f) Unless already done, do the following actions.

(1) At the times specified in Table 1 or Table 2 of this AD, as applicable, perform a high frequency eddy current inspection to detect fatigue cracks of the center hinge bracket of the center flap inner tab (on both wings), in accordance with Airbus Mandatory Service Bulletin A300–57–0250, Revision 01, dated September 29, 2008. If no cracking is found, repeat the inspection thereafter at intervals not to exceed 850 flight cycles.

TABLE 1—AIRPLANES ON WHICH AIRBUS SERVICE BULLETIN A300–57–0205 HAS NOT BEEN DONE

Flight cycles accumulated since first flight as of the effective date of this AD	Compliance time
Less than 6,000 flight cycles	Prior to accumulating 6,000 flight cycles since first flight or within 90 days after the effective date of this AD, whichever occurs later.
6,000 flight cycles or more, but less than 12,000 flight cycles	Within 850 flight cycles after the effective date of this AD.
12,000 flight cycles or more	Within 500 flight cycles after the effective date of this AD.

TABLE 2—AIRPLANES ON WHICH AIRBUS SERVICE BULLETIN A300–57–0205 HAS BEEN DONE

Flight cycles accumulated since Airbus Service Bulletin A300–57–0205 modification as of the effective date of this AD	Compliance time
Less than 6,000 flight cycles	Prior to accumulating 6,000 flight cycles since Airbus Service Bulletin A300–57–0205 modification or within 90 days after the effective date of this AD, whichever occurs later.
6,000 flight cycles or more, but less than 12,000 flight cycles	Within 850 flight cycles after the effective date of this AD.
12,000 flight cycles or more	Within 500 flight cycles after the effective date of this AD.

(2) If any crack is detected during any inspection required by this AD, before further flight, replace the center hinge bracket in accordance with Airbus Mandatory Service Bulletin A300–57–0250, Revision 01, dated September 29, 2008. Within 6,000 flight cycles after replacing the center hinge bracket, do the inspection required by paragraph (f)(1) of this AD, and if no cracking is found, repeat the inspection thereafter at intervals not to exceed 850 flight cycles.

(3) Modifying the inboard tab of the center flaps in accordance with Airbus Service Bulletin A300–57–0252, dated August 27, 2008, terminates the requirements of this AD.

(4) Actions accomplished before the effective date of this AD in accordance with Airbus Mandatory Service Bulletin A300–57–0250, dated November 2, 2007, are considered acceptable for compliance with the corresponding action specified in this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No Differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate,

FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–2125; fax (425) 227–1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(h) Refer to MCAI Airworthiness Directive 2007–0299R2, dated October 28, 2008; Airbus Mandatory Service Bulletin A300–57–0250, Revision 01, dated September 29, 2008; and Airbus Service Bulletin A300–57–0252, dated August 27, 2008; for related information.

Issued in Renton, Washington, on April 22, 2009.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9–9864 Filed 4–29–09; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2009–0283; Airspace Docket No. 09–ASW–8]

Proposed Establishment of Class D Airspace; Fort Worth, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish Class D airspace at Fort Worth Spinks Airport, Fort Worth, TX. Establishment of an air traffic control tower at Fort Worth Spinks Airport has made this action necessary for the safety and management of Instrument Flight Rules (IFR) aircraft operations at Fort Worth Spinks Airport.

DATES: 0901 UTC. Comments must be received on or before June 15, 2009.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2009-0283/Airspace Docket No. 09-ASW-8, at the beginning of your comments. You may also submit comments on the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd, Fort Worth, TX 76193-0530; telephone: (817) 321-7716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2009-0283/Airspace Docket No. 09-ASW-8." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

Additionally, any person may obtain a copy of this notice by submitting a

request to the Federal Aviation Administration (FAA), Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), Part 71 by establishing Class D airspace for IFR operations at Fort Worth Spinks Airport, Fort Worth, TX. The area would be depicted on appropriate aeronautical charts.

Class D airspace areas are published in Paragraph 5000 of FAA Order 7400.9S, dated October 3, 2008, and effective October 31, 2008, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the

scope of that authority as it would establish controlled airspace at Fort Worth Spinks Airport, Fort Worth, TX.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9S, Airspace Designations and Reporting Points, dated October 3, 2008, and effective October 31, 2008, is amended as follows:

Paragraph 5000 Class D Airspace.

* * * * *

ASW TX D Fort Worth Spinks Airport, TX [New]

Fort Worth Spinks Airport, TX
(Lat. 32°33'55" N., long. 97°18'29" W.)

That airspace extending upward from the surface up to but not including 3,000 feet MSL within a 4.1-mile radius of Fort Worth Spinks Airport, and within 1 mile each side of the 173° bearing from the airport extending from the 4.1-mile radius to 4.8 miles south of the airport. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective dates and times will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Issued in Fort Worth, TX on April 22, 2009.

Roger M. Trevino,
Acting Manager, Operations Support Group,
ATO Central Service Center.

[FR Doc. E9-9982 Filed 4-29-09; 8:45 am]

BILLING CODE 4910-13-P