

Actions	Compliance	Procedures
(4) If the cracks identified in paragraph (f)(3) of this AD meet or exceed the limits specified in paragraph 3 of Cessna Citation Alert Service Letter ASL525A-78-01, Revision 1, dated October 27, 2009, replace the thrust attenuator paddle and attachment hardware, as applicable.	(i) If the conditions of paragraph 3.A.(1) of Cessna Citation Alert Service Letter ASL525A-78-01, Revision 1, dated October 27, 2009, are met, replace before further flight after the inspection required in paragraph (f)(3) of this AD. After the replacement, continue with the repetitive inspections specified in paragraph (f)(1) of this AD. (ii) If the conditions of paragraph 3.A.(2) of Cessna Citation Alert Service Letter ASL525A-78-01, Revision 1, dated October 27, 2009, are met, replace within the next 150 hours TIS after the inspection required in paragraph (f)(3) of this AD. After the replacement, continue with the repetitive inspections specified in paragraph (f)(1) of this AD.	Follow Cessna Citation Alert Service Letter ASL525A-78-01, Revision 1, dated October 27, 2009.

#### Alternative Methods of Compliance (AMOCs)

(g) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn:* T.N. Baktha, Aerospace Engineer, 1801 Airport Road, Room 100, Wichita, Kansas 67209; *telephone:* (316) 946-4155; *fax:* (316) 946-4107. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

#### Material Incorporated by Reference

(h) You must use Cessna Citation Alert Service Letter ASL525A-78-01, Revision 1, dated October 27, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, KS 67277; *telephone:* (316) 517-6000; *fax:* (316) 517-8500; *Internet:* <http://www.cessna.com>.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on November 19, 2009.

**Patrick R. Mullen,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9-28234 Filed 11-27-09; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2009-0328; Directorate Identifier 2008-NE-44-AD; Amendment 39-16103; AD 2009-24-11]

**RIN 2120-AA64**

#### Airworthiness Directives; General Electric Company (GE) CF34-1A, CF34-3A, and CF34-3B Series Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for GE CF34-1A, CF34-3A, and CF34-3B series turbofan engines. This AD requires removing from service certain part number (P/N) and serial number (SN) fan blades within compliance times specified in this AD, inspecting the fan blade abradable rub strip on certain engines for wear, inspecting the fan blades on certain engines for cracks, inspecting the aft actuator head hose fitting for correct position, and, if necessary, repositioning the hose fitting. This AD results from a report of an under-cowl fire and a failed fan blade. We are issuing this AD to prevent failure of certain P/N and SN fan blades and aft actuator head hoses, which

could result in an under-cowl fire and subsequent damage to the airplane.

**DATES:** This AD becomes effective January 4, 2010. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of January 4, 2010.

**ADDRESSES:** You can get the service information identified in this AD from General Electric Company, GE- Aviation, Room 285, 1 Newmann Way, Cincinnati, OH 45215, *telephone* (513) 552-3272; *fax* (513) 552-3329; *e-mail:* [geae.aoc@ge.com](mailto:geae.aoc@ge.com). The Docket Operations office is located at Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

**FOR FURTHER INFORMATION CONTACT:** John Frost, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; *e-mail:* [john.frost@faa.gov](mailto:john.frost@faa.gov); *telephone* (781) 238-7756; *fax* (781) 238-7199.

**SUPPLEMENTARY INFORMATION:** The FAA proposed to amend 14 CFR part 39 with a proposed AD. The proposed AD applies to GE CF34-1A, CF34-3A, and CF34-3B series turbofan engines. We published the proposed AD in the **Federal Register** on April 8, 2009 (74 FR 15896). That action proposed to require removing from service certain P/N and SN fan blades within compliance times specified in the proposed AD, inspecting the fan blade abradable rub strip on certain engines for wear, inspecting the fan blades on certain engines for cracks, inspecting the aft actuator head hose fitting for correct position, and, if necessary, repositioning the hose fitting.

### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is provided in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

### Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

### Request To Modify Wording in Compliance Paragraphs (f)(2) Through (f)(6)(ii)

One commenter requests that we modify the wording in proposed AD compliance paragraphs (f)(2) through (f)(6)(ii), by adding words that the actions required by GEAE SB CF34-AL S/B 72-0250 apply only to those engines that have not had the actions of GEAE SB CF34-AL S/B 72-0245 performed. The commenter states that GEAE SB CF34-AL S/B 72-0250 only applies to fan blades with SNs listed in GEAE SB CF34-AL S/B 72-0245.

We do not agree. The proposed AD stated in paragraph (f) that only fan blade SNs listed in GEAE SB CF34-AL S/B 72-0245 are affected. That paragraph is now paragraph (h) in this AD, as we recodified the AD paragraphs to add clarification in response to another comment we received. We did not change the AD.

### Request for Eddy Current Inspection (ECI) for Fan Blades That Have More than 1,200 Cycles-In-Service (CIS)

Bombardier Flexjet and GE Aviation request that we also include an ECI in the AD for fan blades that have more than 1,200 CIS on the effective date of the AD.

We agree. We changed proposed AD paragraph from “(g)(3) For fan blades, P/N 6018T30P14, with more than 850 cycles-since-new (CSN), but fewer than 1,200 CSN on the effective date of this AD, within 350 CIS after the effective date of this AD, perform an initial ECI of the fan blades for cracks” to “(k)(3) For fan blades, P/N 6018T30P14, with more than 850 CSN, perform an initial ECI of the fan blades for cracks within 350 CIS after the effective date of this AD” in this AD.

### Under-Cowl Fire Determination of Cause Not Consistent

GE Aviation states that, in the Discussion section of the proposed AD, the statement that it was not possible to determine the cause of the under-cowl fire was not consistent with the GE fire investigation. GE stated that their fire investigation concluded that the most probable cause of the under-cowl fire was the separation of the variable geometry aft actuator head hose from the fuel control.

We do not agree. The exact cause of the fire could not be determined due to the thermal damage. We did not change the AD.

### Clarification of Gearbox Separation Statement

GE Aviation states that, in the Discussion section of the proposed AD, the statement that the gearbox separated from the engine needs clarification. GE Aviation states that the gearbox is designed to uncouple from the engine during high-load events such as a fan blade out, and the gearbox is secured to the engine by secondary restraint cables. This uncoupling occurred on the left-hand mount, and should not have contributed to the hose failure if the hose was properly aligned.

We do not agree. The wording is factually correct, and we did not state that the separation caused the fire. We did not change the AD.

### Claim That the Fire Event Was a Controlled Fire

GE Aviation claims that the event that this AD results from was a “controlled fire” as the fire had been put out and did not create a hazard for the airplane.

We do not agree. The fire continued to burn unabated until the unidentified fuel source was exhausted. We did not change the AD.

### Recommendation To Include GE Remote Diagnostics

GE Aviation and Mesaba Airlines recommend that GE Remote Diagnostics be included in proposed AD compliance paragraph (f)(6) as an alternate method of compliance (AMOC) for monitoring blade health. GE Aviation also recommends that we allow a recurrent ECI at 600-cycle intervals for consistency between the Regional Jet and Business Jet operators. GE Aviation states that the fan blade tang cracking algorithms developed by GE have been validated analytically, as well as in the field, and contributed substantially to finding three cracked blades during 2008.

We do not agree. We cannot include the GE Remote Diagnostics program,

because it is a program outside regulatory control. Further, the program cannot replace a visual inspection to verify fan blade cracks. Finally, no GE service bulletin requirement or FAA requirement exists for ECI of the fan blades operating in engines in the Regional Jet operations. We did not change the AD.

### Request To Revise the Wording in Proposed AD Compliance Paragraphs (f) and (g)

GE Aviation requests that we revise the wording in proposed AD compliance paragraphs (f) and (g) to clarify our instructions related to operators who fly a Regional Jet with a CF34-3A1 engine in a Business jet application. The commenter states that GEAE SB CF34-AL S/B 72-0245 and SB CF34-AL S/B 72-0250 apply to a small number of Business Jet operators with the CF34-3A1 engine, who fly under the Regional jet manual.

We agree. We changed the compliance section in this AD by adding the requested information and by recodifying the paragraphs.

### Request To Correct a Typographical Error

GE Aviation requests that we correct a service bulletin issue date in paragraph (f), to be July 30, 2008.

We agree. We corrected the date in the AD, which is now in paragraph (h).

### Request To Remove Inspection of Rubstrips at CSN

Mesaba Airlines requests that we remove the requirements to inspect the fan blade rub strips on fan blades with more than 1,200 CSN, within 20 CIS of the AD effective date, and on fan blades with fewer than 1,200 CSN, by 1,220 CSN. The commenter requests that we add a rub strip inspection every 75 CIS or 100 hours-in-service, until the fan blades are replaced. The commenter states that it is difficult to know the CSN on each fan blade.

We do not agree. To reduce the risk of fan blade failure, the rub strips need to be inspected as required in the AD. We did not change the AD.

### Include a Process for Determining Fan Blade Cyclic Limits

Mesaba Airlines states that the FAA should include a process for determining cyclic limits if the fan blades CIS were not established when the fan blades were introduced into service.

We do not agree. If operators do not track fan blade time or CIS, they will need to apply for an alternative method

of compliance (AMOC) to this AD. We did not change the AD.

#### Request for Separate ADs

Mesaba Airlines requests that we issue separate ADs for the Regional Jet fleet and the Business Jet fleet. The commenter feels the proposed AD is far too complex.

We do not agree. The compliance section in the proposed AD is sufficiently direct. We did not change the AD.

#### Request To Define Terms

Mesaba Airlines requests that we define the terms “CSLI” and “HSLI” in the proposed AD compliance section.

In response, we note that we already did, and direct Mesaba Airlines to paragraph (f)(6) in the proposed AD, and in this AD, to compliance paragraph (h)(6).

#### Request To Not Include Service Bulletin Requirements

Mesaba Airlines requests that we not include the requirements of paragraph 3.A.(2)(d) of GEAE SB CF34–AL S/B 72–0250 in the AD.

We agree. We did not include those requirements in the AD.

#### Conclusion

We have carefully reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

#### Costs of Compliance

We estimate that this AD will affect 1,966 engines installed on airplanes of U.S. registry. We estimate that the fan blade inspection and replacement requirement will affect 300 of these engines, and the actuator head hose inspection would affect 1,662 engines. We also estimate that it will take 0.5 work-hour per engine to inspect the fan blade abrasible rub strip, 6 work-hours per engine to visually inspect the fan blades, 11 work-hours per engine to perform an eddy current inspection of the fan blades, and 0.25 work-hour per engine to inspect the actuator head hose fitting, and that the average labor rate is \$80 per work-hour. Required parts will cost \$51,106,600. Based on these figures, we estimate the total cost of the AD to U.S. operators to be \$51,184,000.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue

rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify that this AD:*

- (1) Is not a “significant regulatory action” under Executive Order 12866;
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary at the address listed under **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2009–24–11 General Electric Company:**  
Amendment 39–16103. Docket No.  
FAA–2009–0328; Directorate Identifier  
2008–NE–44–AD.

#### Effective Date

(a) This airworthiness directive (AD) becomes effective January 4, 2010.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to General Electric Company (GE) CF34–1A, CF34–3A, CF34–3A1, CF34–3A2, CF34–3B, and CF34–3B1 turbofan engines. These engines are installed on, but not limited to, Bombardier Canadair Models CL–600–2A12, CL–600–2B16, and CL–600–2B19 airplanes.

#### Unsafe Condition

(d) This AD results from a report of an under-cowl fire and a failed fan blade. We are issuing this AD to prevent failure of certain part number (P/N) and serial number (SN) fan blades and aft actuator head hoses, which could result in an under-cowl fire and subsequent damage to the airplane.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### CF34–3A1 and CF34–3B1 Engines

(f) For CF34–3A1 engines with fan drive shaft, P/N 6036T78P02, and airworthiness limitation section life limit of 22,000 CSN; and

(g) For CF34–3A1 engines with fan drive shaft, P/N 6036T78P02, and airworthiness limitation section life limit of 15,000 CSN that are in compliance with GE Aircraft Engines (GEAE) Service Bulletin (SB) CF34–AL S/B 72–0147, dated May 21, 2003, Revision 01, dated October 17, 2003, Revision 02, dated August 5, 2004, or Revision 3, dated August 28, 2003; and

(h) For CF34–3B1 engines with fan blades, P/Ns 6018T30P14 or 4923T56G08, that have a fan blade SN listed in Appendix A of GEAE SB CF34–AL S/B 72–0245, Revision 01, dated July 30, 2008;

(i) Do the following for the engines meeting the criteria in paragraph (f), (g), or (h) of this AD, as applicable:

(1) Remove fan blades from service within 4,000 cycles-in-service (CIS) after the effective date of this AD or by December 31, 2010, whichever occurs first.

#### Initial Visual Inspection of the Fan Blade Abradable Rub Strip for Wear

(2) For fan blades with 1,200 or more cycles-since-new (CSN) on the effective date of this AD, perform an initial visual inspection of the fan blade abradable rub strip for wear within 20 CIS after the effective date of this AD. Use paragraphs 3.A.(1) through 3.A.(2) of the Accomplishment

Instructions of GEAE SB CF34-AL S/B 72-0250, Revision 01, dated November 26, 2008, to perform the inspection.

(3) For fan blades with fewer than 1,200 CSN on the effective date of this AD, perform an initial visual inspection of the fan blade abradable rub strip for wear within 1,220 CSN. Use paragraphs 3.A.(1) through 3.A.(2) of the Accomplishment Instructions of GEAE SB CF34-AL S/B 72-0250, Revision 01, dated November 26, 2008, to perform the inspection.

(4) If you find a continuous 360 degree rub indication, before further flight, visually inspect the fan blades using paragraphs 3.A.(2)(a) through 3.A.(2)(b) of the Accomplishment Instructions of GEAE SB CF34-AL S/B 72-0250, Revision 01, dated November 26, 2008.

(5) If you find a crack in the retaining pin holes of the fan blade, remove the blade from service.

#### **Repetitive Visual Inspection of the Fan Blade Abradable Rub Strip for Wear**

(6) Within 75 cycles-since-last inspection (CSLI) or 100 hours-since-last-inspection (HSLI), whichever occurs later, perform a visual inspection of the fan blade abradable rub strip for wear. Use paragraphs 3.A.(1) through 3.A.(2) of the Accomplishment Instructions of GEAE SB CF34-AL S/B 72-0250, Revision 01, dated November 26, 2008, to perform the inspection.

(i) If you find a continuous 360 degree rub indication, before further flight, visually inspect the fan blades using paragraphs 3.A.(2)(a) through 3.A.(2)(b) of the Accomplishment Instructions of GEAE SB CF34-AL S/B 72-0250, Revision 01, dated November 26, 2008.

(ii) If you find a crack in the retaining pin holes of the fan blade, remove the blade from service.

#### **Inspection of the Aft Actuator Head Hose Fitting on CF34-3A1 and CF34-3B1 Engines**

(7) Within 750 hours time-in-service (TIS) after the effective date of this AD, visually inspect and, if necessary, reposition the aft actuator head hose fitting. Use paragraph 3.A of the Accomplishment Instructions of GEAE SB CF34-AL S/B 73-0046, Revision 02, dated August 27, 2008, to perform the inspection.

#### **CF34-1A, CF34-3A, CF34-3A2, CF34-3B, and CF34-3A1 Engines**

(j) For CF34-3A1 engines with fan drive shaft, P/N 6036T78P02, and airworthiness limitation section life limit of 15,000 CSN, that are not in compliance with GEAE SB CF34-AL S/B 72-0147, dated May 21, 2003, Revision 01, dated October 17, 2003, Revision 02, dated August 5, 2004, or Revision 3, dated August 28, 2003; and

(k) For CF34-1A, CF34-3A, CF34-3A2, and CF34-3B engines with fan blades, P/N 6018T30P14 or P/N 4923T56G08, that have a fan blade SN listed in Appendix A of GEAE SB CF34-BJ S/B 72-0229, Revision 01, dated July 30, 2008;

(l) Do the following for the engines meeting the criteria in paragraph (j) or (k) of this AD as applicable:

(1) Remove fan blades, P/N 6018T30P14, from service within 2,400 CSN.

(2) Remove fan blades, P/N 4923T56G08, from service within 1,200 CIS since the bushing repair of the fan blade hole.

#### **Initial Eddy Current Inspection of the Fan Blades**

(3) For fan blades, P/N 6018T30P14, with more than 850 CSN, perform an initial eddy current inspection (ECI) of the fan blades for cracks within 350 CIS after the effective date of this AD. Use paragraphs 3.A. or 3.B. of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 72-0229, Revision 01, dated July 30, 2008, to perform the inspection.

(4) For fan blades, P/N 6018T30P14, with 850 or fewer CSN on the effective date of this AD, perform an initial ECI of the fan blades for cracks within 1,200 CSN. Use paragraphs 3.A. or 3.B. of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 72-0229, Revision 01, dated July 30, 2008, to perform the inspection.

(5) If you find a crack in the retaining pin holes of the fan blade, remove the blade from service.

#### **Repetitive ECI of the Fan Blades**

(6) For fan blades, P/N 6018T30P14, within 600 CSLI, perform an ECI of the fan blades for cracks. Use paragraphs 3.A. or 3.B. of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 72-0229, Revision 01, dated July 30, 2008, to perform the inspection.

(7) If you find a crack in the retaining pin holes of the fan blade, remove the blade from service.

#### **Initial Visual Inspection of the Fan Blade Abradable Rub Strip for Wear**

(8) For engines with fan blades, P/N 6018T30P14, installed that have a fan blade SN listed in Appendix A of GEAE SB CF34-BJ S/B 72-0229, Revision 01, dated July 30, 2008, with 1,200 or more CSN on the effective date of this AD, and that haven't had an ECI of the fan blades for cracks, do the following:

(i) Perform an initial inspection of the fan blade abradable rub strip for wear within 20 CIS after the effective date of this AD. Use paragraph 3.A.(1) of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 72-0231, Revision 02, dated November 26, 2008, to perform the inspection.

(ii) If you find a continuous 360 degree rub indication, before further flight, perform a visual inspection of the fan blades for cracks. Use paragraphs 3.A.(2)(a) or 3.A.(2)(b) of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 72-0231, Revision 02, dated November 26, 2008, to perform the inspection.

(iii) If you find a crack in the retaining pin holes of the fan blade, remove the blade from service.

#### **Repetitive Inspection of the Fan Blade Abradable Rub Strip for Wear**

(9) For engines with fan blades, P/N 6018T30P14, installed, if you have performed an ECI of the fan blade, you don't need to inspect the fan blade abradable rub strip for wear.

(10) For engines with fan blades, P/N 6018T30P14, installed, within 75 CSLI or 100 HSLI, whichever occurs later, do the following:

(i) Perform a visual inspection of the fan blade abradable rub strip for wear. Use paragraph 3.A.(1) of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 72-0231, Revision 02, dated November 26, 2008, to perform the inspection.

(ii) If you find a continuous 360 degree rub indication, before further flight, visually inspect the fan blades using paragraphs 3.A.(2)(a) through 3.A.(2)(b) of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 72-0231, Revision 02, dated November 26, 2008.

(iii) If you find a crack in the retaining pin holes of the fan blade, remove the blade from service.

#### **Inspection of the Aft Actuator Head Hose Fitting on CF34-3A1 and CF34-3B Engines**

(11) For CF34-3A1 engines, within 300 hours TIS after the effective date of this AD, visually inspect and, if necessary, reposition the aft actuator head hose fitting. Use paragraph 3.A of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 73-0062, Revision 02, dated August 27, 2008, to perform the inspection.

(12) For CF34-3B engines, within 400 hours TIS after the effective date of this AD, visually inspect and, if necessary, reposition the aft actuator head hose fitting. Use paragraph 3.A of the Accomplishment Instructions of GEAE SB CF34-BJ S/B 73-0062, Revision 02, dated August 27, 2008, to perform the inspection.

#### **Credit for Previous Actions**

(m) Inspections previously performed using the following GEAE SBs meet the requirements specified in the indicated paragraphs:

(1) CF34-AL S/B 72-0250, dated August 15, 2008, meet the requirements specified in paragraphs (i)(2) through (i)(4) of this AD.

(2) CF34-AL S/B 73-0046, Revision 01, dated July 1, 2008, or earlier issue, meet the requirements specified in paragraph (i)(7) of this AD.

(3) CF34-BJ S/B 72-0229, dated April 10, 2008, meet the requirements specified in paragraphs (l)(3) and (l)(4) of this AD.

(4) CF34-BJ S/B 72-0231, Revision 01, dated October 1, 2008, or earlier issue, meet the requirements specified in paragraphs (l)(10)(i) and (l)(10)(ii) of this AD.

(5) CF34-BJ S/B 73-0062, Revision 01, dated July 1, 2008, or earlier issue, meet the requirements specified in paragraphs (l)(11) and (l)(12) of this AD.

#### **Installation Prohibitions**

(n) After the effective date of this AD:

(1) Do not install any fan blade into any CF34-3A1 engine with fan drive shaft, P/N 6036T78P02, with an airworthiness limitation section life limit of 22,000 CSN if that fan blade:

(i) Was installed in a CF34-3A1 engine with fan drive shaft, P/N 6036T78P02, with an airworthiness limitation section life limit of 15,000 CSN; and

(ii) Is listed in Appendix A of GEAE SB CF34-BJ S/B 72-0229, Revision 01, dated July 30, 2008; or

(iii) Is listed in Appendix A of GEAE SB CF34-BJ S/B 72-0230, Revision 01, dated July 30, 2008.

(2) Do not install any fan blade into any CF34–3A1 engine with fan drive shaft, P/N 6036T78P02, with an airworthiness limitation section life limit of 15,000 CSN if that fan blade:

(i) Was installed in any CF34–3A1 engine with fan drive shaft, P/N 6036T78P02, with an airworthiness limitation section life limit of 22,000 CSN and,

(ii) Is listed in Appendix A of GEAE SB CF34–AL S/B 72–0245, Revision 01, dated July 3, 2008.

#### Alternative Methods of Compliance

(o) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

#### Related Information

(p) Contact John Frost, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England

Executive Park, Burlington, MA 01803; e-mail: [john.frost@faa.gov](mailto:john.frost@faa.gov); telephone (781) 238–7756; fax (781) 238–7199, for more information about this AD.

#### Material Incorporated by Reference

(q) You must use the GE Aircraft Engines service information specified in the following Table 1 to do the actions required by this AD.

TABLE 1—MATERIAL INCORPORATED BY REFERENCE

Service Bulletin No.	Page	Revision	Date
CF34–AL S/B 73–0046 Total Pages: 8 .....	All .....	02	August 27, 2008.
CF34–BJ S/B 73–0062 Total Pages: 8 .....	All .....	02	August 27, 2008.
CF34–BJ S/B 72–0229 Total Pages: 158 .....	All .....	01	July 30, 2008.
CF34–BJ S/B 72–0230 Total Pages: 153 .....	All .....	01	July 30, 2008.
CF34–BJ S/B 72–0231 Total Pages: 8 .....	All .....	02	November 26, 2008.
CF34–AL S/B 72–0245 Total Pages: 153 .....	All .....	01	July 03, 2008.
CF34–AL S/B 72–0250 Total Pages: 9 .....	All .....	01	November 26, 2008.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact General Electric Company, GE-Aviation, Room 285, 1 Newmann Way, Cincinnati, OH 45215, telephone (513) 552–3272; fax (513) 552–3329; e-mail: [geae.aoc@ge.com](mailto:geae.aoc@ge.com).

(3) You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on November 18, 2009.

**Peter A. White,**

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E9–28236 Filed 11–27–09; 8:45 am]

BILLING CODE 4910–13–P

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It was noticed on assembly line an elongation of bolts connecting power leads on R700 and R701 shunts. An incorrect tightening torque value is likely to be the cause of the elongation.

This condition, if left uncorrected could lead to heating, electrical arcing or smokes and could result in an in-flight loss of electrical power.

We are issuing this AD to require actions to correct the unsafe condition on these products.

**DATES:** This AD becomes effective January 4, 2010.

On January 4, 2010, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4119; fax: (816) 329–4090.

#### SUPPLEMENTARY INFORMATION:

#### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on September 28, 2009 (74 FR 49345). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

It was noticed on assembly line an elongation of bolts connecting power leads on R700 and R701 shunts. An incorrect tightening torque value is likely to be the cause of the elongation.

This condition, if left uncorrected could lead to heating, electrical arcing or smokes and could result in an in-flight loss of electrical power.

For the reason described above, this Airworthiness Directive (AD) mandates the replacement of the power lead bolts on R700 and R701 shunts.

#### Comments

We gave the public the opportunity to participate in developing this AD. We have considered the comment received.

#### Comment Issue: Costs of Compliance

Ms. Catherine Héreau, SOCAT, states the cost of the required parts (4 bolts) is \$10, not \$50. Consequently, the cost of the proposed AD on U.S. operators is \$2,350 or \$50 per product.

We agree with the commenter, and we are changing the costs of compliance in the final rule AD action to reflect the more accurate estimated costs.

#### Conclusion

We reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2009–0886 Directorate Identifier 2009–CE–045–AD; Amendment 39–16109; AD 2009–24–15]

RIN 2120–AA64

#### Airworthiness Directives; SOCATA Model TBM 700 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.