

Intermediate Pressure Turbine Overspeed (IPTOS) protection function by Data Entry Plug (DEP) reprogramming, which consists in limiting the IPT speed (Engine Thrust) when overheat is detected in IPT, for all A330 aeroplanes fitted with RR Trent 700 engines and equipped with Multi Mode Receivers.

Original issue of AD 2008–0101 had a limited applicability due to Flight Warning Computer compatibility issue with aircraft not equipped with Multi Mode Receivers. Airbus has now developed a new Flight Warning Computer standard T2 whose embodiment is also possible on A330 aeroplane fitted with RR Trent 700 engines not equipped with Multi Mode Receivers.

For the above described reasons, this AD retains the requirement of EASA AD 2008–0101, which is superseded, and extends the applicability to all A330 aeroplanes fitted with RR Trent 700 engines.

#### Actions and Compliance

(f) Unless already done, do the following actions: Within 12 months after the effective date of this AD, do the actions specified in paragraph (f)(1) of this AD.

(1) Reprogram the data entry plug on both engines to activate the intermediate pressure turbine overspeed protection function, including doing applicable revisions of the Airplane Flight Manual (AFM), in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330–73–3049, Revision 01, dated November 13, 2008.

**Note 1:** IPTOS function activation has the following operational consequences: Modification of the AFM and the flightcrew operating manual (FCOM). Accomplishment of the actions specified in Airbus Mandatory Service Bulletin A330–73–3049, Revision 01, dated November 13, 2008 (Airbus Modification 56722), cancels Airbus A330 AFM Supplement 6.03.08, dated June 2, 2006; and Volumes 1 and 3 (1.70.20, 1.70.95, and 3.02.70) of the Airbus A330 FCOM have been modified.

(2) Actions accomplished before the effective date of this AD in accordance with Airbus Mandatory Service Bulletin A330–73–3049, dated November 14, 2007, are considered acceptable for compliance with the corresponding action specified in paragraph (f)(1) of this AD.

#### FAA AD Differences

**Note 2:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1138; fax (425) 227–1149. Before

using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

#### Related Information

(h) Refer to Mandatory Continuing Airworthiness Information EASA Airworthiness Directive 2009–0075, dated April 6, 2009; and Airbus Mandatory Service Bulletin A330–73–3049, Revision 01, dated November 13, 2008; for related information.

#### Material Incorporated by Reference

(i) You must use Airbus Mandatory Service Bulletin A330–73–3049, Revision 01, dated November 13, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80, e-mail [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com); Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221 or 425–227–1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on November 23, 2009.

**Ali Bahrami,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9–28858 Filed 12–9–09; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2009–1114; Directorate Identifier 2009–NM–157–AD; Amendment 39–16134; AD 2007–10–10 R1]

RIN 2120–AA64

#### Airworthiness Directives; Airbus Model A300–600 Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is revising an existing airworthiness directive (AD), which applies to all Airbus Model A300–600 series airplanes. That AD currently requires revising the Airworthiness Limitations section of the Instructions for Continued Airworthiness to incorporate new limitations for fuel tank systems. This AD clarifies the intended effect of the AD on spare and on-airplane fuel tank system components. This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors caused by latent failures, alterations, repairs, or maintenance actions, could result in fuel tank explosions and consequent loss of the airplane.

**DATES:** This AD is effective December 28, 2009.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of December 28, 2009.

On June 27, 2007 (72 FR 28827, May 23, 2007), the Director of the Federal Register approved the incorporation by reference of certain other publications listed in the AD.

We must receive any comments on this AD by January 25, 2010.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE.,

Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>.

### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

### SUPPLEMENTARY INFORMATION:

#### Discussion

On May 7, 2007, we issued AD 2007-10-10, Amendment 39-15051 (72 FR 28827, May 23, 2007). That AD applied to all Airbus Model A300-600 series airplanes. That AD required revising the Airworthiness Limitations section (ALS) of the Instructions for Continued Airworthiness to incorporate new limitations for fuel tank systems.

Critical design configuration control limitations (CDCCLs) are limitation requirements to preserve a critical ignition source prevention feature of the fuel tank system design that is necessary to prevent the occurrence of an unsafe condition. The purpose of a CDCCL is to provide instruction to retain the critical ignition source prevention feature during configuration change that may be caused by alterations, repairs, or maintenance actions. A CDCCL is not a periodic inspection.

#### Actions Since AD Was Issued

Since we issued that AD, we have determined that it is necessary to clarify the AD's intended effect on spare and on-airplane fuel tank system components, regarding the use of maintenance manuals and instructions for continued airworthiness.

Section 91.403(c) of the Federal Aviation Regulations (14 CFR 91.403(c)) specifies the following:

No person may operate an aircraft for which a manufacturer's maintenance manual or instructions for continued airworthiness has been issued that contains an airworthiness limitation section unless the mandatory \* \* \* procedures \* \* \* have been complied with.

Some operators have questioned whether existing components affected by the new CDCCLs must be reworked. We did not intend for the AD to retroactively require rework of components that had been maintained using acceptable methods before the effective date of the AD. Owners and operators of the affected airplanes therefore are not required to rework affected components identified as airworthy or installed on the affected airplanes before the required revisions of the ALS. But once the CDCCLs are incorporated into the ALS, future maintenance actions on components must be done in accordance with those CDCCLs.

#### Relevant Service Information

AD 2007-10-10 cites Airbus A300-600 Fuel Airworthiness Limitations, Document 95A.1929/05, Issue 1, dated December 19, 2005. Since we issued that AD, Airbus has revised the referenced service information and issued Airbus A300-600 Fuel Airworthiness Limitations, Document 95A.1929/05, Issue 2, dated May 16, 2007. The revised service information clarifies the new limitations for fuel tank systems, but adds no new procedures. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of This AD

The affected products have been approved by the aviation authority of another country, and are approved for operation in the United States. We are issuing this AD because we evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. This new AD retains the requirements of the existing AD, and adds a new note to clarify the intended effect of the AD on spare and on-airplane fuel tank system components.

#### Costs of Compliance

This revision imposes no additional economic burden. The current costs for this AD are repeated for the

convenience of affected operators, as follows:

This AD affects about 138 airplanes of U.S. registry. The required actions take about 2 work hours per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the AD for U.S. operators is \$22,080, or \$160 per airplane.

#### FAA's Justification and Determination of the Effective Date

This revision merely clarifies the intended effect on spare and on-airplane fuel tank system components, and makes no substantive change to the AD's requirements. For this reason, it is found that notice and opportunity for prior public comment for this action are unnecessary, and good cause exists for making this amendment effective in less than 30 days.

#### Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not provide you with notice and an opportunity to provide your comments before it becomes effective. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-1114; Directorate Identifier 2009-NM-157-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify that the regulation:*

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator, the FAA amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Amendment 39–15051 (72 FR 28827, May 23, 2007) and adding the following new AD:

**AD 2007–10–10 R1 Airbus:** Amendment 39–16134. Docket No. FAA–2009–1114; Directorate Identifier 2009–NM–157–AD.

#### Effective Date

(a) This airworthiness directive (AD) is effective December 28, 2009.

#### Affected ADs

(b) This AD revises AD 2007–10–10, Amendment 39–15051.

### Applicability

(c) This AD applies to all Airbus Model A300–600 series airplanes, certificated in any category.

**Note 1:** This AD requires revisions to certain operator maintenance documents to include new inspections and critical design configuration control limitations (CDCCLs). Compliance with the operator maintenance documents is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections and CDCCLs, the operator may not be able to accomplish the inspections and CDCCLs described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (j) of this AD. The request should include a description of changes to the required inspections and CDCCLs that will preserve the critical ignition source prevention feature of the affected fuel system.

### Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors caused by latent failures, alterations, repairs, or maintenance actions, could result in fuel tank explosions and consequent loss of the airplane.

### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

*Restatement of Requirements of AD 2007–10–10, With Revised Service Information:*

### Revise Airworthiness Limitations Section (ALS) To Incorporate Fuel Maintenance and Inspection Tasks

(f) Within 3 months after June 27, 2007 (the effective date of AD 2007–10–10), revise the ALS of the Instructions for Continued Airworthiness to incorporate Airbus A300–600 ALS Part 5—Fuel Airworthiness Limitations, dated May 31, 2006, as defined in Airbus A300–600 Fuel Airworthiness Limitations, Document 95A.1929/05, Issue 1, dated December 19, 2005 (approved by the European Aviation Safety Agency (EASA) on March 13, 2006), Section 1, "Maintenance/Inspection Tasks" (hereafter referred to as Section 1 of Issue 1 of Document 95A.1929/05); or Airbus A300–600 Fuel Airworthiness Limitations, Document 95A.1929/05, Issue 2, dated May 16, 2007, Section 1, "Maintenance/Inspection Tasks" (hereafter referred to as "Section 1 of Issue 2 of Document 95A.1929/05"). For all tasks identified in Section 1 of Issue 1 or Issue 2 of Document 95A.1929/05, the initial compliance times start from the later of the times specified in paragraphs (f)(1) and (f)(2) of this AD, and the repetitive inspections must be accomplished thereafter at the intervals specified in Section 1 of Issue 1 or Issue 2 of Document 95A.1929/05, except as provided by paragraph (g) of this AD.

(1) June 27, 2007.

(2) The date of issuance of the original French standard airworthiness certificate or the date of issuance of the original French export certificate of airworthiness.

**Note 2:** Airbus Operator Information Telex (OIT) SE 999.0076/06, dated June 20, 2006, identifies the applicable sections of the Airbus A300–600 airplane maintenance manual necessary for accomplishing the tasks specified in Section 1 of Issue 1 or Issue 2 of Document 95A.1929/05.

### Initial Compliance Time for Task 28–18–00–03–1

(g) For Task 28–18–00–03–1, "Operational check of lo-level/underfull/calibration sensors," identified in Section 1 of Issue 1 or Issue 2 of Document 95A.1929/05: The initial compliance time is the later of the times specified in paragraphs (g)(1) and (g)(2) of this AD. Thereafter, Task 28–18–00–03–1 must be accomplished at the repetitive interval specified in Issue 1 or Issue 2 of Document 95A.1929/05.

(1) Prior to the accumulation of 40,000 total flight hours.

(2) Within 72 months or 20,000 flight hours after June 27, 2007, whichever occurs first.

### Revise ALS To Incorporate CDCCLs

(h) Within 12 months after June 27, 2007, revise the ALS of the Instructions for Continued Airworthiness to incorporate Airbus A300–600 ALS Part 5—Fuel Airworthiness Limitations, dated May 31, 2006, as defined in Airbus A300–600 Fuel Airworthiness Limitations, Document 95A.1929/05, Issue 1, dated December 19, 2005 (approved by the EASA on March 13, 2006), Section 2, "Critical Design Configuration Control Limitations"; or Airbus A300–600 Fuel Airworthiness Limitations, Document 95A.1929/05, Issue 2, dated May 16, 2007, Section 2, "Critical Design Configuration Control Limitations."

### No Alternative Inspections, Inspection Intervals, or CDCCLs

(i) Except as provided by paragraph (j) of this AD: After accomplishing the actions specified in paragraphs (f) and (h) of this AD, no alternative inspections, inspection intervals, or CDCCLs may be used.

### New Information

### Explanation of CDCCL Requirements

**Note 3:** Notwithstanding any other maintenance or operational requirements, components that have been identified as airworthy or installed on the affected airplanes before the revision of the ALS, as required by paragraphs (f) and (h) of this AD, do not need to be reworked in accordance with the CDCCLs. However, once the ALS has been revised, future maintenance actions on these components must be done in accordance with the CDCCLs.

### Alternative Methods of Compliance (AMOCs)

(j) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures

found in 14 CFR 39.19. Send information to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector

(PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

#### Related Information

(k) European Aviation Safety Agency Airworthiness Directive 2006-0201, dated

July 11, 2006, also addresses the subject of this AD.

#### Material Incorporated by Reference

(l) You must use the applicable service information contained in Table 1 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

TABLE 1—ALL MATERIAL INCORPORATED BY REFERENCE

| Document   | Issue          | Date               |
|--|----------------|--------------------|
| Airbus A300-600 ALS Part 5—Fuel Airworthiness Limitations .....            | Original ..... | May 31, 2006.      |
| Airbus A300-600 Fuel Airworthiness Limitations, Document 95A.1929/05 ..... | 1 .....        | December 19, 2005. |
| Airbus A300-600 Fuel Airworthiness Limitations, Document 95A.1929/05 ..... | 2 .....        | May 16, 2007.      |

(1) The Director of the Federal Register approved the incorporation by reference of the service information contained in Table 2

of this AD under 5 U.S.C. 552(a) and 1 CFR part 51.

TABLE 2—NEW MATERIAL INCORPORATED BY REFERENCE

| Document   | Issue   | Date          |
|--|---------|---------------|
| Airbus A300-600 Fuel Airworthiness Limitations, Document 95A.1929/05 ..... | 2 ..... | May 16, 2007. |

(2) The Director of the Federal Register previously approved the incorporation by reference of the service information

contained in Table 3 of this AD on June 27, 2007 (72 FR 28827, May 23, 2007).

TABLE 3—MATERIAL PREVIOUSLY INCORPORATED BY REFERENCE

| Document   | Issue          | Date               |
|--|----------------|--------------------|
| Airbus A300-600 ALS Part 5—Fuel Airworthiness Limitations .....            | Original ..... | May 31, 2006.      |
| Airbus A300-600 Fuel Airworthiness Limitations, Document 95A.1929/05 ..... | 1 .....        | December 19, 2005. |

(3) For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on December 2, 2009.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9-29376 Filed 12-9-09; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2009-1113; Directorate Identifier 2009-NM-238-AD; Amendment 39-16133; AD 2009-25-13]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Bombardier, Inc. Model BD-100-1A10 (Challenger 300) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; request for comments.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation

product. The MCAI describes the unsafe condition as:

There have been 3 reported occurrences of uncontrolled excessive heat from the left hand baggage bay sidewall heater, [part number] P/N 3436-06-1/0, that resulted in the affected sidewall heater panels sustaining heat discoloration and/or scorching of the liner material. The affected sidewall heater is equipped with a thermostat to regulate heating. These reported occurrences are the subject of further investigation. As a preventive measure, until such time as the cause of the occurrences have been determined, deactivation of the left hand baggage bay heater is necessary to avoid the potential for uncontrolled excessive heat by the heater panel, and on the baggage bay compartment, that could lead to flammability issues.

\* \* \* \* \*

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** This AD becomes effective December 28, 2009.

The Director of the Federal Register approved the incorporation by reference of a certain publication as of December 28, 2009.