

intervals) as specified in the ALI (Airworthiness Limitation Items) tasks 57.18.16 have to be reviewed in order to comply with certification requirements. Consequently AIRBUS Service Bulletin (SB) A340-57-5011 has been issued to supersede the ALI tasks 57.18.16.

This AD mandates a repetitive inspection program in order to detect any crack by means of two Non-Destructive Test (NDT) inspection methods (High Frequency Eddy Current and Ultra Sonic).

This AD has been revised in order to exclude from the applicability section, A340-642 aircraft on which a terminating action modification 56026 or SB A340-57-5010 has been embodied and which consists of a large cut-out of the vertical cruciform flange in order to reduce the stress level in this critical area.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Actions

(g) Do the following actions.

(1) At the applicable time specified in the table titled, "THRESHOLDS" in paragraph 1.E.(2) of Airbus Mandatory Service Bulletin A340-57-5011, dated June 27, 2007, or within 3 months after the effective date of this AD, whichever occurs later; except that where the table expresses times in terms of "flight cycles" and "flight hours," those terms mean "total flight cycles" and "total flight hours" for purposes of this AD: Perform the NDT inspections of the cruciform fitting radius at Frame 47 on the right-hand and left-hand sides, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-57-5011, dated June 27, 2007.

(2) Submit a report of the findings of the inspection required by paragraph (g)(1) of this AD using Appendix 01 of Airbus Mandatory Service Bulletin A340-57-5011, dated June 27, 2007, to Airbus, Customer Services Directorate, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex France, Attn: SDC32 Technical Data and Documentation Services; fax (+33) 5 61 93 28 06; e-mail sb.reporting@airbus.com; at the applicable time specified in paragraph (g)(2)(i) or (g)(2)(ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was accomplished prior to the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(3) If no crack is detected during an inspection required by paragraph (g)(1) of this AD, apply sealant before further flight, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-57-5011, dated June 27, 2007. Repeat the inspection required by paragraph (g)(1) of this AD thereafter at the applicable interval specified in paragraph 1.E.(2) of Airbus Mandatory Service Bulletin A340-57-5011, dated June 27, 2007.

(4) If any crack is found during any inspection required by paragraph (g)(1) of

this AD, contact Airbus to get repair instructions and repair before further flight.

(5) Modifying the rear spar vertical cruciform at frame 47 in accordance with Airbus Service Bulletin A340-57-5010, Revision 01, dated April 2, 2008, terminates the inspection requirements of paragraphs (g)(1) and (g)(3) of this AD.

(6) After accomplishing the initial inspections required by paragraph (g)(1) of this AD or after the modification specified in paragraph (g)(5) of this AD is done, the limitation Tasks 57.18.16 (10 different tasks) of Airbus A340-500/600 Airworthiness Limitation Items need not be done.

(7) Modifying the rear spar vertical cruciform at frame 47 is also acceptable for compliance with the requirements of paragraph (g)(5) of this AD if done before the effective date of this AD in accordance with Airbus Service Bulletin A340-57-5010, dated September 28, 2007.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(i) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2007-0207R1, dated November 7, 2007; Airbus Service Bulletin A340-57-5010, Revision 01, dated April 2, 2008; and Airbus Mandatory Service Bulletin A340-57-5011, dated June 27, 2007; for related information.

Material Incorporated by Reference

(j) You must use Airbus Mandatory Service Bulletin A340-57-5011, including Appendix 01, dated June 27, 2007, as applicable, to do the actions required by this AD, unless the AD specifies otherwise. If you accomplish the optional actions specified by this AD, you must use Airbus Service Bulletin A340-57-5010, Revision 01, dated April 2, 2008, to perform those actions, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; fax +33 5 61 93 45 80; e-mail airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information that is incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 16, 2010.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-3485 Filed 2-24-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2009-0876; Airspace Docket No. 09-ASW-24]

Amendment of Class E Airspace; Stamford, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Class E airspace for Stamford, TX, adding additional controlled airspace to accommodate Area Navigation (RNAV) Standard Instrument Approach Procedures (SIAPs) at Arledge Field Airport, Stamford, TX. The FAA is taking this action to enhance the safety and management of Instrument Flight Rule (IFR) operations at the airport.

DATES: *Effective date:* 0901 UTC, June 3, 2010. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone (817) 321-7716.

SUPPLEMENTARY INFORMATION:

History

On November 24, 2009, the FAA published in the **Federal Register** a notice of proposed rulemaking to amend Class E airspace for Stamford, TX, reconfiguring controlled airspace at Arledge Field Airport (74 FR 61289) Docket No. FAA-2009-0876. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9T signed August 27, 2009, and effective September 15, 2009, which is incorporated by reference in 14 CFR Part 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by amending Class E airspace for the Stamford, TX area, adding additional controlled airspace extending upward from 700 feet above the surface to accommodate SIAPs at Arledge Field Airport. This action is necessary for the safety and management of IFR operations at the airport.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial

number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends controlled airspace at Arledge Field Airport, Stamford, TX.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR Part 71.1 of the Federal Aviation Administration Order 7400.9T, Airspace Designations and Reporting Points, signed August 27, 2009, and effective September 15, 2009, is amended as follows:

* * * * *

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface.

* * * * *

ASW TX E5 Stamford, TX [Amended]

Arledge Field Airport, TX
(Lat. 32°54'33" N., long. 99°44'10" W.)

That airspace extending upward from 700 feet above the surface within a 6.4-mile radius of Arledge Field Airport, and within 2 miles each side of the 180° bearing from the airport extending from the 6.4-mile radius to 11.5 miles south of the airport.

Issued in Fort Worth, Texas, on February 4, 2010.

Anthony D. Roetzel,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2010-3716 Filed 2-24-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2009-0929; Airspace Docket No. 09-AGL-32]

Amendment of Class E Airspace; Lima, OH

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Class E airspace at Lima, OH, to accommodate Area Navigation (RNAV) Standard Instrument Approach Procedures (SIAPs) at Lima Allen County Airport, Lima, OH. The FAA is taking this action to enhance the safety and management of Instrument Flight Rule (IFR) operations at the airport.

DATES: Effective 0901 UTC, June 3, 2010. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone (817) 321-7716.

SUPPLEMENTARY INFORMATION:

History

On November 9, 2009, the FAA published in the **Federal Register** a notice of proposed rulemaking to amend Class E airspace for Lima Allen County Airport, Lima, OH (74 FR 57618) Docket No. FAA-2009-0929. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9T signed August 27, 2009, and effective September 15, 2009, which is incorporated by reference in 14 CFR Part 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.