

### (l) New Requirement: Reporting Requirement

Submit a one-time report of the findings (both positive and negative) of the inspections required by paragraphs (i) and (j) of this AD to Airbus, Sebastien Faure, SEES1, SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 31 68; fax +33 5 61 93 36 14; email [sebastien.s.faure@airbus.com](mailto:sebastien.s.faure@airbus.com), at the applicable time specified in paragraph (l)(1) or (l)(2) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

### (m) New Requirement: Terminating Action

Accomplishment of the one-time eddy current inspection or a liquid penetrant inspection required by paragraph (j) of this AD, including doing all applicable repairs, constitutes terminating action for the inspections required by paragraph (i) of this AD.

### (n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: (425) 227-2125; fax: (425) 227-1149; email: [Dan.Rodina@faa.gov](mailto:Dan.Rodina@faa.gov). Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD. AMOCs approved previously in accordance with AD 2010-06-05, Amendment 39-16229 (75 FR 11435, March 11, 2010), are approved as AMOCs for the corresponding provisions of this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of

information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

### (o) Related Information

(1) Refer to MCAI EASA Airworthiness Directive 2011-0163, dated August 30, 2011, and the service information in paragraphs (o)(1)(i) through (o)(1)(vi) of this AD, for related information.

(i) Airbus All Operator Telex A300-53A0391, dated August 9, 2011.

(ii) Airbus All Operator Telex A300-57A6111, dated August 9, 2011.

(iii) Airbus Mandatory Service Bulletin A300-57A6108, including Appendices 01 and 02, dated September 12, 2008.

(iv) Airbus Mandatory Service Bulletin A300-53A0387, including Appendices 01 and 02, dated September 12, 2008.

(v) Airbus Service Bulletin A300-53-0268, Revision 06, dated January 7, 2002.

(vi) Airbus Service Bulletin A300-57-6052, Revision 03, dated May 27, 2002, including Airbus Drawings 15R53810394, Issue A, dated December 21, 1998, and 21R57110247, Issue A, dated June 20, 1997.

(2) For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on August 17, 2012.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-20966 Filed 8-24-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2012-0860; Directorate Identifier 2012-NM-123-AD]

RIN 2120-AA64

### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737-600, -700, -800, and -900ER series airplanes. This proposed AD was prompted by incorrect wire support clamps installed within the left environmental cooling systems (ECS) bay, which could allow wiring to come in contact with the exposed metal of the improper clamp. This proposed AD would require inspections to identify the part number of the wire support clamp, related investigative actions, and corrective actions if necessary. We are proposing this AD to prevent electrical arcing and a potential ignition source, which in combination with flammable fuel vapors could result in a fuel tank explosion, and consequent loss of the airplane.

**DATES:** We must receive comments on this proposed AD by October 11, 2012.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601

Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

### FOR FURTHER INFORMATION CONTACT:

Georgios Roussos, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6482; fax: 425-917-6590; email: [georgios.roussos@faa.gov](mailto:georgios.roussos@faa.gov).

### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-0860; Directorate Identifier 2012-NM-123-AD" at the beginning of your

comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

We reviewed reports of incorrect wire support clamps installed within the left ECS bay, which is a flammable leakage zone. Use of incorrect wire support clamps that are not fully cushioned could allow electrical power wiring to come in contact with the exposed metal of the improper clamp. Power wiring shorts to the exposed metal of the wire support clamp could produce electrical arcing. We are proposing this AD to prevent electrical arcing and a potential ignition source, which in combination with flammable fuel vapors, could result in a fuel tank explosion, and consequent loss of the airplane.

#### Relevant Service Information

We reviewed Boeing Special Attention Service Bulletin 737-28-1303, dated April 26, 2012. The service information describes procedures for a

detailed inspection of certain wire support clamps to identify part number TA0930034-10 wire support clamp and related investigative actions to verify that the flange cushions completely surround the two metal strap sections of the wire support clamp and to detect any possible chafing of the wire bundle within the left side ECS bay, and corrective actions if necessary. Corrective actions include replacing the discrepant clamp with a new or serviceable TA0930034-10 wire support clamp if the part number is incorrect or if the flange cushions do not completely surround the two metal strap sections of the wire support clamp, and repairing or replacing chafed wiring.

#### FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

#### Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously.

#### Costs of Compliance

We estimate that this proposed AD affects 297 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

#### ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Number of airplanes	Cost on U.S. operators
Inspection Group 1 airplanes .....	10 work-hours × \$85 per hour = \$850.	\$0	\$850	185	\$157,250
Inspection Group 2 airplanes .....	2 work-hours × \$85 per hour = \$170	0	170	112	19,040

We estimate the following costs to do any necessary replacements that would

be required based on the results of the proposed inspection. We have no way of

determining the number of aircraft that might need these replacements.

#### ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replacement of wire support clamp .....	1 work-hour × \$85 per hour = \$85 .....	\$3	\$88

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

We have received no definitive data that would enable us to provide cost estimates for the on-condition repair of chafed or damaged wiring specified in this proposed AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701:

“General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify this proposed regulation:*

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**The Boeing Company:** Docket No. FAA–2012–0860; Directorate Identifier 2012–NM–123–AD.

#### (a) Comments Due Date

We must receive comments by October 11, 2012.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to The Boeing Company Model 737–600, –700, –800, and –900ER series airplanes; certificated in any category; as identified in Boeing Special Attention Service Bulletin 737–28–1303, dated April 26, 2012.

#### (d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 28, Fuel System.

#### (e) Unsafe Condition

This AD was prompted by incorrect wire support clamps installed within the left environmental cooling systems (ECS) bay, which could allow wiring to come in contact with the exposed metal of the improper clamp. We are issuing this AD to prevent electrical arcing and a potential ignition source, which in combination with flammable fuel vapors could result in a fuel tank explosion, and consequent loss of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Inspection and Corrective Actions

Within 60 months after the effective date of this AD, do a detailed inspection for part number TA0930034–10 wire support clamp, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737–28–1303, dated April 26, 2012. Do all applicable related investigative and corrective actions before further flight.

#### (h) Parts Installation Prohibition

As of the effective date of this AD, no person may install a wire support clamp that is not part number (P/N) TA0930034–10 within the left ECS bay of any airplane.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (j) Related Information

(1) For more information about this AD, contact Georgios Roussos, Aerospace Engineer, Systems and Equipment Branch,

ANM–130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6482; fax: 425–917–6590; email: [georgios.roussos@faa.gov](mailto:georgios.roussos@faa.gov).

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, Washington 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on August 17, 2012.

**Ali Bahrami,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–20967 Filed 8–24–12; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2012–0859; Directorate Identifier 2012–NM–090–AD]

RIN 2120–AA64

### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Proposed rule; rescission.

**SUMMARY:** We propose to rescind an existing airworthiness directive (AD) that applies to certain The Boeing Company Model 737–600, –700, –700C, –800 and –900 series airplanes; and Model 757–200, –200PF, –200CB, and –300 series airplanes. The existing AD currently requires inspecting to determine if certain motor-operated shutoff valve actuators for the fuel tanks are installed, and related investigative and corrective actions if necessary. The existing AD also requires revising the Airworthiness Limitations (AWLs) section of the Instructions for Continued Airworthiness to incorporate AWL No. 28–AWL–21, No. 28–AWL–22, and No. 28–AWL–24 (for Model 737–600, –700, –700C, –800 and –900 series airplanes); and No. 28–AWL–23, No. 28–AWL–24, and No. 28–AWL–25 (for Model 757–200, –200PF, –200CB, and –300 series airplanes). We issued that AD to prevent electrical energy from lightning, hot shorts, or fault current from entering the fuel tank through the actuator shaft, which could result in fuel tank