

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify that this AD:*

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

*Authority:* 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2009-03-04, Amendment 39-15805 (74 FR 7796, February 20, 2009), and adding the following new AD:

**2012-23-12 Turbomeca S.A.:** Amendment 39-17268; Docket No. FAA-2008-0681; Directorate Identifier 2008-NE-13-AD.

#### (a) Effective Date

This airworthiness directive (AD) is effective January 7, 2013.

#### (b) Affected ADs

This AD supersedes AD 2009-03-04, Amendment 39-15805 (74 FR 7796, February 20, 2009).

#### (c) Applicability

This AD applies to Turbomeca S.A. models Arriel 1E2, 1S, and 1S1 turboshaft engines with FCUs manufactured, repaired, or overhauled on or before March 31, 2008.

#### (d) Unsafe Condition

Turbomeca S.A. informed the European Aviation Safety Agency of a case of a "red disk" plug, adapted for bench testing, which was installed on the FCU on an engine and released for service operation. An engine experienced an in-service high pressure leak event (at the fuel pump outlet) due to cracking of this "red disk" plug. This leak could lead to in-flight flame-out and/or possibly a fire. This AD was prompted by Turbomeca S.A. informing us that FCUs manufactured, repaired, or overhauled after March 31, 2008, do not require inspection. We are issuing this AD to prevent fuel leaks, which could result in a fire and damage to the helicopter.

#### (e) Compliance

Comply with this AD within the compliance times specified, unless already done. Within 100 operating hours from the effective date of this AD, perform a one-time inspection of the plug installed in the FCU 3-way union, part number 9 932 30 706 0.

(1) If the FCU 3-way union plug is unpainted, verify the plug is torqued to between 1.3 and 1.5 daN.m, in accordance with Turbomeca S.A. Mandatory Service Bulletin (MSB) No. 292 73 0817, Version D, dated February 29, 2012, before further flight.

(2) If the FCU 3-way union plug has any red paint on it, replace it with a serviceable plug and torque the plug to between 1.3 and 1.5 daN.m, in accordance with Turbomeca S.A. MSB No. 292 73 0817, Version D, dated February 29, 2012, before further flight.

#### (f) Installation Prohibition

After the effective date of this AD, do not install any FCU manufactured, repaired, or overhauled on or before March 31, 2008, onto any Turbomeca S.A. model Arriel 1E2, 1S, and 1S1 turboshaft engine, unless the FCU 3-way union plug has passed the one-time inspection and torque check required by this AD.

#### (g) Credit for Previous Actions

If you performed the inspections and corrective actions required by this AD using the original issue or any version up to and including Version D of Turbomeca S.A. MSB No. 292 73 0817 before the effective date of this AD, you have met the requirements of this AD.

#### (h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

#### (i) Related Information

(1) For more information about this AD, contact Rose Len, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7772; fax: 781-238-7199; email: [rose.len@faa.gov](mailto:rose.len@faa.gov).

(2) Refer to European Aviation Safety Agency Airworthiness Directive 2012-0063, dated April 17, 2012, for related information.

#### (j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Turbomeca S.A. Mandatory Service Bulletin No. 292 73 0817, Version D, dated February 29, 2012.

(ii) Reserved.

(3) For service information identified in this AD, contact Turbomeca S.A., 40220 Tarnos, France; phone: 33 (0)5 59 74 40 00; telex: 570 042; fax: 33 (0)5 59 74 45 15.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on November 14, 2012.

**Colleen M. D'Alessandro,**

*Assistant Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2012-28637 Filed 11-30-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2012-1049; Airspace Docket No. 12-ANM-12]

**RIN 2120-AA66**

#### Amendment of Area Navigation Route Q-1; CA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; technical amendment; correction.

**SUMMARY:** This action corrects a final rule; technical amendment, published by the FAA in the **Federal Register** on October 29, 2012, that adds two waypoints to the description of area navigation (RNAV) route Q–1. This action corrects the spelling of the TOCOS waypoint.

**DATES:** Effective date 0901 UTC, January 10, 2013. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:** Paul Gallant, Airspace Policy and ATC Procedures Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783.

#### SUPPLEMENTARY INFORMATION:

##### Background

On October 29, 2012, the FAA published a final rule, technical amendment in the **Federal Register** amending the description of RNAV route Q–1 by adding two new waypoints to the route (77 FR 65461). Subsequent to publication, an error was discovered in the spelling of the TOCOS waypoint.

Area Navigation Routes are published in paragraph 6011 of FAA Order 7400.9W, dated August 8, 2012, and effective September 15, 2012, which is incorporated by reference in 14 CFR 71.1. The RNAV route listed in this document will be published subsequently in the Order.

##### Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the TACOS, CA, waypoint published in the **Federal Register** on October 29, 2012 (77 FR 65461) for RNAV route Q–1 is corrected as follows:

*Paragraph 6011 United States Area Navigation Routes*

\* \* \* \* \*

##### Q–1 [Corrected]

On page 65461, second column, line 15, remove “TACOS” and insert “TOCOS.”

On page 65462, line 7, remove “TACOS” and insert “TOCOS.”

Issued in Washington, DC, on November 15, 2012.

**Colby Abbott,**

*Acting Manager, Airspace Policy and ATC Procedures Group.*

[FR Doc. 2012–28999 Filed 11–30–12; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2012–1193; Airspace Docket No. 12–ANM–26]

RIN 2120–AA66

#### Amendment of VOR Federal Airway V–8 in the Vicinity of Rifle, CO

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule, technical amendment.

**SUMMARY:** This action amends VHF Omnidirectional Range (VOR) Federal Airway V–8 in the vicinity of Rifle, CO, to correct the description contained in part 71 to ensure it matches the information contained in the FAA’s aeronautical database, matches the depiction on the associated charts, and to ensure the safety and efficiency of the National Airspace System (NAS).

**DATES:** Effective date 0901 UTC December 3, 2012. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:** Colby Abbott, Airspace Regulations and ATC Procedures Group, Office of Mission Support Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783.

#### SUPPLEMENTARY INFORMATION:

##### History

After a recent review of aeronautical data, the Aeronautical Navigation Products Group identified the current VOR Federal airway V–8 description published in FAA Order 7400.9, Airspace Designations and Reporting Points, did not match the airway information contained in the FAA’s aeronautical database or the charted depiction of the airway. When V–8 was amended in the **Federal Register** of September 30, 1993 (58 FR 51010), the airway was realigned over the Rifle, CO, VHF Omnidirectional Range/Distance Measuring Equipment (VOR/DME) navigation aid between Grand Junction, CO, and Kremmling, CO. In the **Federal Register** of August 9, 2010 (75 FR 47709), V–8 was renamed from the Findlay, OH, VORTAC to the Flag City, OH, VORTAC. The Rifle, CO, VOR/DME was inadvertently deleted from the airway description. The FAA

aeronautical database retained the Rifle, CO, VOR/DME in the airway description correctly and the associated aeronautical charts remain published accordingly. To overcome any confusion or flight safety issues associated with conflicting airway description information being published, the FAA is amending the V–8 legal description to reflect the airway aligned over the Rifle, CO, VOR/DME. Accordingly, since this is an administrative correction to update the V–8 description to be in concert with the FAA’s aeronautical database and charting, notice and public procedures under Title 5 U.S.C. 553(b) are unnecessary.

##### The Rule

The FAA amends Title 14 Code of Federal Regulations (14 CFR) part 71 by amending the legal description of VOR Federal airway V–8 in the vicinity of Rifle, CO. Specifically, the FAA amends V–8 to reflect the airway aligned over the Rifle, CO, VOR/DME; thus, matching the information currently contained in the FAA’s aeronautical database and the charted depiction of the airway.

VOR Federal airways are listed in paragraph 6010 of FAA Order 7400.9W dated August 8, 2012, and effective September 15, 2012, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airway listed in this document will be revised subsequently in the Order.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A,