

paragraph (i)(3) of this AD. Do all corrective actions before further flight. Repeat the internal HFEC inspection thereafter at the time specified in Table 4 or Table 5 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2682, Revision 1, dated May 24, 2012, as applicable.

(1) Before further flight after an inspection required by paragraph (g) of this AD.

(2) Within 2,000 flight cycles after the effective date of this AD.

#### (i) Service Information Clarifications and Exceptions

(1) Paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2682, Revision 1, dated May 24, 2012, specifies certain compliance times in terms of the effective date of AD 2009-06-02, Amendment 39-15838 (74 FR 11013, March 16, 2009). The effective date of AD 2009-06-02 is April 20, 2009.

(2) Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2682, Revision 1, dated May 24, 2012, specifies counting the compliance time "after the revision 1 date of this service bulletin," this AD requires compliance within the applicable time after the effective date of this AD.

(3) Where Boeing Alert Service Bulletin 747-53A2682, Revision 1, dated May 24, 2012, specifies to contact Boeing for repair instructions, this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

#### (j) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 747-53A2682, dated May 8, 2008.

#### (k) Special Flight Permit

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

#### (l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization

Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (m) Related Information

(1) For more information about this AD, contact Berhane Alazar, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-917-6577; fax: 425-917-6590; email: [berhane.alazar@faa.gov](mailto:berhane.alazar@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference may be obtained at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

#### (n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-53A2682, Revision 1, dated May 24, 2012.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 6, 2013.

**Jeffrey E. Duven,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2013-27845 Filed 11-22-13; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2013-0561; Directorate Identifier 2013-NE-23-AD; Amendment 39-17680; AD 2013-24-06]

RIN 2120-AA64

#### Airworthiness Directives; Thielert Aircraft Engines GmbH Reciprocating Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all Thielert Aircraft Engines GmbH TAE 125-01 reciprocating engines. This AD requires applying sealant to close the engine clutch housing (crankcase assembly) opening. This AD was prompted by a report of engine power loss due to engine coolant contaminating the engine clutch. The design of the engine allows the crankcase assembly opening to be susceptible to contamination from external sources. We are issuing this AD to prevent in-flight engine power loss, which could result in loss of control of, and damage to, the airplane.

**DATES:** This AD becomes effective December 30, 2013.

**ADDRESSES:** The Docket Operations office is located at Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (phone: 800-647-5527) is provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7779; fax: 781-238-7199; email: [frederick.zink@faa.gov](mailto:frederick.zink@faa.gov).

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to the specified products. The NPRM was published in the **Federal Register** on August 5, 2013 (78 FR 47228). The NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

A power loss event was reported on an aeroplane equipped with a TAE 125–01 engine. The investigation results showed that the probable cause was contamination of the engine clutch by coolant spillage during the last maintenance operation. The contamination penetrated the clutch housing through an opening located under the coolant tank that was only closed by a not fluid-tight plastic cover.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0561-0002>.

**Comments**

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (78 FR 47228, August 5, 2013).

**Conclusion**

We reviewed the available data and determined that air safety and the public interest require adopting this AD as proposed.

**Costs of Compliance**

We estimate that this AD will affect about 140 engines of U.S. registry. We also estimate that it will take about 2.5 hours per engine to comply with this AD. The average labor rate is \$85 per hour. Required parts cost about \$110 per engine. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$45,150.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2013–24–06 Thielert Aircraft Engines GmbH:** Amendment 39–17680; Docket No. FAA–2013–0561; Directorate Identifier 2013–NE–23–AD.

**(a) Effective Date**

This AD becomes effective December 30, 2013.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all Thielert Aircraft Engines GmbH TAE 125–01 reciprocating engines.

**(d) Reason**

This AD was prompted by a report of engine power loss due to engine coolant contaminating the engine clutch. The design of the engine allows the crankcase assembly opening to be susceptible to contamination from external sources. We are issuing this AD to prevent in-flight engine power loss, which could result in loss of control of, and damage to, the airplane.

**(e) Actions and Compliance**

Unless already done, do the following actions.

(1) After the effective date of this AD at the next annual or 100-hour inspection, whichever comes first, apply sealant to close the engine clutch housing (crankcase assembly) opening.

(2) Thereafter, reapply sealant to the engine clutch housing (crankcase assembly) opening, whenever the sealant is found to be not liquid-tight, or is removed.

(3) Guidance on the sealant and application can be found in Thielert Aircraft Engines GmbH Service Bulletin No. TM TAE 125–0022, dated August 8, 2012.

**(f) Alternative Methods of Compliance (AMOCs)**

The Manager, Engine Certification Office, FAA, may approve AMOCs to this AD. Use the procedures found in 14 CFR 39.19 to make your request.

**(g) Related Information**

(1) For more information about this AD, contact Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781–238–7779; fax: 781–238–7199; email: [frederick.zink@faa.gov](mailto:frederick.zink@faa.gov).

(2) Refer to MCAI European Aviation Safety Agency AD 2013–0109, dated May 22, 2013, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0561-0002>.

(3) Thielert Aircraft Engines GmbH Service Bulletin No. TM TAE 125–0022, dated August 8, 2012, which is not incorporated by reference in this AD, can be obtained from Thielert Aircraft Engines GmbH, using the contact information in paragraph (g)(4) of this AD.

(4) For service information identified in this AD, contact Thielert Aircraft Engines GmbH, Platanenstrasse 14 D–09350, Lichtenstein, Germany, phone: +49–37204–696–0; fax: +49–37204–696–55; email: [info@centurion-engines.com](mailto:info@centurion-engines.com).

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781–238–7125.

**(h) Material Incorporated by Reference**

None.

Issued in Burlington, Massachusetts, on November 14, 2013.

**Colleen M. D'Alessandro,**

*Assistant Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2013-28183 Filed 11-22-13; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[Docket No. USCG-2013-0639]

RIN 1625-AA09

#### Drawbridge Operation Regulation; Hackensack River, Kearney and Jersey City, NJ

**AGENCY:** Coast Guard, DHS.

**ACTION:** Temporary final rule.

**SUMMARY:** The Coast Guard is temporarily modifying the operating schedule that governs the operation of the Route 1 & 9 (Lincoln Highway) Bridge across the Hackensack River, mile 2.0, between Kearny and Jersey City, New Jersey. The bridge owner, New Jersey Department of Transportation, submitted a request to restrict bridge openings during the morning and afternoon rush hour periods to alleviate traffic congestion resulting from area roadway closures. It is expected that this change to the regulations would provide relief to vehicular traffic while continuing to meet the reasonable needs of navigation.

**DATES:** This temporary final rule is effective from March 1, 2014 through March 1, 2016.

**ADDRESSES:** Documents mentioned in this preamble are part of docket USCG-2013-0639. To view documents mentioned in this preamble as being available in the docket, go to <http://www.regulations.gov>, type in the "SEARCH" box and click "SEARCH." Click on Open Docket Folder on the line associated with this rulemaking. You may also visit the Docket Management Facility in room W12-140 on Ground Floor of the Department of Transportation West Building, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**FOR FURTHER INFORMATION CONTACT:** If you have questions on this temporary final rule, call or email Mr. Joe Arca, Project Officer, First Coast Guard District Bridge Branch, 212-668-7165,

[joe.m.arca@uscg.mil](mailto:joe.m.arca@uscg.mil). If you have questions on viewing the docket, call Barbara Hairston, Program Manager, Docket Operations, telephone 202-366-9826.

#### SUPPLEMENTARY INFORMATION:

##### Table of Acronyms

CFR Code of Federal Regulations  
DHS Department of Homeland Security  
FR Federal Register  
NPRM Notice of Proposed Rulemaking  
§ Section Symbol  
U.S.C. United States Code

#### A. Regulatory History and Information

On August 28, 2013, we published a notice of proposed rulemaking (NPRM) entitled Drawbridge Operation Regulations Hackensack River in the *Federal Register* (78 FR 53104). We received no comments on the proposed rule. No public meeting was requested, and none was held.

#### B. Basis and Purpose

The Route 1 & 9 (Lincoln Highway) Bridge at mile 2.0, across the Hackensack River between Kearny and Jersey City, New Jersey, has a vertical clearance of 40 feet at mean high water and 45 feet at mean low water. The drawbridge operation regulations are listed at 33 CFR 117.723.

The waterway users are predominantly recreational vessels and commercial vessels.

The owner of the bridge, New Jersey Department of Transportation, submitted a request to the Coast Guard to temporarily change the drawbridge operating regulations.

The purpose of this temporary final rule is to help provide relief to help reduce vehicular traffic congestion during the morning and afternoon vehicular rush hour periods. Additional vehicular traffic will be detoured across the Route 1 & 9 (Lincoln Highway) Bridges for two years from the adjacent Pulaski Skyway Bridge which will be under construction to replace its deck commencing on March 1, 2014 and continuing through March 1, 2016.

The existing regulations presently require the bridge to open on signal at all times.

Under this temporary final rule the draw shall open on signal; except that, the draw need not open for the passage of vessel traffic between 6 a.m. and 10 a.m. and 2 p.m. and 6 p.m., Monday through Friday, except holidays.

Tide dependent deep draft vessels may request bridge openings during the two rush hour closure periods provided at least a twelve hour advance notice is given.

#### C. Discussion of Comments, Changes and the Final Rule

The Coast Guard received no comments in response to the notice of proposed rulemaking. As a result, no changes have been made to this final rule.

#### D. Regulatory Analyses

We developed this rule after considering numerous statutes and executive orders related to rulemaking. Below we summarize our analyses based on these statutes or executive orders.

##### 1. Regulatory Planning and Review

This rule is not a significant regulatory action under section 3(f) of Executive Order 12866, Regulatory Planning and Review, and does not require an assessment of potential costs and benefits under section 6(a)(3) of that Order. The Office of Management and Budget has not reviewed it under that Order. We believe that this rule is not a significant regulatory action because the bridge provides adequate clearance for recreational vessels in the closed position and the commercial vessels will be able to get openings at any time provided the advance notice is given by calling the number posted at the bridge.

##### 2. Impact on Small Entities

The Regulatory Flexibility Act of 1980 (RFA), 5 U.S.C. 601-612, as amended, requires federal agencies to consider the potential impact of regulations on small entities during rulemaking. The Coast Guard received no comments from the Small Business Administration on this rule. The Coast Guard certifies under 5 U.S.C. 605(b) that this rule will not have a significant economic impact on a substantial number of small entities.

This rule should not have a significant effect on small entities since the bridge provides 40 feet of vertical clearance at mean high water which should accommodate the recreational vessels that transit this waterway. Deep draft commercial vessels can transit at during the two rush hour closure periods provided they give the twelve hour advance notice for openings.

There is no permanent restriction or regulation being imposed by this rule; therefore, the Coast Guard certifies under 5 U.S.C. 605(b) that this temporary final rule will not have a significant economic impact on a substantial number of small entities.

##### 3. Assistance for Small Entities

Under section 213(a) of the Small Business Regulatory Enforcement Fairness Act of 1996 (Pub. L. 104-121), we want to assist small entities in