

(i) Terminating Action

Modifying the STA 2370 pivot bulkhead by replacing the left and right side forward outer chords and upper splice angles, and doing all applicable related investigative and corrective actions, terminates the repetitive inspections required by paragraphs (g) and (h) of this AD for the modified location only. The modification must be done in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-53-0076, dated January 14, 2015, except as required by paragraph (j)(2) of this AD.

(j) Exceptions to Service Bulletin Specifications

(1) Where Boeing Alert Service Bulletin 777-53A0075, dated January 14, 2015, specifies a compliance time "after the Original Issue date of this Service Bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Although Boeing Alert Service Bulletin 777-53A0075, dated January 14, 2015; and Boeing Service Bulletin 777-530076, dated January 14, 2015; specify to contact Boeing for appropriate action, and Boeing Alert Service Bulletin 777-53A0075, dated January 14, 2015, specifies that action as "RC" (Required for Compliance), this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (j)(2) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Narinder Luthra, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6513; fax: 425-917-6590; email: narinder.luthra@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on June 2, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-14231 Filed 6-12-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2015-1982; Directorate Identifier 2014-NM-108-AD]

RIN 2120-AA64

Airworthiness Directives; Fokker Services B.V. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Fokker Services B.V. Model F.28 Mark 1000, 2000, 3000, and 4000 airplanes. This proposed AD was prompted by a design review, which revealed that no controlled bonding provisions are present on a number of critical locations outside the fuel tank. This proposed AD would require installing additional and improved fuel system bonding provisions, and revising the airplane maintenance or inspection program, as applicable, by incorporating fuel airworthiness limitation items and critical design configuration control limitations. We are proposing this AD to

prevent an ignition source in the fuel tank vapor space, which could result in a fuel tank explosion and consequent loss of the airplane.

DATES: We must receive comments on this proposed AD by July 30, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-1982; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2015–1982; Directorate Identifier 2014–NM–108–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2014–0109, dated May 8, 2014 (referred to after this the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Fokker Services B.V. Model F.28 Mark 1000, 2000, 3000, and 4000 airplanes. The MCAI states:

Prompted by an accident * * *, the Federal Aviation Administration (FAA) published Special Federal Aviation Regulation (SFAR) 88 [(66 FR 23086, May 7, 2001)], and the Joint Aviation Authorities (JAA) published Interim Policy INT/POL/25/12.

The review conducted by Fokker Services on the Fokker F28 design, in response to these regulations, revealed that no controlled bonding provisions are present on a number of critical locations outside the fuel tank.

This condition, if not corrected, could create an ignition source in the fuel tank vapour space, possibly resulting in a fuel tank explosions and consequent loss of the aeroplane.

To address this potential unsafe condition, Fokker Services developed a set of fuel tank bonding modifications.

For the reasons described above, this [EASA] AD requires the installation of additional and improved bonding provisions. These modifications do not require opening of the fuel tank access panels.

More information on this subject can be found in Fokker Services All Operators Message AOF28.038#02.

Required actions include revising the airplane maintenance or inspection program, as applicable, by incorporating fuel airworthiness limitation items and critical design configuration control limitations. You may examine the MCAI in the AD docket on the Internet at

<http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–1982.

The FAA has examined the underlying safety issues involved in fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled “Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements” (66 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 (“SFAR 88,” Amendment 21–78, and subsequent Amendments 21–82 and 21–83).

Among other actions, SFAR 88 (66 FR 23086, May 7, 2001) requires certain type design (*i.e.*, type certificate (TC) and supplemental type certificate (STC)) holders to substantiate that their fuel tank systems can prevent ignition sources in the fuel tanks. This requirement applies to type design holders for large turbine-powered transport airplanes and for subsequent modifications to those airplanes. It requires them to perform design reviews and to develop design changes and maintenance procedures if their designs do not meet the new fuel tank safety standards. As explained in the preamble to the rule, we intended to adopt airworthiness directives to mandate any changes found necessary to address unsafe conditions identified as a result of these reviews.

In evaluating these design reviews, we have established four criteria intended to define the unsafe conditions associated with fuel tank systems that require corrective actions. The percentage of operating time during which fuel tanks are exposed to flammable conditions is one of these criteria. The other three criteria address the failure types under evaluation: Single failures, single failures in combination with a latent condition(s), and in-service failure experience. For all four criteria, the evaluations included consideration of previous actions taken that may mitigate the need for further action.

The Joint Aviation Authorities (JAA) has issued a regulation that is similar to SFAR 88 (66 FR 23086, May 7, 2001). (The JAA is an associated body of the European Civil Aviation Conference (ECAC) representing the civil aviation regulatory authorities of a number of

European States who have agreed to cooperate in developing and implementing common safety regulatory standards and procedures.) Under this regulation, the JAA stated that all members of the ECAC that hold type certificates for transport category airplanes are required to conduct a design review against explosion risks.

We have determined that the actions identified in this AD are necessary to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

Related Service Information Under 1 CFR Part 51

Fokker Services B.V. has issued Fokker F28 Appendix SB SBF28–28–059/APP01, dated July 15, 2014, of Fokker F28 Proforma Service Bulletin SBF28–28–059, Revision 1, dated July 15, 2014. The service information describes procedures for the installation of additional bonding provisions outside the fuel tank. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

This AD requires revisions to certain operator maintenance documents to include new actions (*e.g.*, inspections) and/or Critical Design Configuration Control Limitations (CDCCLs). Compliance with these actions and/or CDCCLs is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (k) of this AD. The request should include a description of changes to the required

actions that will ensure the continued operational safety of the airplane.

Differences Between This Proposed AD and the MCAI or Service Information

Although EASA Airworthiness Directive 2014–0109, dated May 8, 2014, specifies both revising the maintenance program to include limitations, and doing certain repetitive actions (e.g., inspections) and/or maintaining CDCCLs, this AD only requires the revision. Requiring a revision of the maintenance program, rather than requiring individual repetitive actions and/or maintaining CDCCLs, requires operators to record AD compliance only at the time the revision is made. Repetitive actions and/or maintaining CDCCLs specified in the airworthiness limitations must be complied with in accordance with 14 CFR 91.403(c).

Costs of Compliance

We estimate that this proposed AD affects 5 airplanes of U.S. registry.

We also estimate that it would take about 11 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$140 per product. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$5,375, or \$1,075 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on

the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Fokker Services B.V.: Docket No. FAA–2015–1982; Directorate Identifier 2014–NM–108–AD.

(a) Comments Due Date

We must receive comments by July 30, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F.28 Mark 1000, 2000, 3000, and 4000 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by a design review, which revealed that no controlled bonding provisions are present on a number of critical locations outside the fuel tank. We are issuing this AD to prevent an ignition source in the fuel tank vapor space, which could result in a fuel tank explosion and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Installation of Bonding Provisions

Within 24 months after the effective date of this AD, install additional and improved fuel system bonding provisions, in accordance with the Accomplishment Instructions of Fokker F28 Appendix SB SBF28–28–059/APP01, dated July 15, 2014, of Fokker F28 Proforma Service Bulletin SBF28–28–059, Revision 1, dated July 15, 2014.

(h) Revision of Maintenance or Inspection Program

At the later of the times specified in paragraphs (h)(1) and (h)(2) of this AD: Revise the airplane maintenance or inspection program, as applicable, by incorporating the fuel airworthiness limitation items and critical design configuration control limitations (CDCCLs) specified in paragraph 1.L.(1)(b) of Fokker F28 Appendix SB SBF28–28–059/APP01, dated July 15, 2014, of Fokker F28 Proforma Service Bulletin SBF28–28–059, Revision 1, dated July 15, 2014.

(1) Before further flight, after accomplishing the installation required by paragraph (g) of this AD.

(2) Within 30 days after the effective date of this AD.

(i) No Alternative Actions, Intervals, and/or CDCCLs

After incorporating the revision required by paragraph (h) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, or CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j)(1) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective

actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Fokker B.V. Service's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0109, dated May 8, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-1982.

(2) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on June 4, 2015.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-14230 Filed 6-12-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2014-0197; Airspace Docket No. 14-AGL-5]

Proposed Amendment of Class E Airspace; Michigan

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); withdrawal.

SUMMARY: This action withdraws the NPRM published in the **Federal Register** on May 6, 2014, proposing to amend Class E Airspace in the State of Michigan. The FAA has determined that withdrawal of the NPRM is warranted as additional analysis is needed.

DATES: The proposed rule published May 6, 2014 (79 FR 25756) is withdrawn as of June 15, 2015.

FOR FURTHER INFORMATION CONTACT: Raul Garza, Jr., Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort

Worth, TX 76137; telephone: 817-222-4075.

SUPPLEMENTARY INFORMATION: An NPRM was published in the **Federal Register** of May 6, 2014 (79 FR 25756) to amend Title 14 Code of Federal Regulations (14 CFR) part 71, by amending Class E Airspace extending upward from 1,200 feet above the surface in the State of Michigan, to enable Minneapolis ARTCC to have greater latitude to use radar vectors and/or altitude changes that would provide a more efficient use of airspace within the NAS. Additional analysis is needed; therefore the NPRM is being withdrawn.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Withdrawal

In consideration of the foregoing, the NPRM for FR Doc. FAA-2014-0197, Airspace Docket No. 14-AGL-5, as published in the **Federal Register** of May 6, 2014 (79 FR 25756) (FR Doc. 2014-10336), is hereby withdrawn.

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854; 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

Issued in Fort Worth, TX, on May 26, 2015.

Robert W. Beck,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2015-14317 Filed 6-12-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2014-0198; Airspace Docket No. 14-AGL-8]

Proposed Amendment of Class E Airspace; South Dakota

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); withdrawal.

SUMMARY: This action withdraws the NPRM published in the **Federal Register** on May 6, 2014, proposing to amend Class E airspace in the State of South Dakota. The FAA has determined that withdrawal of the NPRM is warranted as additional analysis is needed.

DATES: The proposed rule published May 6, 2014 (79 FR 25755) is withdrawn as of June 15, 2015.

FOR FURTHER INFORMATION CONTACT: Raul Garza, Jr., Central Service Center,

Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone: 817-222-4075.

SUPPLEMENTARY INFORMATION: An NPRM was published in the **Federal Register** of May 6, 2014 (79 FR 25755) to amend Title 14 Code of Federal Regulations (14 CFR) part 71 by amending Class E Airspace extending upward from 1,200 feet above the surface in the State of South Dakota, to enable Minneapolis ARTCC to have greater latitude to use radar vectors and/or altitude changes that would provide a more efficient use of airspace within the NAS. Additional analysis is needed; therefore the NPRM is being withdrawn.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Withdrawal

In consideration of the foregoing, the NPRM for FR Doc. FAA-2014-0198, Airspace Docket No. 14-AGL-8, as published in the **Federal Register** of May 6, 2014 (79 FR 25755) (FR Doc. 2014-10335) is hereby withdrawn.

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854; 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

Issued in Fort Worth, TX, on May 26, 2015.

Robert W. Beck,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2015-14303 Filed 6-12-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2014-0199; Airspace Docket No. 14-AGL-9]

Proposed Amendment of Class E Airspace; North Dakota

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); withdrawal.

SUMMARY: This action withdraws the NPRM published in the **Federal Register** on May 6, 2014 proposing to amend Class E airspace in the State of North Dakota. The FAA has determined that withdrawal of the NPRM is warranted as additional analysis is needed.

DATES: The proposed rule published May 6, 2014 (79 FR 25757) is withdrawn as of June 15, 2015.