

2015–12–09 Airbus Helicopters

Deutschland GmbH (Previously Eurocopter Deutschland GmbH) (Airbus Helicopters): Amendment 39–18184; Docket No. FAA–2014–0577; Directorate Identifier 2013–SW–042–AD.

(a) Applicability

This AD applies to Airbus Helicopters Model EC135P1, EC135T1, EC135P2, EC135T2, EC135P2+, EC135T2+, and MBB–BK 117 C–2 helicopters, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as loose attachment hardware between the Smart Electro Mechanical Actuator (SEMA) and a control rod. This condition could result in loss of the control axis and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective July 23, 2015.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 50 hours time in service (TIS), for Model EC135P1, EC135T1, EC135P2, EC135T2, EC135P2+, and EC135T2+ helicopters, do the following:

(i) Using Figure 1 and Figure 2 of Eurocopter Alert Service Bulletin EC135–22A–015, Revision 1, dated January 28, 2013 (ASB EC135–22A–015) as reference, inspect the attachment hardware between the SEMA and the longitudinal actuator control rod to determine whether any of the washers can be moved.

(A) If no washer can be moved, no further action is needed.

(B) If a washer can be moved, replace the four screws and install two additional washers, part number (P/N) EN2139–05016, to connect the SEMA with the control rod. Torque-tighten each screw to 5–6 Nm.

(ii) Using Figure 1 and Figure 2 of ASB EC135–22A–015 as reference, inspect the attachment hardware between the SEMA and the lateral actuator control rod to determine whether any of the washers can be moved.

(A) If no washer can be moved, no further action is needed.

(B) If a washer can be moved, replace the four screws and install two additional washers, P/N EN2139–05016, to connect the SEMA with the control rod. Torque-tighten each screw to 5–6 Nm.

(iii) Using Figure 1, Figure 3, and Figure 4 of ASB EC135–22A–015 as reference, inspect the attachment hardware between the SEMA and the yaw actuator control rod to determine whether any of the washers can be moved.

(A) If no washer can be moved, no further action is needed.

(B) If a washer can be moved, replace the four screws and install two additional washers, P/N EN2139–05016, to connect the SEMA with the control rod. Torque-tighten each screw to 5–6 Nm.

(2) Within 50 hours TIS, for Model MBB BK117 C–2 helicopters, using Figure 1 of Eurocopter Alert Service Bulletin MBB BK117 C–2–22A–009, Revision 1, dated August 3, 2009, as reference, inspect the attachment hardware between the Yaw-SEMA and the Yaw-SEMA control rod to determine whether any of the washers can be moved.

(i) If no washer can be moved, no further action is needed.

(ii) If a washer can be moved, replace the four screws and install two additional washers, P/N EN2139–05016, to connect the SEMA with the control rod. Torque-tighten each screw to 5–6 Nm and apply polyurethane lacquer onto the attachment hardware.

(f) Credit for Previous Actions

If you performed the actions in Eurocopter Alert Service Bulletin EC135–22A–015, Revision 0, dated May 13, 2018, or Eurocopter Alert Service Bulletin MBB BK117 C–2–22A–009, Revision 0, May 13, 2008, before the effective date of this AD, you met the requirements of this AD.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Wilbanks, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222–5110; email matt.wilbanks@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

The subject of this AD is addressed in the European Aviation Safety Agency (EASA) AD No. 2013–0176, dated August 7, 2013. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA–2014–0577.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 2213, Flight Controller.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Eurocopter Alert Service Bulletin EC135–22A–015, Revision 1, dated January 28, 2013.

(ii) Eurocopter Alert Service Bulletin MBB BK117 C–2–22A–009, Revision 1, dated August 3, 2009.

(3) For Airbus Helicopters service information identified in this AD, contact

Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641–0000 or (800) 232–0323; fax (972) 641–3775; or at <http://www.airbushelicopters.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on June 9, 2015.

Lance T. Gant,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2015–14852 Filed 6–17–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY
Coast Guard**33 CFR Part 117**

[Docket No. USCG–2015–0552]

**Drawbridge Operation Regulation;
Chambers Creek, Steilacoom, WA**

AGENCY: Coast Guard, DHS.

ACTION: Notice of deviation from drawbridge regulation.

SUMMARY: The Coast Guard has issued a temporary deviation from the operating schedule that governs the Burlington Northern Santa Fe (BNSF) Chambers Creek Railway Bridge across Chambers Creek, mile 0.0, at Steilacoom, Washington. The deviation is necessary to minimize the effects of train noise on the 2015 U.S. Golf Association Championship held at Chambers Bay Golf Course. This deviation allows the bridge to open only upon 1 hour notice from 7 a.m. to 4 p.m. on June 14, 2015 and 7 a.m. to 5 p.m. each day from June 15, 2015 to June 22, 2015. At all other times the bridge will open on signal in accordance with its normal operating regulation.

DATES: This deviation is effective without actual notice from June 18, 2015 to 5 p.m. on June 22, 2015. For the purposes of enforcement, actual notice will be used from 7 a.m. on June 14, 2015, until June 18, 2015.

ADDRESSES: The docket for this deviation, [USCG–2015–0552] is available at <http://www.regulations.gov>.

Type the docket number in the "SEARCH" box and click "SEARCH." Click on Open Docket Folder on the line associated with this deviation. You may also visit the Docket Management Facility in Room W12-140 on the ground floor of the Department of Transportation West Building, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this temporary deviation, call or email Steven Fischer, Thirteenth Coast Guard District Bridge Program Administrator; telephone 206-220-7282, *Steven.M.Fischer3@uscg.mil*. If you have questions on viewing the docket, call Cheryl Collins, Program Manager, Docket Operations, telephone 202-366-9826.

SUPPLEMENTARY INFORMATION: The Coast Guard has been requested to issue this bridge deviation to allow BNSF to implement noise reduction operations near the Chambers Bay Golf Course during the 2015 U.S. Golf Association Championship being held there. This deviation allows the BNSF Chambers Creek Railway Bridge to open only upon 1 hour notice from 7 a.m. to 4 p.m. on June 14, 2015 and 7 a.m. to 5 p.m. each day from June 15, 2015 to June 22, 2015. At all other times the bridge will open on signal in accordance with its normal operating regulation. Doing so will minimize the number of trains required to idle while awaiting bridge openings.

The BNSF Chambers Creek Railway Bridge across Chambers Creek, mile 0.0, near Steilacoom, Washington provides 50 feet of vertical clearance in the raised position, 10 feet of vertical clearance in the closed position and 80 feet of horizontal clearance. Reference plan is mean high water elevation of 12.2 feet. The normal operation schedule falls under 33 CFR 117.5.

This deviation is effective from 7 a.m. on June 14, 2015 to 5 p.m. on June 22, 2015. The deviation allows the bridge to open only upon 1 hour notice from 7 a.m. to 4 p.m. on June 14, 2015 and 7 a.m. to 5 p.m. each day from June 15, 2015 to June 22, 2015. At all other times the bridge will open on signal in accordance with its normal operating regulation.

Vessels able to pass through the bridge in the closed positions may do so at anytime. The bridge will be able to open for emergencies and there is no immediate alternate route for vessels to pass. The Coast Guard will also inform the users of the waterway of the change in operating schedule for the bridge through Local and Broadcast Notices to

Mariners so that vessels can arrange their transits to minimize any impact caused by the temporary deviation.

In accordance with 33 CFR 117.35(e), the drawbridge must return to its regular operating schedule immediately at the end of the effective period of this temporary deviation. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: June 11, 2015.

Steven M. Fischer,

Bridge Administrator, Thirteenth Coast Guard District.

[FR Doc. 2015-14882 Filed 6-17-15; 8:45 am]

BILLING CODE 9110-04-P

DEPARTMENT OF VETERANS AFFAIRS

38 CFR Part 2

RIN 2900-AP47

Delegations of Authority: Office of Regulation Policy and Management (ORPM)

AGENCY: Department of Veterans Affairs.

ACTION: Final rule.

SUMMARY: The Department of Veterans Affairs is amending its regulations delegating rulemaking authority within the Office of the General Counsel. The amendments reflect current management structure and titles.

DATES: *Effective Date:* June 18, 2015.

FOR FURTHER INFORMATION CONTACT: William F. Russo, Acting Director, Office of Regulation Policy and Management, Office of the General Counsel, U.S. Department of Veterans Affairs, 810 Vermont Avenue NW., Washington, DC 20420, telephone (202) 461-4902. (This is not a toll-free number.)

SUPPLEMENTARY INFORMATION: In 2014, the Department of Veterans Affairs (VA) Office of the General Counsel was restructured, which included changes in the titles of certain officials involved in VA's rulemaking process. Specifically, matters previously handled by the single Deputy General Counsel are now handled by a Principal Deputy General Counsel and two Deputy General Counsels. This final rule amends 38 CFR 2.6(e)(1) to reflect current management structure and titles.

Administrative Procedure Act

This document's publication as a final rule is pursuant to 5 U.S.C. 553(b)(A), which exempts matters pertaining to agency organization, procedure and practice from notice and public

comment requirements. Also, because this notice concerns only such matters, VA finds pursuant to 5 U.S.C. 553(d)(3) good cause in this case to dispense with the delayed effective date requirement.

Executive Order 12866

Under the exemption in section 3(d)(3) of Executive Order 12866 for regulations limited to agency organization, management, or personnel matters, this document is not subject to the Executive Order's review requirements.

Unfunded Mandates

The Unfunded Mandates Reform Act of 1995 requires, at 2 U.S.C. 1532, that agencies prepare an assessment of anticipated costs and benefits before issuing any rule that may result in expenditure by State, local, and tribal governments, in the aggregate, or by the private sector, of \$100 million or more (adjusted annually for inflation) in any one year. This rule will have no such effect on State, local, and tribal governments, or on the private sector.

Paperwork Reduction Act of 1995

This document contains no provisions constituting a collection of information under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501-3521).

Regulatory Flexibility Act

The initial and final regulatory flexibility analysis requirements of sections 603 and 604 of the Regulatory Flexibility Act, 5 U.S.C. 601-612, are not applicable to this rule, because a notice of proposed rulemaking is not required for this rule. Even so, the Secretary hereby certifies that this regulatory amendment will not have a significant economic impact on a substantial number of small entities as they are defined in the Regulatory Flexibility Act. This amendment will not directly affect any small entities. Therefore, this amendment is also exempt pursuant to 5 U.S.C. 605(b), from the initial and final regulatory flexibility analysis requirements of sections 603 and 604.

Catalog of Federal Domestic Assistance

There are no Catalog of Federal Domestic Assistance program numbers for this rule.

Signing Authority

The Secretary of Veterans Affairs, or designee, approved this document and authorized the undersigned to sign and submit the document to the Office of the Federal Register for publication electronically as an official document of the Department of Veterans Affairs.