

Rules and Regulations

Federal Register

Vol. 80, No. 124

Monday, June 29, 2015

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-0951; Directorate Identifier 2015-CE-007-AD; Amendment 39-18190; AD 2015-13-03]

RIN 2120-AA64

Airworthiness Directives; Przedsiębiorstwo Doswiadczalno- Produkcyjne Szybownictwa "PZL- Bielsko" Sailplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Przedsiębiorstwo Doswiadczalno-Produkcyjne Szybownictwa "PZL-Bielsko" Model SZD-50-3 "Puchacz" sailplanes. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as detachment of the rudder cable fitting block from the fuselage. We are issuing this AD to require actions to address the unsafe condition on these products.

DATES: This AD is effective August 3, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of August 3, 2015.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0951; or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor,

Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

For service information identified in this AD, contact Allstar PZL Glider, Sp. z o. o., ul. Cieszyńska 325, 43-300 Bielsko-Biala, Poland; telephone: +48 33 812 50 26; fax: +48 33 812 37 39; email: techsupport@szd.com.pl; Internet: <http://szd.com.pl/en/products/szd-50-3-puchacz>. You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0951.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to add an AD that would apply to all Przedsiębiorstwo Doswiadczalno-Produkcyjne Szybownictwa "PZL-Bielsko" Model SZD-50-3 "Puchacz" sailplanes. The NPRM was published in the **Federal Register** on April 17, 2015 (80 FR 21191). The NPRM proposed to correct an unsafe condition for the specified products and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country. The MCAI states:

An occurrence was reported involving a SZD-50-3 "Puchacz" sailplane, where a rudder cable fitting block, located in the forward part of the fuselage, detached after application of a high load on the steering pedal during spin recovery operation. Subsequent investigations determined that the failure was either caused by a manufacturing deficiency or originated by a crack.

This condition, if not detected and corrected, could lead to further cases of rudder cable fitting block detachment, resulting in reduced control of the sailplane.

To address this unsafe condition, Allstar PZL issued Service Bulletin (SB) No. BE-063/SZD-50-3/2014, to provide inspection and reinforcement instructions.

For the reasons described above, this AD requires accomplishment of a one-time

inspection of both (right hand (RH) and left hand (LH)) rudder cable fitting blocks to verify proper attachment to the fuselage shell and, depending on finding(s), a repair. This AD also requires reinforcement of the affected structural area.

The MCAI can be found in the AD docket on the Internet at: <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0951-0002>.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (80 FR 21191, April 17, 2015) or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (80 FR 21191, April 17, 2015) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (80 FR 21191, April 17, 2015).

Related Service Information Under 14 CFR Part 51

We reviewed Allstar PZL Glider Service Bulletin BE-063/SZD-50-3/2014 "Puchacz", dated December 14, 2014. The service bulletin describes procedures for inspecting the area around the left-hand and right-hand rudder cable fitting blocks for cracks and detachment and making all necessary repairs. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this AD.

Costs of Compliance

We estimate that this AD will affect 5 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the inspection requirement of this AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the inspection requirement of this AD on U.S. operators to be \$425, or \$85 per product.

In addition, we estimate that it will take about 2 work-hours per product to comply with the modification requirement of this AD and will require parts costing \$100, for a cost of \$270 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0951; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and

other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2015-13-03 Przedsiebiorstwo Doswiadczalno-Produkcyjne Szybownictwa "PZL-Bielsko":
Amendment 39-18190; Docket No. FAA-2015-0951; Directorate Identifier 2015-CE-007-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective August 3, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Przedsiebiorstwo Doswiadczalno-Produkcyjne Szybownictwa "PZL-Bielsko" Model SZD-50-3 "Puchacz" sailplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 27: Flight Controls.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as detachment of the rudder cable fitting block from the fuselage. We are issuing this AD to prevent detachment of the rudder cable fitting block from the fuselage, which if not detected and corrected, could result in reduced control.

(f) Actions and Compliance

Unless already done, do the actions in paragraphs (f)(1) through (f)(3) of this AD:

- (1) Within 30 days after August 13, 2015 (the effective date of this AD), inspect the area around both the left-hand (LH) and the right-hand (RH) rudder cable fitting blocks following paragraph 3.1. of the INSTRUCTIONS section in Allstar PZL

Glider Service Bulletin BE-063/SZD-50-3/2014 "Puchacz", dated December 14, 2014.

(2) If, during the inspection required in paragraph (f)(1) of this AD, any crack or fitting block detachment is found, before further flight, repair and reinforce the attachment of both the LH and RH rudder cable fitting blocks. Do this repair and reinforcement following paragraph 3.2. of the INSTRUCTIONS section in Allstar PZL Glider Service Bulletin BE-063/SZD-50-3/2014 "Puchacz", dated December 14, 2014.

(3) Unless already done following the requirement in paragraph (f)(2) of this AD, within the next 12 months after August 3, 2015 (the effective date of this AD), reinforce the attachment of both the LH and RH rudder cable fitting blocks. Do this reinforcement following paragraph 3.2. of the INSTRUCTIONS section in Allstar PZL Glider Service Bulletin BE-063/SZD-50-3/2014 "Puchacz", dated December 14, 2014.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any sailplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2015-0046, dated March 16, 2015, for related information. You may examine the MCAI on the Internet at: <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0951-0002>.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Allstar PZL Glider Service Bulletin BE-063/SZD-50-3/2014 "Puchacz", dated December 14, 2014.

(ii) Reserved.

(3) For PZL-Bielsko service information identified in this AD, contact Allstar PZL Glider, Sp. z o. o., ul. Cieszyńska 325, 43-300 Bielsko-Biala, Poland; telephone: +48 33 812 50 26; fax: +48 33 812 37 39; email:

techsupport@szd.com.pl; Internet: <http://szd.com.pl/en/products/szd-50-3-puchacz>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0951.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>

Issued in Kansas City, Missouri, on June 18, 2015.

William Schinostock,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-15620 Filed 6-26-15; 8:45 am]

BILLING CODE 4910-13-P

SECURITIES AND EXCHANGE COMMISSION

17 CFR Part 232

[Release Nos. 33-9849; 34-75242; 39-2504; IC-31680]

Adoption of Updated EDGAR Filer Manual

AGENCY: Securities and Exchange Commission.

ACTION: Final rule.

SUMMARY: The Securities and Exchange Commission (the Commission) is adopting revisions to the Electronic Data Gathering, Analysis, and Retrieval System (EDGAR) Filer Manual and related rules to reflect updates to the EDGAR system. The updates are being made primarily to add new submission form types N-CR and N-CR/A for Current Report of Money Market Fund Material Events; update submission form types ABS-15G and ABS-15G/A for Asset-backed securities reporting based on Rule 15Ga-2; no longer display OMB expiration date on submission form types 13F and 13H; no longer provide support for the 2013 US GAAP financial reporting and 2013 EXCH taxonomies; documentation only corrections to Chapter 3, “Index to Forms,” of the “EDGAR Filer Manual, Volume II: EDGAR Filing,” which include adding submission types 8-K12B and 8-K12B/A to Table 3-3, “Securities Exchange Act—Registration and Report Submission Types Accepted by EDGAR”; and documentation only changes to “EDGAR Filer Manual,

Volume II: EDGAR Filing” for Section 508 compliance. The EDGAR system is scheduled to be upgraded to support this functionality on June 15, 2015.

DATES: Effective June 29, 2015. The incorporation by reference of the EDGAR Filer Manual is approved by the Director of the Federal Register as of June 29, 2015.

FOR FURTHER INFORMATION CONTACT: In the Division of Corporate Finance, for questions concerning Form ABS-15G, contact Heather Mackintosh at (202) 551-8111, in the Division of Investment Management, for questions concerning Form N-CR, contact Heather Fernandez at (202) 551-6708, and in the Office of Information Technology, contact Tammy Borkowski at (202) 551-7208.

SUPPLEMENTARY INFORMATION: We are adopting an updated EDGAR Filer Manual, Volume II. The Filer Manual describes the technical formatting requirements for the preparation and submission of electronic filings through the EDGAR system.¹ It also describes the requirements for filing using EDGARLink Online and the Online Forms/XML Web site.

The revisions to the Filer Manual reflect changes within Volume II entitled EDGAR Filer Manual, Volume II: “EDGAR Filing,” Version 32 (June 2015). The updated manual will be incorporated by reference into the Code of Federal Regulations.

The Filer Manual contains all the technical specifications for filers to submit filings using the EDGAR system. Filers must comply with the applicable provisions of the Filer Manual in order to assure the timely acceptance and processing of filings made in electronic format.² Filers may consult the Filer Manual in conjunction with our rules governing mandated electronic filing when preparing documents for electronic submission.³

The EDGAR system will be upgraded to Release 15.2 on June 15, 2015 and will introduce the following changes:

EDGAR will be updated to add new submission form types N-CR and N-CR/A to EDGARLink Online. These new submission form types can be accessed by selecting the ‘EDGARLink Online Form Submission’ link on the

EDGAR Filing Web site. Additionally, filers can construct XML submissions for these submission form types by following the “EDGARLink Online XML Technical Specification” document available on the SEC’s Public Web site (<http://www.sec.gov/info/edgar.shtml>).

Submission form types ABS-15G and ABS-15G/A will be updated based on final Rule 15Ga-2.

The OMB expiration date will no longer be displayed on submission form types 13F-HR, 13F-HR/A, 13F-NT, 13F-NT/A, 13H, 13H-A, 13H-Q, 13H-I, 13H-T, and 13H-R.

EDGAR will no longer provide support for the US-GAAP-2013 and EXCH-2013 taxonomies. Please see <http://www.sec.gov/info/edgar/edgartaxonomies.shtml> for a complete listing of supported standard taxonomies.

Documentation only corrections were made to Chapter 3, “Index to Forms,” of the “EDGAR Filer Manual, Volume II: EDGAR Filing,” which include adding submission types 8-K12B and 8-K12B/A to Table 3-3, “Securities Exchange Act—Registration and Report Submission Types Accepted by EDGAR.”

Documentation only changes were made to “EDGAR Filer Manual, Volume II: EDGAR Filing” for Section 508 compliance.

Along with the adoption of the Filer Manual, we are amending Rule 301 of Regulation S-T to provide for the incorporation by reference into the Code of Federal Regulations of today’s revisions. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

The updated EDGAR Filer Manual will be available for Web site viewing and printing; the address for the Filer Manual is <http://www.sec.gov/info/edgar.shtml>. You may also obtain paper copies of the EDGAR Filer Manual from the following address: Public Reference Room, U.S. Securities and Exchange Commission, 100 F Street, NE., Washington, DC 20549, on official business days between the hours of 10:00 a.m. and 3:00 p.m.

Since the Filer Manual and the corresponding rule changes relate solely to agency procedures or practice, publication for notice and comment is not required under the Administrative Procedure Act (APA).⁴ It follows that the requirements of the Regulatory Flexibility Act⁵ do not apply.

The effective date for the updated Filer Manual and the rule amendments

¹ We originally adopted the Filer Manual on April 1, 1993, with an effective date of April 26, 1993. Release No. 33-6986 (April 1, 1993) [58 FR 18638]. We implemented the most recent update to the Filer Manual on May 11, 2015. See Release No. 33-9773 (May 26, 2015) [80 FR 29942].

² See Rule 301 of Regulation S-T (17 CFR 232.301).

³ See Release No. 33-9773 in which we implemented EDGAR Release 15.1.1. For additional history of Filer Manual rules, please see the cites therein.

⁴ 5 U.S.C. 553(b).

⁵ 5 U.S.C. 601-612.