

5, Fuel Airworthiness Limitations, Revision 01, dated July 9, 2014, or within 60 days after the effective date of this AD, whichever occurs later. Incorporating the requirements of this paragraph terminates the requirements of paragraphs (g) through (k) of this AD.

(m) New Requirement of This AD: No Alternative Actions, Intervals, or CDCCLs

After the maintenance or inspection program has been revised as required by paragraph (l) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, or CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (n)(1) of this AD.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(ii) AMOCs approved previously in accordance with for AD 2012-20-07, are approved as AMOCs for the corresponding provisions of this AD.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0260, dated December 5, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5589.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office—ELAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on March 31, 2016.

Victor Wicklund,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-08367 Filed 4-13-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-5590; Directorate Identifier 2016-NM-018-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000) airplanes. This proposed AD was prompted by reports of undesirable changes in the Reference Airspeed (RAS) Bug, occurring during flight without pilot input. This proposed AD would require replacing the flight control computer (FCC). We are proposing this AD to prevent uncommanded pitch changes, which could result in deviation from a safe flight path.

DATES: We must receive comments on this proposed AD by May 31, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5590; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Assata Dessaline, Aerospace Engineer, Avionics and Services Branch, ANE-172, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7301; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-5590; Directorate Identifier 2016-NM-018-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2016-02,

dated January 20, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000) airplanes. The MCAI states:

There have been numerous reports of uncommanded changes in the Reference Airspeed (RAS) Bug during flight. When the Auto Flight Control System (AFCS) is in a speed mode (CLB, DES, IAS or MACH), the flight director will show vertical guidance to achieve or maintain the reference airspeed. If the autopilot is engaged, the aeroplane will automatically follow that vertical guidance and cause the aeroplane to pitch up or pitch down. Investigation revealed that this uncommanded reference airspeed changes were caused by the FCC that did not correctly read the input data from the Input/Output Concentrator. If not corrected, these

uncommanded pitch changes could create hazard for continued safe flight. This [Canadian] AD mandates installation of a new filter to the Input/Output Circuit Card in the FCC.

Uncommanded pitch changes, if not corrected, could result in deviation from a safe flight path. Corrective actions include replacing the FCC. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5590.

Related Service Information Under 1 CFR Part 51

We reviewed Bombardier Service Bulletin 601R-22-018, Revision A, dated November 3, 2015; and Service Bulletin 670BA-22-009, dated August 7, 2015. The service information describes procedures for replacing the FCCs. This service information is reasonably available because the interested parties have access to it

through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 1,008 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace FCC	3 work-hours × \$85 per hour = \$255 per airplane.	\$2,800	\$3,055	\$3,079,440

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier Inc.: Docket No. FAA-2016-5590; Directorate Identifier 2016-NM-018-AD.

(a) Comments Due Date

We must receive comments by May 31, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000) airplanes, certificated in any category, all serial numbers, that are equipped with a flight control computer (FCC) with a part number and serial number listed in paragraph 1A., Effectivity, of Bombardier Service Bulletin 601R-22-018, Revision A, dated November 3, 2015; or Service Bulletin 670BA-22-009, dated August 17, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto Flight.

(e) Reason

This AD was prompted by reports of undesirable changes in the Reference Airspeed (RAS) bug, occurring during flight without pilot input. We are issuing this AD to prevent uncommanded pitch changes, which could result in deviation from a safe flight path.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replace the FCC for Certain Airplanes

Within 33 months after the effective date of this AD: Remove the FCC from the integrated avionic processor system (IAPS) and replace the FCC in accordance with the Accomplishment Instructions of the applicable service information in paragraph (g)(1) or (g)(2) of this AD:

- (1) Bombardier Service Bulletin 601R-22-018, Revision A, dated November 3, 2015; or
- (2) Bombardier Service Bulletin 670BA-22-009, dated August 17, 2015.

(h) Parts Installation Limitation

As of 12 months after the effective date of this AD, no person may install any FCC having a part or serial number identified in Bombardier Service Bulletin 601R-22-018, Revision A, dated November 3, 2015; or Bombardier Service Bulletin 670BA-22-009, dated August 17, 2015, unless "SB 50" is marked on the FCC modification chart (MOD chart).

(i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin SB 601R-22-018, dated August 17, 2015.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation

(TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2016-02, dated January 20, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5590.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on April 5, 2016.

Suzanne Masterson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-08533 Filed 4-13-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE INTERIOR**Bureau of Indian Affairs****25 CFR Part 30**

**[167A2100DD/AAKC001030/
A0A501010.999900 253G]**

**Notice of Intent To Establish a
Negotiated Rulemaking Committee**

AGENCY: Bureau of Indian Affairs, Interior.

ACTION: Reopening of comment period.

SUMMARY: On November 9, 2015, the Bureau of Indian Education (BIE) published a notice of intent requesting comments and nominations for Tribal representatives for the Accountability Negotiated Rulemaking Committee (Committee). The comment period for this notice of intent closed December 24, 2015. The BIE is reopening the comment period for Tribes to nominate individuals for membership on the Committee and is expanding the scope of what the Committee will address. The BIE also solicits comments on the proposal to establish the Committee, including comments on additional interests not identified in this notice of intent and comments on the expansion of the scope of the Committee.

DATES: Submit nominations for Committee members or written

comments on this notice of intent on or before May 31, 2016.

ADDRESSES: You may submit nominations for Committee members or written comments on this notice of intent by any of the following methods:

- Send comments or nominations to Ms. Sue Bement, Designated Federal Officer, Bureau of Indian Education, 1011 Indian School Road NW., Suite 332, Albuquerque, New Mexico 87104; email: AYPcomments@bia.gov; Telephone: (505) 563-5274; Fax: (505) 563-5281; or
- Hand-carry comments or use an overnight courier service to Manuel Lujan Jr. Building, Building II, Suite 332, 1011 Indian School Road NW., Suite 332, Albuquerque, New Mexico 87104.

FOR FURTHER INFORMATION CONTACT: Ms. Sue Bement, Designated Federal Officer; Telephone: (505) 563-5274; Fax (505) 563-5281.

SUPPLEMENTARY INFORMATION:**I. Background**

On November 9, 2015, we published a notice of intent requesting nominations for a negotiated rulemaking committee to recommend revisions to the existing regulations for BIE's accountability system (80 FR 69161). In that notice of intent, the BIE solicited nominations from Tribes whose students attend BIE-funded schools operated either by BIE or by the Tribe through a contract or grant, to nominate Tribal representatives to serve on the Committee and Tribal alternates to serve when the representative is unavailable.

Since that time, the Every Student Succeeds Act (ESSA), Public Law 114-95, has become law requiring an update to the subject, scope, and issues that the Committee will address.

II. Every Student Succeeds Act (ESSA)

The ESSA reauthorizes and amends the Elementary and Secondary Education Act of 1965 (ESEA). ESSA Section 8007(2) directs the Secretary of the Interior, in consultation with the Secretary of Education, if so requested, to use a negotiated rulemaking process to develop regulations for implementation no later than the 2017-2018 academic year. The regulations will define the standards, assessments, and accountability system consistent with Section 1111 of the ESEA, for BIE-funded schools on a national, regional, or Tribal basis. The regulations will be developed in a manner that considers the unique circumstances and needs of such schools and the students served by such schools.