

by § 25.143(a), and in addition to the requirements of § 25.143(a) and in the absence of other limiting factors, the following special conditions are proposed based on § 25.333(b):

a. The positive limiting load factor must not be less than:

(1) 2.5g for the normal state of the electronic flight control system with the high lift devices retracted up to V_{mo}/M_{mo} . The positive limiting load factor may be gradually reduced down to 2.25g above V_{mo}/M_{mo} .

(2) 2.0g for the normal state of the electronic flight control system with the high lift devices extended.

b. The negative limiting load factor must be equal to or more negative than:

(1) Minus 1.0g for the normal state of the electronic flight control system with the high lift devices retracted.

(2) 0.0g for the normal state of the electronic flight control system with high lift devices extended.

c. Maximum reachable positive load factor wings level may be limited by the characteristics of the electronic flight control system or flight envelope protections (other than load factor protection) provided that:

(1) The required values are readily achievable in turns, and

(2) Wings level pitch up responsiveness is satisfactory.

d. Maximum achievable negative load factor may be limited by the characteristics of the electronic flight control system or flight envelope protections (other than load factor protection) provided that:

(1) Pitch down responsiveness is satisfactory, and

(2) From level flight, 0g is readily achievable or alternatively, a satisfactory trajectory change is readily achievable at operational speeds. For the FAA to consider a trajectory change as satisfactory, the applicant should propose and justify a pitch rate that provides sufficient maneuvering capability in the most critical scenarios.

e. Compliance demonstration with the above requirements may be performed without ice accretion on the airframe.

f. These special conditions do not impose an upper bound for the normal load factor limit, nor does it require that the limiter exist. If the limit is set at a value beyond the structural design limit maneuvering load factor “n” of §§ 25.333(b), 25.337(b) and 25.337(c), there should be a very obvious positive tactile feel built into the controller so that it serves as a deterrent to inadvertently exceeding the structural limit.

Issued in Des Moines, Washington.

Suzanne Masterson,

Acting Manager, Transport Standards Branch, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2019-06647 Filed 4-5-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0188; Product Identifier 2018-NM-174-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747-8F, and 747-8 series airplanes. This AD was prompted by reports of uncommanded movement of the Captain’s and First Officer’s seats. This proposed AD would require, for the Captain’s and First Officer’s seats, repetitive horizontal actuator identifications, repetitive checks of the horizontal movement system (HMS), a detailed inspection of the HMS for certain airplanes, and applicable on-condition actions. This proposed AD would also require an inspection to determine the part number and, if applicable, the serial number of the Captain’s and First Officer’s seats and applicable on-condition actions. This proposed AD would also provide an optional terminating action for the repetitive checks of the HMS for certain airplanes. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by May 23, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA

90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0188.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0188; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3569; email: Brandon.Lucero@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-0188; Product Identifier 2018-NM-174-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received reports of uncommanded movement of the Captain’s and First Officer’s seats. An operator reported that during a takeoff, the First Officer’s seat unlocked from its

seat tracks and moved aft. The First Officer was unable to control the airplane and the Captain took over the controls to avoid a rejected takeoff. The unlocking of the seat from the seat tracks was caused by actuator damage, which was a result of incorrect adjustment of the seat's manual release lever cable, which allowed the clutch mechanism to only partially engage.

In addition, one operator reported that the Captain's seat could not be locked in position after the horizontal position of the seat was adjusted in flight. The seat became unlocked from the track and moved freely forward and aft. Control was given to the First Officer for approach and landing. An inspection found that the horizontal actuator output shaft had broken. When a horizontal actuator output shaft breaks, the pilot cannot prevent seat movement in a forward and aft direction and cannot lock the seat in position. A broken horizontal actuator output shaft is the result of high loads that exceed the design limits that are caused by a stalled motor that can occur due to high mechanical resistance to motion during powered operation of the seat. Foreign object debris (FOD) in the seat tracks is another condition that can result in a stalled motor and cause the horizontal actuator output shaft to break.

This condition, if not addressed, could result in uncommanded movement of the Captain's or First Officer's seat during a critical part of a flight, such as takeoff or landing, and could cause a flight control obstruction or unintended flight control input, which could lead to reduced controllability of the airplane.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Special Attention Service Bulletin 747-25-3644, Revision 1, dated July 17, 2018. This service information describes procedures for an inspection to determine the part number, and, if applicable, the serial number of the Captain's and First Officer's seats and applicable on-condition actions. On-condition actions include an inspection of each seat's fore/aft and vertical manual control levers for looseness; moving the adjustment nut, tightening

the lock nut, readjusting the control lever, and doing a functional test; and installing a serviceable seat.

We also reviewed Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018. This service information describes procedures for repetitive horizontal actuator identifications, repetitive checks of the HMS, a detailed inspection of the HMS, and applicable on-condition actions. On-condition actions include clearing the seat tracks of FOD, an overhaul of the HMS, and checks of the HMS. The service information also describes procedures for an optional terminating action for the repetitive checks by installing a serviceable Captain's or First Officer's seat.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishment of the actions identified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-25-3644, Revision 1, dated July 17, 2018, described previously, except as discussed under "Differences Between this Proposed AD and the Service Information," and except for any differences identified as exceptions in the regulatory text of this proposed AD.

This proposed AD would also require accomplishment of the actions identified as "RC" (required for compliance) in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018, described previously except as discussed under "Differences Between this Proposed AD and the Service Information," and except for any differences identified as exceptions in the regulatory text of this proposed AD.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov>

by searching for and locating Docket No. FAA-2019-0188.

Differences Between This Proposed AD and the Service Information

Where Boeing Special Attention Service Bulletin 747-25-3644, Revision 1, dated July 17, 2018, specifies to do the actions within 72 months after the original issue date of the service bulletin, this proposed AD would require accomplishment of those actions within 36 months after the effective date of this AD. The 36-month compliance time corresponds with the compliance time in Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018. We have determined a 36-month compliance time is appropriate for doing the actions specified in this proposed AD. We have coordinated this difference with Boeing.

The effectivity of Boeing Special Attention Service Bulletin 747-25-3644, Revision 1, dated July 17, 2018; and Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018, is limited to The Boeing Company Model 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747-8F, and 747-8 series airplanes equipped with Ipeco part number series 3A090 and 3A258 Captain's and First Officer's powered seats, line number 699 and on. However, the applicability of this proposed AD includes all The Boeing Company Model 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747-8F, and 747-8 series airplanes. Because the affected parts are rotatable parts, we have determined that these parts could later be installed on airplanes that were initially delivered with acceptable parts, thereby subjecting those airplanes to the unsafe condition. This difference has been coordinated with Boeing.

Costs of Compliance

We estimate that this proposed AD affects 95 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Seat identification (part and serial number).	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$8,075 per seat.
Detailed inspection, horizontal movement system.	1 work-hour × \$85 per hour = \$85, per seat.	0	\$85 per seat	\$8,075 per seat.
Checks, horizontal movement system ...	2 work-hour × \$85 per hour = \$170 per seat, per check cycle.	0	\$170 per seat, per check cycle.	\$16,150 per seat, per check cycle.

We estimate the following costs to do any necessary on-condition actions that would be required. We have no way of determining the number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS *

Action	Labor cost	Parts cost	Cost per product
Overhaul or replacement, horizontal movement system.	Up to 15 work-hours × \$85 per hour = \$1,275, per seat.	Up to \$6,400 per seat	Up to \$7,675 per seat.
Inspection of each seat's fore/aft and vertical manual control levers.	1 work-hour × \$85 per hour = \$85, per seat.	0	\$85 per seat.
Installation of serviceable seats	1 work-hour × \$85 per hour = \$85, per seat.	0	\$85 per seat.
Clearing FOD	1 work-hour × \$85 per hour = \$85, per seat.	0	\$85 per seat.
Functional test, adjusted control lever cable.	1 work-hour × \$85 per hour = \$85, per seat.	0	\$85, per seat.

* The estimated cost for tooling to align an affected seat for adjustment of the control lever cable is up to \$46,064.

We have received no definitive data that would enable us to provide cost estimates for the optional terminating action for the on-condition repetitive checks specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is

normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2019-0188; Product Identifier 2018-NM-174-AD.

(a) Comments Due Date

The FAA must receive comments on this AD action by May 23, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-

400F, 747–8F, and 747–8 series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by reports of uncommanded movement of the Captain's and First Officer's seats. We are issuing this AD to address uncommanded movement of the Captain's and First Officer's seats. An uncommanded seat movement during a critical part of a flight, such as takeoff or landing, could cause a flight control obstruction or unintended flight control input, which could lead to reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Horizontal Actuator Identification, Detailed Inspection, and Repetitive Checks of Horizontal Movement System and On-Condition Actions

Except as specified in paragraph (i) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 747–25–3653, Revision 1, dated October 19, 2018, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–25–3653, Revision 1, dated October 19, 2018.

(h) Seat Identification and On-Condition Actions

Within 36 months after the effective date of this AD, do an inspection of the nameplate on the Captain's and First Officer's seats for the part number, and serial number as applicable, and do all applicable on-condition actions in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–25–3644, Revision 1, dated July 17, 2018. A review of the airplane maintenance records may be used for the seat inspection if the part number and serial number can be conclusively determined from that review.

(i) Exceptions to Service Information Specifications

For purposes of determining compliance with the requirements of this AD: Where Boeing Special Attention Service Bulletin 747–25–3653, Revision 1, dated October 19, 2018, uses the phrase "the original issue date of this service bulletin," this AD requires using "the effective date of this AD."

(j) Terminating Action for Repetitive Inspections

Installation of a serviceable Captain's or First Officer's seat as specified in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–25–3653, Revision 1, dated October 19, 2018, terminates the repetitive inspections required by paragraph (g) of this AD, for that seat only.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (i) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3569; email: Brandon.Lucero@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on April 1, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–06792 Filed 4–5–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0193; Product Identifier 2018–NM–159–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede Airworthiness Directive (AD) 2018–22–13, which applies to certain Airbus SAS Model A350–941 and –1041 airplanes. AD 2018–22–13 requires revising the airplane flight manual (AFM) to provide the flightcrew with updated procedures related to inboard aileron fault operations. Since we issued AD 2018–22–13, we have determined that additional actions are necessary to address the unsafe condition and that additional airplanes are subject to the unsafe condition. This proposed AD would also require modifying the electronic centralized aircraft monitoring (ECAM) procedures by installing an Airbus Temporary Quick Change (ATQC) and activating an ECAM temporary change (ETC). We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by May 23, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS,