

Transport Standards Branch, FAA; or EASA; or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: For any service information referenced in EASA Emergency AD 2019-0040-E that contains RC procedures and tests: Except as required by paragraph (j)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (k) Related Information

For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) Emergency AD 2019-0040-E, dated February 21, 2019.

(ii) [Reserved]

(3) For EASA Emergency AD 2019-0040-E, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); Internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA Emergency AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA Emergency AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA Emergency AD 2019-0040-E may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0115.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on February 25, 2019.

**Dionne Palermo,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019-03723 Filed 3-4-19; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0957; Product Identifier 2018-NM-102-AD; Amendment 39-19570; AD 2019-03-18]

RIN 2120-AA64

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all Airbus SAS Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; and Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes. This AD was prompted by reports of cracks that were found after improperly performed magnetic particle inspections of the main landing gear (MLG) sliding tubes were done. This AD requires repetitive general visual inspections of the affected MLG sliding tubes for cracks and replacement if necessary. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective April 9, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 9, 2019.

**ADDRESSES:** For service information identified in this final rule, contact Airbus, Airworthiness Office—EIAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0957.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0957; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday

through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; and Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes. The NPRM published in the **Federal Register** on November 8, 2018 (83 FR 55833). The NPRM was prompted by reports of cracks that were found after improperly performed magnetic particle inspections of the MLG sliding tubes were done. The NPRM proposed to require repetitive general visual inspections of the affected MLG sliding tubes for cracks and replacement if necessary.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0136, dated June 26, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for all Airbus SAS Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; and Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes. The MCAI states:

During a walk-around inspection, prior to aeroplane dispatch, an A320 MLG was found collapsed. Investigation revealed that, following a magnetic particle inspection of the MLG sliding tube, performed improperly during overhaul, cracks were initiated, eventually leading to fatigue fracture. A limited number of MLG sliding tubes have been identified that may have been subject to the same improper inspection during the last overhaul.

This condition, if not detected and corrected, could lead to MLG sliding tube fracture, possibly resulting in MLG collapse,

damage to the aeroplane, and injury to occupants.

To address this potential unsafe condition, Airbus issued the SB [Service Bulletin A320–32–1461], providing instructions for repetitive general visual inspections (GVI) of the affected parts until next overhaul.

For the reasons described above, this [EASA] AD requires repetitive GVI of the affected parts [for cracks] and, depending on findings, replacement.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0957.

**Comments**

We gave the public the opportunity to participate in developing this final rule. We have considered the comments received.

**Support for the NPRM**

Air Line Pilots Association, International (ALPA) stated that it supports the NPRM. Another commenter, Kolby Brown, indicated support for the NPRM.

**Conclusion**

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

**Related Service Information Under 1 CFR Part 51**

Airbus has issued Service Bulletin A320–32–1461, dated April 11, 2018. This service information describes procedures for repetitive general visual inspections of affected MLG sliding tubes and replacement of affected MLG sliding tubes. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Costs of Compliance**

We estimate that this AD affects 817 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS \***

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 2 work-hours × \$85 per hour = \$170 .....	\$0	Up to \$170 .....	Up to \$138,890.

\* Table does not include estimated costs for reporting.

We estimate that it would take about 1 work-hour per product to comply with the reporting requirement in this AD. The average labor rate is \$85 per hour. Based on these figures, we estimate the

cost of reporting the inspection results on U.S. operators to be \$9,945, or \$85 per product.

We estimate the following costs to do any necessary on-condition actions that

would be required based on the results of any required actions. We have no way of determining the number of aircraft that might need these on-condition actions:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
19 work-hours × \$85 per hour = \$1,615 .....	\$185	\$1,800

**Paperwork Reduction Act**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120–0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800

Independence Ave. SW, Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES–200.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on

the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2019-03-18 Airbus SAS:** Amendment 39-19570; Docket No. FAA-2018-0957; Product Identifier 2018-NM-102-AD.

#### (a) Effective Date

This AD is effective April 9, 2019.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Airbus SAS Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; and Model A320-211, -212, -214, -216, -231, -232, and

-233 airplanes, certificated in any category, all manufacturer serial numbers.

#### (d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

#### (e) Reason

This AD was prompted by reports of cracks that were found after improperly performed magnetic particle inspections of the main landing gear (MLG) sliding tubes were done. We are issuing this AD to address this condition, which could result in fracture of the MLG sliding tube, possibly resulting in MLG collapse, damage to the airplane, and injury to occupants.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Definitions

For the purposes of this AD, the definitions specified in paragraphs (g)(1) and (g)(2) of this AD apply.

(1) An affected part is any MLG sliding tube, having a part number (P/N) and serial number (S/N) listed in Figure 1 to paragraph (g)(1) of this AD, that has been last overhauled between October 27, 2003, and September 21, 2009, inclusive.

**Figure 1 to paragraph (g)(1) of this AD – Affected parts: P/N and**

S/N

Part number	Serial number	Part number	Serial number	Part number	Serial number
201160302	1071	201371302	B198-4649	201371304	B0544888
201160302	1116B	201371302	B274-4849	201371304	B0751922
201160302	73B	201371302	B225-4715	201371304	B1392028
201160302	1309B	201371302	B228-4755	201371304	B1655066
201160302	1024B	201371302	1801B	201371304	B1025007
201160302	64B	201371302	4441B	201371304	B994937
201160324	B2414670	201371302	B197-4656	201371304	B019-05
201160324	B013-4846	201371302	B210-4687	201371304	B1261991
201160324	B235-4749	201371302	B227-4697	201371304	B123-4994
201160324	1321B	201371302	SS4353B	201371304	B0334860
201160324	MAL1161	201371302	SS4375	201371304	B0234843
201160324	1057	201371304	B168-1948	201371304	B0364875
201160324	MAL-1315	201371304	B951935	201371304	B042-1899
201160324	12088	201371304	B003-4830	201371304	B554896
201160324	1693B	201371304	B005-4815	201371304	B0474885
201371302	B2584800	201371304	B006-4819	201371304	B0494851
201371302	B210-4684	201371304	B0181916	201371304	B0924936
201371302	B196-1879	201371304	B0211889	201371304	B1064967
201371302	B241-4668	201371304	B0311902	201371304	B1054968
201371302	B264-4787	201371304	B026-1895	201371304	B1081962
201371302	B265-4808	201371304	B029-1904	201371304	B013-4845
201371302	B2564777	201371304	B006-4829	201371304	B0374865
201371302	B2704816	201371304	B0281900	201371304	B1194983
201371302	B196-1880	201371304	B0254853	201371304	B4675255
201371302	B2714811	201371304	B0271893	201371304	B1111974
201371302	B229-4729	201371304	B0321906		
201371302	B261-4810	201371304	B003-4821		
201371302	B2724797	201371304	B009-4818		

(2) Group 1 airplanes are those that have an affected part installed. Group 2 airplanes are those that do not have an affected part installed.

**(h) Repetitive Inspections**

For Group 1 airplanes: Within 500 flight cycles after the effective date of this AD, and, thereafter, at intervals not to exceed 500 flight cycles, accomplish a general visual inspection for cracks of each affected part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-32-1461, dated April 11, 2018.

**(i) Corrective Action**

If any crack is found during any inspection required by paragraph (h) of this AD: Before further flight, replace the affected part, in

accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-32-1461, dated April 11, 2018.

**(j) Terminating Action for Certain Actions Required by Paragraph (h) of This AD**

Accomplishment of an overhaul of an affected part after September 21, 2009, constitutes terminating action for the repetitive general visual inspections required by paragraph (h) of this AD for that affected part.

**(k) Reporting**

Submit a report of findings (both positive and negative) of the inspections specified in paragraph (h) of this AD to Airbus, in accordance with Airbus Service Bulletin A320-32-1461, dated April 11, 2018, at the

applicable time specified in paragraph (k)(1) or (k)(2) of this AD. If operators have reported findings as part of obtaining any corrective actions approved by Airbus SAS's European Aviation Safety Agency (EASA) Design Organization Approval (DOA), operators are not required to report those findings as specified in this paragraph.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

**(l) Exception to Paragraphs (h) and (i) of This AD**

An airplane embodying Airbus Modification 161202 (Evolution (EV) MLG) is not affected by the requirements of paragraphs (h) and (i) of this AD, provided it is determined that no affected parts are installed on that airplane. A review of airplane delivery and/or maintenance records is acceptable to make this determination, provided those records can be relied upon for that purpose and the part number and serial number of the MLG sliding tube can be positively identified from that review.

**(m) Parts Installation**

(1) For Group 1 airplanes: From the effective date of this AD, it is allowed to install on any airplane an affected part, or an MLG equipped with an affected part, provided that, within the last 500 flight cycles before installation, the part passed an inspection specified in paragraph (h) of this AD, and that, following installation, the part is inspected as required by this AD.

(2) For Group 2 airplanes: From the effective date of this AD, do not install on any airplane an affected part.

**(n) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (o)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by The Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

**(o) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0136, dated June 26, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0957.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

**(p) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A320-32-1461, dated April 11, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on February 14, 2019.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019-03414 Filed 3-4-19; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

**[Docket No. FAA-2017-0347; Airspace Docket No. 17-AAL-3]**

**RIN 2120-AA66**

**Modification of Class E Airspace for the Following Alaska Towns; Hooper Bay, AK; Kaltag, AK; King Salmon, AK; Kodiak, AK; Manokotak, AK; and Middleton Island, AK**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies Class E airspace extending upward from 1,200 feet above the surface at Hooper Bay Airport, AK; Kaltag Airport, AK; King Salmon Airport, AK; Kodiak Airport, AK; Manokotak Airport, AK; and Middleton Island Airport, AK. This action adds exclusionary language to the legal descriptions of these airports to exclude Class E airspace extending beyond 12 miles from the shoreline and ensures the safety and management of aircraft within the National Airspace System. Also, an editorial change is made in the airspace designation for King Salmon Airport. This action also corrects an error in the coordinates of Kodiak Airport and the Middleton Island VOR/DME.

**DATES:** Effective 0901 UTC, June 20, 2019. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11C, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For