

access to Government information and services, and for other purposes.

USDA has not identified any relevant Federal rules that duplicate, overlap or conflict with this proposed rule.

Further, the Board's meeting was widely publicized throughout the almond industry, and all interested persons were invited to attend the meeting and participate in Board deliberations. Like all Board meetings, the December 4, 2017, meeting was a public meeting, and all entities, both large and small, were able to express their views on this issue.

Also, the Board has a number of appointed committees to review certain issues and make recommendations to the Board. The Committee met on November 16, 2017, and discussed this issue in detail. That meeting was also a public meeting, and both large and

small entities were able to participate and express their views.

Finally, interested persons are invited to submit comments on this proposed rule, including the regulatory and information collection impacts of this action on small businesses.

A small business guide on complying with fruit, vegetable, and specialty crop marketing agreements and orders may be viewed at: <http://www.ams.usda.gov/rules-regulations/moa/small-businesses>. Any questions about the compliance guide should be sent to Richard Lower at the previously mentioned address in the **FOR FURTHER INFORMATION CONTACT** section.

A 30-day comment period is provided to allow interested persons to respond to this proposal. All written comments timely received will be considered before a final determination is made on this matter.

List of Subjects in 7 CFR Part 981

Almonds, Marketing agreements, Nuts, Reporting and recordkeeping requirements.

For the reasons set forth in the preamble, 7 CFR part 981 is proposed to be amended as follows:

PART 981—ALMONDS GROWN IN CALIFORNIA

■ 1. The authority citation for 7 CFR part 981 continues to read as follows:

Authority: 7 U.S.C. 601–674.

■ 2. In § 981.401, revise the table in paragraph (b) and add paragraph (c) to read as follows:

§ 981.401 Adjusted kernel weight.

* * * * *
(b) * * *

	Computation No. 1		Computation No. 2	
	Deliveries with less than 95 percent kernels		Deliveries with 95 percent or more kernels	
	Percent of sample	Weight (pounds)	Percent of sample	Weight (pounds)
1. Actual gross weight of delivery		10,000		10,000
2. Percent of edible kernel weight	53.000		84.000	
3. Less weight loss in processing ¹	1.000		0.000	
4. Less excess moisture of edible kernels (excess moisture × line 2)	1.060		1.680	
5. Net percent shell out (line 2 – lines 3 and 4)	50.940		82.320	
6. Net edible kernels (line 5 × line 1)		5,094		8,232
7. Percent of inedible kernels (from sample)	12.000		12.000	
8. Less excess moisture of inedible kernels (excess moisture from sample × line 7)	0.240		0.240	
9. Net percent inedible kernels (line 7 – line 8)	11.760		11.760	
10. Total inedible kernels (line 9 × line 1)		1,176		1,176
11. Adjusted kernel weight (line 6 + line 10)		6,270		9,408

¹ Only applies to deliveries with less than 95 percent kernels.

(c) *Computation Adjustments.* If applicable, adjustments shall be made by rounding such that the sample computation percentages total equals 100 percent. Rounding adjustments shall be made as follows: First adjust the foreign material percentage; if there is no foreign material in the sample, then adjust the excess moisture percentage; or if there is no foreign material or excess moisture in the sample, adjust the inedible kernels percentage.

Dated: April 16, 2018.

Bruce Summers,
Acting Administrator, Agricultural Marketing Service.

[FR Doc. 2018–08249 Filed 4–19–18; 8:45 am]

BILLING CODE 3410–02–P

FEDERAL ELECTION COMMISSION

11 CFR Chapter 113

[Notice 2018–07]

Rulemaking Petition: Former Candidates' Personal Use; Correction

AGENCY: Federal Election Commission.

ACTION: Rulemaking Petition; Notification of Availability; Correction.

SUMMARY: The Federal Election Commission published a Notification of Availability in the **Federal Register** on March 21, 2018 regarding a Petition for Rulemaking it received on February 5, 2018. The petition asked the Commission to revise and amend the existing rules concerning the personal use of campaign funds, specifically to clarify the application of those rules to former candidates and officeholders. The published document contained

errors in the **ADDRESSES** and **SUPPLEMENTARY INFORMATION** captions.

FOR FURTHER INFORMATION CONTACT: Mr. Robert M. Knop, Assistant General Counsel, 1050 First Street NE, Washington, DC 20463, (202) 694–1650 or (800) 424–9530.

CORRECTION: In the **Federal Register** of March 21, 2018, 83 FR 12283, in the **ADDRESSES** caption, in the first column, correct the first paragraph to read:

ADDRESSES: All comments must be in writing. Commenters are encouraged to submit comments electronically via the Commission's website at <http://sers.fec.gov/fosers/rulemaking.htm?pid=2883684>, which references REG 2018–01. Alternatively, commenters may submit comments in paper form, addressed to the Federal Election Commission, Attn.: Robert M. Knop, Assistant General Counsel, 1050 First Street NE, Washington, DC 20463.

In the **SUPPLEMENTARY INFORMATION** caption, in the third column, correct the first full paragraph to read:

The Commission seeks comments on the petition. The public may inspect the petition on the Commission's website at <http://sers.fec.gov/fosers/rulemaking.htm?pid=2883684>, or in the Commission's Public Records Office, 1050 First Street NE, 12th Floor, Washington, DC 20463, Monday through Friday, from 9 a.m. to 5 p.m.

On behalf of the Commission.

Dated: April 3, 2018.

Caroline C. Hunter,

Chair, Federal Election Commission.

[FR Doc. 2018-08264 Filed 4-19-18; 8:45 am]

BILLING CODE 6715-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9395; Product Identifier 2016-SW-027-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for various Airbus Helicopters Deutschland GmbH (Airbus Helicopters) Model MBB-BK117 and Model BO-105 helicopters. This proposed AD would require removing the swashplate bellows (bellows) and repetitively inspecting the swashplate assembly. This proposed AD is prompted by reports of loose and missing clamps installed on bellows. The proposed actions are intended to detect and prevent an unsafe condition on these products.

DATES: We must receive comments on this proposed AD by June 19, 2018.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- *Fax:* 202-493-2251.

- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9395; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the European Aviation Safety Agency (EASA) AD, the economic evaluation, any comments received, and other information. The street address for Docket Operations (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>.

You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

FOR FURTHER INFORMATION CONTACT: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email matthew.fuller@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or

before the closing date for comments. We will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. We may change this proposal in light of the comments we receive.

Discussion

EASA, which is the aviation authority for Germany, has issued AD No. 2016-0142, dated July 19, 2016, to correct an unsafe condition for Airbus Helicopters Model MBB-BK 117A-1, MBB-BK 117A-3, MBB-BK 117A-4, MBB-BK 117B-1, MBB-BK 117B-2, MBB-BK 117C-1, MBB-BK 117C-2, MBB-BK 117C-2e, BO-105A, BO-105C, BO-105D, BO105S, BO-105LS A-3 helicopters.

EASA advises of several reports of a lower clamp found missing from the bellows and damaging the swashplate bearing ring before becoming detached. EASA states an investigation showed that over-torquing can damage the clamp, which may have caused the clamp to become loose and detach. According to EASA, this condition, if not detected and corrected, could lead to loss of a swashplate clamp, resulting in loss of helicopter control. A detached clamp could damage the swashplate and pitch link or strike the tail rotor. EASA states that its AD is considered interim action and a further AD to implement a terminating action will follow.

FAA's Determination

These helicopters have been approved by the aviation authority of Germany and are approved for operation in the United States. Pursuant to our bilateral agreement with Germany, EASA, its technical representative, has notified us of the unsafe condition described in its AD. We are proposing this AD because we evaluated all known relevant information and determined that an unsafe condition is likely to exist or develop on other products of the same type design.

Related Service Information Under 14 CFR Part 51

We reviewed Airbus Helicopters Alert Service Bulletin (ASB) BO105-40A-107 for Model BO105 C-series, D-series and S-series helicopters; ASB BO105 LS-40A-12 for Model BO-105LS A-3 helicopters; ASB MBB-BK117-40A-115 for Model MBB-BK 117A-1, MBB-BK 117A-3, MBB-BK 117A-4, MBB-BK 117B-1, MBB-BK 117B-2, and MBB-BK 117C-1 helicopters; and ASB MBB-BK117 C-2-62A-007 for Model MBB-BK 117C-2 and MBB-BK 117C-2e helicopters. These ASBs are all Revision 4 and all dated May 23, 2016. We also