

Terminating Action

(j) At the applicable compliance time in paragraph (j)(1) or (j)(2) of this AD, replace any MLG bogie beam pivot pin having P/N 161T1145-2, -3, or -4, with a new, improved pivot pin having P/N 161T1145-5; and do all applicable related investigative and corrective actions before further flight; in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 767-32A0199, Revision 2, dated May 26, 2005. Where the Note at the end of Table 1 in paragraph 1.E., "Compliance," of the service bulletin specifies to contact Boeing for a longer compliance time for "Group 2 airplanes that have been operated at weights less than 353,000 pounds since pivot pin installation": Operators must contact the Manager, Seattle ACO, for an alternative method of compliance in accordance with paragraph (l) of this AD for any requests for a longer compliance time. Doing the replacement in accordance with this paragraph terminates the requirements of this AD for that pivot pin.

(1) For airplanes identified in the service bulletin as Group 1 airplanes: Within 96 months after the effective date of this AD.

(2) For airplanes identified in the service bulletin as Group 2 airplanes: Within 48 months after the effective date of this AD.

Actions Accomplished According to Previous Issues of Service Bulletin

(k) Replacing any pivot pin with a new, improved pivot pin having P/N 161T1145-5, before the effective date of this AD in accordance with the service bulletins identified in Table 1 of this AD is considered acceptable for compliance with the corresponding action specified in this AD.

TABLE 1.—PREVIOUS ISSUES OF SERVICE BULLETIN

Boeing Alert Service Bulletin	Revision	Date
767-32A0199	Original	April 8, 2004.
767-32A0199	1	July 22, 2004.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, Seattle ACO, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(m) You must use Boeing Alert Service Bulletin 767-32A0202, dated July 22, 2004; and Boeing Alert Service Bulletin 767-32A0199, Revision 2, dated May 26, 2005; as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on March 24, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-3194 Filed 4-6-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-23798; Directorate Identifier 2005-NM-162-AD; Amendment 39-14543; AD 2006-07-16]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-400 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier Model DHC-8-400 series airplanes. This AD requires replacing all domed anchor nuts at all attachment locations of the upper fuel access panels of the center wing in the wet bay location with new nuts. This AD results from reported cases of corroded dome anchor nuts at the attachment locations of the upper surface of the fuel access panel of the center wing. We are issuing this AD to prevent corrosion or perforation of domed anchor nuts, which could result in arcing and ignition of fuel vapor in the center wing fuel tank during a lightning strike and consequent explosion of the fuel tank.

DATES: This AD becomes effective May 12, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of May 12, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

George Duckett, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, suite 410, Westbury, New York 11590; telephone (516) 228-7325; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Bombardier Model DHC-8-400 series airplanes. That NPRM was published in the **Federal Register** on February 8, 2006 (71 FR 6411). That NPRM proposed to require replacing all domed anchor nuts at all attachment locations of the upper fuel access panels of the center wing in the wet bay location with new nuts.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Change to NPRM

We have revised the telephone number in the **FOR FURTHER INFORMATION CONTACT** paragraph.

Conclusion

We have carefully reviewed the available data, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

This AD will affect about 20 airplanes of U.S. registry. The required actions will take about 62 work hours per airplane, at an average labor rate of \$65 per work hour. Required parts will cost about \$300 per airplane. Based on these figures, the estimated cost of the AD for U.S. operators is \$86,600, or \$4,330 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under

Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The Federal Aviation Administration (FAA) amends § 39.13

by adding the following new airworthiness directive (AD):

2006-07-16 Bombardier, Inc. (Formerly de Havilland, Inc.): Amendment 39-14543. Docket No. FAA-2006-23798; Directorate Identifier 2005-NM-162-AD.

Effective Date

- (a) This AD becomes effective May 12, 2006.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Bombardier Model DHC-8-400 series airplanes, certificated in any category; serial numbers 4001, and 4003 through 4115 inclusive.

Unsafe Condition

- (d) This AD results from reported cases of corroded dome anchor nuts at the attachment locations of the upper surface of the fuel access panel of the center wing. We are issuing this AD to prevent corrosion or perforation of domed anchor nuts, which could result in arcing and ignition of fuel vapor in the center wing fuel tank during a lightning strike and consequent explosion of the fuel tank.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Replacement With Corrosion Resistant Anchor Nuts

- (f) At the applicable time in Table 1 of this AD, replace all domed anchor nuts at all attachment locations of the upper fuel access panels of the center wing in the wet bay location with new, corrosion-resistant anchor nuts. Do all the actions in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-57-10, Revision "A," dated March 14, 2005.

TABLE 1.—COMPLIANCE TIME

For airplanes having serial number(s)—	On which the inspection(s) specified in—	Do the replacement—
(1) 4108 through 4115 inclusive	None	Within 48 months after the date of issuance of the original standard Canadian airworthiness certificate or the date of issuance of the original Canadian export certificate of airworthiness, or within 2 months after the effective date of this AD, whichever occurs later.
(2) 4001, and 4003 through 4107 inclusive	Bombardier Service Bulletin 84-57-11, dated February 25, 2005; or Revision 'A,' dated March 9, 2005; have been done before the effective date of this AD. Bombardier Service Bulletin 84-57-12, dated March 11, 2005, has been done before the effective date of this AD. Bombardier Service Bulletin 84-57-11, dated February 25, 2005, or Revision 'A,' dated March 9, 2005; or Bombardier Service Bulletin 84-57-12, dated March 11, 2005; has not been done before the effective date of this AD.	Within 24 months after those inspections, or within 2 months after the effective date of this AD, whichever occurs later. Within 48 months after that inspection, or within 2 months after the effective date of this AD, whichever occurs later. Within 3 months after the effective date of this AD.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(h) Canadian airworthiness directive CF-2005-08R1, dated August 10, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(i) You must use Bombardier Service Bulletin 84-57-10, Revision 'A,' dated March 14, 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on March 24, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-3196 Filed 4-6-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-23672; Directorate Identifier 2005-NM-237-AD; Amendment 39-14544; AD 2006-07-17]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 727, 727C, 727-100, 727-100C, and 727-200 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Boeing transport category airplanes. This AD requires determining if the terminal fittings of the spars of the wings are made of 7079 aluminum alloy material. For any positive finding, the AD requires doing repetitive inspections for cracks and corrosion of all exposed surfaces of the terminal fitting bores; doing repetitive inspections for cracks, corrosion, and other surface defects, of all exposed surfaces, including the flanges, of the terminal fitting; applying corrosion inhibiting compound to the terminal fittings; and repairing or replacing any cracked, corroded, or defective part with a new part. This AD also provides for an optional terminating action for the repetitive inspections. This AD results from reports of cracking of the terminal fittings of the spars of the wings. We are issuing this AD to detect and correct stress-corrosion cracking of the terminal fittings, which could result in the failure of one of the terminal fitting connections. Such a failure, combined with a similar failure of one of the other three terminal fittings, could result in the inability of the airplane structure to carry fail-safe loads, which could result in loss of structural integrity of the wing attachment points.

DATES: This AD becomes effective May 12, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of May 12, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Daniel F. Kutz, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6456; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:**Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office

(telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Boeing transport category airplanes. That NPRM was published in the **Federal Register** on January 25, 2006 (71 FR 4069). That NPRM proposed to require determining if the terminal fittings of the spars of the wings are made of 7079 aluminum alloy material. For any positive finding, the NPRM proposed to require doing repetitive inspections for cracks and corrosion of all exposed surfaces of the terminal fitting bores; doing repetitive inspections for cracks, corrosion, and other surface defects, of all exposed surfaces, including the flanges, of the terminal fitting; applying corrosion inhibiting compound to the terminal fittings; and repairing or replacing any cracked, corroded, or defective part with a new part. The NPRM also proposed to provide an optional terminating action for the repetitive inspections.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comment received. The commenter, Boeing, supports the NPRM.

Conclusion

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

Interim Action

This AD is considered to be interim action. The inspection reports that are required by this AD will enable the manufacturer to obtain better insight into the extent of the cracking and corrosion of the terminal fittings of the front and rear spars of the wings in the fleet, and to develop additional action if necessary to address the unsafe condition. If additional action is identified, we may consider further rulemaking.

Costs of Compliance

There are about 302 airplanes of the affected design in the worldwide fleet. This AD will affect about 157 airplanes of U.S. registry. The determination of forging number/material identification will take about 4 work hours per airplane, at an average labor rate of \$65