

(a) Applicability

This AD applies to Model AS332L2 and Model EC225LP helicopters, certificated in any category, with an extended aluminum splice installed on frame 5295, except helicopters with steel splice kit part number 332A08-2649-3072 installed.

Note 1 to paragraph (a) of this AD: Helicopters with Modification (MOD) 0726517 have an extended aluminum splice installed.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack on helicopter frame 5295. This condition could result in structural failure of the frame and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective June 27, 2018.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Before a splice reaches 1,700 hours time-in-service (TIS), within 50 hours TIS, or before the helicopter reaches 11,950 hours TIS, whichever occurs later, do the following:

(i) Install the rail support cut-out and identify the right-hand and left-hand junction profile in accordance with the Accomplishment Instructions, paragraph 3.B.2, of Airbus Helicopters Alert Service Bulletin (ASB) No. EC225-05A038, Revision 0, dated April 15, 2014 (ASB EC225-05A038), or ASB No. AS332-05.00.97, Revision 0, dated April 15, 2014 (ASB AS332-05.00.97), whichever is applicable to your helicopter.

(ii) Inspect each splice for a crack in the area depicted as Area Y in Figure 3 of ASB EC225-05A038 or ASB AS332-05.00.97, whichever is applicable to your helicopter. If a crack exists, repair or replace the splice before further flight.

(2) Thereafter at intervals not to exceed 110 hours TIS, inspect each splice for a crack in the area depicted as Area Y in Figure 3 of ASB EC225-05A038 or ASB AS332-05.00.97. If a crack exists, repair or replace the splice before further flight.

(f) Credit for Actions Previously Completed

Installing rail support cut-outs in accordance with MOD 0728090 or Airbus Helicopters Service Bulletin No. 05-019, Revision 4, dated September 22, 2014, before the effective date of this AD is considered acceptable for compliance with the corresponding actions specified in paragraph (e)(1)(i) of this AD.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Gary Roach, Aviation Safety Engineer, Regulations & Policy Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177;

telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

(1) Airbus Helicopters Service Bulletin (SB) No. 05-019, Revision 4, dated September 22, 2014, and Eurocopter Helicopters (now Airbus Helicopters) SB No. 53-003, Revision 4, and SB No. 53.01.52, Revision 5, both dated July 23, 2010, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2014-0098-E, dated April 25, 2014. You may view the EASA AD on the internet at <http://www.regulations.gov> in Docket No. FAA-2015-3883.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 5310, Fuselage Main, Structure.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Alert Service Bulletin No. EC225-05A038, Revision 0, dated April 15, 2014.

(ii) Airbus Helicopters Alert Service Bulletin No. AS332-05.00.97, Revision 0, dated April 15, 2014.

(3) For Airbus Helicopters service information identified in this AD, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued in Fort Worth, Texas, on May 16, 2018.

Scott A. Horn,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2018-10921 Filed 5-22-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2018-0188; Product Identifier 2018-CE-002-AD; Amendment 39-19285; AD 2018-10-10]

RIN 2120-AA64

Airworthiness Directives; Diamond Aircraft Industries GmbH Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments

SUMMARY: We are superseding Airworthiness Directive (AD) 2017-01-12, AD 2017-11-08, and AD 2017-15-09 for certain Diamond Aircraft Industries GmbH Model DA 42 airplanes. This AD results from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and address an unsafe condition on an aviation product. The MCAI describes the unsafe condition as uncommanded engine shutdown during flight due to failure of the propeller-regulating valve caused by hot exhaust gases coming from fractured engine exhaust pipes. We are issuing this AD to require actions to address the unsafe condition on these products.

DATES: This AD is effective June 12, 2018.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of June 12, 2018.

The Director of the Federal Register approved the incorporation by reference of certain other publications listed in this AD as of May 31, 2017 (82 FR 24843, May 31, 2017) and August 1, 2017 (82 FR 35630, August 1, 2017).

We must receive comments on this AD by July 9, 2018.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.

• **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A-2700 Wiener Neustadt, Austria, telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; internet: <http://www.diamondaircraft.com>. You may review copies of the referenced service information at the FAA, Small Airplane Standards Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <http://www.regulations.gov> by searching for locating Docket No. FAA-2018-0188.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0188; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued AD 2017-01-12, Amendment 39-18779 (82 FR 5359, January 18, 2017) (“AD 2017-01-12”); AD 2017-11-08, Amendment 39-18907 (82 FR 24843, May 31, 2017) (“AD 2017-11-08”), and AD 2017-15-09, Amendment 39-18969 (82 FR 35630, August 1, 2017) (“AD 2017-15-09”). Those ADs required actions intended to address an unsafe condition on certain Diamond Aircraft Industries GmbH Model DA 42 airplanes and was based

on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

Since we issued AD 2017-01-12, AD 2017-11-08, and AD 2017-15-09, the European Aviation Safety Agency (EASA) has issued a new AD.

The EASA, which is the Technical Agent for the Member States of the European Community, has issued AD No. 2017-0254, dated December 21, 2017 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Two cases were reported of uncommanded engine in-flight shutdown (IFSD) on DA 42 aeroplanes. Subsequent investigation identified that these occurrences were due to failure of the propeller regulating valve, caused by hot exhaust gases coming from fractured engine exhaust pipes. The initiating cracks on the exhaust pipes were not detected during previous inspections, since those exhaust pipes are equipped with non-removable heat shields that do not allow inspection for certain sections of the exhaust pipe.

This condition, if not corrected, could lead to further cases of IFSD or overheat damage, possibly resulting in a forced landing, with consequent damage to the aeroplane and injury to occupants.

To address this potential unsafe condition, Diamond Aircraft Industries (DAI) developed an exhaust pipe without a directly attached integral heat shield that allows visual inspection over the entire exhaust pipe length. DAI issued Mandatory Service Bulletin (MSB) 42-120 and relevant Working Instruction (WI) WI-MSB 42-120, providing instructions to install the modified exhaust pipes. As an interim measure, an additional bracket was designed to hold the exhaust pipe in place in case of a pipe fracture. EASA issued AD 2016-0156 (later revised), requiring replacement of the exhaust pipes with pipes having the new design, or installation of the additional brackets.

After EASA AD 2016-0156R1 was issued, cracks were found during inspection on modified exhaust pipes. Further investigation determined that, with the modified exhaust pipe design, vibration leads to cracking. Consequently, DAI published MSB 42-129, providing instructions for inspection of modified exhaust pipes, and EASA issued AD 2017-0090, retaining the requirements of EASA AD 2016-0156R1, which was superseded, and additionally requiring repetitive inspections of modified exhaust pipes and, depending on findings, repair or replacement.

After EASA AD 2017-0090 was issued, cracks were found on additional brackets, as previously installed per DAI WI-MSB 42-120. Prompted by these findings, DAI revised MSB 42-120 and the relevant part of WI-MSB 42-120 (now at Revision 4), providing improved instructions for the installation of brackets, and additional instructions to inspect those brackets. Consequently, EASA issued AD 2017-0120, retaining the requirements of EASA AD 2017-0090, which

was superseded, and additionally requiring those actions for the additional brackets. That [EASA] AD also required reinstallation of the additional brackets in accordance with improved instructions.

Since EASA AD 2017-0120 was issued, it has been determined that installation of additional exhaust pipe brackets, combined with additional inspections, is the most adequate solution to address the original unsafe condition, while it was also established that the modified exhaust pipes without directly attached heat shield are not adequate as replacement parts. Durability analysis of the design is still under investigation and further improvements in the exhaust design are expected.

For the reasons described above, this [EASA] AD partially retains the requirements of EASA AD 2017-0120, which is superseded, removing the option to install a modified exhaust pipe without direct heat shield, and adding inspection requirements for aeroplanes modified in accordance with Section III.2 of DAI WI-MSB 42-120 Revision 3 or later (installation of additional brackets), and for aeroplanes on which an exhaust pipe with directly attached heat shield was re-installed in accordance with DAI OSB 42-131.

You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0188.

Relative Service Information Under 1 CFR Part 51

Diamond Aircraft Industries GmbH (DAI) has issued Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, Work Instruction WI-MSB 42-120, Revision 4, dated December 20, 2018, Mandatory Service Bulletin MSB-42-129, dated May 17, 2017, and Work Instruction WI-OSB 42-131, dated December 20, 2017. DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, and Work Instruction WI-MSB 42-120, Revision 4, dated December 20, 2018, have identical procedures for installing additional engine exhaust pipe clamps with spring washers on original engine exhaust pipes. DAI Work Instruction WI-MSB 42-120, Revision 4, dated December 20, 2018, also includes procedures for inspecting the original engine exhaust pipe for cracks. DAI Mandatory Service Bulletin MSB-42-129, dated May 17, 2017, describes procedures for inspecting the modified engine exhaust pipe for cracks. DAI Work Instruction WI-OSB 42-131, dated December 20, 2017, describes procedures for replacing either the original or the modified engine exhaust pipe if cracks are found. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this AD.

FAA’s Determination and Requirements of This AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

FAA’s Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to

the flying public justifies waiving notice and comment prior to adoption of this rule because affected engine exhaust pipes could crack and cause hot gases to leak from fractured exhaust pipes and lead to an uncommanded engine in-flight shutdown. Therefore, we find good cause that notice and opportunity for prior public comment are impracticable. In addition, for the reason stated above, we find that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the ADDRESSES section.

Include “Docket No. FAA–2018–0188; Directorate Identifier 2018–CE–002–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD will affect 130 products of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS

| Action | Labor cost | Parts cost | Cost per product | Cost on U.S. operators |
|--|---|--------------------------|------------------|------------------------|
| Inspect engine exhaust pipe | 2 work-hours × \$85 = \$170 | N/A | \$170 | \$22,100 |
| Install additional engine exhaust pipe clamps with spring washers. | 4 work-hours × \$85 per hour = \$340 (for both clamps). | \$100 (for both clamps). | 440 | 57,300 |
| Inspect engine exhaust pipe clamps | 2 work-hours × \$85 per hour = \$170 | N/A | 170 | 22,100 |

We estimate the following costs to do any necessary replacements that will be

required based on the results of the inspections. We have no way of

determining the number of airplanes that may need these replacements:

ON-CONDITION COSTS

| Action | Labor cost | Parts cost | Cost per product |
|--|---|----------------------------|------------------|
| Replace cracked engine exhaust pipe | 4 work-hours × \$85 per hour = \$340 | \$1,900 | |
| Replace cracked engine exhaust pipe clamps | 4 work-hours × \$85 per hour = \$340 (for both clamps). | \$100 (for both clamps) .. | \$440 |

We estimate that 20 of the affected airplanes have the “modified exhaust pipes,” Diamond Aircraft Industries P/N D60–9078–06–01_01 or Technify P/N 52–7810–H0014 01, installed that may be subject to replacement by this AD and 110 of the affected airplanes are subject to the initial installation of additional engine exhaust pipe clamps and spring washers, inspections, and the conditional replacement requirement of this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more

detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C.

In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to small airplanes, gliders, balloons, airships, domestic business jet transport airplanes, and associated appliances to the Director of the Policy and Innovation Division.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Amendment 39–18779 (82 FR 5359, January 18, 2017), Amendment 39–18907 (82 FR 24843, May 31, 2017), and Amendment 39–18969 (82 FR 35630, August 1, 2017) and adding the following new AD:

2018–10–10 Diamond Aircraft Industries GmbH: Amendment 39–19285; Docket No. FAA–2018–0188; Directorate Identifier 2018–CE–002–AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective June 12, 2018.

(b) Affected ADs

This AD replaces 2017–01–12, Amendment 39–18779 (82 FR 5359, January 18, 2017) (“AD 2017–01–12”); AD 2017–11–08, Amendment 39–18907 (82 FR 24843, May 31, 2017) (“AD 2017–11–08”), and AD 2017–15–09, Amendment 39–18969 (82 FR 35630, August 1, 2017) (“AD 2017–15–09”).

(c) Applicability

This AD applies to Diamond Aircraft Industries GmbH Model DA 42 airplanes, serial numbers 42.004 through 42.427 and 42.AC001 through 42.AC151, certificated in any category, that have either a TAE 125–02–99 or TAE 125–02–114 engine installed, and:

- (1) are equipped with an original engine exhaust pipe, Diamond Aircraft Industries (DAI) part number (P/N) D60–9078–06–01 or

Technify P/Ns 52–7810–H0001 02, 52–7810–H0001 03, 52–7810–H0001 04; or

- (2) are equipped with a modified engine exhaust pipe DAI P/N D60–9078–06–01_01 or Technify 52–7810–H0014 01.

(d) Subject

Air Transport Association of America (ATA) Code 78: Engine Exhaust.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and address an unsafe condition on an aviation product. It has been determined that installation of additional exhaust pipe brackets, combined with additional inspections, is the most adequate solution to address the original unsafe condition, while it was also established that the modified exhaust pipes without directly attached heat shield are not adequate as replacement parts. Durability analysis of the design is still under investigation and further improvements in the exhaust design are expected. For these reasons, this AD removes the option to install a modified exhaust pipe without direct heat shield, adds inspection requirements for airplanes modified in accordance with Section III.2 of Diamond Aircraft Industries (DAI) WI–MSB 42–120 Revision 3, dated July 6, 2017 (installation of additional brackets), and for airplanes on which an exhaust pipe with directly attached heat shield was re-installed in accordance with DAI Work Instruction WI–OSB 42–131, dated December 20, 2017. The MCAI describes the unsafe condition as uncommanded engine shutdown during flight due to failure of the propeller regulating valve caused by hot exhaust gases coming from fractured engine exhaust pipes. We are issuing this AD to prevent failure of the propeller regulating valve, which could result in forced landing, consequent damage and occupant injury.

(f) Compliance

Unless already done, do the following actions.

- (1) An airplane is only required to have the actions of either (g) or (h) of this AD accomplished depending on the configuration.

- (2) For the purpose of this AD, if the flight hours accumulated since first installation of an affected exhaust pipe or additional exhaust pipe clamp is not known, use the total hours time-in-service (TIS) accumulated on the airplane.

(g) Actions for Airplanes With Installed Original Engine Exhaust Pipes as of June 12, 2018 (the Effective Date of This AD)

See Appendix 1 to AD 2018–10–10 for a chart of required actions. An original engine exhaust pipe is defined in paragraph (c), Applicability, of this AD.

- (1) At the applicable compliance time in paragraphs (g)(1)(i) and (ii) of this AD, and repetitively thereafter at intervals not to exceed 500 hours time-in-service (TIS), inspect the installed engine exhaust pipe. Do this inspection following section III.4—Inspection of exhaust pipe in the INSTRUCTIONS section of DAI Work

Instruction WI–MSB 42–120, Revision 4, dated December 20, 2017.

- (i) *If the engine exhaust pipe has 1,300 hours TIS or less since first installed on an airplane as of June 12, 2018 (the effective date of this AD):* Before or upon accumulating 1,500 hours TIS since the engine exhaust pipe was first installed on an airplane, and repetitively thereafter at intervals not to exceed 500 hours TIS.

- (ii) *If the engine exhaust pipe has more than 1,300 hours TIS since first installed on an airplane as of June 12, 2018 (the effective date of this AD):* Within the next 200 hours TIS after June 12, 2018 (the effective date of this AD), and repetitively thereafter at intervals not to exceed 500 hours time-in-service (TIS).

(2) During any inspection required in paragraph (g)(1) of this AD, if the engine exhaust pipe does not pass the inspection criteria, before further flight replace the engine exhaust pipe following section III.1—Re-installation of Exhaust Pipes with Directly Attached Heat Shield in the INSTRUCTIONS section of DAI Work Instruction WI–OSB 42–131, dated December 20, 2017 (which includes installing additional engine exhaust pipe clamps, an exhaust sheet, and incorporates spring washers). After replacement continue with the 500-hour TIS repetitive inspections.

- (i) If only the engine exhaust pipe heat shield is loose, a one-time single weld is allowed following section III.3—Repair of Heat Shields of DAI P/N D60–9078–06–01/ Technify P/Ns 52–7810–H0001 03 and 52–7810–H0001 04 in the INSTRUCTIONS section of DAI Work Instruction WI–OSB 42–131, dated December 20, 2017. After a repair of the heat shield, if a single weld point is subsequently found cracked, the heat shield is considered to be loose and the exhaust pipe must be replaced. After replacement or repair, continue with the 500-hour TIS repetitive inspections.

- (ii) Engine exhaust pipes re-qualified following section III.2—Re-Qualification of Exhaust Pipes DAI P/N D60–9078–06–01/ Technify P/Ns 52–7810–H0001 02, 52–7810–H0001 03, or 52–7810–H0001 04 in the INSTRUCTIONS section of DAI Work Instruction WI–OSB 42–131, dated December 20, 2017, are considered to have accumulated 1,500 hours TIS.

- (3) Before further flight after the initial inspection required in paragraph (g)(1) of this AD and if no cracks were found or a repair to the exhaust pipe heat shield was done as required in paragraph (g)(2)(i) of this AD, then install additional engine exhaust pipe clamps, DAI P/Ns D60–7806–00–01 and D60–7806–00–02, and exhaust sheet, P/N D60–7806–00–03, and incorporate spring washers. Do the installations following III.2 Action 2—installation of additional exhaust clamp in the INSTRUCTIONS section of DAI Work Instruction WI–MSB 42–120, Revision 3, dated July 6, 2017, or Revision 4, dated December 20, 2017. See figure 1 to paragraph (g)(3) of this AD for additional information on the sequence of installation actions as identified in DAI Work Instruction WI–MSB 42–120, Revision 3, dated July 6, 2017 and Revision 4, dated December 20, 2017.




Figure 1 to paragraph (g)(3) of this AD:
Sequence of Actions for Exhaust Clamp Installation Identified in
DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, and
Revision 4, dated December 20, 2017

(4) During any engine exhaust pipe clamp and exhaust sheet with spring washer installation/replacement required in paragraphs (g)(2), (3), (6), and (7) of this AD, if the exhaust clamp assembly cannot be installed without side force using step 10 of III.2 Action 2—installation of additional exhaust clamp in the INSTRUCTIONS section of DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, or Revision 4, dated December 20, 2017, before further flight contact the FAA at the address specified in paragraph (i) of this AD to obtain and incorporate an FAA-approved repair/modification approved specifically for this AD. The FAA will coordinate with the European Aviation Safety Agency (EASA) and DAI for the development of a repair/modification to address the specific problem.

(5) At the applicable compliance time in paragraphs (g)(5)(i) and (ii) of this AD and repetitively thereafter at intervals not to exceed 25 hours TIS, remove and inspect each engine exhaust clamp for cracks. Do this inspection following III.3 Action 3—Inspection of exhaust clamp for cracks of the INSTRUCTIONS section of DAI Work Instruction WI-MSB 42-120, Revision 3,

dated July 6, 2017, or Revision 4, dated December 20, 2017.

(i) *If the engine exhaust pipe clamp has less than 40 hours TIS since first installed on an airplane as of June 12, 2018 (the effective date of this AD):* Before or upon accumulating 50 hours TIS since the engine exhaust pipe clamp was first installed on an airplane.

(ii) *If the engine exhaust pipe clamp has 40 hours TIS or more since first installed on an airplane as of June 12, 2018 (the effective date of this AD):* Within the next 10 hours TIS after June 12, 2018 (the effective date of this AD).

(6) Before further flight after any inspection required in paragraph (g)(5) of this AD and no crack is found, reinstall the engine exhaust pipe clamp, and incorporate spring washers following III.2 Action 2—installation of additional exhaust clamp in the INSTRUCTIONS section of DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, or Revision 4, dated December 20, 2017. See figure 1 to paragraph (g)(3) of this AD for additional information on the sequence of installation actions as identified in DAI Work Instruction WI-MSB

42-120, Revision 3, dated July 6, 2017, and or Revision 4, dated December 20, 2017. Continue with the 25-hour TIS repetitive inspection as long as no cracks are found.

(7) Before further flight after any inspection required in paragraph (g)(5) of this AD and a cracked engine exhaust pipe clamp is found, replace the cracked engine exhaust pipe clamp with a new engine exhaust pipe clamp and incorporate spring washers following the service instructions specified in paragraph (g)(6) of this AD. All newly installed engine exhaust pipe clamps are subject to an initial 50-hour TIS and repetitive 25-hour TIS inspections for cracks following the service instructions specified in paragraph (g)(5) of this AD.

(h) Actions for Airplanes With Installed Modified Engine Exhaust Pipes as of June 12, 2018 (the Effective Date of This AD)

See Appendix 2 to AD 2018-10-10 for a chart of required actions. A modified engine exhaust pipe is defined in paragraph (c), Applicability, of this AD.

(1) At the applicable compliance time in paragraphs (h)(1)(i) and (ii) of this AD and repetitively thereafter at intervals not to

exceed 50 hours TIS, inspect each engine exhaust pipe for cracks. Do this inspection following I.9 Accomplishment/Instructions in DAI Mandatory Service Bulletin MSB-42-129, dated May 17, 2017.

(i) *If the engine exhaust pipe has less than 40 hours TIS since first installed on an airplane as of June 12, 2018 (the effective date of this AD):* Before or upon accumulating 50 hours TIS since the affected engine exhaust pipe was first installed on an airplane, repetitively thereafter inspect at intervals not to exceed 50 hours TIS.

(ii) *If the engine exhaust pipe has 40 hours TIS or more since first installed on an airplane as of June 12, 2018 (the effective date of this AD):* Within the next 10 hours TIS after June 12, 2018 (the effective date of this AD), repetitively thereafter inspect at intervals not to exceed 50 hours TIS.

(2) If a crack is found during any inspection required by paragraph (h)(1) of this AD, before further flight replace the engine exhaust pipe with an engine exhaust pipe, DAI P/N D60-9078-06-01 or Technify P/Ns 52-7810-H0001 02, 52-7810-H0001 03, or 52-7810-H0001 04. Do the replacement following section III.1—Re-installation of Exhaust Pipes with Directly Attached Heat Shield in the INSTRUCTIONS section of DAI Work Instruction WI-OSB 42-131, dated December 20, 2017, which includes installing additional engine exhaust pipe clamps, an exhaust sheet, and incorporates spring washers.

(3) After installing an engine exhaust pipe, DAI P/N D60-9078-06-01 or Technify P/Ns 52-7810-H0001 02, 52-7810-H0001 03, or 52-7810-H0001 04 (which includes installing additional engine exhaust pipe clamps, an exhaust sheet, and incorporates spring washers), repetitively thereafter inspect at intervals not to exceed 500 hours TIS. Do this inspection following section III.4—Inspection of exhaust pipe in the INSTRUCTIONS section of DAI Work Instruction WI-MSB 42-120, Revision 4, dated December 20, 2017.

(4) During any inspection required in paragraph (h)(3) of this AD, if the engine exhaust pipe does not pass the inspection criteria, before further flight replace the engine exhaust pipe following section III.1—Re-installation of Exhaust Pipes with Directly Attached Heat Shield in the INSTRUCTIONS section of DAI Work Instruction WI-OSB 42-131, dated December 20, 2017 (which includes installing additional engine exhaust pipe clamps, an exhaust sheet, and incorporates spring washers). After replacement, continue with the 500-hour TIS repetitive inspections.

(i) If only the engine exhaust pipe heat shield is loose, a one-time single weld is allowed following section III.3—Repair of Heat Shields of DAI P/N D60-9078-06-01/Technify P/Ns 52-7810-H0001 03 and 52-7810-H0001 04 in the INSTRUCTIONS section of DAI Work Instruction WI-OSB 42-131, dated December 20, 2017. After a repair of the heat shield, if a single weld point is subsequently found cracked, the heat shield is considered to be loose and the exhaust pipe must be replaced. After replacement or repair, continue with the 500-hour TIS repetitive inspections.

(ii) Engine exhaust pipes re-qualified following section III.2—Re-Qualification of Exhaust Pipes DAI P/N D60-9078-06-01/Technify P/Ns 52-7810-H0001 02, 52-7810-H0001 03, or 52-7810-H0001 04 in the INSTRUCTIONS section of DAI Work Instruction WI-OSB 42-131, dated December 20, 2017, are considered to have accumulated 1,500 hours TIS.

(5) During any engine exhaust pipe clamp, exhaust sheet with spring washer installation/replacement required in paragraphs (h)(2), (4), (7), and (8) of this AD, if the exhaust clamp assembly cannot be installed without side force using step 10 of III.2 Action 2—installation of additional exhaust clamp in the INSTRUCTIONS section of DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, or Revision 4, dated December 20, 2017, before further flight contact the FAA at the address

specified in paragraph (i) of this AD to obtain and incorporate an FAA-approved repair/modification approved specifically for this AD. The FAA will coordinate with the European Aviation Safety Agency (EASA) and DAI for the development of a repair/modification to address the specific problem.

(6) At the applicable compliance time in paragraphs (h)(6)(i) and (ii) of this AD and repetitively thereafter at intervals not to exceed 25 hours TIS, remove and inspect each engine exhaust clamp for cracks. Do this inspection following III.3 Action 3—Inspection of exhaust clamp for cracks of the INSTRUCTIONS section of DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, or Revision 4, dated December 20, 2017.

(i) *If the engine exhaust pipe clamp has less than 40 hours TIS since first installed on an airplane as of June 12, 2018 (the effective date of this AD):* Before or upon accumulating 50 hours TIS since the engine exhaust pipe clamp was first installed on an airplane.

(ii) *If the engine exhaust pipe clamp has 40 hours TIS or more since first installed on an airplane as of June 12, 2018 (the effective date of this AD):* Within the next 10 hours TIS after June 12, 2018 (the effective date of this AD).

(7) Before further flight after any inspection required in paragraph (h)(6) of this AD and no crack is found, reinstall the engine exhaust pipe clamp and incorporate spring washers following III.2 Action 2—installation of additional exhaust clamp in the INSTRUCTIONS section of DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, or Revision 4, dated December 20, 2017. See figure 2 to paragraph (g)(7) of this AD for additional information on the sequence of installation actions as identified in DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, and or Revision 4, dated December 20, 2017. Continue with the 25-hour TIS repetitive inspection as long as no cracks are found.




Figure 2 to paragraph (h)(7) of this AD:
Sequence of Actions for Exhaust Clamp Installation Identified in
DAI Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017, and
Revision 4, dated December 20, 2017

(8) Before further flight after any inspection required in paragraph (h)(6) of this AD and a cracked engine exhaust pipe clamp is found, replace the cracked engine exhaust pipe clamp with a new engine exhaust pipe clamp and incorporate spring washers following the service instructions specified in paragraph (h)(7) of this AD. All newly installed engine exhaust pipe clamps are subject to an initial 50-hour TIS and repetitive 25-hour TIS inspections for cracks following the service instructions specified in paragraph (h)(9) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901

Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(j) Related Information

Refer to MCAI EASA AD No. 2017-0254, dated December 21, 2017, for related information. You may examine the MCAI on the internet at <http://www.regulations.gov> by

searching for and locating Docket No. FAA-2018-0188.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on June 12, 2018.

(i) Diamond Aircraft Industries GmbH Work Instruction WI-MSB 42-120, Revision 4, dated December 20, 2017.

(ii) Diamond Aircraft Industries GmbH Work Instruction WI-OSB 42-131, dated December 20, 2017.

(4) The following service information was approved for IBR on May 31, 2017 (82 FR 24843, May 31, 2017).

(i) Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB-42-129, dated May 17, 2017.

(ii) Reserved.

(5) The following service information was approved for IBR on August 1, 2017 (82 FR 35630, August 1, 2017).

(i) Diamond Aircraft Industries GmbH Work Instruction WI-MSB 42-120, Revision 3, dated July 6, 2017.

(ii) Reserved.

(6) For Diamond Aircraft Industries GmbH service information identified in this AD,

contact Diamond Aircraft Industries GmbH, N.A. Otto-Strasse 5, A-2700 Wiener Neustadt, Austria, telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; internet: <http://www.diamondaircraft.com>.

(7) You may view this service information at FAA, Small Airplane Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <http://www.regulations.gov>

by searching for locating Docket No. FAA-2018-0188.

(8) You may view the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

BILLING CODE 4910-13-P

Appendix 1 to AD 2018-10-10


Actions for Airplanes With Installed Original Engine Exhaust Pipes, Diamond Aircraft Industries (DAI) P/N D60-9078-06-01 or Technify P/Ns 52-7810-H0001 02, 52-7810-H0001 03, or 52-7810-H0001 04

Repetitively Inspect Engine Exhaust Pipes for Cracks and Replace or Repair as Required

Install Engine Exhaust Pipe Clamps and Spring Washers on Engine Exhaust Pipes

Repetitively Inspect Engine Exhaust Pipe Clamps for Cracks and Replace as Necessary

Appendix 2 to AD 2018-10-10



Issued in Kansas City, Missouri, on May 11, 2018.

Melvin J. Johnson,

*Aircraft Certification Service, Deputy
Director, Policy and Innovation Division,
AIR-601.*

[FR Doc. 2018-10580 Filed 5-22-18; 8:45 am]

BILLING CODE 4910-13-C

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2018-0447; Product
Identifier 2018-NM-080-AD; Amendment
39-19290; AD 2018-11-02]

RIN 2120-AA64

**Airworthiness Directives; Lockheed
Martin Corporation/Lockheed Martin
Aeronautics Company**

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Final rule; request for
comments.

SUMMARY: We are adopting a new
airworthiness directive (AD) for all
Lockheed Martin Corporation/Lockheed
Martin Aeronautics Company Model
188A and 188C airplanes; and Model
P3A, P-3A, and P3B airplanes type
certificated under various other type
certificate holders. Certain variants of
Model 188A and 188C airplanes are
known as “P-3” series airplanes. P-3
series airplanes include but are not
limited to Model CP-140, NP-3A, P3A,
P-3A, P3B, P-3B, P-3C, P-3P, and WP-
3D airplanes. This AD requires a
borescope inspection of the aileron