

Issued in Des Moines, Washington, on June 12, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division,  
Aircraft Certification Service.

[FR Doc. 2018-13477 Filed 7-5-18; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0585; Product Identifier 2018-NM-070-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc., Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. This proposed AD was prompted by reports that non-conforming FIREX squib wire harness connectors may have been installed, which could result in FIREX squib wire harness connectors being connected to the wrong FIREX bottle connectors on affected aircraft. This proposed AD would require a visual inspection of the connections between the FIREX squib wire harness connectors and FIREX bottle connectors, installation of split ring lanyards on the FIREX squib wire harness connectors, and corrective actions if necessary. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by August 20, 2018.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval,

Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0585; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** John DeLuca, Aerospace Engineer, Avionics and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7369; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2018-0585; Product Identifier 2018-NM-070-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

##### Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2018-08R1, dated March 2, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition

for certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. The MCAI states:

Bombardier, Inc., has been made aware that non-conforming squib connector wire harnesses may have been installed on one of the two engine FIREX bottle installations on some of the affected aeroplanes. The subject non conformity of squib connector wire length can allow cross connection between the two squib connectors on one of the engine FIREX bottles, preventing proper function of the engine FIREX system.

In the event of an engine fire, this wiring discrepancy may potentially misroute the supply of fire extinguishing agent to the wrong engine, or limit the supply from both FIREX bottles to only one engine, [and could result in the inability to extinguish an engine fire,] hence impacting the operational safety of the aeroplane.

Bombardier, Inc., issued service bulletins (SB) 700-26-011, 700-26-5003, 700-26-6003, and 700-1A11-26-004, for the affected model aeroplanes, to address the potentially unsafe condition caused by the non-conforming FIREX bottle squib connector wiring.

The original version of this [Canadian] AD was issued to mandate compliance with the above-mentioned SBs, as applicable.

Revision 1 of this [Canadian] AD is issued to correct an error in the applicability section of the original AD.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0585.

#### Related Service Information Under 14 CFR Part 51

We reviewed the following service information:

- Bombardier Service Bulletin 700-1A11-26-004, Revision 01, dated February 15, 2018.
- Bombardier Service Bulletin 700-26-011, Revision 01, dated February 15, 2018.
- Bombardier Service Bulletin 700-26-5003, Revision 01, dated February 15, 2018.
- Bombardier Service Bulletin 700-26-6003, Revision 01, dated February 15, 2018.

This service information describes procedures for a visual inspection of the connections between the FIREX squib wire harness connectors and the FIREX bottle connectors to determine whether the connectors are installed correctly, and installation of split ring lanyards on the FIREX squib wire harness connectors. This service information also describes procedures for re-connecting incorrectly installed connectors to the appropriate mating connectors and an operational test of the fire extinguishing system. These documents are distinct since they apply

to different airplane models in different configurations. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination**

This product has been approved by the aviation authority of another country, and is approved for operation

in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type designs.

**Proposed AD Requirements**

This proposed AD would require accomplishing the actions specified in the service information described previously.

**Costs of Compliance**

We estimate that this proposed AD affects 358 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection/Modification .....	2 work-hours × \$85 per hour = \$170 .....	\$55	\$225	\$80,550

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all known costs in our cost estimate.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Bombardier, Inc.:** Docket No. FAA–2018–0585; Product Identifier 2018–NM–070–AD.

**(a) Comments Due Date**

We must receive comments by August 20, 2018.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes, certificated in any category, serial numbers 9001 through 9839 inclusive, and serial number 9998.

**(d) Subject**

Air Transport Association (ATA) of America Code 26, Fire protection.

**(e) Reason**

This AD was prompted by reports that non-conforming FIREX squib wire harness connectors may have been installed, which could result in FIREX squib wire harness connectors being connected to the wrong FIREX bottle connectors on affected aircraft. We are issuing this AD to address this wiring discrepancy, which, in the event of an engine fire, could result in misrouting the supply of fire extinguishing agent to the wrong engine, or limit the supply from both FIREX bottles to only one engine, which could result in the inability to extinguish an engine fire.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Within 1,000 flight hours or 15 months, whichever occurs first, after the effective date of this AD, perform a visual inspection for correct connections between the FIREX squib wire harness connectors and FIREX bottle connectors, and install split ring lanyards on the FIREX squib wire harness connectors, in accordance with the Accomplishment Instructions of the applicable service information listed in figure 1 to paragraph (g) of this AD. If any incorrect connections are

found: Before further flight, re-connect the connectors to the appropriate mating connectors and do an operational test of the

fire extinguishing system, in accordance with the Accomplishment Instructions of the

applicable service information specified in figure 1 to paragraph (g) of this AD.

**Figure 1 to paragraph (g) of this AD – Service Information Applicability**

<b>Airplane Model</b>	<b>Bombardier Service Information</b>
BD-700-1A10	Service Bulletin 700-26-011, Revision 01, dated February 15, 2018
BD-700-1A10	Service Bulletin 700-26-6003, Revision 01, dated February 15, 2018
BD-700-1A11	Service Bulletin 700-1A11-26-004, Revision 01, dated February 15, 2018
BD-700-1A11	Service Bulletin 700-26-5003, Revision 01, dated February 15, 2018

**(h) Credit for Previous Actions**

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the applicable service information listed in paragraphs (h)(1) through (h)(4) of this AD.

(1) Bombardier Service Bulletin 700-1A11-26-004, dated December 28, 2017.

(2) Bombardier Service Bulletin 700-26-011, dated December 28, 2017.

(3) Bombardier Service Bulletin 700-26-5003, dated December 28, 2017.

(4) Bombardier Service Bulletin 700-26-6003, dated December 28, 2017.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by

the DAO, the approval must include the DAO-authorized signature.

**(j) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2018-08R1, dated March 2, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0585.

(2) For more information about this AD, contact John DeLuca, Aerospace Engineer, Avionics and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7369; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on June 25, 2018.

**Dionne Palermo,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018-14401 Filed 7-5-18; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2018-0553; Product Identifier 2017-NM-138-AD]

RIN 2120-AA64

**Airworthiness Directives; Bombardier, Inc., Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt an airworthiness directive (AD) for certain Bombardier, Inc., Model DHC-8-102, -103, and -106 airplanes, Model DHC-8-200 series airplanes, and Model DHC-8-300 series airplanes. This proposed AD was prompted by reports of arcing and smoke emanating from the windshield, caused by loose or damaged windshield heater terminal lugs. This proposed AD would require revising the maintenance or inspection program to incorporate maintenance review board (MRB) tasks for general visual inspections of the windshield moisture seal. This proposed AD would also require re-torquing the windshield heater terminal lugs, applying a coating to the windshield heater screw heads, doing a chemical cleaning of the wiring and components, doing a visual inspection of the wiring and components, doing an operational test of the pilot's and co-pilot's windshield heating system, and repair if necessary.