

it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Gulfstream Aerospace Corporation: Docket 96–NM–143–AD.

Applicability: All Model G–159 airplanes, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct corrosion and cracking of the spot-welded skins of the lower wing plank splices and certain structural assemblies, which could result in reduced controllability of the airplane, accomplish the following:

Note 1: A note in the Accomplishment Instructions of the Gulfstream customer bulletin instructs operators to contact Gulfstream if any difficulty is encountered in accomplishing the customer bulletin. However, any deviation from the instructions provided in the customer bulletin must be approved as an alternative method of compliance (AMOC) under paragraph (h) of this AD.

Non-Destructive Testing Inspections of the Fuselage, Empennage, and Flight Controls

(a) Within 9 months after the effective date of this AD, perform a non-destructive test

(NDT) to detect corrosion of the skins of the elevators, ailerons, rudder and rudder trim tab, flaps, aft lower fuselage, and vertical and horizontal stabilizers; in accordance with the Accomplishment Instructions of Gulfstream GI Customer Bulletin (CB) 337B, including Appendix A, dated August 17, 2005. The corrosion criteria must be determined by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Gulfstream Tool ST905–377 is also an acceptable method of determining the corrosion criteria.

(1) If no corrosion or cracking is detected, repeat the inspection thereafter at intervals not to exceed 18 months.

(2) If any corrosion is detected that meets the criteria of "light" or "mild" corrosion, repeat the NDT inspections of that component thereafter at intervals not to exceed 12 months.

(3) If any corrosion is detected that meets the criteria of "moderate" corrosion: Within 9 months after the initial inspection, repeat the NDT inspection of that component, and within 18 months since the initial inspection, repair or replace the component with a serviceable component in accordance with the CB.

(4) If any corrosion is detected that meets the criteria of "severe" corrosion, before further flight, replace the component with a serviceable component in accordance with the CB.

Existing Repairs

(b) If any existing repairs are found during the inspections required by paragraph (a) of this AD, before further flight, ensure that the repairs are in accordance with a method approved by the Manager, Atlanta ACO.

Inspections of the Lower Wing Plank

(c) Except as provided in paragraph (f) of this AD: Within 9 months after the effective date of this AD, perform NDT inspections to detect corrosion and cracking of the lower wing plank splices, in accordance with the Accomplishment Instructions of Gulfstream GI CB 337B, including Appendix A, dated August 17, 2005.

(1) If no corrosion or cracking is detected, repeat the NDT inspection at intervals not to exceed 18 months.

(2) If any corrosion or cracking is detected, before further flight, perform all applicable investigative actions and corrective actions in accordance with the customer bulletin.

Repair Removal Threshold

(d) For repairs specified in Appendix A of Gulfstream GI CB 337B, dated August 17, 2005: Within 144 months after the date of the repair installation, remove the repaired component and replace it with a new or serviceable component, in accordance with Gulfstream GI CB 337B, including Appendix A, dated August 17, 2005.

Prior Blending in the Riser Areas

(e) If, during the performance of the inspections required by paragraph (c) or (f) of this AD, the inspection reveals that prior blending has been performed on the riser areas: Before further flight, perform an eddy current or fluorescent penetrant inspection, as applicable, to evaluate the blending, and accomplish appropriate corrective actions, in

accordance with the Accomplishment Instructions of Gulfstream GI CB 337B, including Appendix A, dated August 17, 2005. If any blend-out is outside the limits specified in the CB, before further flight, repair in a manner approved by the Manager, Atlanta ACO.

For Airplanes With New Lower Wing Planks

(f) For airplanes with new lower wing planks: Within 144 months after replacement of the lower wing planks with new lower wing planks, or within 9 months after the effective date of this AD, whichever occurs later, perform all of the actions, including any other related investigative actions and corrective actions, specified in paragraph (c) of this AD.

Reporting Requirement

(g) Within 30 days of performing the inspections required by this AD: Submit a report of inspection findings (both positive and negative) to Gulfstream Aerospace Corporation; Attention: Technical Operations—Structures Group, Dept. 893, Mail Station D–25, 500 Gulfstream Road, Savannah, Georgia 31408. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120–0056.

Alternative Methods of Compliance

(h)(1) The Manager, Atlanta ACO, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Issued in Renton, Washington, on June 30, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6–10911 Filed 7–11–06; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2006–25328; Directorate Identifier 2006–NM–130–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier Model DHC–8–400 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier Model DHC-8-400 series airplanes. This proposed AD would require inspecting for fouling and chafing damage of the outboard brake control cable of the main landing gear, replacing the control cable if necessary, reworking the control cable cover, and, if applicable, manufacturing/installing an offset plate on the control cable cover. This proposed AD is prompted by a review of brake control cable operation conducted by the manufacturer. We are proposing this AD to prevent abrasion and wear of the outboard brake control cable, which could lead to cable separation and reduced control of airplane braking.

DATES: We must receive comments on this proposed AD by August 11, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- **DOT Docket Web site:** Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- **Government-wide rulemaking Web site:** Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- **Mail:** Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL-401, Washington, DC 20590.

- **Fax:** (202) 493-2251.

- **Hand Delivery:** Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada, for service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Ezra Sasson, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, suite 410, Westbury, New York 11590; telephone (516) 228-7320; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the

ADDRESSES section. Include the docket number "FAA-2006-25328; Directorate Identifier 2006-NM-130-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, notified us that an unsafe condition may exist on certain Bombardier Model DHC-8-400 series airplanes. TCCA advises that a review conducted by the manufacturer revealed that the outboard brake control cable can become fouled on two fasteners on the pilot's bulkhead cover assembly. This condition, if not corrected, could result in abrasion and wear of the outboard brake control cable, which could lead to cable separation and reduced control of airplane braking.

Relevant Service Information

Bombardier has issued Service Bulletin 84-53-37, Revision 'C,' dated December 5, 2005. The service bulletin describes procedures for inspecting for fouling and chafing damage of the main landing gear outboard brake control cable, replacing the control cable if necessary, reworking the control cable cover, and, if not already installed, manufacturing/installing an offset plate on the control cable cover.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. TCCA mandated the service information and issued Canadian airworthiness directive CF-2006-05, dated March 31, 2006, to ensure the continued airworthiness of these airplanes in Canada.

FAA's Determination and Requirements of the Proposed AD

These airplane models are manufactured in Canada and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, TCCA has kept the FAA informed of the situation described above. We have examined TCCA's findings, evaluated all pertinent information, and determined that we need to issue an AD for airplanes of this type design that are certificated for operation in the United States.

Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously, except as discussed under "Clarification of Inspection Terminology."

Clarification of Inspection Terminology

The service bulletin specifies a "visual inspection;" however, this proposed AD would require a "general visual inspection." We have included the definition of a general visual inspection in a note in the proposed AD.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD, at an average labor rate of \$80 per work hour.

ESTIMATED COSTS

Action	Work hours	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Inspect brake cable	1	N/A	\$80	17	\$1,360.
Rework cable cover	3	N/A	240	17	4,080.
Manufacture/ install offset plate, as applicable	3	200	440	Up to 17	Up to \$7,480.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc. (Formerly de Havilland, Inc.): Docket No. FAA-2006-25328; Directorate Identifier 2006-NM-130-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by August 11, 2006.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Bombardier Model DHC-8-400 series airplanes, certificated in any category; having serial numbers 4003, 4004, 4006, 4008 through 4064 inclusive, 4072, and 4073.

Unsafe Condition

- (d) This AD results from a review of brake control cable operation conducted by the manufacturer. We are issuing this AD to prevent abrasion and wear of the outboard brake control cable, which could lead to cable separation and reduced control of airplane braking.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection of Control Cable

- (f) Within 12 months after the effective date of this AD, perform a general visual inspection for fouling and chafing damage of the outboard brake control cable of the main landing gear, in accordance with the Accomplishment Instructions of Bombardier

Service Bulletin 84-53-37, Revision "C," dated December 5, 2005.

Note 1: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Control Cable Cover Rework Only

(g) If no fouling or damage is found during the inspection required by paragraph (f) of this AD: Within 24 months after the accomplishment date of the inspection, rework the control cable cover and, as applicable, manufacture/install the offset plate assembly; in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-53-37, Revision "C," dated December 5, 2005.

Cable Replacement and Control Cable Cover Rework

(h) If any fouling or damage is found during the inspection required by paragraph (f) of this AD: Before further flight, replace the control cable with a new control cable, rework the control cable cover and, if not already installed, manufacture/install the offset plate assembly; in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-53-37, Revision "C," dated December 5, 2005.

Actions Accomplished According to Previous Issue of Service Bulletin

(i) Actions accomplished before the effective date of this AD in accordance with Bombardier Service Bulletin 84-53-37, Revision "A," dated October 17, 2005; or Revision "B," dated November 24, 2005; are considered acceptable for compliance with the corresponding actions specified in this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to

which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(k) Canadian airworthiness directive CF-2006-05, dated March 31, 2006, also addresses the subject of this AD.

Issued in Renton, Washington, on July 3, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-10912 Filed 7-11-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2006-25069; Airspace Docket No. 06-AWP-9]

Proposed Modification of Class E Airspace; Honolulu International Airport, HI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to modify the Class E airspace area at Honolulu International Airport, HI. The establishment of an Area Navigation (RNAV) Required Navigation Performance (RNP) Instrument Approach Procedures (IAP) to Runway (RWY) 08L and 26L at Honolulu International Airport, Honolulu, HI has made this proposal necessary. Additional controlled airspace extending upward from 700 feet or more above the surface of the earth is needed to contain aircraft executing the RNAV (RNP) IAP to RWY 08L/26L at Honolulu International Airport. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Honolulu International Airport, Honolulu, HI.

DATES: Comments must be received on or before August 28, 2006.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2006-25069/ Airspace Docket No. 06-AWP-9 at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal,

any comments received, and any final dispositions in person in the Docket Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the Office of the Regional Western Terminal Operations, Federal Aviation Administration, at 15000 Aviation Boulevard, Lawndale, California 90261, telephone number (310) 725-6502.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with the comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2006-25069/Airspace Docket No. 06-AWP-9." The postcard will be date/time stamped and returned to the commenter. All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the Superintendent of Document's Web page at <http://www.access.gpo.gov/nara>.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, Office of Air Traffic

Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both document numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedures.

The Proposal

The FAA is considering an amendment to 14 CFR part 71 by modifying the Class E airspace area at Honolulu International Airport, Honolulu, HI. The establishment of a RNAV (RNP) IAP to RWY 08L/26L at Honolulu International Airport has made this proposal necessary. Additional controlled airspace extending upward from 700 feet above the surface is needed to contain aircraft executing the RNAV (RNP) IAP to RWY 08L/26L at Honolulu International Airport. The intended effect of this proposal is to provide adequate controlled airspace for aircraft executing the RNAV (RNP) IAP to RWY 08L/26L at Honolulu International Airport, HI. Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9N dated September 1, 2005, and effective September 15, 2005, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in this Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will affect air traffic procedures and air navigation, it is certified that this proposed rule would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).