

directive in that it would require revising the AFM within 10 days after the effective date of this AD. In developing an appropriate compliance time for this AD, the FAA considered not only the DGAC's recommendation of revising the AFM as of the effective date of the French airworthiness directive, but the degree of urgency associated with addressing the subject unsafe condition, the average utilization of the affected fleet, and the time necessary to perform the revision (less than one hour). In light of all of these factors, the FAA finds a 10-day compliance time for completing the required AFM revision to be warranted, in that it represents an appropriate interval of time allowable for affected airplanes to continue to operate without compromising safety.

Costs of Compliance

This proposed AD would affect about 62 airplanes of U.S. registry, it would take approximately 1 work hour per airplane to accomplish the proposed AFM revision, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$4,960, or \$80 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA-2006-25421; Directorate Identifier 2006-NM-074-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by August 23, 2006.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to all Airbus Model A310 airplanes, certificated in any category.

Unsafe Condition

- (d) This AD results from several incidents of pitch oscillations with high vertical loads that occurred during turbulence at high altitudes. We are issuing this AD to prevent pitch oscillations during turbulence, which could result in reduced controllability of the airplane.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Revision of Airplane Flight Manual (AFM)

- (f) Within 10 days after the effective date of this AD, revise the Limitations section of

the Airbus A310 AFM to include the information in Temporary Revision (TR) 2.03.00/21, dated April 11, 2005. This may be done by inserting a copy of the TR into the AFM. When the TR has been included in the general revisions of the AFM, those general revisions may be inserted into the AFM, provided the relevant information in the general revisions is identical to that in the TR.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(h) French airworthiness directive F-2005-114, dated July 6, 2005, also addresses the subject of this AD.

Issued in Renton, Washington, on July 14, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-11722 Filed 7-21-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25422; Directorate Identifier 2006-NM-095-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 and EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all EMBRAER Model EMB-135 and EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. This proposed AD would require inspecting the fuel quantity indication system (FQIS) wire harness and the DC fuel pump wire harness to determine if the harnesses are properly attached at their respective attachment points and

properly separated from one another, and performing corrective actions if necessary. This proposed AD results from a report that the FQIS wire harness may not be properly attached at its attachment points or properly separated from the DC fuel pump wire harness. We are proposing this AD to prevent chafing between those harnesses or chafing of the harnesses against adjacent airplane structure or components, which could present a potential ignition source that could result in a fire or explosion.

DATES: We must receive comments on this proposed AD by August 23, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
 - Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
 - Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.
 - Fax: (202) 493-2251.
 - Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- Contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil, for service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number “FAA-2006-25422; Directorate Identifier 2006-NM-095-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT’s complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

The Departamento de Aviação Civil (DAC), which is the airworthiness authority for Brazil, notified us that an unsafe condition may exist on all EMBRAER Model EMB-135 and EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. The DAC advises that the fuel quantity indication system (FQIS) wire harness may not be properly attached at its attachment points and may not be properly separated from the DC fuel pump wire harness, due to the design of the area. This condition, if not corrected, could allow chafing between those harnesses or chafing of those harnesses against adjacent airplane structure or components, which could present a potential ignition source that could result in a fire or explosion.

Relevant Service Information

EMBRAER has issued Service Bulletin 145-28-0025, Revision 04, dated November 7, 2005. The service bulletin describes procedures for a one-time visual inspection of the FQIS harness and DC fuel pump wire harness to determine if the harnesses are properly attached at their respective attachment points and properly separated from one another. The inspection involves examining the condition of the harness

attachment points, making sure the harnesses cannot chafe against each other or against adjacent structure or components, and making sure that the harnesses are not attached to each other. As a corrective action if a discrepancy is found, the service bulletin describes procedures for rerouting the DC fuel pump wire harness if any harness is not properly attached or separated.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The DAC mandated the service information and issued Brazilian airworthiness directive 2006-03-01, dated April 19, 2006, to ensure the continued airworthiness of these airplanes in Brazil.

FAA’s Determination and Requirements of the Proposed AD

These airplane models are manufactured in Brazil and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DAC has kept the FAA informed of the situation described above. We have examined the DAC’s findings, evaluated all pertinent information, and determined that we need to issue an AD for airplanes of this type design that are certificated for operation in the United States.

Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously, except as discussed under “Difference Between the Proposed AD and Service Information.”

Difference Between the Proposed AD and Service Information

EMBRAER Service Bulletin 145-28-0025, Revision 04, does not specify a corrective action if a broken, frayed, cracked, or damaged wire, or a damaged harness, is found. This proposed AD would require that any such damage be repaired in accordance with relevant sections of the standard wiring practices manual.

Costs of Compliance

This proposed AD would affect about 494 airplanes of U.S. registry. The proposed actions would take about 1 work hour per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$39,520, or \$80 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the

AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Empresa Brasileira De Aeronautica S.A. (EMBRAER): Docket No. FAA-2006-25422; Directorate Identifier 2006-NM-095-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by August 23, 2006.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes; certificated in any category.

Unsafe Condition

(d) This AD results from a report that the fuel quantity indication system (FQIS) wire harness may not be properly attached or separated from the DC fuel pump wire harness. We are issuing this AD to prevent chafing between those harnesses or chafing of the harnesses against adjacent airplane

structure or components, which could present a potential ignition source that could result in a fire or explosion.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspecting Harnesses for Proper Attachment and Separation

(f) Within 5,000 flight hours after the effective date of this AD: Do a one-time general visual inspection of the FQIS wire harness and the DC fuel pump wire harness to determine if the harnesses are properly attached at their respective attachment points and properly separated from one another, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145-28-0025, Revision 04, dated November 7, 2005. All applicable corrective actions must be done before further flight.

Note 1: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Further Corrective Actions

(g) If any broken, frayed, cracked, or damaged wire, or a damaged harness, is found: Before further flight, repair the damaged wire or harness in accordance with relevant sections of the standard wiring practices manual.

Actions Accomplished Previously

(h) Actions done before the effective date of this AD in accordance with one of the service bulletins identified in Table 1 of this AD are acceptable for compliance with the corresponding actions required by this AD.

TABLE 1.—PREVIOUS ISSUES OF THE SERVICE INFORMATION

EMBRAER Service Bulletin	Revision level	Date
145-28-0025	None	April 19, 2004.
145-28-0025	01	June 9, 2004.
145-28-0025	02	November 8, 2004.
145-28-0025	03	April 28, 2005.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(j) Brazilian airworthiness directive 2006-03-01, dated April 19, 2006, also addresses the subject of this AD.

Issued in Renton, Washington, on July 14, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E6-11724 Filed 7-21-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Highway Administration

23 CFR Part 505

[FHWA Docket No. FHWA-05-23393]

RIN 2125-AF08

Projects of National and Regional Significance Evaluation and Rating

AGENCY: Federal Highway Administration (FHWA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); request for comments.

SUMMARY: Section 1301 of the Safe, Accountable, Flexible, Efficient Transportation Equity Act: A Legacy for Users (SAFETEA-LU) (Pub. L. 109-59; 119 Stat. 1144) established a program to provide grants to States for Projects of National and Regional Significance (PNRS) to improve the safe, secure, and efficient movement of people and goods throughout the United States and to improve the health and welfare of the national economy. Section 1301 requires the Secretary of Transportation (Secretary) to establish regulations on the manner in which the proposed projects will be evaluated and rated, in order to determine which projects shall receive grant funding. This proposed rule would establish the required evaluation and rating guidelines for proposed projects. If this rule were adopted, a proposed project would become eligible to be funded under this program only if the Secretary finds that the project meets the requirements of the rule. In making such findings, the Secretary will evaluate and rate each project as "highly recommended," "recommended," or "not recommended" based on the results of preliminary engineering, the project justification criteria, and the degree of non-Federal financial commitment.

DATES: Comments must be received on or before September 22, 2006. Late-filed comments will be considered to the extent practicable.

ADDRESSES: Mail or hand deliver comments to the U.S. Department of Transportation, Docket Management Facility, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590, or submit electronically at [http://](http://dms.dot.gov/submit)

dms.dot.gov/submit, or fax comments to (202) 366-7909.

Alternatively, comments may be submitted to the Federal eRulemaking portal at <http://www.regulations.gov>. All comments should include the docket number that appears in the heading of this document. All comments received will be available for examination and copying at the above address from 9 a.m. to 5 p.m., e.t., Monday through Friday, except Federal holidays. Those desiring notification of receipt of comments must include a self-addressed, stamped postcard or you may print the acknowledgment page that appears after submitting comments electronically. Anyone is able to search the electronic form of all comments in any one of our dockets by the name of the individual submitting the comment (or signing the comment, if submitted on behalf of an association, business, or labor union). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (Volume 65, Number 70, Pages 19477-78) or you may visit <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Mr. Edward Strocko, Office of Freight Management and Operations, HOFM-1, (202) 366-2997, Ms. Alla Shaw, Office of the Chief Counsel, (202) 366-1042, or Ms. Diane Mobley, Office of the Chief Counsel, (202) 366-1372, Federal Highway Administration, 400 Seventh St., SW., Washington, DC 20590. Office Hours are from 7:45 a.m. to 4:15 p.m., e.t., Monday through Friday, except Federal holidays.

SUPPLEMENTARY INFORMATION:

Electronic Access and Filing

You may submit or retrieve comments online through the Document Management System (DMS) at: <http://dms.dot.gov/submit>. Electronic submission and retrieval help and guidelines are available under the help section of the Web site. Alternatively, internet users may access all comments received by the U.S. DOT Docket Facility by using the universal resource locator (URL) <http://dms.dot.gov>. It is available 24 hours each day, 365 days each year. Please follow the instructions. An electronic copy of this document may also be downloaded by accessing the Office of the Federal Register's home page at: <http://www.archives.gov> or the Government Printing Office's Web page at <http://www.gpoaccess.gov/nara>.

Background

Section 1301 of SAFETEA-LU establishes a program to finance critical,

high-cost transportation infrastructure facilities that address critical national economic and transportation needs. These projects often involve multiple levels of government, agencies, modes of transportation, and transportation goals and planning processes that are not easily addressed or funded within existing surface transportation program categories. Projects of National and Regional Significance would have national and regional benefits, including improving economic productivity by facilitating international trade, relieving congestion, and improving transportation safety by facilitating passenger and freight movement. Additionally, this program would further the goals of the Secretary's Congestion Initiative.¹

The benefits of PNRS would accrue beyond local areas and States to the Nation as a whole. A program dedicated to constructing PNRS would improve the safe, secure, and efficient movement of people and goods throughout the United States as well as improve the health and welfare of the national economy. The FHWA specifically invites comments that contribute to an understanding and a quantification of the term national and/or regional economic benefits.

Under the proposed regulations, a State seeking a grant for a proposed PNRS would submit to the Secretary an application that demonstrates the ability of the proposed project to enhance the national transportation system, generate national economic benefits, reduce congestion, improve transportation safety, and attract non-Federal investment.

The Secretary shall evaluate and rate each proposed project as "highly recommended," "recommended," or "not recommended" based on the results of preliminary engineering, the project justification criteria, and degree of non-Federal financial commitments. If the Secretary finds that the proposed project meets the requirements of the regulations, and there is a reasonable likelihood that the project will continue to meet such requirements, the Secretary may issue a letter of intent to obligate an amount from future available budget authority specified in law or execute a full funding grant agreement

¹ Speaking before the National Retail Foundation's annual conference on May 16, 2006, in Washington, DC, U.S. Transportation Secretary Norman Mineta unveiled a new plan to reduce congestion plaguing America's roads, rail and airports. The National Strategy to Reduce Congestion on America's Transportation Network includes a number of initiatives designed to reduce transportation congestion and is available at the following URL: <http://isddc.dot.gov/OLPFiles/OST/012988.pdf>.