

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Saab Aircraft AB: Docket 96–NM–167–AD.

Applicability: Model SAAB 2000 series airplanes having serial numbers 005 through 029 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent false fire warning inputs of the engines and Auxiliary Power Unit (APU), which could result in unnecessary diversion of the airplane, resultant increased risks to the airplane, passengers, and crew, and the potential for an overweight landing; accomplish the following:

(a) Within 4 months after the effective date of this AD, replace the existing fire (engine/APU), tailpipe, and bleed-air overheat detector control units with new, improved control units, in accordance with Saab Service Bulletin 2000–26–002, dated May 9, 1995.

(b) As of the effective date of this AD, no person shall install a fire, tailpipe, or bleed-air detector control unit having part number 25000020–21, 25000021–31, or 25000020–11, on any airplane.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM–113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM–113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD

can be accomplished. Issued in Renton, Washington, on April 25, 1997.

Neil D. Schalekamp,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Dos. 97–11333 Filed 4–30–97; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96–NM–170–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A300–600 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A300–600 series airplanes. This proposal would require repetitive inspections to detect fatigue cracking in the left and right wings in the area where the top skin attaches to the center spar; and repair or modification of this area, if necessary. This proposal is prompted by a report from the manufacturer indicating that, during full-scale fatigue testing of the airframe, fatigue cracking was detected in this area. The actions specified by the proposed AD are intended to detect and correct this cracking, which could reduce the residual strength of the top skin of the wings, and consequently affect the structural integrity of the airframe.

DATES: Comments must be received by June 12, 1997.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–103, Attention: Rules Docket No. 96–NM–170–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Charles Huber, Aerospace Engineer,

Standardization Branch, ANM–113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (206) 227–2589; fax (206) 227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 96–NM–170–AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM–103, Attention: Rules Docket No. 96–NM–170–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, has notified the FAA that an unsafe condition may exist on certain Airbus Model A300–600 series airplanes. The DGAC advises that it has received a report from the manufacturer indicating that, during full-scale fatigue testing of the airframe, fatigue cracking was detected in an area of the wing where the top skin attaches to the center spar between ribs 1 and 7. This cracking originated in clearance fit fastener holes of joints between the skin and the center

spar, and was detected between 33,000 and 49,000 simulated flights.

Initially, it was thought that this cracking was limited to a few airplanes. The manufacturer, however, has found that cracking is more widespread, and is apparently caused by shear stresses resulting from loads on the landing gear.

This fatigue cracking, if not detected and corrected, could reduce the residual strength of the top skin of the wings, and consequently affect the structural integrity of the airframe.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A300-57-6044, Revision 2, dated September 6, 1995, which describes procedures for conducting repetitive inspections to detect fatigue cracking in the left and right wings in the area where the top skin attaches to the center spar between ribs 1 and 7; and repair or modification of this area, if necessary.

The modification (Airbus Modification 10089) entails reinforcement of this area and is intended to prevent cracking. If that modification has not been installed prior to the initial inspection, operators must inspect using either a detailed visual inspection or a high frequency eddy current (HFEC) technique to detect fatigue cracking, and repair, if necessary. Should cracking exceed 75 mm per rib bay, however, Airbus recommends the installation of the modification. If Airbus Modification 10089 has been installed prior to the initial inspection, operators are to conduct a low frequency eddy current inspection to detect fatigue cracking of the inboard and rear edges of the top skin reinforcing plate.

The Airbus service bulletin references Airbus Service Bulletin A300-57-6041, Revision 4, dated November 16, 1995, as an additional source of service information for installing Airbus Modification 10089.

The DGAC classified Airbus Service Bulletin A300-57-6044 as mandatory and issued French airworthiness directive (C/N) 95-086-180(B) R1, dated December 6, 1995, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed

of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require repetitive inspections to detect fatigue cracking in the left and right wings in the area where the top skin attaches to the center spar between ribs 1 and 7; and repair or modification of this area, if necessary.

Repair of cracking found on airplanes on which Airbus Modification 10089 has been accomplished would be required to be accomplished in accordance with a method approved by the FAA. Other actions would be required to be accomplished in accordance with Airbus Service Bulletin A300-57-6044, described previously.

Cost Impact

The FAA estimates that 35 Airbus Model A300-600 series airplanes of U.S. registry would be affected by this proposed AD.

For airplanes on which Airbus Modification 10089 has not been installed, it would take approximately 2 hours to accomplish each detailed visual inspection or 3 hours to accomplish each HFEC inspection. The average labor rate is \$60 per work hour.

Based on these figures, the cost impact of each proposed inspection on U.S. operators is estimated to be either \$120 or \$180 per airplane, depending on the type of inspection conducted.

For airplanes on which Airbus Modification 10089 has been installed, it would take approximately 3 hours to accomplish each low frequency eddy current inspection.

The average labor rate is \$60 per work hour. Based on these figures, the cost impact of each proposed inspection on U.S. operators is estimated to be \$180 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects

on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus: Docket 96-NM-170-AD.

Applicability: Model A300-600 series airplanes, on which Airbus Modification 10160 has not been installed during production; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or

repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct fatigue cracking in the left and right wings in the area where the top skin attaches to the center spar, which could reduce the residual strength of this skin, and consequently affect the structural integrity of the airframe, accomplish the following:

(a) For airplanes on which Airbus Modification 10089 has not been installed: Prior to the accumulation of 18,000 total landings, or within 1,500 landings after the effective date of this AD, whichever occurs later, conduct either a detailed visual inspection or a high frequency eddy current (HFEC) inspection to detect fatigue cracking in the left and right wings in the area where the top skin attaches to the center spar between ribs 1 and 7, in accordance with Airbus Service Bulletin A300-57-6044, Revision 2, dated September 6, 1995.

(1) If no cracking is detected, conduct repetitive inspections thereafter at the following intervals:

(i) If the immediately preceding inspection was conducted using detailed visual techniques, conduct the next inspection within 5,000 landings.

(ii) If the immediately preceding inspection was conducted using HFEC techniques, conduct the next inspection within 9,500 landings.

(2) If any cracking is detected or suspected during any detailed visual inspection required by paragraph (a), (a)(1), or (a)(3)(i) of this AD, prior to further flight, confirm this finding and the length of this cracking by conducting a HFEC inspection, in accordance with the service bulletin. If no cracking is confirmed during the HFEC inspection, accomplish the repetitive inspection required by paragraph (a)(1)(ii) of this AD at the time specified in that paragraph.

(3) If any cracking is detected or confirmed during any HFEC inspection required by paragraph (a), (a)(1), or (a)(2) of this AD:

(i) If the cracking is 75 mm or less per rib bay, prior to further flight, repair in accordance with the service bulletin. Thereafter, conduct repetitive detailed visual inspections of the repaired area at intervals not to exceed 50 landings, in accordance with the service bulletin.

(ii) If the cracking exceeds 75 mm per rib bay, prior to further flight, install Airbus Modification 10089, in accordance with the service bulletin. Thereafter, conduct a low frequency eddy current inspection in accordance with the requirements of paragraph (b) of this AD.

Note 2: The Airbus service bulletin references Airbus Service Bulletin A300-57-6041, Revision 4, dated November 16, 1995, as an additional source of service information for installing Airbus Modification 10089.

(b) For airplanes on which Airbus Modification 10089 has been installed: Prior to the accumulation of 22,000 total landings after this modification has been installed, or within 1,500 landings after the effective date of this AD, whichever occurs later, conduct

a low frequency eddy current inspection to detect fatigue cracking in the inboard and rear edges of the top skin reinforcing plates, in accordance with Airbus Service Bulletin A300-57-6044, Revision 2, dated September 6, 1995.

(1) If no cracking is detected, repeat this inspection thereafter at intervals not to exceed 11,000 landings.

(2) If any cracking is detected, prior to further flight, repair in accordance with a method approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Thereafter, repeat this inspection at intervals not to exceed 11,000 landings.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 25, 1997.

Neil D. Schalekamp,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 97-11332 Filed 4-30-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 97-AWP-20]

Proposed Establishment of Class E Airspace; Davis/Woodlands/Winters, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to establish a Class E airspace area at Davis/Woodland/Winters, CA. The development of a Global Positioning System (GPS) Runway (RWY) 16/34 and a VHF Omnidirectional Range (VOR) RWY 34 Standard Instrument Approach Procedure (SIAP) at Yolo County-Davis/Woodland/Winters Airport has made this proposal necessary. The intended effect of this proposal is to provide

adequate controlled airspace for Instrument Flight Rules (IFR) operations at Yolo County-Davis/Woodland/Winters Airport, Davis/Woodland/Winters, CA.

DATES: Comments must be received on or before June 13, 1997.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Attn: Manager, Operations Branch, AWP-530, Docket No. 97-AWP-20, Air Traffic Division, P.O. Box 92007, Worldway Postal Center, Los Angeles, California, 90009.

The official docket may be examined in the Office of the Assistant Chief Counsel, Western Pacific Region, Federal Aviation Administration, Room 6007, 15000 Aviation Boulevard, Lawndale, California, 90261.

An informal docket may also be examined during normal business at the Office of the Manager, Operations Branch, Air Traffic Division at the above address.

FOR FURTHER INFORMATION CONTACT: William Buck, Airspace Specialist, Operations Branch, AWP-530, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California, 90261, telephone (310) 725-6556.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with the comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 97-AWP-20." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light