

it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket (otherwise, an evaluation is not required). A copy of it, if filed, may be obtained from the Rules Docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by removing Airworthiness Directive (AD) 97-15-13, Amendment 39-10087, and by adding a new AD to read as follows:

**97-15-13 R1 Raytheon Aircraft Company:** Amendment 39-10131; Docket No. 96-CE-60-AD. Revises AD 97-15-13, Amendment 39-10087.

**Applicability:** The following airplane models and serial numbers, certificated in any category:

Model	Serial Nos.
1900 .....	UA-1 through UA-3.
1900C .....	UB-1 through UB-74, and UC-1 through UC-174.
1900C (C-12J).	UD-1 through UD-6.
1900D .....	UE-1 through UE-157.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For

airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required within the next 200 hours time-in-service after the effective date of this AD, unless already accomplished.

To prevent moisture from accumulating and freezing in the airstair door handle and latch housing, which could result in the door freezing shut and passengers not being able to evacuate the airplane in an emergency situation, accomplish the following:

(a) Install lubrication fittings in the airstair door handle and latch housing mechanisms in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Raytheon Mandatory Service Bulletin No. 2572, dated July, 1996.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

(d) The installation required by this AD shall be done in accordance with Raytheon Mandatory Service Bulletin No. 2572, dated July, 1996. This incorporation by reference was previously approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51 as of September 5, 1997 (62 FR 39927, July 25, 1997). Copies may be obtained from the Raytheon Aircraft Company, P.O. Box 85, Wichita, Kansas 67201-0085. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment (39-10131) revises AD 97-15-13, Amendment 39-10087.

(f) This amendment (39-10131) becomes effective on September 22, 1997.

Issued in Kansas City, Missouri, on September 8, 1997.

**James E. Jackson,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 97-25052 Filed 9-19-97; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97-ANE-03; Amendment 39-10138; AD 97-19-18]

RIN 2120-AA64

#### Airworthiness Directives; AlliedSignal Inc. TSCP700-4B and -5 Auxiliary Power Units

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment supersedes an existing airworthiness directive (AD), applicable to AlliedSignal Inc. (formerly AiResearch and Garrett) TSCP700-4B and -5 Series Auxiliary Power Units (APUs), that currently requires restretching the first stage low pressure compressor (LPC) tie rods, or replacing affected disks at or before 8,000 cycles since new (CSN). This amendment requires removing from service affected disks, replacing them with serviceable parts, and establishing a life limit of 8,000 CSN for affected disks. This amendment is prompted by a report of a first stage LPC disk rim separation due to low cycle fatigue on an APU that had its tie rods restretched in accordance with the current AD. The actions specified by this AD are intended to prevent first stage LPC disk rim separation due to low cycle fatigue, which could result in an uncontained APU failure and damage to the aircraft.

**DATES:** Effective October 27, 1997.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 27, 1997.

**ADDRESSES:** The service information referenced in this AD may be obtained from AlliedSignal Aerospace, Attn: Data Distribution, M/S 64-3/2101-201, P.O. Box 29003, Phoenix, AZ 85038-9003; telephone (602) 365-2493, fax (602) 365-5577. This information may be examined at the Federal Aviation Administration (FAA), New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA 01803-5299; or at

the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Robert Baitoo, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712-4137; telephone (562) 627-5245; fax (562) 627-5210.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 88-24-07, Amendment 39-6062 (53 FR 46439, November 17, 1988), which is applicable to AlliedSignal Inc. (formerly AiResearch and Garrett) TSCP700-4B and -5 series auxiliary power units (APUs), was published in the **Federal Register** on March 18, 1997 (62 FR 12774). That action proposed to eliminate the option of restretching the tie rods, and require removing from service affected disks in accordance with a schedule derived from calculations in AlliedSignal Inc. Service Bulletin (SB) No. TSCP700-49-7266, dated June 16, 1996, replacing affected disks with serviceable parts, and establishing a life limit of 8,000 cycles since new (CSN) for affected disks.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

One commenter (the manufacturer) states that the AD should not imply that the tie rod restretch is ineffective, as the manufacturer believes that the tie rod restretch is beneficial in minimizing disk liberation. The FAA concurs that tie rod restretching is beneficial; however, the FAA has determined through analysis that the life limit of affected disks must be reduced to 8,000 CSN regardless of tie rod restretch in order to ensure safe operation.

Three commenters concur with the rule as proposed.

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that 100 APUs installed on aircraft of U.S. registry will be affected by this AD, no additional work hours per APU to accomplish the proposed actions if the actions are accomplished during APU overhaul, 8 work hours to accomplish the required

actions if the actions are not accomplished during APU overhaul, and that the average labor rate is \$60 per work hour. Based on these figures, and that the work would not be performed during overhaul, the total cost impact of the AD on U.S. operators is estimated to be \$48,000.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### **List of Subjects in 14 CFR Part 39**

Air Transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### **Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### **§ 39.13 [Amended]**

2. Section 39.13 is amended by removing Amendment 39-6062 (53 FR 46439, November 17, 1988) and by adding a new airworthiness directive,

Amendment 39-XXXX, to read as follows:

**97-XX-XX AlliedSignal Inc.:** Amendment 39-XXXX. Docket 97-ANE-03. Supersedes AD 88-24-07, Amendment 39-6062.

**Applicability:** AlliedSignal Inc. (formerly AiResearch and Garrett) TSCP700-4B and -5 auxiliary power units (APUs), with first stage low pressure compressor (LPC) disks, Part Number (P/N) 3606429-1, installed on but not limited to Airbus A300 series, and McDonnell Douglas DC-10 and KC-10 (military) series aircraft.

**Note 1:** This airworthiness directive (AD) applies to each APU identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For APUs that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent first stage LPC disk rim separation due to low cycle fatigue, which could result in an uncontained APU failure and damage to the aircraft, accomplish the following:

(a) Remove from service first stage LPC disks, P/N 3606429-1, in accordance with the schedule derived from calculations in paragraph C.(3) of AlliedSignal Service Bulletin (SB) No. TSCP700-49-7266, dated June 16, 1996, and the removal procedures described in the Accomplishment Instructions of that SB, and replace with serviceable parts.

(b) Except as provided in paragraph (a), this AD establishes a life limit of 8,000 cycles since new (CSN) for first stage LPC disks, P/N 3606429-1.

(c) The definition of a disk cycle may be found in the applicable AlliedSignal Inc. APU Component Maintenance Manual.

(d) Except as provided in paragraph (e) of this AD, no alternative replacement times may be approved for first stage LPC disks, P/N 3606429-1.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles Aircraft Certification Office.

**Note 2:** Information concerning the existence of approved alternative method of compliance with this AD, if any, may be obtained from the Los Angeles Aircraft Certification Office.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

(g) The actions required by this AD shall be done in accordance with the following AlliedSignal Inc. SB:

Document No.	Pages	Date
TSCP700-49-7266. Total pages: 6.	1-6	June 16, 1996.

This incorporation by reference was approved by the Director of the **Federal Register** in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from AlliedSignal Aerospace, Attn: Data Distribution, M/S 64-3/2101-201, P.O. Box 29003, Phoenix, AZ 85038-9003; telephone (602) 365-2493, fax (602) 365-5577. Copies may be inspected at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment becomes effective on October 27, 1997.

Issued in Burlington, Massachusetts, on September 12, 1997.

**Mark C. Fulmer,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 97-24910 Filed 9-19-97; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97-NM-36-AD; Amendment 39-10141; AD 97-20-03]

RIN 2120-AA64

#### Airworthiness Directives; de Havilland Model DHC-7 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to all de Havilland Model DHC-7 series airplanes, that requires revising the Airplane Flight Manual (AFM) to prohibit positioning of the power levers below the flight idle stop during flight, and to add a statement of the consequences of such positioning of the power levers. This amendment is prompted by incidents and accidents involving airplanes equipped with turboprop engines in which the propeller ground beta range was used

improperly during flight. The actions specified by this AD are intended to prevent loss of airplane controllability, or engine overspeed and consequent loss of engine power caused by the power levers being positioned below the flight idle stop when the airplane is in flight.

**EFFECTIVE DATE:** October 27, 1997.

**ADDRESSES:** Information pertaining to this rulemaking action may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York.

#### FOR FURTHER INFORMATION CONTACT:

Peter LeVoci, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7514; fax (516) 568-2716.

#### SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all de Havilland Model DHC-7 series airplanes was published in the **Federal Register** on April 15, 1997 (62 FR 18304). That action proposed revising the Limitations Section of the Airplane Flight Manual (AFM) to prohibit positioning the power levers below the flight idle stop while the airplane is in flight, and to add a statement of the consequences of positioning the power levers below the flight idle stop while the airplane is in flight.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule, but remarks that, if an inherent design problem exists on the affected airplanes to allow flightcrews to select the power levers below the flight idle stop while in flight, the FAA should consider the addition of a mechanical means to preclude such selection. The FAA acknowledges the commenter's concern, and may consider additional rulemaking to address that concern in the future on certain airplanes. However, until such final action is identified, the FAA considers it appropriate to proceed with issuance of this final rule. No change to the final rule is required.

## Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

## Cost Impact

The FAA estimates that 45 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$2,700, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

## Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

## Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows: