

Rules and Regulations

Federal Register

Vol. 62, No. 191

Thursday, October 2, 1997

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

FARM CREDIT ADMINISTRATION

12 CFR Part 602

RIN 3052-AB77

Releasing Information; Effective Date

AGENCY: Farm Credit Administration.

ACTION: Notice of effective date.

SUMMARY: The Farm Credit Administration (FCA) published a final rule under part 602 on August 1, 1997 (62 FR 41253). The final rule amends the regulations governing the release of information. The objective of the final rule is to conform applicable FCA regulations to the requirements of the Freedom of Information Act (FOIA), 5 U.S.C. 552, as amended by the Electronic Freedom of Information Act Amendments of 1996, Pub. L. 104-231, and to clarify the address of the FCA official who receives FOIA requests for records. In accordance with 12 U.S.C. 2252, the effective date of the final rule is 30 days from the date of publication in the **Federal Register** during which either or both Houses of Congress are in session. Based on the records of the sessions of Congress, the effective date of the regulations is October 2, 1997.

EFFECTIVE DATE: The regulation amending 12 CFR part 602 published on August 1, 1997 (62 FR 41253) is effective October 2, 1997.

FOR FURTHER INFORMATION CONTACT:

John Hays, Policy Analyst, Policy Development and Risk Control, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4498; or

Jane Virga, Senior Attorney, Office of General Counsel, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4020, TDD (703) 883-4444.

(12 U.S.C. 2252(a) (9) and (10))

Dated: September 29, 1997.

Floyd Fithian,

Secretary, Farm Credit Administration Board.

[FR Doc. 97-26162 Filed 10-1-97; 8:45 am]

BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96-SW-30-AD; Amendment 39-10149; AD 97-20-12]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Helicopter Systems Model MD-900 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to McDonnell Douglas Helicopter Systems (MDHS) Model MD-900 helicopters, that requires removing certain serial-numbered main rotor swashplate bearings (bearings) and replacing them with airworthy bearings. This amendment is prompted by reports that inspections of several helicopters revealed that the outer bearing race had been rotating relative to the swashplate assembly, which was evidenced by wear marks in the rotating swashplate. The actions specified by this AD are intended to prevent possible heat accumulation and resulting damage to the bearing caused by the bearing races rotating relative to the bearing seat, which could result in degraded helicopter response to pilot control input and possible loss of control of the helicopter.

EFFECTIVE DATE: November 6, 1997.

FOR FURTHER INFORMATION CONTACT: Mr. Greg DiLibero, Aerospace Engineer, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Blvd., Lakewood, California 90712, telephone (310) 627-5231, fax (310) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to MDHS Model MD-900 helicopters was published in the **Federal Register** on January 29, 1997

(62 FR 4217). That action proposed to require, before further flight, inspecting the bearing, part number (P/N) 900C3010100-101, to determine if a bearing having serial number (S/N) 059150-E0019, S/N 059150-E0020, S/N 059150-E0021, S/N 059150-E0022, S/N 059150-E0023, S/N 059150-E0024, S/N 059150-E0025, S/N 059150-E0026, S/N 059150-E0027, S/N 059150-E0028, S/N 059150-E0029, or S/N 059150-E0030 is installed; and, if installed, removing and replacing that bearing with an airworthy bearing.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed, with two changes. The FAA has determined that special flight permits may be issued to operate the helicopter to a location where the requirements of this AD can be accomplished. This is now stated in paragraph (i) of the AD. Also, the FAA has determined that this AD should only apply to the Model MD-900 helicopters, not the Model MD-900 "series" helicopters. Therefore, the word "series" is removed from the applicability paragraph of this AD. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that 20 helicopters of U.S. registry will be affected by this AD, that it will take approximately 1.5 work hours per helicopter to determine the bearing's S/N, 12 work hours per helicopter to remove and replace a bearing, and that the average labor rate is \$60 per work hour. Replacement bearings would cost \$8,765 per helicopter, however, replacement bearings are covered by a manufacturer's warranty. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$5,400, assuming five helicopters will require removal and replacement of the bearing.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various

levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

97-20-12 McDonnell Douglas Helicopter Systems: Amendment 39-10149. Docket No. 96-SW-30-AD.

Applicability: Model MD-900 helicopters, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (h) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification,

alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required before further flight, unless accomplished previously.

To prevent possible heat accumulation and resulting damage to the main rotor swashplate bearing (bearing) caused by the bearing races rotating relative to the bearing seat, which could result in degraded helicopter response to pilot control input and possible loss of control of the helicopter, accomplish the following:

- (a) Disconnect the lower end of the main rotor pitch links. Disconnecting the drive link may make the inspection easier.
- (b) Cut the safety wire and remove the inner and outer labyrinth seals, part number (P/N) 900C2010194-101 and P/N 900C201190-101, respectively, and the inner and outer bearing retaining rings.
- (c) Inspect the bearing, part number (P/N) 900C3010100-101, to determine if it has one of the following serial numbers (S/N): S/N 059150-E0019, S/N 059150-E0020, S/N 059150-E0021, S/N 059150-E0022, S/N 059150-E0023, S/N 059150-E0024, S/N 059150-E0025, S/N 059150-E0026, S/N 059150-E0027, S/N 059150-E0028, S/N 059150-E0029, or S/N 059150-E0030.

Note 2: S/N's similar to those above were produced without the character "E" in the number. This AD is only concerned with those that contain the character "E".

(d) Enter into the helicopter Log Book the bearing S/N.

(e) If a bearing having one of the S/N's stated in paragraph (c) of this AD is installed on the helicopter, remove the bearing and replace it with an airworthy bearing prior to further flight.

(f) Prior to the installation of a swashplate assembly, inspect the bearing in accordance with the requirements of this AD.

(g) Report the results of all inspections required by this AD within 72 hours to the Manager, Los Angeles Aircraft Certification Office, 3960 Paramount Blvd., Lakewood, California 90712. Reporting requirements have been approved by the Office of Management and Budget and assigned OMB control number 2120-0056.

(h) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Los Angeles Aircraft Certification Office.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles Aircraft Certification Office.

(i) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(j) This amendment becomes effective on November 6, 1997.

Issued in Fort Worth, Texas, on September 24, 1997.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 97-25970 Filed 10-1-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-CE-94-AD; Amendment 39-10150; AD 97-20-14]

RIN 2120-AA64

Airworthiness Directives; Mitsubishi Heavy Industries, Ltd., MU-2B Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all Mitsubishi Heavy Industries, Ltd. (Mitsubishi) MU-2B series airplanes. This AD requires incorporating information into the Limitations Section of the Airplane Flight Manual (AFM) that would require pilot training before flight into known or forecast icing conditions after a certain date. This AD results from the Federal Aviation Administration's analysis that the current training level of the pilots-in-command (PIC) of the MU-2B series airplanes makes it difficult for pilots to recognize adverse operating conditions and operate safely while flying in icing conditions. Similar training to that required in this AD for pilots of other high performance airplanes has shown a lower accident rate over time after the training than before. The actions specified by this AD are intended to decrease the chance of icing-related incidents or accidents of the MU-2B series airplanes due to pilot error.

DATES: Effective October 17, 1997.

Comments for inclusion in the Rules Docket must be received on or before November 24, 1997.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 97-CE-94-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Information related to this AD may be examined at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. John Dow, Aerospace Engineer, FAA,